


s.22

GOVERNMENT
AGENT

SEP 01 1987

KAMLOOPS

August 28th, 1987.

Water Recorders Office
7 West Seymour Street
Kamloops B.C.
V2C 1E5

Dear Sir:

I Along with ^{s.22} and ^{s.22} are owners of
Lake front lot ^{s.22} forming part of District lot 2920.

Recently we discovered that Mr. Petr Sura of lot 4 plan 21015 applied and received a license to control a stream for his own use. This transpired apparently in 1984. Since that time Mr. Sura proceeded to construct a water reservoir and divert the flow of all springs into his reservoir thereby affecting the domestic water supply of all cottage owners located on Lake front property below him. All of this transpired without the knowledge of any of the Cottage owners.

In 1980 when ^{s.22} and ^{s.22} purchased lot ^{s.22} there was a small stream running along one side of the lot. This was tapped some distance up the mountain side and led down to the Cottage in a 1" black poly pipe to provide us with a domestic water supply. Up until 1985 there was sufficient flow in this stream to provide us with water all summer and fall up to end of October. Since 1985 with the work performed by Mr. Sura the flow on these ~~spr-~~ings has decreased to the point that there is insufficient water to provide us and the other Cottage owners with an adequate supply of domestic water from July onward.

I would appreciate if you would advise me as to any and all procedures and resources we may have to rectify this present situation. In our opinion it is not right for someone to grab all of the limited flow of water from the few small springs that exist in the area thereby depriving others of a suitable source of domestic water supply.

Yours truly

s.22



Province of
British Columbia

Ministry of
Environment

1259 Dalhousie Drive
Kamloops
British Columbia
V2C 5Z5
Telephone: (604) 374-9717

YOUR FILE

3000652

OUR FILE

September 15, 1987

s.22

Cited sketches
are absent

JN 29 Jun/22

Dear Sir:

RE: Diversion of Water by Mr. Petr Sura

Thankyou for your letter of August 28, 1987. Field inspection of Mr. Sura's installation in November, 1986 showed him to be tapping a single surface source located approximately as shown on the attached sketch. This source may be tributary of the small stream s.22 (2nd sketch attached).

We will schedule a further inspection of the site to ensure that no unauthorized changes have been made since our previous visit which would divert other sources into the reservoir.

At the time of an application for a water licence, applicants are required to notify only downstream licence holders on the same source or connected stream. As only Lots s.2 and s.22 have rights on s.22, and they are upstream of Mr. Sura's lot, no notice was required to be given.

Yours truly,

J.A. Truscott, A.Sc.T.,
Engineering Technician

JAT:lb
Enc.