Incident Report Page 1 of 4

PROVINCE OF BRITISH COLUMBIA

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: DSQ 2014 07 16 17 01

Location of Incident: 38082 CLARKE DRIVE SQUAMISH BC V8B 0L6

of Occupants (At time of fire): 0 # of Injured: 0 # of Deaths: 0 Total Dollar Loss Estimate: \$.22

Related to Wildland Interface Fire: NO Property Value: \$.22 Content Value: \$.22 Total Value at Risk: \$.22

Code Name : Code Description

PROPERTY COMPLEX: 3400 RESIDENTIAL - SINGLE DETACHED

PROPERTY CLASSIFICATION: 3110 YEAR-ROUND USE DWELLING - 1-FAMILY

GENERAL CONSTRUCTION: 1000 COMBUSTIBLE CONSTRUCTION - OPEN WOOD JOIST

BUILDING HEIGHT: $0020\ 2$ STORIES ABOVE GRADE

GROUND FLOOR AREA: 2000 101 TO 500M2 (1077 - 5382FT2)

YEAR OF CONSTRUCTION: 0066 1966 TO 1968

MANUAL FIRE PROTECTION: 7000 NO MANUAL FIRE PROTECTION

OUTSIDE FIRE PROTECTION: 7000 FIRE DEPARTMENT ONLY

SPRINKLER PROTECTION: 7000 NO SPRINKLER PROTECTION

AUTOMATIC FIRE ALARM SYSTE: 1000 NO FIRE ALARM SYSTEM

SMOKE ALARM OPERATION: 0000 ALARM OPERATION CANNOT BE DETERMINED

INITIAL DETECTION: 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S

TRANSMISSION OF ALARM: 1000 911

FIRE SERVICE: 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT

INCIDENT: 1000 FIRE - FIRE DEPARTMENT ATTENDED

ACTION TAKEN: 3000 EXTINGUISHED BY FIRE DEPARTMENT

METHOD OF FIRE CONTROL: 4500 65MM/77MM (2 1/2"/3") HOSE -2 OR MORE HAND LINES

FIRE ORIGIN, LEVEL : 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)

FIRE ORIGIN, AREA: 9300 PARKING AREA

EXTENT OF FIRE: 6000 EXTENDED BEYOND PROPERTY OF ORIGIN EXTENT OF DAMAGE: 6000 EXTENDED BEYOND BUILDING OF ORIGIN

IGNITING OBJECT: 0000 CANNOT BE DETERMINED FUEL OR ENERGY: 0000 CANNOT BE DETERMINED FORM OF HEAT: 0000 CANNOT BE DETERMINED

MATERIAL FIRST IGNITED: 0000 CANNOT BE DETERMINED

ACT OR OMISSION: 0000 CANNOT BE DETERMINED

Investigating Officer LAFC Badge #

FULTON, BOB 1138

Telephone

ReportDate 2015-03-04

604-898-9666

Incident Report Page 2 of 4

PROVINCE OF BRITISH COLUMBIA Ministry of Justice Emergency Management BC / Office of the Fire Commissioner FIRE REPORT - STRUCTURE (NARRATIVE)

INCIDENT NUMBER: DSQ 2014 07 16 17 01

Remarks:

FIRE STARTED IN THE CARPORT AREA ON A HOT AFTERNOON (30 DEGREES PLUS) FUELED BY HIGH WINDS. (30 K PLUS) THERE WERE SEVERAL POSSIBLE SOURCES OF IGNITION IN THE AREA OF ORIGIN INCLUDING DISCARDED OILY RAGS, BATTERIES CHARGING AND GRINDING HAD TAKEN PLACE. THE FIRE DAMAGE WAS TOO EXTENSIVE TO DETERMINE A CAUSE.

Investigating Officer FULTON, BOB LAFC Badge # 1138

adge # Telephone 604-898-9666

ReportDate

2015-03-04

Page 3 of 4 Incident Report

PROVINCE OF BRITISH COLUMBIA

FIRE REPORT - STRUCTURE (NAMES)

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

INCIDENT NUMBER: DSQ 2014 07 16 17 01

: OWNER

: < 22

Name no. : 1

Name

: \$.22 : 38082 CLARKE DRIVE Address

SQUAMISH BRITISH COLUMBIA

Claims Adjuster Name Claims Adjuster Firm

: 1. DALGLEISH, HEATHER

Claim Number

: 1. DALGLEISH INSURANCE ADJUSTMENT e 22 :1. WAWANESA MUTAL INS CO.

Insurance Company s 22

Policy Number

LOSS ESTIMATES:

Property Loss: c 22

Content Loss: s 22

Total Loss: s 22

Name Status

Phone

REMARKS:

Investigating Officer LAFC Badge # Telephone ReportDate FULTON, BOB 604-898-9666 1138 2015-03-04

> Page 3 of 4 JAG-2015-50479 2015-03-30

Incident Report Page 4 of 4