Incident Report Page 1 of 5

PROVINCE OF BRITISH COLUMBIA

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: DLF 2013 06 20 01 01

Location of Incident: 991 BONAVISTA PL

LANGFORD DISTRICT BC

# of Injured: 0 # of Deaths: 0 # of Occupants (At time of fire): 6 Total Dollar Loss Estimate: \$5.22

Related to Wildland Interface Fire: NO Property Value: \$5.22 Content Value: \$s.22 Total Value at Risk: \$5.22

> Code Name: **Code Description**

PROPERTY COMPLEX: 3400 RESIDENTIAL - SINGLE DETACHED

PROPERTY CLASSIFICATION: 3110 YEAR-ROUND USE DWELLING - 1-FAMILY

GENERAL CONSTRUCTION: 2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST

BUILDING HEIGHT: 0020 2 STORIES ABOVE GRADE

GROUND FLOOR AREA: 2000 101 TO 500M2 (1077 - 5382FT2)

YEAR OF CONSTRUCTION: 2002 2002

MANUAL FIRE PROTECTION: 7000 NO MANUAL FIRE PROTECTION

OUTSIDE FIRE PROTECTION: 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT

SPRINKLER PROTECTION: 7000 NO SPRINKLER PROTECTION

AUTOMATIC FIRE ALARM SYSTE: 1000 NO FIRE ALARM SYSTEM

SMOKE ALARM OPERATION: 1000 ALARM ACTIVATED - ASSISTED OCCUPANT(S) IN EVACUATING

INITIAL DETECTION: 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S

TRANSMISSION OF ALARM: 1000 911

FIRE SERVICE: 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT

INCIDENT: 1000 FIRE - FIRE DEPARTMENT ATTENDED

ACTION TAKEN: 3000 EXTINGUISHED BY FIRE DEPARTMENT

METHOD OF FIRE CONTROL: 4500 65MM/77MM (2 1/2"/3") HOSE -2 OR MORE HAND LINES

FIRE ORIGIN, LEVEL: 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)

FIRE ORIGIN, AREA: 9200 COURT, PATIO, TERRACE

EXTENT OF FIRE: 5000 CONFINED TO BUILDING OF ORIGIN

EXTENT OF DAMAGE: 6000 EXTENDED BEYOND BUILDING OF ORIGIN

IGNITING OBJECT: 1080 SMOKER (MEAT, FISH, ETC.)

FUEL OR ENERGY: 6000 ELECTRICITY

FORM OF HEAT: 6000 HOT OBJECT - DIRECT HEAT BY CONDUCTION OR RADIATION, NO DIRE

MATERIAL FIRST IGNITED: 0000 CANNOT BE DETERMINED ACT OR OMISSION: 0000 CANNOT BE DETERMINED

Investigating Officer LAFC Badge #

Telephone ReportDate 250-478-9555 AUBREY, CHRIS 2293 2013-07-11

Page 2 of 5 Incident Report

PROVINCE OF BRITISH COLUMBIA

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE (PRODUCT/EQUIPMENT)

INCIDENT NUMBER: DLF 2013 06 20 01 01

LOG# : 168895

ITEM TYPE : APPLIANCE MISC. - SMALL

ITEM DESCRIPTION

: SMOKEHOUSE PRODUCTS CERT. AGENCY1 MAKE MODEL : LITTLE CHIEF CERT. AGENCY2 YEAR CERT. AGENCY3

LICENSE NO. CERT. AGENCY4 SERIAL NO. CERT. AGENCY5

MAKE : SMOKEHOUSE PRODUCTS

COMMENTS:

Investigating Officer LAFC Badge # Telephone ReportDate 250-478-9555 AUBREY, CHRIS 2013-07-11 2293

Incident Report Page 3 of 5

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE (NARRATIVE)

INCIDENT NUMBER: DLF 2013 06 20 01 01

## Remarks:

FIRE DEPARTMENT WAS CALLED TO A RESIDENTIAL STRUCTURE FIRE THAT WAS WELL INVOLVED WHEN FIRE CREWS ARRIVED. MULTIPLE 2.5 INCH AND 1.75 INCH LINES WERE USED TO SUPPRESS THE FIRE IN ADDITION TO A LADDER MONITOR AND A GROUND MONITOR. FIRE WAS CONTAINED TO THE BUILDING OF ORIGIN, BUT THERE WAS SOME SMOKE DAMAGE TO THE NEIGHBOURING HOUSES. INVESTIGATION DETERMINED THAT THE SOURCE OF IGNITION WAS A FISH SMOKER, BUT THE CIRCUMSTANCES AS TO HOW THE FIRE STARTED COULD NOT BE DETERMINED. OWNER VERIFIED THAT HE WAS USING THE SMOKER THAT NIGHT AND THERE WAS HEAVY WINDS WHICH MAY HAVE CAUSED THE SMOKER TO FALL OFF THE TABLE IT WAS ON AND ONTO COMBUSTIBLE MATERIAL, HOWEVER A MALFUNCTION WITH THE SMOKER CANNOT BE RULED OUT. THE FIRE BURNED THROUGH THE DECK ABOVE AND THEN DRIVEN INTO THE SOFFITS AND SECOND FLOOR WINDOW DUE TO THE HIGH WINDS.

Investigating Officer AUBREY, CHRIS LAFC Badge # 2293

Telephone 250-478-9555

ReportDate 2013-07-11

Page 4 of 5 Incident Report

PROVINCE OF BRITISH COLUMBIA

FIRE REPORT - STRUCTURE (NAMES)

Name Status

Phone

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

INCIDENT NUMBER: DLF 2013 06 20 01 01

: OWNER

: s.22

Name no. : 1

:s.22 Name Address

: 991 BONAVISTA PL

VICTORIA BRITISH COLUMBIA

Claims Adjuster Name Claims Adjuster Firm : Claim Number Insurance Company Policy Number

LOSS ESTIMATES:

Content Loss: \$.22 Total Loss: \$.22 Property Loss: S.22

REMARKS:

**Investigating Officer** LAFC Badge # Telephone

ReportDate 250-478-9555 2013-07-11 AUBREY, CHRIS 2293

Incident Report Page 5 of 5