Incident Report Page 1 of 4

PROVINCE OF BRITISH COLUMBIA

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: CLA 2015 03 10 21 01

Location of Incident: 201 - 20579 LANGLEY BYPASS LANGLEY CITY BC V3A 5E8

# of Occupants (At time of fire): 0 # of Injured: 0 # of Deaths: 0 Total Dollar Loss Estimate: \$.21

Related to Wildland Interface Fire: NO Property Value: § 21 Content Value: \$.21 Total Value at Risk: \$.21

Code Name: Code Description

PROPERTY COMPLEX: 6900 INDUSTRIAL MANUFACTURING

PROPERTY CLASSIFICATION: 6840 MOTOR VEHICLE MANUFACTURING & ASSEMBLY -

GENERAL CONSTRUCTION: 4000 NON-COMBUSTIBLE CONSTRUCTION - EXPOSED STEEL

BUILDING HEIGHT: 0020 2 STORIES ABOVE GRADE

GROUND FLOOR AREA: 4000 1001 TO 2500M2 (10765 - 26910FT2)

YEAR OF CONSTRUCTION: 1977 1977

MANUAL FIRE PROTECTION: 4000 EXTINGUISHER ONLY

OUTSIDE FIRE PROTECTION: 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT

SPRINKLER PROTECTION: 7000 NO SPRINKLER PROTECTION

AUTOMATIC FIRE ALARM SYSTE: 1000 NO FIRE ALARM SYSTEM

SMOKE ALARM OPERATION: 9900 NO SMOKE ALARM INSTALLED

INITIAL DETECTION: 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S

TRANSMISSION OF ALARM: 1000 911

FIRE SERVICE: 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT

INCIDENT: 1000 FIRE - FIRE DEPARTMENT ATTENDED

ACTION TAKEN: 3000 EXTINGUISHED BY FIRE DEPARTMENT

METHOD OF FIRE CONTROL: 4700 COMBINATIONS OF 38/42MM (1 1/2"/1 3/4"), 65MM (2 1/2"), 7

FIRE ORIGIN, LEVEL: 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)

FIRE ORIGIN, AREA: 4700 VEHICLE STORAGE - INCLUDES GARAGE, CARPORT. (EXCLUDES OUTSID

EXTENT OF FIRE: 5000 CONFINED TO BUILDING OF ORIGIN

EXTENT OF DAMAGE: 5000 CONFINED TO BUILDING OF ORIGIN

IGNITING OBJECT : 0000 CANNOT BE DETERMINED

FUEL OR ENERGY: 0000 CANNOT BE DETERMINED

FORM OF HEAT : 0000 CANNOT BE DETERMINED

MATERIAL FIRST IGNITED: 0000 CANNOT BE DETERMINED

ACT OR OMISSION: 1240 SUSPICIOUS - SUSPECT NOT IDENTIFIED

Investigating Officer LAFC Badge #
GUNN, ROBIN 2705

LAFC Badge # Telephone ReportDate 2705 604-514-2883 2015-04-08

Incident Report Page 2 of 4

PROVINCE OF BRITISH COLUMBIA Ministry of Justice Emergency Management BC / Office of the Fire Commissioner FIRE REPORT - STRUCTURE (NARRATIVE)

INCIDENT NUMBER: CLA 2015 03 10 21 01

## Remarks:

REPORT OF FIRE IN SOUTH END OF WAREHOUSE. FIRE GREW QUICKLY AND CONSUMED HALF OF THE BUILDING. TWO BUSINESSES WERE TOTAL LOSSES AND TWO SUFFERED WATER AND SMOKE DAMAGE. RCMP DEEMED FIRE SUSPICIOUS AND TOOK CONTROL OF THE INVESTIGATION. RCMP FILE 2015-7951. INVESTIGATION STILL ONGOING. FINDINGS AT SCENE WERE UNDETERMINED.

Investigating Officer GUNN, ROBIN LAFC Badge #

2705

Telephone 604-514-2883 ReportDate 2015-04-08

Incident Report Page 3 of 4

PROVINCE OF BRITISH COLUMBIA

FIRE REPORT - STRUCTURE (NAMES)

Name Status

Phone

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

INCIDENT NUMBER: CLA 2015 03 10 21 01

:s.22

: BUSINESS OWNER

Name no. : 1

Name : LAYBOURN, DAWN

Address : 201 - 20579 LANGLEY BYPASS

LANGLEY BRITISH COLUMBIA V3A 5E8

Claims Adjuster Name : 1. LOCKWOOD, CHRIS Claims Adjuster Firm : 1. CHARLES TAYLOR

Claim Number

: s.22 : 1. ROYAL SUN ALLIANCE Insurance Company

Policy Number s.22

LOSS ESTIMATES:

Content Loss: s.21 Total Loss: s.21 Property Loss: s.21

REMARKS:

Investigating Officer LAFC Badge # Telephone ReportDate GUNN, ROBIN 604-514-2883 2705 2015-04-08

3 of 4

Incident Report Page 4 of 4