



## **Dangerous Goods** Incident Report



## **DGIR 130313 - INLAND**

Category: Code 1

Incident Date Time: 2013-04-30 1600

MCTS#:

Spiller: **BELL CANADA** Location: 2071 LAKE PLACID ROAD Area: WHISTLER DISTRICT MOE Region: Lower **EMBC Region: SWE** Material(s): Mainland Region R-22 REFRIGERANT Amount(s): 10.4 KG Received From: Caller A: s.22 Caller B: Org: BELL CANADA Ora: Phone: s.22 Phone: Alternate: Alternate: Time: Time: Received by EMBC Operations Officer: MARIE When Received: 2013-05-01 06:31 Affected Environment : Atmosphere Other: Type of Spilling: Other Spill Type: Equipment Failure Accidents: Sector: Unknown Advised that there was a leak on a suction line of an air conditioner at the above location which resulted in a release of Response: system was repaired and recharged with 10.4 kg Jurisdiction: Provincial Task # :140514 Amount: \$50 Issued To: ED STOCKERL Notification: 0636 briefed MOE RO Ed Stockerl. Code 1. 0731 faxed MOE Surrey, MOE Nelson

Risk Calculation [PT / +ES 3 + IS

H-03 ENU-AIR JECTER - COMMERCIAL ENF ACTION - NONE

PRIMARY: SAILUER SECONTARY - ER CONFATERA

LAT: 50,094216 LONG: -122,990542

Printed 2013-05-01 at 07:31:45

**Emergency Coordination Center** Phone 1-800-663-3456 Fax (250) 952-4872

Page 1 of 1