

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: CQU 2017 12 13 13 01

Location of Incident: **521 DONNELLY
QUESNEL BC V2J6B7**

of Occupants (At time of fire): **10** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$22**

Related to Wildland Interface Fire: **NO** Property Value: **\$22** Content Value: **\$22** Total Value at Risk: **\$22**

Code Name : Code Description

PROPERTY COMPLEX : 3400 RESIDENTIAL - SINGLE DETACHED
PROPERTY CLASSIFICATION : 3110 YEAR-ROUND USE DWELLING - 1-FAMILY
GENERAL CONSTRUCTION : 2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST
BUILDING HEIGHT : 0020 2 STORIES ABOVE GRADE
GROUND FLOOR AREA : 2000 101 TO 500M2 (1077 - 5382FT2)
YEAR OF CONSTRUCTION : 2005 2005
MANUAL FIRE PROTECTION : 7000 NO MANUAL FIRE PROTECTION
OUTSIDE FIRE PROTECTION : 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION : 7000 NO SPRINKLER PROTECTION
AUTOMATIC FIRE ALARM SYSTE : 1000 NO FIRE ALARM SYSTEM
SMOKE ALARM OPERATION : 9500 ALARM NOT ACTIVATED - UNKNOWN
INITIAL DETECTION : 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM : 1000 911
FIRE SERVICE : 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN : 3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL : 4300 38MM/42MM (1 1/2"/1 3/4") HOSE - 2 OR MORE HAND LINES
FIRE ORIGIN, LEVEL : 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)
FIRE ORIGIN, AREA : 7500 WALL ASSEMBLY - INCLUDES CONCEALED WALL SPACE
EXTENT OF FIRE : 6000 EXTENDED BEYOND PROPERTY OF ORIGIN
EXTENT OF DAMAGE : 6000 EXTENDED BEYOND BUILDING OF ORIGIN
IGNITING OBJECT : 2310 WOOD STOVE (INCLUDES PELLET STOVE)
FUEL OR ENERGY : 1000 SOLID FUEL (E.G. COAL, WOOD, PELLETS, PAPER OR WASTE USED FO
FORM OF HEAT : 6000 HOT OBJECT - DIRECT HEAT BY CONDUCTION OR RADIATION, NO DIRE
MATERIAL FIRST IGNITED : 9500 INSULATION, ELECTRIC - CONFINED TO ELECTRICAL EQUIPMENT - IN
ACT OR OMISSION : 5400 OTHER INSTALLATION DEFICIENCY

Investigating Officer	LAFB Badge #	Telephone	ReportDate
KNORR, ROGER	1471	250-992-5121	2017-12-14

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE** (NARRATIVE)

INCIDENT NUMBER: **CQU 2017 12 13 13 01**

Remarks:

THE OCCUPANT OF THE HOME INSTALLED A PELLET STOVE IN A BASEMENT WALL. THE INSTALLATION WAS NOT WET CERTIFIED. THE HOT GAS VENT PIPE WAS ENCLOSED INSIDE A WALL WITH ELECTRICAL WIRES WHICH RAN THROUGH WOOD STUDS. THE WIRES WERE FOUND TO BE TOUCHING THE VENT PIPE CAUSING THE INSULATION ON THE WIRE TO BURN IGNITING THE STUDS ON FIRE. THE BOTTOM OF THE WALL WAS LEFT OPEN SO OXYGEN AND AIR FLOW HELPED THIS FIRE BURN UPWARDS.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
KNORR, ROGER	1471	250-992-5121	2017-12-14

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE** (NAMES)INCIDENT NUMBER: **CQU 2017 12 13 13 01**

Name no. : 1
Name : s.22
Address :

Name Status : OWNER
Phone : s.??

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.22

Content Loss : s.

Total Loss : s.22

REMARKS:

Name no. : 2
Name : s.22
Address : 521 DONNELLY
QUESNEL BRITISH COLUMBIA V2J 6B7

Name Status : OCCUPANT
Phone : s.??

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.

Content Loss : s.22

Total Loss : s.22

REMARKS:

Investigating Officer : LAFB Badge #
KNORR, ROGER : 1471

Telephone :
250-992-5121
ReportDate :
2017-12-14

