

PROVINCE OF BRITISH COLUMBIA  
Ministry of Justice  
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE**INCIDENT NUMBER: **CKE 2014 06 16 11 02**

Location of Incident: **4489 LAKESHORE RD  
KELOWNA BC**

# of Occupants (At time of fire): **0**      # of Injured: **0**      # of Deaths: **0**      Total Dollar Loss Estimate: **\$5,000**

Related to Wildland Interface Fire: **NO**      Property Value: **\$0**      Content Value: **\$0**      Total Value at Risk: **\$0**

**Code Name :      Code Description**

PROPERTY COMPLEX : 1300 EDUCATIONAL INSTITUTION (NON-RESIDENTIAL)  
PROPERTY CLASSIFICATION : 1320 ELEMENTARY SCHOOL - INCLUDES COMBINED  
KINDERGARTEN/ELEMENTAR  
GENERAL CONSTRUCTION : 4000 NON-COMBUSTIBLE CONSTRUCTION - EXPOSED STEEL  
BUILDING HEIGHT : 0020 2 STORIES ABOVE GRADE  
GROUND FLOOR AREA : 2000 101 TO 500M2 (1077 - 5382FT2)  
YEAR OF CONSTRUCTION : 1993 1993  
MANUAL FIRE PROTECTION : 4000 EXTINGUISHER ONLY  
OUTSIDE FIRE PROTECTION : 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT  
SPRINKLER PROTECTION : 1000 COMPLETE SPRINKLER PROTECTION - SUPERVISED (ON-SITE OR OFF-S  
AUTOMATIC FIRE ALARM SYSTE : 3000 FIRE ALARM SYSTEM - OFF-SITE MONITORING AGENCY  
SMOKE ALARM OPERATION : 9500 ALARM NOT ACTIVATED - UNKNOWN  
INITIAL DETECTION : 8000 NO INITIAL DETECTION (EXTINGUISHED BEFORE DETECTION)  
TRANSMISSION OF ALARM : 7000 TELEPHONE DIRECT TO FIRE DEPARTMENT OTHER THAN 911  
FIRE SERVICE : 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT  
INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED  
ACTION TAKEN : 2000 BURNED OUT - NO EXTINGUISHMENT ATTEMPTED/NEEDED  
METHOD OF FIRE CONTROL : 8100 COMPLETELY BURNED OUT BEFORE ARRIVAL OF FIRE DEPARTMENT  
FIRE ORIGIN, LEVEL : 4000 2ND STOREY OR OVER 3M TO 6M (10FT TO 20FT) ABOVE GRADE  
FIRE ORIGIN, AREA : 6900 UTILITY & EQUIPMENT AREA - UNCLASSIFIED (DESCRIBE)  
EXTENT OF FIRE : 1000 CONFINED TO OBJECT OF ORIGIN  
EXTENT OF DAMAGE : 2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN  
IGNITING OBJECT : 6900 ELECTRICAL EQUIPMENT - UNCLASSIFIED (DESCRIBE)  
FUEL OR ENERGY : 6000 ELECTRICITY  
FORM OF HEAT : 0000 CANNOT BE DETERMINED  
MATERIAL FIRST IGNITED : 9900 MISCELLANEOUS - UNCLASSIFIED (DESCRIBE)  
ACT OR OMISSION : 4900 MECHANICAL/ELECTRICAL FAILURE/MALFUNCTION - UNCLASSIFIED (DE

Investigating Officer      LAFC Badge #  
HOLLIER, LAWRENCE T      1324

Telephone      ReportDate  
250-860-6419      2014-06-17

PROVINCE OF BRITISH COLUMBIA  
Ministry of Justice  
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE** (NARRATIVE)INCIDENT NUMBER: **CKE 2014 06 16 11 02**

---

**Remarks:**

CREWS ARRIVED TO FIND A FIRE THAT HAD PREVIOUSLY BURNED ITSELF OUT. THERMAL IMAGING CAMERA AND RAYTEC GUN WERE USED FOR TEMPERATURE CHECKS. ALL OK. NO EXTENSION FROM ALARM PANEL OTHER THAN SOME SMOKE STAINING. PR'S ON SCENE.

---

Investigating Officer	L AFC Badge #	Telephone	ReportDate
HOLLIER, LAWRENCE T	1324	250-860-6419	2014-06-17

PROVINCE OF BRITISH COLUMBIA  
Ministry of Justice  
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE** (NAMES)

INCIDENT NUMBER: **CKE 2014 06 16 11 02**

Name no. : 1  
Name **s.22**  
Address : 0 4489 LAKESHORE RD.  
KELOWNA BRITISH COLUMBIA

Name Status : BUSINESS OCCUPANT  
Phone **s.22**

Claims Adjuster Name :  
Claims Adjuster Firm :  
Claim Number :  
Insurance Company :  
Policy Number :

LOSS ESTIMATES:

Property Loss : \$5,000

Content Loss : \$0

Total Loss : \$5,000

REMARKS:

Investigating Officer : LAFC Badge #  
HOLLIER, LAWRENCE T 1324

Telephone :  
250-860-6419  
ReportDate :  
2014-06-17

