

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **OUTDOOR**INCIDENT NUMBER: **DNC 2015 07 20 14 01**

Location of Incident:

**6507 NORTH ROAD
NORTH COWICHAN BC V9L 6K9**# of Occupants (At time of fire): **0** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$22**Related to Wildland Interface Fire: **NO** Property Value: **\$22** Content Value: **\$22** Total Value at Risk: **\$22****Code Name : Code Description**

PROPERTY CLASSIFICATION : 8190 OUTDOOR PROPERTY - UNCLASSIFIED (DESCRIBE)

TRANSMISSION OF ALARM : 1000 911

FIRE SERVICE : 2000 VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT ONLY

INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED

ACTION TAKEN : 3000 EXTINGUISHED BY FIRE DEPARTMENT

METHOD OF FIRE CONTROL : 9900 MISCELLANEOUS METHOD OF FIRE CONTROL & EXTINGUISHMENT - UNCL

FIRE ORIGIN, AREA : 9900 OUTSIDE AREA - UNCLASSIFIED (DESCRIBE)

EXTENT OF FIRE : 2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN

IGNITING OBJECT : 9100 HEAT TREATMENT EQUIPMENT - INCLUDES FURNACE, OVEN, QUENCH TA

FUEL OR ENERGY : 4200 FUEL GAS - PROPANE

FORM OF HEAT : 2000 SPARK, ELECTRICAL - INCLUDES ARC, DISCHARGE. (EXCLUDES STATI

MATERIAL FIRST IGNITED : 1000 ROOF COVERING - WOOD

ACT OR OMISSION : 7900 HUMAN FAILING - UNCLASSIFIED (DESCRIBE)

Investigating Officer
CLARK, ROBLAFC Badge #
999Telephone
250-746-3100ReportDate
2015-08-28

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **OUTDOOR** (NARRATIVE)

INCIDENT NUMBER: **DNC 2015 07 20 14 01**

Remarks:

THE FIRE ORIGINATED FROM HIGH WINDS CAUSING THE MAIN HYDRO FEED LOCATED INSIDE THE PROPERTY LINE OF THE GOLF COURSE ON THE NORTH SIDE TO ARC AND COME UNDONE. THE ENERGIZED LINE CROSSED OVER THE WIRE FENCE WHICH ENERGIZED THE FENCE AND IGNITED THE UNDERBRUSH ALONG THE FENCE FOR APPROXIMATELY 1 KM TO THE EAST. THERE WAS NO FIRE DAMAGE TO ANY STRUCTURES. THE FIRE WAS SUPPRESSED BY A MULTIPLE HALL RESPONSE AND HELICOPTER AIR DROPS FROM COASTAL FIRE CENTRE.

Investigating Officer	LAFC Badge #	Telephone	ReportDate
CLARK, ROB	999	250-746-3100	2015-08-28

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **OUTDOOR** (NAMES)INCIDENT NUMBER: **DNC 2015 07 20 14 01**

Name no. : 1
Name : HUI, MING
Address : 6507 NORTH ROAD
DUNCAN BRITISH COLUMBIA V9L 6K9

Name Status : OWNER
Phone : 250-746-8993

Claims Adjuster Name : 1. ROWE, RICHARD
Claims Adjuster Firm : 1. CLAIMS PRO
Claim Number : 1. 551105933
Insurance Company : 1. CONTINENTAL CASUALTY CO.
Policy Number : s.22

LOSS ESTIMATES:

Property Loss : s.22

Content Loss : s.22

Total Loss : s.22

REMARKS:

THE FIRE ORIGINATED FROM HIGH WINDS CAUSING THE MAIN HYDRO FEED LOCATED INSIDE THE PROPERTY LINE OF THE GOLF COURSE ON THE NORTH SIDE TO ARC AND COME UNDONE. THE ENERGIZED LINE CROSSED OVER THE WIRE FENCE WHICH ENERGIZED THE FENCE AND IGNITED THE UNDERBRUSH ALONG THE FENCE FOR APPROXIMATELY 1 KM TO THE EAST. THERE WAS NO FIRE DAMAGE TO ANY STRUCTURES. THE FIRE WAS SUPPRESSED BY A MULTIPLE HALL RESPONSE AND HELICOPTER AIR DROPS FROM COASTAL FIRE CENTRE.

Name no. : 2
Name : DUNCAN MEADOWS, GOLF COURSE LTD.
Address : 6507 NORTH ROAD
DUNCAN BRITISH COLUMBIA V9L 6K9

Name Status : BUSINESS OCCUPANT
Phone : 250-746-8993

Claims Adjuster Name : 1. ROWE, RICK
Claims Adjuster Firm : 1. CLAIMS PRO
Claim Number : 1. 551105933
Insurance Company : 1. CNA CANADA CONTINENTAL CASUALTY CO.
Policy Number : s.22

LOSS ESTIMATES:

Property Loss : \$0

Content Loss : \$0

Total Loss : \$0

REMARKS:

THE FIRE ORIGINATED FROM HIGH WINDS CAUSING THE MAIN HYDRO FEED LOCATED INSIDE THE PROPERTY LINE OF THE GOLF COURSE ON THE NORTH SIDE TO ARC AND COME UNDONE. THE ENERGIZED LINE CROSSED OVER THE WIRE FENCE WHICH ENERGIZED THE FENCE AND IGNITED THE UNDERBRUSH ALONG THE FENCE FOR APPROXIMATELY 1 KM TO THE EAST. THERE WAS NO FIRE DAMAGE TO ANY STRUCTURES. THE FIRE WAS SUPPRESSED BY A MULTIPLE HALL RESPONSE AND HELICOPTER AIR DROPS FROM COASTAL FIRE CENTRE.

Investigating Officer : LAFC Badge #
CLARK, ROB : 999

Telephone : 250-746-3100
ReportDate : 2015-08-28

