Incident Report Page 1 of 4

PROVINCE OF BRITISH COLUMBIA

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: VUC 2016 06 17 23 01

Location of Incident: ALDER ROAD UCLUELET BC

of Occupants (At time of fire): 1 # of Injured: 0 # of Deaths: 0 Total Dollar Loss Estimate \$.22

Related to Wildland Interface Fire: NO Property Value: \$.22 Content Value: \$.22 Total Value at Risk: \$.22

Code Name: Code Description

PROPERTY COMPLEX: 9400 UTILITY

PROPERTY CLASSIFICATION: 4390 ELECTRONIC EQUIPMENT - UNCLASSIFIED (DESCRIBE)

GENERAL CONSTRUCTION: 2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST

BUILDING HEIGHT: 0010 1 STORY ABOVE GRADE

GROUND FLOOR AREA: 1000 1 TO 100M2 (1 - 1076FT2)

YEAR OF CONSTRUCTION: 0061 1961 TO 1965

MANUAL FIRE PROTECTION: 7000 NO MANUAL FIRE PROTECTION

OUTSIDE FIRE PROTECTION: 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT

SPRINKLER PROTECTION: 7000 NO SPRINKLER PROTECTION

AUTOMATIC FIRE ALARM SYSTE: 1000 NO FIRE ALARM SYSTEM

SMOKE ALARM OPERATION: 9900 NO SMOKE ALARM INSTALLED

INITIAL DETECTION: 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S

TRANSMISSION OF ALARM: 1000 911

FIRE SERVICE: 2000 VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT ONLY

INCIDENT: 1000 FIRE - FIRE DEPARTMENT ATTENDED

ACTION TAKEN: 3000 EXTINGUISHED BY FIRE DEPARTMENT

METHOD OF FIRE CONTROL: 7600 FOAM-WATER SYSTEM

FIRE ORIGIN, LEVEL: 9000 EXPOSURE FIRE

FIRE ORIGIN, AREA: 6900 UTILITY & EQUIPMENT AREA-UNCLASSIFIED (DESCRIBE)

EXTENT OF FIRE: 6000 EXTENDED BEYOND PROPERTY OF ORIGIN

EXTENT OF DAMAGE: 6000 EXTENDED BEYOND BUILDING OF ORIGIN

IGNITING OBJECT: 6900 ELECTRICAL EQUIPMENT - UNCLASSIFIED (DESCRIBE)

FUEL OR ENERGY: 6000 ELECTRICITY

FORM OF HEAT: 0000 CANNOT BE DETERMINED

MATERIAL FIRST IGNITED: 1900 BUILDING COMPONENTS - UNCLASSIFIED (DESCRIBE)

ACT OR OMISSION: 4400 ELECTRICAL SHORT CIRCUIT

Investigating Officer LAFC Badge # Telephone ReportDate

TED, EEFTINK 2671 250-725-5497 2017-02-01

Incident Report Page 2 of 4

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE (NARRATIVE)
INCIDENT NUMBER: VUC 2016 06 17 23 01

Remarks:

THE ELECTRICAL BUILDING AND THE ASSOCIATED STORAGE BUILDING THAT SERVICES THE TRAILER PARK WAS FULLY ENGULFED IN FLAMES WHEN THE UCUELET VOLUNTEER FIRE BRIGADE ARRIVED ON SCENE. THE HEART THAT GENERATED OFF THE ELECTRICAL/STORAGE BUILDING STARTED TO MELT THE SIDING ON THE BRAVO SIDE OF A MOBILE HOME LOCATED APPROXIMATELY 35 FEET AWAY. THE MELTING OF THE SIDING CREATED A FIRE IN THE WALL OF THE MOBILE HOME, WHICH TRAVELED INTO THE CEILING. WHEN THE UCUELET VOLUNTEER FIRE BRIGADE ARRIVED ON SCENE THE TRAILER WAS SMOKING FROM THE SIDES OF THE HOME WITH NO FLAMES.

Investigating Officer TED, EEFTINK

LAFC Badge #

2671

Telephone 250-725-5497

ReportDate 2017-02-01

Incident Report Page 3 of 4

PROVINCE OF BRITISH COLUMBIA

FIRE REPORT - STRUCTURE (NAMES)

Name Status

Phone

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

INCIDENT NUMBER: VUC 2016 06 17 23 01

: OWNER

Name no. : 1

: s.22 Name

Address

Claims Adjuster Name Claims Adjuster Firm Claim Number Insurance Company Policy Number

LOSS ESTIMATES:

Total Loss: \$.22 Content Loss: s.22 Property Loss: s.22

REMARKS:

NOT SURE ABOUT THE PROPERTY LOSS - ESTIMATE \$.22 AND NOT SURE ABOUT CONTENT, LOSS - ESTIMATE s.22 . PLEASE FOLLOW UP WITH THE INSURANCE COMPANY.

LAFC Badge # Investigating Officer Telephone ReportDate TED, EEFTINK 2671 250-725-5497 2017-02-01 Incident Report Page 4 of 4