

PROVINCE OF BRITISH COLUMBIA
 Ministry of Justice
 Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: **DDE 2017 04 17 20 12**

Location of Incident: **7480 115TH ST
 DELTA BC**

of Occupants (At time of fire): **0** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$22**

Related to Wildland Interface Fire: **NO** Property Value: **\$22** Content Value: **\$22** Total Value at Risk: **\$22**

Code Name : Code Description

PROPERTY COMPLEX : 3400 RESIDENTIAL - SINGLE DETACHED
 PROPERTY CLASSIFICATION : 3110 YEAR-ROUND USE DWELLING - 1-FAMILY
 GENERAL CONSTRUCTION : 2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST
 BUILDING HEIGHT : 0020 2 STORIES ABOVE GRADE
 GROUND FLOOR AREA : 2000 101 TO 500M2 (1077 - 5382FT2)
 YEAR OF CONSTRUCTION : 1978 1978
 MANUAL FIRE PROTECTION : 0000 CANNOT BE DETERMINED
 OUTSIDE FIRE PROTECTION : 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
 SPRINKLER PROTECTION : 0000 CANNOT BE DETERMINED
 AUTOMATIC FIRE ALARM SYSTE : 0000 CANNOT BE DETERMINED
 SMOKE ALARM OPERATION : 0000 ALARM OPERATION CANNOT BE DETERMINED
 INITIAL DETECTION : 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
 TRANSMISSION OF ALARM : 1000 911
 FIRE SERVICE : 1000 CAREER FIRE DEPARTMENT ONLY
 INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED
 ACTION TAKEN : 3000 EXTINGUISHED BY FIRE DEPARTMENT
 METHOD OF FIRE CONTROL : 4300 38MM/42MM (1 1/2"/1 3/4") HOSE - 2 OR MORE HAND LINES
 FIRE ORIGIN, LEVEL : 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)
 FIRE ORIGIN, AREA : 4700 VEHICLE STORAGE - INCLUDES GARAGE, CARPORT. (EXCLUDES OUTSID
 EXTENT OF FIRE : 5000 CONFINED TO BUILDING OF ORIGIN
 EXTENT OF DAMAGE : 5000 CONFINED TO BUILDING OF ORIGIN
 IGNITING OBJECT : 0000 CANNOT BE DETERMINED
 FUEL OR ENERGY : 0000 CANNOT BE DETERMINED
 FORM OF HEAT : 0000 CANNOT BE DETERMINED
 MATERIAL FIRST IGNITED : 0000 CANNOT BE DETERMINED
 ACT OR OMISSION : 0000 CANNOT BE DETERMINED

Investigating Officer
 WOOD, DAVID

LAFC Badge #
 2632

Telephone
 604-946-8541

ReportDate
 2017-06-08

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE** (NARRATIVE)

INCIDENT NUMBER: **DDE 2017 04 17 20 12**

Remarks:

SUMMARY- STRUCTURE FIRE CONCLUSION THE MOST PROBABLE CAUSE OF THE FIRE AT THIS TIME WAS THAT OF ARSON. WITH THE DETECTION OF THE HYDROCARBONS AT ALL THREE FIRES AT DIFFERENT LOCATIONS AROUND THE HOUSE AND NO OTHER SOURCES OF IGNITION I AM QUITE CONFIDENT WITH THIS THEORY. UNFORTUNATELY THERE WAS NO EVIDENCE COLLECTED THAT WOULD BE ABLE TO LEAD US TO THE PERSON OR PERSONS WHO SET THE FIRE. THE POLICE INVESTIGATION IS CLOSED AS WELL.

Investigating Officer	LAFB Badge #	Telephone	ReportDate
WOOD, DAVID	2632	604-946-8541	2017-06-08

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE** (NAMES)

INCIDENT NUMBER: **DDE 2017 04 17 20 12**

Name no. : 1
Name : **s.22**
Address : 0

Name Status : OWNER
Phone :

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : **s.22**

Content Loss : **s.22**

Total Loss : **s.22**

REMARKS:

Investigating Officer : LAFC Badge #
WOOD, DAVID : 2632

Telephone : ReportDate
604-946-8541 : 2017-06-08

