Incident Report Page 1 of 4

PROVINCE OF BRITISH COLUMBIA

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: **DWH 2013 11 22 16 01**

Location of Incident: 4338 MAIN STREET
WHISTLER BC V0N 1B4

of Occupants (At time of fire): 1 # of Injured: 0 # of Deaths: 0 Total Dollar Loss Estimate: \$0

Related to Wildland Interface Fire: NO Property Value: \$0 Content Value: \$0 Total Value at Risk: \$0

Code Name: Code Description

PROPERTY COMPLEX: 3900 RESIDENTIAL - WITH BUSINESS/MERCANTILE, UP TO 3 STORIES

PROPERTY CLASSIFICATION: 3250 APARTMENT, TOWNHOUSE - OVER 20 UNITS WITH OR W/O BUSINESS

GENERAL CONSTRUCTION: 2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST

BUILDING HEIGHT: 0030 3 STORIES ABOVE GRADE

GROUND FLOOR AREA: 0000 CANNOT BE DETERMINED

YEAR OF CONSTRUCTION: 0000 CANNOT BE DETERMINED

MANUAL FIRE PROTECTION: 4000 EXTINGUISHER ONLY

OUTSIDE FIRE PROTECTION: 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT

SPRINKLER PROTECTION: 1000 COMPLETE SPRINKLER PROTECTION - SUPERVISED (ON-SITE OR OFF-S

AUTOMATIC FIRE ALARM SYSTE : 3000 FIRE ALARM SYSTEM - OFF-SITE MONITORING AGENCY

SMOKE ALARM OPERATION: 1000 ALARM ACTIVATED - ASSISTED OCCUPANT(S) IN EVACUATING

INITIAL DETECTION: 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S

TRANSMISSION OF ALARM: 1000 911

FIRE SERVICE: 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT

INCIDENT: 1000 FIRE - FIRE DEPARTMENT ATTENDED

ACTION TAKEN: 3000 EXTINGUISHED BY FIRE DEPARTMENT

METHOD OF FIRE CONTROL: 4500 65MM/77MM (2 1/2"/3") HOSE -2 OR MORE HAND LINES

FIRE ORIGIN, LEVEL: 5000 3RD STOREY OR OVER 6M TO 9M (20FT TO 30FT) ABOVE GRADE

FIRE ORIGIN, AREA: 7200 EXTERIOR BALCONY - INCLUDES OPEN PORCH, DECK

EXTENT OF FIRE: 5000 CONFINED TO BUILDING OF ORIGIN

EXTENT OF DAMAGE: 5000 CONFINED TO BUILDING OF ORIGIN

 ${\tt IGNITING\ OBJECT\ :\ 7700\ TORCH\ -\ OTHER\ THAN\ CUTTING,\ WELDING\ -\ INCLUDES\ PLUMBER'S\ FUR}$

FUEL OR ENERGY: 4200 FUEL GAS - PROPANE

FORM OF HEAT: 4000 DIRECT FLAME

MATERIAL FIRST IGNITED: 1900 BUILDING COMPONENTS - UNCLASSIFIED (DESCRIBE)

ACT OR OMISSION: 2600 TORCH TOO CLOSE

Investigating Officer LAFC Badge # Telephone ReportDate

KIRKWOOD, SHEILA 1512 604-935-8264 2013-12-06

Incident Report Page 2 of 4

PROVINCE OF BRITISH COLUMBIA Ministry of Justice Emergency Management BC / Office of the Fire Commissioner FIRE REPORT - STRUCTURE (NARRATIVE)
INCIDENT NUMBER: DWH 2013 11 22 16 01

Remarks:

TORCH-ON ROOFING ON EXTERIOR BALCONY OF UNIT 322 TOOK PLACE AT APPROXIMATELY 1300 ON NOV 22, 2013. FIRE ON EXTERIOR BALCONY OF UNIT 322 CALLLED IN BY VISUAL SIGHTING AT 1632. FIRE ARRIVING ENGINE REPORTED BALCONY FULLY INVLOVED WITH FLAME TRAVELLING UP THE OUTSIDE OF THE BUILDING ONTO THE ROOF AND INTO THE SOFFITS. ADDITIONAL INFORMATION SUPPLIED: THIS HAS BEEN SUBMITTED AS ONE REPORT, A FIRE REIGNITED ON THE FOLLOWING DAY RELATED TO THE 1ST FIRE. SHEILA KIRKWOOD RESORT MUNICIPALITY OF WHISTLER

Investigating Officer KIRKWOOD, SHEILA LAFC Badge # 1512

6

Telephone Re 604-935-8264 20

ReportDate 2013-12-06

Incident Report Page 3 of 4

PROVINCE OF BRITISH COLUMBIA

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE (NAMES)

INCIDENT NUMBER: DWH 2013 11 22 16 01

Name no.: 1Name Status: OWNERName: \$.22Phone\$.22

Address :

Claims Adjuster Name : Claims Adjuster Firm : Claim Number : Insurance Company : Policy Number :

LOSS ESTIMATES:

Property Loss: \$0 Content Loss: \$0 Total Loss: \$0

REMARKS:

STRATA MANAGER FOR BUILDING

Investigating Officer LAFC Badge # Telephone ReportDate KIRKWOOD, SHEILA 1512 604-935-8264 2013-12-06

Page 3 of 4TRA-2017-72196 2017-07-07 Incident Report Page 4 of 4