

NSC #: 00000200944818

NAME: VIMAC TRANSPORT LTD.

Carrier’s Safety Performance

Your NSC Carrier Profile is a record that keeps track of indicators of your on-road safety performance. These indicators are:

- * the number and type of at-fault accidents involving the vehicle(s) operating under your Safety Certificate (NSC points are removed from the profile for accidents if it can be determined that the driver was less than 50% at fault);
- * roadside (CVSA) vehicle inspections that put a vehicle or driver out-of-service;
- * contraventions (e.g. violation tickets) which have been deemed guilty; and
- * an overall total of accidents, out-of-service CVSA inspections, and contraventions.

The above items may have occurred while operating in BC or other North American jurisdictions.

Most items recorded on a Carrier Profile are assigned NSC profile points. The following chart indicates your point scores in each of the above categories.

PROFILE SCORES	FLEET SIZE	CONTRA-VENTIONS	OUT OF SERVICE CVSA	ACCIDENTS	OVERALL
VIMAC TRANSPORT LTD.	14.85	1.14	0.40	0.00	1.54
ANNUAL PROVIN MEDIAN	9.01 -20.00	0.53	0.47	0.25	0.80

The chart compares your scores to the provincial average for carriers with the same or similar fleet size. Fleet size is determined by the number of days that your vehicle(s) have been operating under your NSC certificate over a 12-month period. Each 365 vehicle licenced days, or portion thereof, is considered to be one vehicle.

For your information, a copy of your Carrier Profile report is enclosed. The report shows information for each of the incidents recorded for your fleet. Please review the profile. If you find any inconsistencies, please report them to the NSC program office by mail, or by faxing a copy of the profile page(s) to (250) 952-0578. Indicate the discrepancy(s) and reason(s) why. If NSC points appear for an accident for which you were not considered to be 50% or more at fault, please provide a copy of this information from your insurance provider. The NSC program office will investigate and, where applicable, make the necessary corrections as promptly as possible.

To monitor your on-road safety performance, you may request a copy of your Carrier Profile on a regular basis. Send a letter, fax, or e-mail to the NSC program office requesting a copy of your Carrier Profile report.

NSC CARRIER: BC 00000200944818

RECIPIENT ADDRESS:
BAMORRIS
REQUESTED ONLINE AND E-MAILED TO
<BARBARA.MORRIS@GOV.BC.CA>

VIMAC TRANSPORT LTD.
130-5200 MILLER RD
RICHMOND, BC, CAN, V7B 1K5

TOTAL NUMBER OF CURRENTLY LICENSED VEHICLES: 10.00

CARRIER SAFETY RATING

PROFILE STATUS:	SATISFACTORY
AUDIT STATUS:	UNAUDITED
CARRIER SAFETY RATING:	SAT-UNAUDITED

INTERVENTIONS	DATE
-----	-----
WARNING LETTER	2006-03-01

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
PROFILE SCORES AS OF JANUARY 2015

NSC CARRIER: BC 00000200944818

MONTH	NUMBER OF VEHICLE DAYS	12 MONTHS TOTAL DAYS	AVERAGE FLEET SIZE	CONTRAVENTIONS PROFILE	CVSA PROFILE	ACCIDENT PROFILE	TOTAL PROFILE SCORE
2015-01	333	5421	14.85	1.14	0.40	0.00	1.54 **
2014-12	353	5595	15.33	1.11	0.39	0.00	1.50
2014-11	335	5769	15.81	1.27	0.38	0.00	1.65
2014-10	444	5965	16.34	1.29	0.55	0.00	1.84
2014-09	539	6110	16.74	0.90	0.54	0.12	1.56
2014-08	558	6108	16.73	0.96	0.54	0.12	1.62
2014-07	541	6087	16.68	0.90	0.54	0.12	1.56
2014-06	494	6086	16.67	1.08	0.36	0.12	1.56
2014-05	474	6115	16.75	1.07	0.36	0.12	1.55
2014-04	486	6179	16.93	0.89	0.35	0.12	1.36
2014-03	461	6201	16.99	0.88	0.18	0.12	1.18
2014-02	403	6233	17.08	0.70	0.18	0.12	1.00
2014-01	507	6260	17.15	0.99	0.17	0.12	1.28
2013-12	527	6246	17.11	1.17	0.18	0.23	1.58
2013-11	531	6263	17.16	0.99	0.17	0.23	1.39
2013-10	589	6302	17.27	0.98	0.00	0.23	1.21
2013-09	537	6287	17.22	0.99	0.00	0.12	1.11
2013-08	537	6291	17.24	0.93	0.00	0.12	1.05
2013-07	540	6332	17.35	0.92	0.00	0.12	1.04
2013-06	523	6365	17.44	0.86	0.00	0.11	0.97
2013-05	538	6356	17.41	1.03	0.00	0.11	1.14
2013-04	508	6367	17.44	1.09	0.00	0.11	1.20
2013-03	493	6385	17.49	1.09	0.00	0.11	1.20
2013-02	430	6430	17.62	1.08	0.00	0.11	1.19
2013-01	493	6556	17.96	0.95	0.00	0.11	1.06
2012-12	544	6698	18.35	0.76	0.00	0.00	0.76
2012-11	570	6774	18.56	0.75	0.00	0.00	0.75
2012-10	574	6805	18.64	0.59	0.16	0.00	0.75
2012-09	541	6841	18.74	0.59	0.16	0.00	0.75
2012-08	578	6870	18.82	0.48	0.16	0.00	0.64
2012-07	573	6882	18.85	0.53	0.32	0.00	0.85
2012-06	514	6897	18.90	0.42	0.48	0.00	0.90
2012-05	549	6953	19.05	0.26	0.47	0.00	0.73
2012-04	526	6993	19.16	0.21	0.47	0.00	0.68
2012-03	538	7036	19.28	0.21	0.47	0.00	0.68
2012-02	556	7046	19.30	0.21	0.47	0.00	0.68
2012-01	635	6972	19.10	0.05	0.47	0.00	0.52
2011-12	620	6904	18.92	0.05	0.48	0.00	0.53
2011-11	601	6904	18.92	0.21	0.48	0.00	0.69
2011-10	610	6903	18.91	0.37	0.32	0.00	0.69
2011-09	570	6935	19.00	0.37	0.32	0.00	0.69
2011-08	590	7001	19.18	0.36	0.31	0.00	0.67
2011-07	588	7080	19.40	0.46	0.15	0.00	0.61
2011-06	570	7224	19.79	0.76	0.00	0.00	0.76
2011-05	589	7385	20.23	0.74	0.00	0.00	0.74

SECTION 2

PAGE: 2

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
PROFILE SCORES AS OF JANUARY 2015

NSC CARRIER: BC 00000200944818

MONTH	NUMBER OF VEHICLE	12 MONTHS DAYS TOTAL	AVERAGE FLEET SIZE	CONTRAVENTIONS PROFILE	CVSA PROFILE	ACCIDENT PROFILE	TOTAL PROFILE SCORE
2011-04	569	7540	20.66	0.87	0.00	0.00	0.87
2011-03	548	7696	21.08	1.14	0.00	0.00	1.14
2011-02	482	7932	21.73	1.20	0.00	0.00	1.20

**NOTE: THE CARRIER PROFILE STATUS IS DETERMINED BY YOUR PROFILE SCORES IN RELATION TO THRESHOLD LEVELS FOR FLEETS OF SIMILAR SIZE. THE TABLE BELOW SHOWS THE THRESHOLD VALUES AND CORRESPONDING PROFILE STATUS BASED ON YOUR CURRENT FLEET SIZE FOR THE CURRENT MONTH:

	PROFILE STATUS		
	SATISFACTORY	CONDITIONAL	UNSATISFACTORY
CONTRAVENTIONS	< 3.60	3.60- 9.59	> 9.59
CVSA	< 1.94	1.94- 4.43	> 4.43
ACCIDENTS	< 1.73	1.73- 3.22	> 3.22
TOTALS	< 5.33	5.33-10.82	>10.82

VEHICLE REG #	VEHICLE PLATE #	VEH YEAR	VEHICLE MAKE	VEHICLE MODEL	EFFECTIVE DATE	OWNER NAME	GVW	INSPECTION DECAL	DECAL EXPIRY DATE
00117717	5738KW	1999	FREIGHTLIN		2014-05-22		00014500	EP87019	2015-04-30
00832875	EV2509	1999	ISUZU	FTR	2014-12-31		00013000	EP89093	2015-07-31
00909407	HL3236	2001	GMC	2WHDR	2014-03-09	s22	00007900	EM26742	2014-09-30
02000793	HT9515	2000	VOLVO		2014-12-20		00036500	ER67462	2015-06-30
02903501	0750JP	2005	GMC		2014-01-21		00005490		
03400212	ER2117	2006	INTERNATNA		2014-09-19	VIMAC TRANSPORT LTD	00011790	EN82279	2014-10-31
03869254	HJ0561	2007	MITSUBISHI		2015-01-10		00008000	EC37937	2010-10-31
05892422	HJ0481	1998	HINO		2014-05-10	s22	00014500	EQ30498	2015-05-31
06825321	CT6045	1991	INTERNATNA		2014-10-15	VIMAC TRANSPORT LTD	00014000	EN82325	2014-10-31
08590418	7952KF	1993	GMC	2WHDR	2014-11-24	VIMAC TRANSPORT LTD	00011790	ER80322	2015-11-30

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-FEB-03 TO: 2015-FEB-03

NSC CARRIER: BC 00000200944818

VEHICLE REGISTRATION: 00025917 PLATE HC4123 99 GMC					
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-12-04	CVIP	S5935	EL19920	8730199	INSPECTION PASSED
2012-12-04	CVIP	S5935		8730188	VEHICLE INSPECTION REJECTED
VEHICLE REGISTRATION: 00117717 PLATE 5738KW FRHT					
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-08-08	CVSA				INSPECTION PASSED
2014-04-10	CVSA			8313700	VIOLATIONS PRESENT
2014-04-01	CVIP	S5335	EP87019	9504493	INSPECTION PASSED
2014-04-01	CVIP	S5335		9504492	VEHICLE INSPECTION REJECTED
2013-04-03	CVIP	S5335	EM10299	8865092	INSPECTION PASSED
2013-04-03	CVIP	S5335		8865090	VEHICLE INSPECTION REJECTED
2013-04-02	CVSA			8147041	VIOLATIONS PRESENT
2013-04-02	N&O			8147041	NOTICE & ORDER 2
2012-10-22	CVSA				VIOLATIONS PRESENT
2012-06-28	CVSA				VIOLATIONS PRESENT
2012-03-01	CVIP	S6872	EH33871	8413677	INSPECTION PASSED
VEHICLE REGISTRATION: 00309504 PLATE EV2517 96 FORD					
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-03-08	CVIP	S5335	EP86983	9447034	INSPECTION PASSED
2014-03-08	CVIP	S5335		9447033	VEHICLE INSPECTION REJECTED
2013-04-10	CVSA			8150240	VIOLATIONS PRESENT
2013-03-22	CVIP	S5335	EM10286	8849420	INSPECTION PASSED
2013-03-22	CVIP	S5335		8849393	VEHICLE INSPECTION REJECTED
2012-03-02	CVIP	S6872	EH33875	8415102	INSPECTION PASSED
VEHICLE REGISTRATION: 00467377 PLATE FG9909 00 GMC					
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-12-04	CVIP	S3353	EL44339	8726611	INSPECTION PASSED
2012-07-09	CVSA			8100044	VIOLATIONS PRESENT
2012-04-17	CVSA			8093182	VIOLATIONS PRESENT
VEHICLE REGISTRATION: 00702945 PLATE DE9818 98 GMC					
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-04-30	CVIP	S5335	EP88997	9570308	INSPECTION PASSED
2013-04-02	CVIP	S6703	EM55982	8863507	INSPECTION PASSED
2013-04-02	CVIP	S6703		8863493	VEHICLE INSPECTION REJECTED
2012-03-14	CVIP	S6703	EJ51796	8426196	INSPECTION PASSED
2012-03-14	CVIP	S6703		8426173	VEHICLE INSPECTION REJECTED
2012-02-27	CVIP	S4223	RD04035	8411903	VEHICLE INSPECTION REJECTED

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-FEB-03 TO: 2015-FEB-03

NSC CARRIER: BC 00000200944818

VEHICLE REGISTRATION: 00778705		PLATE HK5240		06	GMC	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME	
2014-02-22	CVIP	S4676	EP40444	9414744	INSPECTION PASSED	
2013-02-28	CVIP	S4676	EM22421	8820751	INSPECTION PASSED	
2012-12-12	CVSA			8115308	INSPECTION PASSED	
2012-02-18	CVIP	S6268		8399674	VEHICLE INSPECTION REJECTED	
2012-02-18	CVIP	S6268	EH96511	8399675	INSPECTION PASSED	
VEHICLE REGISTRATION: 00832875		PLATE EV2509		99	ISUZU	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME	
2014-07-12	CVIP	S5335	EP89093	9738930	INSPECTION PASSED	
2014-07-12	CVIP	S5335		9738929	VEHICLE INSPECTION REJECTED	
2014-06-28	CVIP	S5335	RD04571	9709211	VEHICLE INSPECTION REJECTED	
2013-06-03	CVIP	S5935	EM55257	8964271	INSPECTION PASSED	
2013-06-03	CVIP	S5935		8964263	VEHICLE INSPECTION REJECTED	
2012-05-04	CVIP	S6872	EH36142	8488758	INSPECTION PASSED	
VEHICLE REGISTRATION: 00909407		PLATE HL3236		2001	GMC	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME	
2014-07-07	CVSA			8346203	OUT OF SERVICE	
2014-03-11	CVSA			8296665	VIOLATIONS PRESENT	
VEHICLE REGISTRATION: 01287680		PLATE 6168JK		2003	GMC	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME	
2014-10-23	CVSA			8394365	VIOLATIONS PRESENT	
2014-06-09	CVSA				INSPECTION PASSED	
VEHICLE REGISTRATION: 02356386		PLATE HM9517		2005	VOLVO	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME	
2014-08-21	CVSA			8368280	VIOLATIONS PRESENT	
2014-08-03	CVIP	S7076	ER11094	9793710	INSPECTION PASSED	
2014-06-04	CVSA			8334454	VIOLATIONS PRESENT	
VEHICLE REGISTRATION: 02538661		PLATE FF1750		2005	HINO	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME	
2013-09-30	CVSA			8221480	VIOLATIONS PRESENT	
2013-07-03	CVSA			8187881	VIOLATIONS PRESENT	
2013-03-21	CVIP	S6353	EM39735	8846523	INSPECTION PASSED	
VEHICLE REGISTRATION: 03031972		PLATE 46940D		1969	GINDY	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME	
2014-06-04	CVSA			8334454	VIOLATIONS PRESENT	

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-FEB-03 TO: 2015-FEB-03

NSC CARRIER: BC 00000200944818

VEHICLE REGISTRATION: 03400212 PLATE ER2117 06 INTERNATNA

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-11-15	CVIP	S7076	ER80261	10027614	INSPECTION PASSED
2014-04-30	CVSA			8320570	INSPECTION PASSED
2014-02-28	CVSA			8291101	INSPECTION PASSED
2013-10-08	CVIP	S4223	EN82279	9151806	INSPECTION PASSED
2013-10-08	CVIP	S4223		9151805	VEHICLE INSPECTION REJECTED
2013-09-30	CVIP	S4223	RD04034	9140510	VEHICLE INSPECTION REJECTED
2013-08-02	CVSA				INSPECTION PASSED
2012-09-07	CVIP	S4223		8631353	VEHICLE INSPECTION REJECTED
2012-09-07	CVIP	S4223	EK10988	8631356	INSPECTION PASSED

VEHICLE REGISTRATION: 03785256 PLATE HV4018 07 INTERNATNA

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-05-19	CVIP	S5384	EJ39796	8504659	INSPECTION PASSED

VEHICLE REGISTRATION: 04326871 PLATE EX9387 97 FORD

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-03-28	CVIP	S5335	EP87012	9493038	INSPECTION PASSED
2014-03-28	CVIP	S5335		9493037	VEHICLE INSPECTION REJECTED

VEHICLE REGISTRATION: 04627758 PLATE ET6733 98 INTERNATNA

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-11-05	CVIP	S5417	EL21976	8696247	INSPECTION PASSED
2012-11-05	CVIP	S5417		8696237	VEHICLE INSPECTION REJECTED

VEHICLE REGISTRATION: 05074918 PLATE DY1168 98 GMC

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-04-29	CVIP	S5335	EP87066	9570081	INSPECTION PASSED
2014-04-29	CVIP	S5335		9570080	VEHICLE INSPECTION REJECTED
2013-04-09	CVIP	S5335	EM55877	8875168	INSPECTION PASSED
2013-04-04	CVIP	S5335	RD04176	8866238	VEHICLE INSPECTION REJECTED
2012-03-01	CVIP	S6872	EH33870	8412932	INSPECTION PASSED
2012-03-01	CVIP	S6872		8412924	VEHICLE INSPECTION REJECTED

VEHICLE REGISTRATION: 05892422 PLATE HJ0481 98 HINO

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-05-10	CVIP	S4168	EQ30498	9595085	INSPECTION PASSED
2014-05-10	CVIP	S4168		9595084	VEHICLE INSPECTION REJECTED

VEHICLE REGISTRATION: 05994813 PLATE HM9889 88 PETERBILT

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-09-29	CVIP	S7076	ER22505	9925798	INSPECTION PASSED
2014-09-29	CVIP	S7076		9925797	VEHICLE INSPECTION REJECTED
2013-08-25	CVIP	S7076	EN62249	9092458	INSPECTION PASSED
2013-02-09	CVIP	S3353	EM10604	8803266	INSPECTION PASSED

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-FEB-03 TO: 2015-FEB-03

NSC CARRIER: BC 00000200944818

VEHICLE REGISTRATION: 05994813	PLATE HM9889	88 PETERBILT	(CONTINUED)
2013-02-09 CVIP S3353		8803249	VEHICLE INSPECTION REJECTED
2012-12-18 CVSA		8115786	VIOLATIONS PRESENT
2012-08-29 CVIP S7079	EK75465	8619623	INSPECTION PASSED
2012-08-29 CVIP S7079		8619613	VEHICLE INSPECTION REJECTED
2012-02-27 CVIP S7079	EH96739	8408549	INSPECTION PASSED
2012-02-27 CVIP S7079		8408540	VEHICLE INSPECTION REJECTED

VEHICLE REGISTRATION: 06825321	PLATE CT6045	91 INTERNATNA			
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-11-15	CVIP	S7076	ER80262	10027619	INSPECTION PASSED
2013-10-22	CVIP	S4223	EN82325	9167606	INSPECTION PASSED
2013-10-22	CVIP	S4223		9167594	VEHICLE INSPECTION REJECTED
2013-08-19	CVSA			8205091	INSPECTION PASSED
2012-10-11	CVIP	S4223	EL01056	8668225	INSPECTION PASSED
2012-10-11	CVIP	S4223		8668200	VEHICLE INSPECTION REJECTED

VEHICLE REGISTRATION: 08590418	PLATE 7952KF	93 GMC			
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-05-08	CVIP	S4223	EM68784	8919271	INSPECTION PASSED
2013-05-08	CVIP	S4223		8919263	VEHICLE INSPECTION REJECTED
2012-02-06	CVIP	S4223	EH72556	8387199	INSPECTION PASSED
2012-02-06	CVIP	S4223		8387195	VEHICLE INSPECTION REJECTED

VEHICLE REGISTRATION: 08946228	PLATE	94 GMC			
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-03-15	CVIP	S5335	EM10277	8840928	INSPECTION PASSED
2012-03-23	CVIP	S5335	EJ07797	8437073	INSPECTION PASSED
2012-03-23	CVIP	S5335		8437054	VEHICLE INSPECTION REJECTED
2012-03-14	CVSA			8092598	VIOLATIONS PRESENT
2012-03-14	N&O			8087253	NOTICE & ORDER 2
2012-03-14	N&O			8092598	NOTICE & ORDER 2
2012-03-03	CVIP	S6872	EH33876	8415555	INSPECTION PASSED

VEHICLE REGISTRATION: 09533686	PLATE 49148C	2010 UTILITY			
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-12-18	CVSA			8115786	INSPECTION PASSED

VEHICLE REGISTRATION: 09562010	PLATE 9252HK	99 FREIGHTLIN			
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-04-16	CVIP	S5335	EJ62993	8461931	INSPECTION PASSED
2012-04-16	CVIP	S5335		8461911	VEHICLE INSPECTION REJECTED

**MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-FEB-03 TO: 2015-FEB-03**

NSC CARRIER: BC 00000200944818

VEHICLE REGISTRATION: 10201395 PLATE 49148D 2011 TRANELUSA

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-08-21	CVSA			8368280	INSPECTION PASSED

VEHICLE REGISTRATION: 10858740 PLATE HA6066 ISU

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-10-04	CVSA				VIOLATIONS PRESENT

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
DRIVERS CONTRAVENTIONS
ISSUED WHILE OPERATING FOR THE CARRIER
FROM: 2012-FEB-03 TO: 2015-FEB-03

NSC CARRIER: BC 00000200944818

VIOLATION DATE	ACT TIME	SECTION	EQUI CODE	DESCRIPTION	LOCATION	JR TICKET#	PLATE	JR PTS	DISP	DATE

2012-01-25	09:15	MVA 185.3A	s22 0113	DISOBEY RAILWAY STOP SIGN	RICHMOND	CLASS: 560 BC AH656293661	STATUS: NORMAL 6168JK	BC 3		2012-02-20
2014-03-11	15:35	MVA 214.21	s22 0226	USE ELECTRONIC DEVICE/DRIVING	DELTA	CLASS: 500 BC AH804577761	STATUS: NORMAL EN5873	BC 3		2014-03-22
2013-09-06	17:42	MVA 214.21	0226	USE ELECTRONIC DEVICE/DRIVING	VANCOUVER	BC AH816190781	EN5873	BC 3		2013-09-18
2012-03-22	10:40	MVA 214.21	0226	USE ELECTRONIC DEVICE/DRIVING	RICHMOND	BC AH596708461	5313LD	BC 1		2013-09-04
2012-10-29	13:46	CTR 7.32	0702	BYPASS WEIGH SCALE	DELTA	BC AH333444171	EN5873	BC 3		2012-11-22
2012-05-08	13:45	MVA 214.21	0226	USE ELECTRONIC DEVICE/DRIVING	DELTA	BC AH670822071	5313LD	BC 1		2012-05-11
2014-08-21	08:20	MVR 37.18051	s22 0442	FAIL TO FORWARD LOG/DOCUMENTS	LAIDLAW	CLASS: 100 BC AH764270061	STATUS: NORMAL HM9517	BC 2		2014-09-21
2013-01-18	14:40	MVA 220.4	s22 0212	FAIL TO WEAR SEAT BELT	VANCOUVER	CLASS: 500 BC AH775284152	STATUS: NORMAL DT8838	BC 2		2013-02-18
2014-04-13	17:37	MVA 219.1	s22 0604	IMPROPERLY EQUIPPED M.V.	KAMLOOPS	CLASS: 500 BC AH763215131	STATUS: NORMAL HJ0561	BC 3		2014-05-13
2013-10-23	22:20	MVA 125	0317	DISOBEY TRAFFIC CONTROL DEVICE	KNUTSFORD	BC AH763148231	ED8991	BC 3		2013-11-22
2013-06-30	03:27	MVA 129.1	0104	RED LIGHT AT INTERSECTION	VANCOUVER	BC ST007613971	ED8991	BC 3		2013-07-18
2014-09-16	09:15	MVA 158.2B	s22 0313	PASS ON RIGHT OFF ROADWAY	BURNABY	CLASS: 500 BC AH600208161	STATUS: NORMAL 0750JP	BC 3		2014-10-17
2012-08-24	10:05	MVA 220.4	0212	FAIL TO WEAR SEAT BELT	COQUITLAM	BC AH675942101	0750JP	BC 2		2012-09-24
2012-06-20	13:55	MVA 220.4	0212	FAIL TO WEAR SEAT BELT	BURNABY	BC AH722753841	0750JP	BC 2		2012-07-21
2013-12-04	12:38	MVA 161.A	s22 0317	DISOBEY TRAFFIC SIGN/SIGNAL	VANCOUVER	CLASS: 160 BC AH817084171	STATUS: NORMAL 0750JP	BC 3		2013-12-05
2014-07-21	10:24	MVA 146.7	s22 0004	SPEED AGAINST MUNICIPAL SIGN	VANCOUVER	CLASS: 500 BC AH849821911	STATUS: NORMAL HL3236	BC 1		2014-08-21
2013-01-02	05:57	MVA 195.1B	0334	DRIVE WHILE VIEW OBSTRUCTED	RICHMOND	BC AH657044311	EA0793	BC 3		2013-01-16
2012-05-15	07:29	MVA 129.1	s22 0104	RED LIGHT AT INTERSECTION	DELTA	CLASS: 500 BC ST004229731	STATUS: NORMAL 6298JV	BC 3		2012-06-05
2014-09-29	13:05	MVA 214.21	s22 0226	USE ELECTRONIC DEVICE/DRIVING	LANGLEY	CLASS: 500 BC AH865670161	STATUS: NORMAL EV2509	BC 3		2014-10-29
2014-10-22	11:40	MVR 37.233	s22 0500	NO INSPECTION REPORT	PITT MEADO	CLASS: 500 BC AH462242001	STATUS: NORMAL ER2117	BC 2		2014-11-24
2013-01-07	13:55	MVR 35.33	0900	DRIVER OPER COMM VEH/INSECURE	BURNABY	BC AH599515191	DE9818	BC 3		2013-02-06

TOTALS		NUMBER OF CONTRAVENTIONS		NUMBER OF NSC POINTS						
		21		52						

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
DRIVERS CONTRAVENTIONS PENDING
ISSUED WHILE OPERATING FOR THE CARRIER
FROM: 2012-FEB-03 TO: 2015-FEB-03

NSC CARRIER: BC 00000200944818

VIOLATION DATE	TIME	ACT SECTION	EQUI CODE	DESCRIPTION	LOCATION	JR	TICKET#	PLATE	JR

2014-03-10	10:00	MVA 128.1A	s22 0105	YELLOW LIGHT AT INTERSECTION	CLASS: 560 SURREY BC		STATUS: NORMAL AH801626301	HA6066	BC
2013-10-23	16:07	MVA 144.1B	s22 0016	DRIVE WITHOUT CONSIDERATION	CLASS: 500 RICHMOND BC		STATUS: HOLD AH767679811	FF1750	BC
2014-09-17	13:00	MVA 220.4	s22 0212	FAIL TO WEAR SEAT BELT	CLASS: 160 LANGLEY BC		STATUS: HOLD AH834856831	HJ0481	BC
TOTALS		NUMBER OF PENDING CONTRAVENTIONS							

3									

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-FEB-03 TO: 2015-FEB-03

NSC CARRIER: BC 00000200944818

INSP DATE VEH TYPE	TIME PLATE#	LEVEL JR	MICRO# VEH REG	NSC PTS VEHICLE DESC	LOCATION	DL# PASS/FAIL	DLJR INSPECTION	DRIVER NAME ITEM DEFECT(S)
2014-10-23 POWER UNIT	09:42 6168JK	2 BC	8394365 01287680	0 2003 GMC	NEW WESTMI	FAIL	s22 41	
2014-08-21 POWER UNIT TRAILER 1	08:06 HM9517 49148D	3 BC BC	8368280 02356386 10201395	0 2005 VOLVO 2011 TRANELUSA	LAIDLAW	FAIL PASS	s22 40	
2014-08-08 TRUCK	12:34 5738KW	3 BC	0406391 00117717	0 FRHT	SC33 BOW	PASS	s22	
2014-07-07 POWER UNIT	07:36 HL3236	2 BC	8346203 00909407	3 2001 GMC	DELTA	OOS	s22 52	
2014-06-09 TRUCK	14:24 6168JK	3 BC	9840902 01287680	0 GMC	ROADSIDE	PASS	s22	
2014-06-04 POWER UNIT TRAILER 1	07:47 HM9517 46940D	1 BC BC	8334454 02356386 03031972	0 2005 VOLVO 1969 GINDY	HOPE	FAIL FAIL	s22 43 46 55 51	
2014-04-30 POWER UNIT	06:35 ER2117	3 BC	8320570 03400212	0 2006 INTERNATNA	LAIDLAW	PASS	s22	
2014-04-13 POWER UNIT	17:27 HJ0561	1 BC	8315031 03869254	3 2007 MITSUBISHI	KAMLOOPS J	OOS FAIL	s22 46 41	
2014-04-10 POWER UNIT	10:52 5738KW	1 BC	8313700 00117717	0 1999 FREIGHTLIN	NEW WESTMI	FAIL	s22 41 51	
2014-03-11 POWER UNIT	13:16 HL3236	1 BC	8296665 00909407	0 2001 GMC	DELTA	FAIL	s22 43 46 55	
2014-02-28 POWER UNIT	14:21 ER2117	1 BC	8291101 03400212	0 2006 INTERNATNA	LAIDLAW	PASS	s22	
2013-11-05 POWER UNIT	10:52 FD0592	1 BC	8284761 00909407	3 2001 GMC	DELTA	OOS FAIL	s22 52 44 45 55	
2013-10-04 TRUCK	12:11 HA6066	3 BC	7607455 10858740	0 ISU	NB	FAIL	s22 40	
2013-09-30 POWER UNIT	11:57 FF1750	1 BC	8221480 02538661	0 2005 HINO	LANGLEY	FAIL	s22 40	

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-FEB-03 TO: 2015-FEB-03

NSC CARRIER: BC 00000200944818

INSP DATE VEH TYPE	TIME PLATE#	LEVEL JR	MICRO# VEH REG	NSC PTS VEHICLE DESC	LOCATION	DL# PASS/FAIL	DLJR INSPECTION	DRIVER NAME ITEM DEFECT(S)
2013-08-19 POWER UNIT	11:06 CT6045	1 BC	8205091 06825321	0 1991 INTERNATNA	DELTA	PASS		s22
2013-08-02 TRUCK	14:33 ER2117	3 BC	6885269 03400212	0 INTL	BLAINE, WA	PASS		s22
2013-07-03 POWER UNIT	11:31 FF1750	1 BC	8187881 02538661	0 2005 HINO	DELTA	FAIL	42 44	s22
2013-04-10 POWER UNIT	11:35 BY0638	1 BC	8150240 00309504	0 1996 FORD	NEW WESTMI	FAIL	44	s22
2013-04-02 POWER UNIT	21:05 5738KW	3 BC	8147041 00117717	0 1999 FREIGHTLIN	SURREY	FAIL	40 55	s22
2012-12-18 POWER UNIT TRAILER 1	10:15 0761KV 49148C	3 BC BC	8115786 05994813 09533686	0 1988 PETERBILT 2010 UTILITY	DELTA	FAIL PASS	40	s22
2012-12-12 POWER UNIT	10:49 EN5873	3 BC	8115308 00778705	0 2006 GMC	NEW WESTMI	PASS		s22
2012-10-22 TRUCK	06:30 5738KW	2 BC	4189596 00117717	0 FRHT	SC33 BOW	FAIL	40	s22
2012-07-09 POWER UNIT	10:45 DT8838	1 BC	8100044 00467377	0 2000 GMC	DELTA	FAIL	42 44 46	s22
2012-06-28 TRUCK	09:30 5738KW	3 BC	3066843 00117717	0 FRHT	SC38 STA	FAIL	40	s22
2012-04-17 POWER UNIT	15:30 DT8838	1 BC	8093182 00467377	0 2000 GMC	DELTA	FAIL	41 51	s22
2012-03-14 POWER UNIT	12:35 CR2767	2 BC	8092598 08946228	0 1994 GMC	DELTA	FAIL	41 42 48 55	s22
TOTALS			NUMBER OF INSPECTION REPORTS	NUMBER OF UNITS INSPECTED	NUMBER OF NSC POINTS			
			26	31	9			

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
ACCIDENT INFORMATION
FROM: 2012-FEB-03 TO: 2015-FEB-03

NSC CARRIER: BC 00000200944818

VEHICLE REPORT#	VEHICLE D/L PLATE	JR DRIVER NAME	DATE	TIME	TYP	LOCATION	JR	FAULT RESP	NSC PTS	CHR LAID

R4501044	FF1750	s22	2013-10-23	15:16	PD	RICHMOND	BC	F	2	Y
R4451469	EA0793		2013-01-02	00:00	PD	RICHMOND	BC	F	2	Y

TOTALS	NUMBER OF ACCIDENT REPORTS	NUMBER OF NSC POINTS

	2	4