



**FINAL INSPECTION  
CONFIRMATION NUMBER**  
**10050158**

**PLACE DECAL  
HERE**  
**EQ26060**

**DECAL EXPIRY DATE**  
**31 MAY 2015**

**INSPECTION RESULT:** Pass  
**INSPECTION TYPE:** Complete  
**REASON FOR INSPECTION:** Semi-Annual  
**COLLISION REPAIR FACILITY:**

**WORK ORDER #**  
**INSPECTION START DATE** 26 NOV 2014 13:35  
**INSPECTION COMPLETE DATE** 26 NOV 2014 14:13

**REASON NOTE:**  
**TECHNICIAN NAME:**  
**PHONE #:**

**INSPECTOR'S NUMBER:** M11530  
**INSPECTOR'S NAME:** HOSKINS, ROBERT JOHN  
**LICENCE EXPIRY DATE:** 31-MAR-2015  
**FACILITY NUMBER:** S6192  
**FACILITY NAME:** PORT COQUITLAM TIRE LTD.  
**INSPECTION CLASS:** 1 - Motor vehicle with lic. GVW of 5,500 kgs or less

**OWNER/LESSEE:** HALLCON ASSET MANAGEMENT INC  
**ADDRESS:** 1010-5775 YONGE ST  
**CITY:** NORTH YORKE **PROV:** ON **POSTAL CODE:** M2M4J1  
**REGISTRATION #:** 10569606 **VEH. JURISDICTION:** BC **PLATE:** EM1050  
**YEAR:** 2008 **MAKE:** CHEVROLET **MODEL:** EXPRS  
**BODY STYLE:** BUS **VIN:** 1GAHG39K581134294  
**ODOMETER:** 345954 KM **FUEL TYPE:** Gasoline  
**UNIT/FLEET #:** 5462 **BRAKE TYPE:** Hydraulic

"F" Failed "R" Repaired Same Day "P" Passed "PC" Passed With Caution "O" Out Of Service "NA" Not Applicable

	F	R	P	PC	O	NA		F	R	P	PC	O	NA
<b>Section 1 - Power Train</b>			✓				Pressure Fuel						
							Liquid Propane Gas						✓
							Compressed Natural Gas						✓
<b>Section 2 - Suspension</b>			✓				Pressure Fuel Inspector's Name & Number						
<b>Section 3 - Hydraulic Brakes</b> REPLACE LEAKING MASTER CYLINDER AND FRONT AND REAR CALIPERS			✓				<b>Air Brake Chamber Type, Size and Push Rod Stroke Measurement (mm)</b>						
<b>Section 3A - Air Brakes</b>						✓	Axle # 1 2 3 4 5 6 7 8 9						
<b>Section 4 - Steering</b>			✓				Type:						
<b>Section 5 - Instruments, Auxiliary Equipment</b>						✓	Size:						
<b>Section 6 - Lamps</b>			✓				Slack:						
<b>Section 7 - Electrical System</b> REPLACED RIGHT REAR ABS PIGTAIL DUE TO INTERMITTENT SHORT			✓				Left:						
<b>Section 8 - Body &amp; Frame</b>			✓				Right:						
<b>Section 9 - Tires &amp; Wheels</b>			✓				Comments:						
<b>Section 10 - Couplers &amp; Hitches</b>						✓	<b>Air Brake Camshaft Rotation Measurement (degrees)</b>						
<b>Section 11 - Other Vehicle Components</b>						✓	Axle # 1 2 3 4 5 6 7 8 9						
							Left:						
							Right:						
							Comments:						
							<b>Brake Lining/Pad Measurement (mm)</b>						
							Axle # 1 2 3 4 5 6 7 8 9						
							Type: Pad Pad						
							Left: 12 10						
							Right: 12 10						
							Comments: 1 - BRAKE PADS REPLACED; 2 - SERVICED REAR BRAKES						
							<b>Rotor/Drum Measurement (mm)</b>						
							Axle # 1 2 3 4 5 6 7 8 9						
							Type: Rotor Rotor						
							Left: 38.10 28.81						
							Right: 38.10 28.81						
							Comments: 1 - ROTORS REPLACED						
<b>General Inspection Comments:</b> VEHICLE CAME IN WITH LOW/ SOFT BRAKE PEDAL AND SERVICE TRACTION LIGHT ON INTERMITTENTLY. WE FOUND LEAKING MASTER CYLINDER ,SEIZED REAR CALIPER SLIDES ,WARPED FRONT BRAKE ROTORS CAUSING BRAKE PULSATION													

Inspector's Name **HOSKINS, ROBERT JOHN**

Signature

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

**NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION**

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement Branch, by writing to P.O. Box 9250, Stn Prov. Gov't, Victoria, BC V8W 9J2, by e-mailing to vehicle.inspections@gov.bc.ca or calling 250-952-0577.



INSPECTION RESULT: Fail  
INSPECTION TYPE: Complete  
REASON FOR INSPECTION: Semi-Annual  
COLLISION REPAIR FACILITY:

WORK ORDER #  
INSPECTION START DATE: 26 NOV 2014 13:35  
INSPECTION COMPLETE DATE: 26 NOV 2014 14:13

REASON NOTE:  
TECHNICIAN NAME:  
PHONE #:

INSPECTOR'S NUMBER: M11530  
INSPECTOR'S NAME: HOSKINS, ROBERT JOHN  
LICENCE EXPIRY DATE: 31-MAR-2015  
FACILITY NUMBER: S6192  
FACILITY NAME: PORT COQUITLAM TIRE LTD.  
INSPECTION CLASS: 1 - Motor vehicle with lic. GVW of 5,500 kgs or less

OWNER/LESSEE: HALLCON ASSET MANAGEMENT INC  
ADDRESS: 1010-5775 YONGE ST  
CITY: NORTH YORKE PROV: ON POSTAL CODE: M2M4J1  
REGISTRATION #: 10569606 VEH. JURISDICTION: BC PLATE: EM1050  
YEAR: 2008 MAKE: CHEVROLET MODEL: EXPRS  
BODY STYLE: BUS VIN: 1GAHG39K581134294  
ODOMETER: 345954 KM FUEL TYPE: Gasoline  
UNIT/FLEET #: 5462 BRAKE TYPE: Hydraulic

"F" Failed "R" Repaired Same Day "P" Passed "PC" Passed With Caution "O" Out Of Service "NA" Not Applicable

	F	R	P	PC	O	NA		F	R	P	PC	O	NA			
<b>Section 1 - Power Train</b>			✓				Pressure Fuel									
							Liquid Propane Gas						✓			
							Compressed Natural Gas						✓			
<b>Section 2 - Suspension</b>			✓				Pressure Fuel Inspector's Name & Number									
<b>Section 3 - Hydraulic Brakes</b> REPLACE LEAKING MASTER CYLINDER AND FRONT AND REAR CALIPERS			✓				<b>Air Brake Chamber Type, Size and Push Rod Stroke Measurement (mm)</b>									
<b>Section 3A - Air Brakes</b>						✓	Axle #	1	2	3	4	5	6	7	8	9
<b>Section 4 - Steering</b>			✓				Type:									
<b>Section 5 - Instruments, Auxillary Equipment</b>						✓	Size:									
<b>Section 6 - Lamps</b>			✓				Slack:									
<b>Section 7 - Electrical System</b> REPLACED RIGHT REAR ABS PIGTAIL DUE TO INTERMITTENT SHORT			✓				Left:									
<b>Section 8 - Body &amp; Frame</b>			✓				Right:									
<b>Section 9 - Tires &amp; Wheels</b>			✓				Comments:									
<b>Section 10 - Couplers &amp; Hitches</b>						✓	<b>Air Brake Camshaft Rotation Measurement (degrees)</b>									
<b>Section 11 - Other Vehicle Components</b>						✓	Axle #	1	2	3	4	5	6	7	8	9
							Left:									
							Right:									
							Comments:									
							<b>Brake Lining/Pad Measurement (mm)</b>									
							Axle #	1	2	3	4	5	6	7	8	9
							Type:	Pad	Pad							
							Left:	12	10							
							Right:	12	10							
							Comments:	1 - BRAKE PADS REPLACED; 2 - SERVICED REAR BRAKES								
							<b>Rotor/Drum Measurement (mm)</b>									
							Axle #	1	2	3	4	5	6	7	8	9
							Type:	Rotor	Rotor							
							Left:	38.10	28.81							
							Right:	38.10	28.81							
							Comments:	1 - ROTORS REPLACED								

General Inspection Comments:  
VEHICLE CAME IN WITH LOW/ SOFT BRAKE PEDAL AND SERVICE TRACTION LIGHT ON INTERMITTENTLY. WE FOUND LEAKING MASTER CYLINDER ,SEIZED REAR CALIPER SLIDES ,WARPED FRONT BRAKE ROTORS CAUSING BRAKE PULSATION

Inspector's Name HOSKINS, ROBERT JOHN Signature

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.  
NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VP at the Commercial Vehicle Safety Enforcement Branch, by writing to P.O. Box 9250, Stn Prov. Gov't, Victoria, BC V8W 9J2, by e-mailing to vehicle.inspections@gov.bc.ca or calling 250-952-0577.





VEHICLE INSPECTION REPORT / NOTICE and ORDER

Vehicle(s) inspected this 26 of NOV YR 2014 at 11:03 (24hr Clock) on HWY 7 at or near Port Coquitlam
INSPECTION LEVEL: 5 - Vehicle Only CAMPAIGN: CVSA Violation Ticket #:

INSPECTION RESULT: Violations Present

INSPECTION ITEMS NOTED BELOW TO BE REPAIRED: PRIOR TO NEXT DISPATCH

SEND PROOF OF REPAIRS TO: 310-1500 Woolridge Street Coquitlam V3K0B8 /FAX:604-527-2214

Power Unit: Violations Present CVSA decal:
Owner: HALLCON CREW TRANSPORT INC
Address: 1010-5775 YONGE ST
City: NORTH YORK Prov: ON Postal Code: M2M4J1
Registration: 10569606 NSC #: 201269008 Jur: BC
Plate #: EM1050 Year: 2008 Make: CHEVROLET
Body Style: BUS VIN: 1GAHG39K581134294
GVW: 0003948 Odometer: 263938 KM
CVIP decal: EQ26060 CVIP Jur: BC
Cargo Seal #: UN: DG Type:

INSPECTION RESULTS table with columns: INSPECTION ITEMS, #, PU, COMMENTS. Rows include Driver, Steering, Braking System, Suspension, Exhaust System, Miscellaneous.

BRAKE INFORMATION table with columns: Unit, Axle #, Brake Type, Chamber Type, Chamber Size, Slack Type, Left, Right.

ADDITIONAL COMMENTS:
PT Licence # 71510

Peace Officer (Inspector): M.ZAKUS Number: MV927 Signature:
310-1500 Woolridge Street Coquitlam V3K0B8 Assist:
I HEREBY ACKNOWLEDGE RECEIPT OF A COPY OF THIS INSPECTION REPORT. DRIVER SIGNATURE:

SEE REVERSE FOR DETAILS REGARDING COMPLIANCE.

The information on this form is collected under the authority of the Motor Vehicle Act, Section 217. The information will be used to process your vehicle inspection and/or Notice and Order. If you have any questions please contact the issuing Officer or call CVSE at (250) 952-0577. Visit www.cvse.ca

## VEHICLE INSPECTION COMPLIANCE INFORMATION

ON THE DATE AND PLACE NOTED A VEHICLE(S) REGISTERED IN YOUR NAME WAS INSPECTED IN ORDER TO ENSURE THE SAFE PERFORMANCE OF THE VEHICLE(S). THE COMPONENTS MARKED WITH AN "O" MUST BE CORRECTED IMMEDIATELY. THE COMPONENTS MARKED WITH AN "X" MUST BE REPAIRED BEFORE THE TIMEFRAME INDICATED. THE COMPONENTS MARKED WITH A "C" ARE NOTED TO MAKE YOU AWARE OF POSSIBLE VIOLATIONS. "PU" INDICATES POWER UNIT, "T1" TRAILER #1, "T2" TRAILER #2 AND "T3" TRAILER #3.

ANY QUERIES REGARDING THIS REPORT SHOULD BE DIRECTED TO THE COMMERCIAL VEHICLE SAFETY AND ENFORCEMENT BRANCH, MINISTRY OF TRANSPORTATION AND INFRASTRUCTURE, PO BOX 9250 STN PROV GOVT, VICTORIA, BC V8W 9J2. VISIT WWW.CVSE.CA

### NOTICE

The owner may choose not to have the vehicle inspected or repaired, but rather to surrender the vehicle license and number plates to the Vice President Operations – ICBC or his/her designate. Should the vehicle license and number plates be surrendered or seized by a Peace Officer, the vehicle owner must make a separate application to ICBC or its agents for a refund.

It is the obligation of the registered owner to advise a subsequent registered owner of any outstanding vehicle inspection requirements.

### DISPOSITION

Violation(s) corrected:      Yes     No       Date: \_\_\_\_\_      Agency: \_\_\_\_\_  
 Peace Officer (Print): \_\_\_\_\_      Number: \_\_\_\_\_

### WARNING

IT IS AN OFFENCE TO OPERATE A VEHICLE WHICH DOES NOT COMPLY WITH THE MOTOR VEHICLE ACT AND REGULATIONS OR THIS NOTICE AND ORDER. FAILURE TO COMPLY WITH A NOTICE AND ORDER MAY RESULT IN THE REFUSAL OF FURTHER VEHICLE LICENSE TRANSACTIONS. PENALTIES FOR OPERATING A VEHICLE IN CONTRAVENTION OF A NOTICE AND ORDER INCLUDE A FINE AND SEIZURE OF THE VEHICLE LICENSE AND NUMBER PLATES.

The information on this form is collected under the authority of the Motor Vehicle Act, Section 217. The information will be used to process your vehicle inspection and/or Notice and Order. If you have any questions please contact the issuing Officer or call CVSE at (250) 952-0577. Visit [www.cvse.ca](http://www.cvse.ca)

MV3110E (072013)

THIS REPORT MUST BE RETAINED BY THE CARRIER FOR THE CURRENT YEAR PLUS FOUR YEARS



VEHICLE INSPECTION REPORT / NOTICE and ORDER

Vehicle(s) inspected this 27 of NOV YR 2014 at 11:29 (24hr Clock) on HWY 7 at or near Port Coquitlam
INSPECTION LEVEL: 5 - Vehicle Only CAMPAIGN: CVSA Violation Ticket #:

INSPECTION RESULT: Violations Present

INSPECTION ITEMS NOTED BELOW TO BE REPAIRED: PRIOR TO NEXT DISPATCH
SEND PROOF OF REPAIRS TO: 310-1500 Woolridge Street Coquitlam V3K0B8 /FAX:604-527-2214

Power Unit: Violations Present CVSA decal:
Owner: HALLCON CREW TRANSPORT INC
Address: 1010-5775 YONGE ST
City: NORTH YORK Prov: ON Postal Code: M2M4J1
Registration: 10569606 NSC #: 201269008 Jur: BC
Plate #: EM1050 Year: 2008 Make: CHEVROLET
Body Style: BUS VIN: 1GAHG39K581134294
GVW: 0003948 Odometer: 345954 KM
CVIP decal: EQ26060 CVIP Jur: BC
Cargo Seal #: UN: DG Type:

INSPECTION RESULTS table with columns: INSPECTION ITEMS, #, PU, COMMENTS. Rows include Driver, Steering, Braking System, Suspension, Hubs/Tires/Wheels/Rims, Exhaust System, Miscellaneous.

BRAKE INFORMATION table with columns: Unit, Axle #, Brake Type, Chamber Type, Chamber Size, Slack Type, Left, Right. Rows for PU on axles 1 and 2.

ADDITIONAL COMMENTS:
Vehicle is not allowed to carry passengers until all repairs and concerns are address

Peace Officer (Inspector): M.ZAKUS Number: MV927 Signature:
310-1500 Woolridge Street Coquitlam V3K0B8 Assist:
I HEREBY ACKNOWLEDGE RECEIPT OF A COPY OF THIS INSPECTION REPORT. DRIVER SIGNATURE:

SEE REVERSE FOR DETAILS REGARDING COMPLIANCE.

The information on this form is collected under the authority of the Motor Vehicle Act, Section 217. The information will be used to process your vehicle inspection and/or Notice and Order. If you have any questions please contact the issuing Officer or call CVSE at (250) 952-0577. Visit www.cvse.ca



## VEHICLE INSPECTION COMPLIANCE INFORMATION

ON THE DATE AND PLACE NOTED A VEHICLE(S) REGISTERED IN YOUR NAME WAS INSPECTED IN ORDER TO ENSURE THE SAFE PERFORMANCE OF THE VEHICLE(S). THE COMPONENTS MARKED WITH AN "O" MUST BE CORRECTED IMMEDIATELY. THE COMPONENTS MARKED WITH AN "X" MUST BE REPAIRED BEFORE THE TIMEFRAME INDICATED. THE COMPONENTS MARKED WITH A "C" ARE NOTED TO MAKE YOU AWARE OF POSSIBLE VIOLATIONS. "PU" INDICATES POWER UNIT, "T1" TRAILER #1, "T2" TRAILER #2 AND "T3" TRAILER #3.

ANY QUERIES REGARDING THIS REPORT SHOULD BE DIRECTED TO THE COMMERCIAL VEHICLE SAFETY AND ENFORCEMENT BRANCH, MINISTRY OF TRANSPORTATION AND INFRASTRUCTURE, PO BOX 9250 STN PROV GOVT, VICTORIA, BC V8W 9J2. VISIT [WWW.CVSE.CA](http://WWW.CVSE.CA)

### NOTICE

The owner may choose not to have the vehicle inspected or repaired, but rather to surrender the vehicle license and number plates to the Vice President Operations – ICBC or his/her designate. Should the vehicle license and number plates be surrendered or seized by a Peace Officer, the vehicle owner must make a separate application to ICBC or its agents for a refund.

It is the obligation of the registered owner to advise a subsequent registered owner of any outstanding vehicle inspection requirements.

### DISPOSITION

Violation(s) corrected:      Yes     No       Date: \_\_\_\_\_      Agency: \_\_\_\_\_  
 Peace Officer (Print): \_\_\_\_\_      Number: \_\_\_\_\_

### WARNING

IT IS AN OFFENCE TO OPERATE A VEHICLE WHICH DOES NOT COMPLY WITH THE MOTOR VEHICLE ACT AND REGULATIONS OR THIS NOTICE AND ORDER. FAILURE TO COMPLY WITH A NOTICE AND ORDER MAY RESULT IN THE REFUSAL OF FURTHER VEHICLE LICENSE TRANSACTIONS. PENALTIES FOR OPERATING A VEHICLE IN CONTRAVENTION OF A NOTICE AND ORDER INCLUDE A FINE AND SEIZURE OF THE VEHICLE LICENSE AND NUMBER PLATES.

The information on this form is collected under the authority of the Motor Vehicle Act, Section 217. The information will be used to process your vehicle inspection and/or Notice and Order. If you have any questions please contact the issuing Officer or call CVSE at (250) 952-0577. Visit [www.cvse.ca](http://www.cvse.ca)

MV3110E (072013)

THIS REPORT MUST BE RETAINED BY THE CARRIER FOR THE CURRENT YEAR PLUS FOUR YEARS

**Lobo, Nicole TRAN:EX**

---

**From:** Ron Davidson <ron.davidson@hallconcrewtransport.com>  
**Sent:** Friday, November 28, 2014 8:31 AM  
**To:** Zakus, Mike TRAN:EX  
**Subject:** Hallcon Vans

Here is my web address

Ron Davidson



**Regional Manager (BC Central)**  
47405 Sumac Drive Box 176  
Boston Bar B.C. V0K 1C0  
Phone 604 206 0184  
Fax 604 867 9533  
[ron.davidson@hallconcrewtransport.com](mailto:ron.davidson@hallconcrewtransport.com)

## Lobo, Nicole TRAN:EX

---

**From:** ron.davidson@hallconcrewtransport.com  
**Sent:** Friday, November 28, 2014 11:54 AM  
**To:** Zakus, Mike TRAN:EX  
**Subject:** Re: Hallcon Vans

Yes thanks

Sent from my BlackBerry 10 smartphone on the TELUS network.

**From:** Zakus, Mike TRAN:EX  
**Sent:** Friday, November 28, 2014 11:17  
**To:** Ron Davidson  
**Subject:** RE: Hallcon Vans

Thanks Ron here are copies of your two bus inspections,  
Please let me know you received them

Mike Zakus  
Area Vehicle Inspector  
Commercial Vehicle Safety & Enforcement  
Ministry Of Transportation & Infrastructure  
313-1500 Woolridge Street, Coquitlam, B.C. V3K 0B8  
Cell Phone 604 619-7646

**From:** Ron Davidson [<mailto:ron.davidson@hallconcrewtransport.com>]  
**Sent:** Friday, November 28, 2014 8:31 AM  
**To:** Zakus, Mike TRAN:EX  
**Subject:** Hallcon Vans

Here is my web address

Ron Davidson



**Regional Manager (BC Central)**  
47405 Sumac Drive Box 176  
Boston Bar B.C. V0K 1C0  
Phone 604 206 0184  
Fax 604 867 9533  
[ron.davidson@hallconcrewtransport.com](mailto:ron.davidson@hallconcrewtransport.com)