Actions Taken from 2012-04-28 to 2017-04-28

Name:	LOUISIANA-PACIFIC CANADA LTD.		Number:	00165599
Address:	RR1 SITE 13 COMP 2 FORT ST JOHN BC V1J4M6		Location Code	09
inspection IC		IMS Article	ramana Continua di Kacamatan Kabupatèn Kabupatèn Kabupatèn Kabupatèn Kabupatèn Kabupatèn Kabupatèn Kabupatèn K	Action Actions Taken Date
269866	A01/A60049A60049 A60049 CP 240 Blk S0911	Ft. St. John Pilot Project R (1)(A)	egulation 28	Compliance Nr 2013-01-09
Case No.	E Site Atticle		5477034348287537987836649	Action Action Taken Takén

No Enforcement Actions Found

Actions Taken from 2012-04-28 to 2017-04-28

Name:	LOUISIANA-PACIFIC CANADA LTD.	Number:	00165599	
Address:	FOREST RESOURCES DIVISION 1018 1508 102ND AVENUE DAWSON CREEK BC V1G2E;	Location Code	04	
Inspection IC	CIMS Site Article	Control State Control Control Control Control	Scuon Action	
	No Compliance Actions Found			
Case No	LANGERS LEGIS ESPECIA CONTRACTOR DE CONTRA EL CONTRACTOR DE CONTRACTOR D	n Oukcome A	EL STAN ERRO DE CELAT ESCAPERA PER ENCEPCIO CONTRACTO A CALLACTA PER PE	

Date Printed; 2
User ID; 10

Environment:

2017-04-28 IDIR\THUNT PROD

Actions Taken from 2012-04-28 to 2017-04-28

Name:	LOÙISIANA-PACIFIC CANADA LTD.	Number:	00165599			
Address:	OSB SECTION PO BOX 2338 DAWSON CREEK BC V1G4P2	Location Code	03			
inspection II	CIMS D. Site Article		ction Action			
	No Compliance Actions Found					
ERA Case No Sile Affice Contravention Outcome Action Action Taken Status Status Taken Bate						
No Enforcement Actions Found						

Environment:

Actions Taken from 2012-04-28 to 2017-04-28

Name:	LOUISIANA-PÀCIFIC CANADA LTD.	Number:	00165599 02		
Address:	FOREST RESOURCES DIVISION 116 116 AVENUE, DAWSON CREEK BC V1G3C8	Location Code			
Inspection I	ČIMS D Site Article	PROFESSION (1998)	Action Action Taken Date		
•	No Compliance Actions Found				
ERA Case No Site Article Contravention Oucome Action Action Taken Status Taken Contravention Oucome					
No Enforcement Actions Found					

Actions Taken from 2012-04-28 to 2017-04-28

Name:	LOUISIANA-PAÇIFIC CANADA LID.	Number:	00165599	
Address:	116 116 AVENUE DAWSON CREEK BC V1G3C8	Location Code	00	
Inspection (I	CIMS Site Article		ccion Action	
	No Compliance Actions Found			
Case No	ERA Sile Aricle Contraver Status	ntion Culcame A Status I	xctlon Action Taken aken Date	
	No Enforcement Actions Found			



INSPECTION REPORT



RECORD ID: 031456 IDIR\CEMSLIE 08:41 May 16, 2016

ONTROPHED CHOSE	Natural Resource Officer: Christopher Emslie		<u> </u>			11	Date of Inspection: Apr 08, 2016	
Client:	lr	n Attendance:				ompliance	Status:	
LOUISIANA-PACIFIC CANADA LTD., C/O					Meged Non-	eged Non-Compliance		
CANADIAN FORE PRODUCTS								
Client Contact In							atitude:	
RR1 SITE 13 CON FORT ST JOHN,B						56	6.428583	
V1J4M6						L	ongitude:	
							21.326761	
Secondary Tenur								
Alleged Non-Com aNC# Estimated	Parent A		ion	Section	Desci	ription	Action Taken	
2264 Oct 20, 2015	Forest and Rang Practices Act			1 (1)(b)	carry out, construence, damage	uct, modify, e, destroy a	Compliance Notice	
Warning Ticket:				ERA Cas	se #:			
Description and C	comments:							

Upon receiving a complaint of damage to a range licence holder's fence. Natural Resource Officers EMSLIE and DYKE conducted a site inspection of the Range Licence Area RAN076539 fence line that borders and crosses to the west side of Road Permit R19606. Officer EMSLIE noted several locations between coordinates 56.49593, -121.43861 and 56.48920, -121.43708 where the fence was damaged by debris that appeared to be pushed and piled on top as a result of road construction and maintenance. A gate at coordinate 56.49593, -121.43861 was present; however, buried under piled debris, gravel and mud from the road rendering it unusable.

COMPLIANCE NOTICE:

The Road Permit Holder: LOUISIANA-PACIFIC CANADA LTD., C/O CANADIAN FOREST PRODUCTS Client: 00165599 Location Code: 09

is hereby requested to remove any and all debris from the fence adjoining R19606 Road between coordinates 56.49593, -121.43861 and 56.48920, -121.43708, to repair any downed wire and to place new posts where posts have been knocked over and damaged by the piling of debris. These repairs will be made to the satisfaction of Natural Resource Officer Chris Emslie on or before June 1, 2016. Inaction or failure to repair the aforementioned

	of these repairs as recent forestry operations throughout acted as a natural range barrier. As a result, there is an les that previously required no maintenance. Contact				
Natural Resource Officer: [Christopher Emslie]	Sent to:				
inatural Resource Officer: [Offistopher Emshe]	RR1 SITE 13 COMP 2,,				
Signature: X	FORT ST JOHN,BC,CANADA V1J4M6				
Leartify that this inspection conforms to Ministry compliance procedures.					
Attachments and Comments:					
1) R19606 Damage to Range Development jpg Damage area	Delivered via:				
defineation 2) Photo Guide of Debris - R19606.pdf Photo Guide of Debris Damage					
	Email: X Fax:				
	Mail: Hand Delivery:				