From: Baudin, Clive FLNR:EX

To: s.22

 Cc:
 Baudin, Clive FLNR:EX

 Subject:
 Jeffries Road inspection.

 Date:
 May 5, 2016 11:41:08 AM

 Attachments:
 inspectionReport032849.pdf

Here is the Attached inspection. Let me know if you received it. Thanks.

Clive Baudin RFT

Natural Resource Officer

South Island Field Team / West Coast Region

Ministry of Forests, Lands and Natural Resource Operations

250-746-1281

## To Report a Natural Resource Violation:

Call **1-844- NRO- TIPS** (676-8477)

Webpage: https://www.for.gov.bc.ca/hen/nrv/report.htm



Client: s.22

## **INSPECTION REPORT**



**RECORD ID: 032849** 

s.15

Apr 15, 2016

11:35 May 05, 2016

Natural Resource Officer:

In Attendance:

Region: West Coast

Field Unit: South Island

Date of Inspection:

Compliance Status:
Alleged Non-Compliance

| s.22                         | Mark Kissinger | Alleged Non-Compliance    |  |
|------------------------------|----------------|---------------------------|--|
| Client Contact Infor<br>s.22 | rmation:       | <b>Latitude:</b> 48.76046 |  |
|                              |                | Longitude:<br>-123.7825   |  |
| Location Descriptions.22     | on:            |                           |  |
| Primary Tenure/Aut           | horization:    |                           |  |
| TENURE REQUIRED              | D/NRIS         |                           |  |
| Secondary Tenure/            | Authorization: |                           |  |

## Alleged Non-Compliance Summary:

| aNC# | Estimated<br>Incident Date | Parent Act           | Act/Regulation           | Section        | Description                     | Action Taken      |
|------|----------------------------|----------------------|--------------------------|----------------|---------------------------------|-------------------|
| 3744 | Apr 15, 2016               | Water Sustainability | Water Sustainability Act | 106 (2)(b)(ii) | Make changes in and about a     | Compliance Notice |
| ı    |                            | Act                  |                          |                | stream without lawful authority |                   |

| Warning Ticket: | ERA Case #: |
|-----------------|-------------|
|                 |             |

## **Description and Comments:**

On 2016-04-15 a inspection of your property was conducted to determine if development activates may be impacting Dot Brooke running adjacent to your property. Drainage works were being conducted directing water towards Dot Brooke it was noted that weeping pipe was buried along with drain rock and covered with geo textile fabric. Other ongoing activities were burning and active ditch and drainage construction. On the North side of the property runs a Brooke called Dot Brooke and below are several water licence holders that make use of this water. This inspection reveals that your drainage works have come extremely close to being in contravention of the Water Sustainability Act where your works have just nearly encroached the high water mark of Dot Brooke. Please be advised that any works in and about a stream, below the high water mark must first be approved under a Section 11 notification or approval under the Water Sustainability Act. Information is available online and applications can be found at this link for future reference. http://www2.gov.bc.ca/gov/content/environment/air-land-water/water-licensing-rights/working-around-water

Secondly a small dug pond was discovered on your property on the south side and it is partly feed by what would be considered a minor stream under the Water Sustainability Act a stream is defined in the act as follows. stream" means

(a) a natural watercourse, including a natural glacier course, or a natural body of water, whether or not the stream channel of the stream has been modified, or

| (b) a natural source of water supply,  |   |
|--|---|
| including, without limitation, a lake, pond, river, creek, susually containing water, including ice, but does not incompliance Notice:   | spring, ravine, gulch, wetland or glacier, whether or not clude an aquifer;   |
| Upon reviewing your dug pond and the surrounding dipond, I note that it is in line with a small drainage chanwas also a plastic conduit pipe installed across the streis located the lay of the land would suggests that it was pond and is mostly filled by ground water from the slop potential overflow of this pond during periods of high premainly filled by ground water. For these reason the Mi | nel which would fall under the definition of a stream. There cam. I have taken into consideration that where the pond is a low lying spot without any visible stream exiting the bes above. The surrounding ditch work will address any recipitation and the pond will be considered a dugout nistry will not require you to seek a water licence for the mitted to use the water for any purpose such as domestic low the high water mark in the stream or pond unless a for a water licence is applied for. Please review the licence web address provided above so you will be able to |
| Natural Bassures Officers [Clive Boudin]   | Sent to:  |
| Natural Resource Officer: [Clive Baudin]   | s.22  |
| Signature: X   |   |
| I certify that this inspection conforms to Ministry compliance procedures.   | -<br>_1   |
| Attachments and Comments:  | Delivered via:  |
|  | Email: X Fax:   |
|  | Mail: Hand Delivery:  |
|  |   |

