

## IAO Resource Team SSBC:EX

---

**From:** Environmental Emergencies Spill Reports ENV:EX  
**Sent:** Wednesday, October 7, 2015 2:09 PM  
**To:** Grant, Alex J ENV:EX  
**Subject:** FW: DGIR 151923 - VIR - OIL TANK

---

From: [SGPEP.ECC1@gov.bc.ca](mailto:SGPEP.ECC1@gov.bc.ca)  
Sent: Wednesday, October 07, 2015 2:08:57 PM (UTC-08:00) Pacific Time (US & Canada)  
To: Environmental Emergencies Spill Reports ENV:EX  
Subject: DGIR 151923 - VIR - OIL TANK

DGIR 151923  
PEP Task Number:

---

Incident Date: 2015-10-07 13:33  
Incident Time: 2015-10-07 13:33  
Report Date: 2015-10-07  
Report Time: 13:33

---

Spiller: UNKNOWN

Caller 1 / Agency:  
CAPT ROB KIVELL / OAK BAY FD - Business: 250-592-6121 - :

Caller 2 / Agency:  
/ - : - :

---

Location: 2667 CAVENDISH STREET  
Area: OAK BAY DISTRICT  
PEP Region: VIR  
MOE Region: Vancouver Island Region

Affected Env: Ground  
Spill Type: Equipment Failure  
Sector: Public  
Jurisdictions:  
1: Provincial

---

Material: OIL TANK UNKNOWN

---

Details:  
625 gallon storage tank was being excavated by Victoria tank service and found that it had been leaking into clay based soil environment. No water ways affected.

Response:

SNC Lavilin has been contacted for remediation.

---

Notifications:

1338 paged MOE RO

1340 briefed MOE RO Alex Grant code 1 Prov

1344 briefed PDM

1344 faxed MOE Nanaimo

Report Compiled By: MIKE Operations 2 ECC - 2015-10-07 13:33

---

Environmental Emergency Response Officer:

Date:

Notification Coding: Code 1 / Code 2

MOE Response: Exercise / Potential / No Field Response / Field Response / IMT Activation

Notes: