

Close Report	Previous	Next
--------------	----------	------

Enforcement Routing Sheet #18-6418

Complaint Received By: DAWN (Admin ECC)

Date / Time received:

2019-01-09 13:12

Area: COQUITLAM - MAPLE RIDGE - SOUTH COAST REGION

COORS OR#:

Caller Name: WWW ORR ONLINE SUBMISSION
Mail / Street Address: s.22
City:
Postal Code:
Referred By:
Contact Numbers
 Cellular s.22

CALLER INFORMATION

VIOLATION DETAILS

Violation Date: 01/06/2019

Violation Time: ++

Violation in Progress? No

Violation Type: FISHERIES

Offense Witnessed:

See Report

Offense Location:

Coquitlam River

Offense Details:

Date: Sunday, January 6th, 2019

River: Coquitlam River,

Over flow channel & outflow channel from local gravel pits are impacting water quality and fish habitat downstream. Water is clear above the siltation ponds and muddy, with plumes of sediment downstream from the silt pond outflows.

Settling Ponds are not performing as designed and have not been maintained. They have filled with sediment resulting in reduced retention time and settling efficiency.

there are two specific point sources of pollution:

1- the overflow from the settling ponds during rainfall events

2-the outflow channel from the settling ponds which discharges approx 750m downstream from the overflow outflow.

Description of the Suspect

Local Gravel Pits, Cewe, Allard & Lafarge

Transport Involved

N/A

Witnesses

N/A

Additional Comments

Pictures available to support. Please let me know how I can provide them.

DESCRIPTION				
Name (if known)				
Description	Sex	Race	Height	Weight
	Eyes	Hair	Glasses	Smoker
	Build	Complexion	Distinguishing Features	
Clothing				
Vehicle				
Weapons				
Other Details				
	Sex	Race	Height	Weight

	Eyes	Hair	Glasses	Smoker
	Build	Complexion	Distinguishing Features	
Name (if known)				
Description	Sex	Race	Height	Weight
	Eyes	Hair	Glasses	Smoker
	Build	Complexion	Distinguishing Features	
Description	Sex	Race	Height	Weight
	Eyes	Hair	Glasses	Smoker
	Build	Complexion	Distinguishing Features	
Name (if known)				
Description	Sex	Race	Height	Weight
	Eyes	Hair	Glasses	Smoker
	Build	Complexion	Distinguishing Features	
Clothing				
Vehicle				
Weapons				
Other Details				

Notification:

2019-01-09 13:14 Email to: Fraser North [MAPLE RIDGE] [COS.FraserNorthZone@gov.bc.ca] Sent from SGPEP.ECC1@gov.bc.ca

From: Beck, Tanner ENV:EX
To: Beck, Tanner ENV:EX
Subject: FW: Notification of ERS 18-6934 - VERNON - VERNON
Date: Wednesday, February 27, 2019 2:10:59 PM

COORs and close.

2019-02-27 ~ 1001hrs - CO BECK called the COM and was informed that yesterday at the time of the report he followed an Emterra truck from Lake Country all the way to Vernon and observed a steady flow of paper waste flying out onto the highway from inside the large green box on the back of the truck. The COM estimates that roughly 30-40 pieces of paper waste exited the box and landed on the highway during the time he observed it. The truck had a white cab with Emterra on the door. COM is willing to act as a witness if needed.

1358hrs – CO BECK called Vernon Emterra Supervisor s.22 and left a message requesting a call back.

1405hrs – CO BECK spoke to s.22 and informed him of the issue. He was able to identify the truck involved and will have a meeting with his drivers regarding the issue and tarping their loads. He will also speak to the specific driver involved. File can be closed as advice provided.

MU: 8-22
Offence: VA 204(2) - Litter on hwy.
Suspect: Emterra Environmental
Outcome: Advice
Officer Time: 1hr
Instructions:

Thank you,

Conservation Officer Tanner Beck
North Okanagan Zone | Conservation Officer Service | Ministry of Environment and Climate Change Strategy
4607B – 23rd Street, Vernon, BC, V1T 4K7
Phone: (250) 260-3037 Fax: (250) 549-3599

Report all Poachers and Polluters
(24 HRS) at 1-877-952-7277(RAPP) or www.rapp.bc.ca

-----Original Message-----

From: COS North Okanagan Zone ENV:EX
Sent: Tuesday, February 26, 2019 5:48 PM
To: Lockwood, Josh ENV:EX; Myroniuk, Terry A ENV:EX; Seitz, Ed ENV:EX; Owens, Ken G ENV:EX; Beck, Tanner ENV:EX; Richardson, Michael ENV:EX; Kneller, Micah ENV:EX; Hanratty, Jeff ENV:EX
Subject: FW: Notification of ERS 18-6934 - VERNON - VERNON

From: admin.ecc@pep.gov.bc.ca
Sent: February-26-19 5:47:32 PM (UTC-08:00) Pacific Time (US & Canada)
To: COS North Okanagan Zone ENV:EX
Subject: Notification of ERS 18-6934 - VERNON - VERNON

Notification of ERS 18-6934 - VERNON - VERNON

You can access the document at the following URL:
https://wildlife1.embc.gov.bc.ca/ECCLog_FY1819/COSIncident.nsf/ERSsByDate/7537C5F851804E87882583AE00096721?OpenDocument

Enforcement Routing Sheet #18-6934

Complaint Received By: CHUCK (Admin ECC) Date / Time received: 2019-02-26 17:42

Area: VERNON - VERNON - OKANAGAN REGION

COORS OR#:

CALLER INFORMATION

Caller Name: s.22

Mail / Street Address / City: NOT REQUIRED, VERNON, BC Postal Code:

Referred By:

CONTACT NUMBERS

Cellular: s.22

VIOLATION DETAILS:

Violation Date: 2019-02-26

Violation Time: Ongoing

Violation in Progress: No

Violation Type: DUMPING

Offense Witnessed: Uncovered dump truck spreading garbage.

Offense Location: On Highway 97 heading from Oyama to Vernon - northbound.

Offense Details: Advised an uncovered dump truck is spreading (blowing out) paper and other debris along the roadway at the above location.

DESCRIPTION

Name (If known): Enterra truck

Sex:

Race:

Height:

Weight:

Eyes:

Hair:

Glasses:

Smoker:

Build:

Complexion:

Distinguishing Features:

Clothing:

Vehicle:

Weapons:

Other Details:



Report Date: September 18, 2019

File: UA79205

Report Number: 134683

REGISTERED MAIL

Baird Cattle Co.
17256 8 Avenue
Surrey, BC
V3S 9R5

Dear Baird Cattle Co.

Re: Warning Letter, Unauthorized Discharge, 17256 8th Avenue Surrey B.C.

On May 16, 2019, Ministry of Environment, Environmental Protection Division staff conducted an inspection of your facility, located at 17256 8th Avenue Surrey B.C.. The inspection determined that Baird Cattle Co. is out of compliance with the *Environmental Management Act*, Part 2 Prohibitions and Authorizations, Section 6(3) waste disposal. This Warning Letter lists the compliance verification information below.

By discharging waste under Agricultural Waste Control Regulation without a valid authorization Baird Cattle Co. commits an offence under the *Environmental Management Act (EMA)*. Section 120(3) of *EMA* states as follows:

120(3) A person who contravenes any of the following commits an offence and is liable on conviction to a fine not exceeding \$1 000 000 or imprisonment for not more than 6 months, or both: (a) section 6 (2), (3) or (4) [waste disposal];...

It should also be noted that, as an alternative to prosecution of the offence referenced above, the Ministry may initiate action to impose an administrative penalty against Baird Cattle Co.. The *Administrative Penalties Regulation (EMA)* (B.C. Reg. 133/2014) (APR) was brought into force in 2014. The APR describes the prescribed provisions of the *EMA* as well as that of specified regulations under which administrative penalties can be assigned. Section 12(1) of the APR states as follows:

12(1) A person who contravenes section 6 (2), (3) or (4), 7, 8, 9 (1) or (4), 11, 25 (2), 40 (1), (2), (3), (6) or (7), 48 (8), (10) or (15), 55 (1), 72 (1) or (2) or 76.2 of the Act is liable to an administrative penalty not exceeding \$75 000.

I request that Baird Cattle Co. immediately implement the necessary changes or modifications to correct the non-compliance(s) listed above with the *Environmental Management Act*. Further, I request that Baird Cattle Co. notify this office in writing, by email or letter within 30 days of this letter, advising what corrective measures have been taken, and what else is being done, to prevent similar non-compliances in the future.

Please submit your response to the Ministry's Compliance Mailbox at EnvironmentalCompliance@gov.bc.ca.

As a result of this Warning, this authorization will be prioritized for follow-up inspection. The corrective measures will be reviewed by an Officer as part of the next inspection.

Finally, if you fail to take the necessary actions to restore compliance, you may be subject to escalating enforcement action. This Warning Letter and the alleged violations and circumstances to which it refers, will form part of the compliance history of Baird Cattle Co. and will be taken into account in the event of future violations.

Baird Cattle Co. failed to comply with the *Environmental Management Act*, section 6(3) as outlined below.

Inspection Details:

Requirement Description:	Environmental Management Act, Environmental Management Act 6 (3): Subject to subsection (5), a person must not introduce or cause or allow to be introduced into the environment, waste produced by a prescribed activity or operation.
Details/Findings:	<p>On May 16, 2019, Ministry of Environment and Climate Change Strategy staff conducted an onsite inspection of the Baird Cattle Co Ltd's (Baird Cattle) agricultural operation located at 17256 8th Avenue in Surrey, BC. The inspection was triggered by complaints of liquid agricultural by-products stored in a lagoon not in accordance with the setback requirements as listed in the Code of Practice for Agricultural Environmental Management (the Code). Sandra Baird was present at the time of the inspection.</p> <p>During the inspection on May 16, 2019, Ministry staff observed black effluent in the ditch located at the eastern base of the agricultural by-product storage lagoon onsite. This indicates waste produced by a prescribed operation (Agricultural Operation) is being introduced into the environment, in contravention of section 6(3) of the Act.</p>
Compliance:	Out
Actions to be taken:	1) Implement the necessary changes or modifications immediately to address this situation and to bring it into compliance. 2) Notify this office by email or letter within 30 days of this letter, advising what corrective measures have been taken, and what else is being done, to bring this authorization into compliance.
Requirement Description:	Environmental Management Act, Code of Practice for Agricultural Environmental Management (EMA) 2 (2)(a): This code applies to an agricultural operation described in subsection (3) that is carried out in British Columbia (a) on (i) an agricultural land base that is owned, rented or leased, and managed, by the person who carries out the agricultural operation, and (ii) land that is not zoned for residential purposes, and
Details/Findings:	Baird Cattle owns and operates an agricultural operation (cattle feedlot) on the agricultural land base on land that is not zoned for residential purposes.
Compliance:	In

Requirement Description:	<p>Environmental Management Act, Code of Practice for Agricultural Environmental Management (EMA)</p> <p>17(1)(a): A person who, for the purposes of an agricultural operation, performs an activity described in column 1 of the following table must ensure a setback of at least the distances, in m, set out opposite the activity in columns 2 to 4: Item 1a; Column 1 Activity - Storing agricultural by-products using (a) a permanent storage structure, on-ground under-pen storage or temporary field storage of less than 2 weeks; Column 2 Drinking water source (m) - 30; Column 3 Watercourse, other than a drinking water source (m) - 15; Column 4 Property boundary (m) - 4.5.</p>
Details/Findings:	<p>Baird Cattle utilizes a lagoon on the property which is a permanent storage structure of agricultural by-product (contaminant runoff) produced by the agricultural operation.</p> <p>The lagoon does not meet the minimum setback distances to a watercourse (other than drinking water) or to a property boundary for storing agricultural by-products using a permanent storage structure.</p>
Compliance:	Out
Requirement Description:	<p>Environmental Management Act, Code of Practice for Agricultural Environmental Management (EMA)</p> <p>18: Despite section 17 [setback requirements], the setbacks set out in column 4 of the table to that section do not apply to an existing permanent storage structure, or existing on-ground under-pen storage, if stored contents cannot escape.</p>
Details/Findings:	<p>During the inspection on May 16, 2019, Ministry staff observed black effluent in the ditch located at the eastern base of the lagoon, with no effluent upstream indicated the escape of stored contents to the inspecting Ministry staff. Therefore the setbacks set out in column 4 of table 17 do apply.</p> <p>Further, a report titled "Environmental recommendations Border Feedlot & Baird Cattle Company 17256 8 Avenue, Surrey BC" provided to the Ministry by Baird Cattle dated September 5, 2018, advocates that the lagoon's berming be assessed by a geotechnical professional for stability, which has not been completed at the time of this inspection.</p>
Compliance:	Out
Actions to be taken:	Retain the services of a qualified professional to assess the lagoon.

Requirement Description:	Environmental Management Act, Code of Practice for Agricultural Environmental Management (EMA) 32 (c): A person may store and use solid agricultural by-products, or carry out an agricultural composting process, only as follows: (c) solid agricultural by-products may be stored only in a permanent storage structure or as temporary field storage
Details/Findings:	<p>Solid agricultural by-products were observed by Ministry staff during the inspection stored neither within permanent storage structure or stored as temporary field storage.</p> <p>Two manure piles were observed stored to the east of the lagoon partially covered and contained to the east with a lock block wall (Photos 1 & 2).</p> <p>Three large piles were observed stored south of the lagoon (Photos 3 & 4) as previously documented in IR-79205 from February 2018. The three large piles of agricultural by-product were surrounded by contaminated runoff which was being pumped into the lagoon (Photos 3, 4 & 5).</p>
Compliance:	Out
Requirement Description:	Environmental Management Act, Code of Practice for Agricultural Environmental Management (EMA) 34: A person who stores agricultural by-products must ensure all of the following: (a) that any leachate generated during storage is collected or contained until it can be used in applying nutrients to land; (b) that runoff is diverted away from the storage structure or storage area; (c) that the storage structure or storage area is maintained so as to prevent contaminated runoff, leachate, wastewater and solids from escaping; (d) if contaminated runoff, leachate, wastewater or solids escape from storage, they do not enter a watercourse, cross a property boundary, or go below the seasonal high water table; (e) that air contaminants from stored agricultural by-products do not cross a property boundary; (f) that agricultural by-products are stored in a manner that will deter the attraction of, and access by, domestic pets, wildlife and vectors.
Details/Findings:	<p>Leachate generated west of the lagoon was not being contained to the storage area</p> <p>Contaminated runoff from the agricultural by-product piles was observed contained and being transferred to the lagoon for storage until it is applied to a neighboring agricultural field as a nutrient source.</p>
Compliance:	Out

Requirement Description:	Environmental Management Act, Code of Practice for Agricultural Environmental Management (EMA) 35: A person who uses a permanent storage structure must ensure that the structure has sufficient capacity to store agricultural by-products until they are (a) applied as a fertilizer or soil conditioner, or (b) transported away from the agricultural land base.
Details/Findings:	The lagoon appeared very nearing maximum capacity. Sandra Baird informed Ministry staff during the inspection that the lagoon effluent will soon be applied to a neighboring agricultural field as nutrient source.
Compliance:	In
Requirement Description:	Environmental Management Act, Code of Practice for Agricultural Environmental Management (EMA) 36 (1): A person who stores liquid manure in a permanent storage structure must ensure that the structure is one of the following: (a) an existing permanent storage structure; (b) a modified permanent storage structure and the modification was (i) designed by a qualified professional who considered the entire structure and this code, and (ii) constructed according to that design; (c) a new permanent storage structure that was designed by a qualified professional and constructed according to that design.
Details/Findings:	The lagoon which stores contaminated runoff and leachate from the agricultural by-products stored around the site may also contain liquid manure. Liquid manure in the Code means untreated liquid excreta from livestock, whether or not it is mixed with wastewater. The lagoon is an existing permanent storage structure and therefore is in compliance with this section of the Code.
Compliance:	In
Requirement Description:	Environmental Management Act, Code of Practice for Agricultural Environmental Management (EMA) 43 (2): A person who distributes manure or the product of an agricultural composting process in units of 5 m3 or less must keep an annual record of the following: (a) the total amount distributed, expressed in m3; (b) the dates that distribution began and ended; (c) the type of agricultural by-product distributed.
Details/Findings:	This requirement began on February 28, 2019, therefore this section is being included for promotional compliance. Compliance is not determined at the time of this inspection.

Compliance:	Not Determined
Actions to be taken:	Please record the information required by this section for future compliance inspections.
Requirement Description:	Environmental Management Act, Code of Practice for Agricultural Environmental Management (EMA) 43 (3): A person who distributes manure or the product of an agricultural composting process in units of more than 5 m3 must keep, for each distribution, a receipt that (a) is signed by the receiver, and (b) shows all of the following: (i) the amount distributed, expressed in m3; (ii) the date of distribution; (iii) the type of agricultural by-product distributed; (iv) the name and business contact information of the receiver.
Details/Findings:	This requirement began on February 28, 2019, therefore this section is being included for promotional compliance. Compliance is not determined at the time of this inspection.
Compliance:	Not Determined
Actions to be taken:	Please record the information required by this section for future compliance inspections.
Requirement Description:	Environmental Management Act, Code of Practice for Agricultural Environmental Management (EMA) 43 (4): A person who distributes a product resulting from an agricultural composting process must not describe the product as "compost" or "composted".
Details/Findings:	Baird Cattle advertises steer manure for sale on their website that is not described as compost or composted.
Compliance:	In

Requirement Description:	Environmental Management Act, Code of Practice for Agricultural Environmental Management (EMA) 65: A person who keeps 5 or more animal units must make and keep records of all of the following: (a) the total number of animals; (b) the total amount of manure, including bedding mixed with the manure, collected annually, expressed in m3, and divided according to the type of animal the manure is from and whether the manure is liquid or solid; (c) the amount of manure, expressed in m3, managed by (i) distribution in accordance with section 43 [distribution of manure or agricultural compost], or (ii) application as fertilizer or a soil conditioner in accordance with Division 4 [Nutrient Application and Management] of Part 6.
Details/Findings:	This requirement began on February 28, 2019, therefore this section is being included for promotional compliance. Compliance is not determined at the time of this inspection.
Compliance:	Not Determined
Actions to be taken:	Please ensure to record the information required by this section for future compliance inspections.

Compliance History:
 2018-03-16 Inspection Record 79205 - Non-compliant with the Agricultural Waste Control Regulation.

Please be advised that this inspection report may be published on the provincial government website within 7 days.

Below are attachments related to this inspection.

If you have any questions about this warning, please contact the undersigned.

Yours truly,

Stewart Paterson
 Environmental Protection Officer

cc:

Attachments:

1) 2019-05-16 IR-134683 - Baird Cattle Co - Photo Record.pdf Photo record - IR134683

Deliver via:

Email: ☒ Fax: ☐ Mail: ☐
 Registered Mail: ☒ Hand Delivery: ☐

**Ministry of Environment
and Climate Change
Strategy**

Compliance
Environmental
Protection Division

Mailing Address:
2nd Fl
10470-152nd St
Surrey BC V3R 0Y3

Telephone: 604 582 5200
Facsimile: 604 930 7119
Website: www.gov.bc.ca/env

DISCLAIMER:

Please note that sections of the permit, regulation or code of practice referenced in this inspection record are for guidance and are not the official version. Please refer to the original permit, regulation or code of practice.

To see the most up to date version of the regulations and codes of practices please visit
<http://www.bclaws.ca>

If you require a copy of the original permit, please contact the inspector noted on this inspection record.

It is also important to note that this inspection record does not necessarily reflect each requirement or condition of the authorization therefore compliance is noted only for the requirements or conditions listed in the inspection record.

Authorization: UA79205	Baird Cattle Company Ltd.
NRIS IR #: 134683	(May 16, 2019) Site Inspection Photos

Photo 1

Agricultural by-products stored neither in a permeant storage structure or as temporary field storage.

Photo taken west of the lagoon east of the tributary, facing north.



Photo 2

Agricultural by-products stored neither in a permeant storage structure or as temporary field storage.

West of the lagoon, east of the tributary. Photo facing south-west.



Authorization: UA79205	Baird Cattle Company Ltd.
NRIS IR #: 134683	(May 16, 2019) Site Inspection Photos

Photo 3

Three agricultural by-product piles stored neither in a permeant storage structure or as temporary field storage.

Photo taken standing on the south berm of the lagoon, facing south.



Photo 4

Contaminated runoff at the base of the agricultural by-product piles located south of the lagoon.

Photo taken standing on the south berm of the lagoon, facing south.



Authorization: UA79205	Baird Cattle Company Ltd.
NRIS IR #: 134683	(May 16, 2019) Site Inspection Photos

Photo 5

Contaminated runoff ponding south of the lagoon. A pump is setup to transfer the effluent into the lagoon.

Photo taken standing south-west of the lagoon, facing south-east.



Photo 6

Lagoon at Baird Cattle.

Photo taken standing on the south berm of the lagoon, facing north.



Authorization: UA79205	Baird Cattle Company Ltd.
NRIS IR #: 134683	(May 16, 2019) Site Inspection Photos

Photo 7

PVC pipes which transfer contaminated runoff from the agricultural operation into the south-west corner of the lagoon.

Photo taken standing on the south berm of the lagoon, facing north-west.



Photo 8

Eastern berm of the lagoon/
Eastern property boundary.

Photo taken standing on the south-east corner of the lagoon berm, facing north.



Authorization: UA79205	Baird Cattle Company Ltd.
NRIS IR #: 134683	(May 16, 2019) Site Inspection Photos

Photo 9

Eastern edge of lagoon berm along the east property boundary.

A ditch runs north to south and feeds a tributary that flows into Little Campbell River to the immediate south of the property.

Photo facing north.



Photo 10

Black effluent in the ditch at the base of the lagoon berm along the east property boundary.

Photo taken standing on the property to the east of Baird Cattle Co.



Authorization: UA79205	Baird Cattle Company Ltd.
NRIS IR #: 134683	(May 16, 2019) Site Inspection Photos

Document : 2019-05-16 IR-134683 - Baird Cattle Co - Photo Record.pdf

Document comment: Photo record - IR134683

From: Ciara.DoyleWaters@pep.gov.bc.ca
To: [COS Fraser South Zone ENV:EX](#)
Subject: Notification of ERS 20-6778 - SURREY - DELTA
Date: October 23, 2020 10:35:07 AM

Notification of ERS 20-6778 - SURREY - DELTA

You can access the document at the following URL:

https://wildlife1.embc.gov.bc.ca/ECCLog_FY2021/COSIncident.nsf/ERSsByDate/83476CFF6DEBC3418825860A00604BA9?OpenDocument

Enforcement Routing Sheet #20-6778.

Complaint Received By: CIARA - OPS 6 (Ciara Doyle-Waters)

Date / Time received: 2020-10-23 10:31

Area: DELTA - SURREY - SOUTH COAST REGION

COORS OR#:

CALLER INFORMATION

Caller Name: **s.22**

Mail / Street Address / City: NA, DELTA, BC

Postal Code:

Referred By:

CONTACT NUMBERS

Cellular: **s.22**

VIOLATION DETAILS:

Violation Date: 2020-10-23

Violation Time:

Violation in Progress: No

Violation Type: DUMPING

Offense Witnessed: dumping

Offense Location: 917 Cliveden Ave

Offense Details: Advises that this recycling outlet make pellets out of recycled material and the pellets are all over the place.

DESCRIPTION

Name (If known): Merlin Plastics Supply Inc

Sex:

Race:

Height:

Weight:

Eyes:

Hair:

Glasses:

Smoker:

Build:

Complexion:

Distinguishing Features:

Clothing:

Vehicle:

Weapons:

Other Details:

Close Report	Previous	Next
--------------	----------	------

Enforcement Routing Sheet #20-8981

Complaint Received By: MIKE OPS 1 (Mike Dryburgh)

Date / Time received:

2021-02-04 02:22

Area: BURNABY - NORTH VANCOUVER - SOUTH COAST REGION

COORS OR#:

CALLER INFORMATION

Caller Name: s.22 RAPP REPORT)
Mail / Street s.22
Address:
City: s.22
Postal Code:
Referred By:
Contact Numbers
 Cellular s.22

VIOLATION DETAILS

Violation Date: 02/04/2021 **Violation Time:** **Violation in Progress?** No
Violation Type: DUMPING
Offense Witnessed:
 dumping
Offense Location:
 UBC
Offense Details:
 Details of the violation
 Hello,

I would like to pass on some very disturbing information and hope that your News team will investigate.

I have it very good authority that since September of 2020 University of BC Custodial staff under direction of management have been disposing of filled chemical and soap dispensers in dumpsters on the campus.

s.22

Thank you very much!
 Description of the Suspect
 UBC Custodial Services Management

Witnesses

s.22

DESCRIPTION

Name (if known)				
Description	Sex	Race	Height	Weight
	Eyes	Hair	Glasses	Smoker
	Build	Complexion	Distinguishing Features	

Clothing				
Vehicle				
Weapons				
Other Details				
	Sex	Race	Height	Weight
	Eyes	Hair	Glasses	Smoker
	Build	Complexion	Distinguishing Features	
Name (if known)				
Description	Sex	Race	Height	Weight
	Eyes	Hair	Glasses	Smoker
	Build	Complexion	Distinguishing Features	
Description	Sex	Race	Height	Weight
	Eyes	Hair	Glasses	Smoker
	Build	Complexion	Distinguishing Features	
Name (if known)				
Description	Sex	Race	Height	Weight
	Eyes	Hair	Glasses	Smoker
	Build	Complexion	Distinguishing Features	
Clothing				
Vehicle				
Weapons				
Other Details				

Notification:

2021-02-04 02:24 Email to: Sea-to-Sky [NORTH VANCOUVER, SQUAMISH] [COS.SeatoSkyZone@gov.bc.ca] Sent from SGPEP.ECC1@gov.bc.ca

Enforcement Routing Sheet #21-4609

Complaint Received By: DAWN - OPS 2 (Dawn Davis)

Date / Time received:

2021-08-23 10:26

Area: NEW WESTMINSTER - SURREY - SOUTH COAST REGION

COORS OR#:

CALLER INFORMATION

Caller Name: s.22
Mail / Street -
Address:
City: s.22
Postal Code:
Referred By: KELLEN NICHOLLS VIA EMAIL / DFO
Contact Numbers
Cellular s.22

VIOLATION DETAILS

Violation Date: 08/23/2021

Violation Time:

Violation in Progress? No

Violation Type: DUMPING

Offense Witnessed:

Dumping

Offense Location:

10 Spruce Street

Offense Details:

DFO Occurrence # 21-2227

Received the following via the ORR email reporting line:

Hello,

Everyday I see Urban Impact hose out their garbage trucks over a large storm drain beside the Fraser River in New Westminster. Attached is a pic of the storm drain they use, I couldn't get one of them using it as s.22

It would be good to send an observer here to witness their actions as the trucks come back at the end of the day. 4-4:45 pm.

Urban Impact

10 SPRUCE STREET,

NEW WESTMINSTER, BC, CANADA

V3L 5G6

Thank you,

s.22

DESCRIPTION				
Name (if known)				
Description	Sex	Race	Height	Weight
	Eyes	Hair	Glasses	Smoker
	Build	Complexion	Distinguishing Features	
Clothing				
Vehicle				
Weapons				
Other Details				
	Sex	Race	Height	Weight
	Eyes	Hair	Glasses	Smoker
	Build	Complexion	Distinguishing Features	

Name (if known)				
Description	Sex	Race	Height	Weight
	Eyes	Hair	Glasses	Smoker
	Build	Complexion	Distinguishing Features	
Description	Sex	Race	Height	Weight
	Eyes	Hair	Glasses	Smoker
	Build	Complexion	Distinguishing Features	
Name (if known)				
Description	Sex	Race	Height	Weight
	Eyes	Hair	Glasses	Smoker
	Build	Complexion	Distinguishing Features	
Clothing				
Vehicle				
Weapons				
Other Details				

Notification:

2021-08-23 10:34 Email to: Fraser South [CHILLIWACK , SURREY] [COS.FraserSouthZone@gov.bc.ca] Sent from SGPEP.ECC1@gov.bc.ca



Case Summary

Details

Case File #:	201908162	Opened Date:	2019-10-02 02:56 PM
Category:	CO SERVICE	Discovery Date:	2019-05-16
Type:	ENVIRONMENTAL	Closed Date:	2019-10-02 03:05 PM
Status:	Closed	Admin Org Unit:	FRASER SOUTH ZONE
Opened By:	WILSON, MARIE	Source:	CONSERVATION OFFICER FOUND
Lead Investigator:	SMITH, MURRAY : 15709	Source Ref #:	
Lead Investigator's Phone:		Other Source Agency:	
Paper File Created:	No	Transferred to Agency:	
Electronic Case File:	No	Other Transferred Agency:	
Investigation Review Process:	No	Joint Investigation:	No
Investigation Review Date:		Transferred Agency Contact:	
Investigation Start Date:	2019-05-16	Lead Agency:	MINISTRY OF ENVIRONMENT MINISTRY OF ENVIRONMENT
Joint Agency Contact:		Joint Agency:	
Other Joint Agency:		Joint Agency Phone:	
Case Description:	WARNING LETTER TO BAIRD CATTLE CO. REPORT 134683, FILE UA79205		

Members:

Name	Phone Number	Start Date	End Date
SMITH, MURRAY : 15709		2019-10-02	2029-09-29
WILSON, MARIE		2019-10-02	2029-09-29

Parties Involved:

Name	DOB	Role	Nature of Involvement	Phone No.	Address
BAIRD CATTLE CO		SUBJECT OF COMPLAINT	DISCHARGING WASTE UNDER AGRICULTURAL WASTE CONTROL REGULATION WITHOUT A VALID AUTHORIZATION BAIRD CATTLE CO		17256 8 AVENUE SURREY BC. V3S 9R5

Sites:

Site	Site Type	Description
1. 2-4; FRASER SOUTH ZONE		17256 8TH AVENUE SURREY B.C.,

Notes:

Date	Name	Comments
2019-10-02	WILSON, MARIE	OPEN FILE, ATTACH LTR. CLOSE

Continuation Report:

Date	Time	Name	Report
------	------	------	--------

Attachments:

Attach#	Description	Photo	File	Attached By	Attached Date
1	20190918_COR_LETTERNo _BAIRD-CATTLE- CO_WW_REP_134683 LETTER SIGNED BY STEWART PATERSON, EPO		20190918_COR_LETTER_ BAIRD-CATTLE- CO_WW_REP_134683.PD F	WILSON, MARIE	2019-10-02

Contravention No.1**ENVIRONMENTAL MANAGEMENT ACT 6 (3) : INTRODUCE WASTE BY
PRESCRIBED ACTIVITY OR OPERATION****Species:****Est. Incident Date**

2019-05-19 0:00

Party:

BAIRD CATTLE CO

Site:1. 2-4; FRASER SOUTH ZONE;
17256 8TH AVENUE SURREY
B.C.,.**Party Address:**17256 8 AVENUE SURREY
BC V3S 9R5**Enforcement Actions****Enforcement Action No. 1****Type:**

ADMINISTRATIVE ACTION

Effective Date:

2019-09-18

End Date:2019-09-18**Admin Action Type:**

ADVISORY LETTER

Comments:

WARNING LTR SENT BY STEWART PATERSON, EPO, ATTACHED

Vehicles:



Case Summary

Details

Case File #:	201903421	Opened Date:	2019-06-01 01:50 PM
Category:	CO SERVICE	Discovery Date:	2019-06-01
Type:	ENVIRONMENTAL	Closed Date:	2019-06-04 12:34 PM
Status:	Closed	Admin Org Unit:	FRASER SOUTH ZONE
Opened By:	STARK, ALICIA	Source:	CONSERVATION OFFICER FOUND
Lead Investigator:	STARK, ALICIA	Source Ref #:	
Lead Investigator's Phone:		Other Source Agency:	
Paper File Created:	No	Transferred to Agency:	
Electronic Case File:	No	Other Transferred Agency:	
Investigation Review Process:	No	Joint Investigation:	No
Investigation Review Date:		Transferred Agency Contact:	
Investigation Start Date:	2019-06-01	Lead Agency:	MINISTRY OF ENVIRONMENT MINISTRY OF ENVIRONMENT
Joint Agency Contact:		Joint Agency:	
Other Joint Agency:		Joint Agency Phone:	
Case Description:	ERS 19-1131	Joint Agency Case No:	

CALLER IS PARKED NEAR THE GFL SITE AND A LARGE EAGLE JUST CRAPPED ON HIS VEHICLE. HIS CONCERN IS THAT THE DROPPINGS ARE FILLED WITH PLASTIC FROM THE DUMP. HE HAS TAKEN A PICTURE AND THE EAGLE AND THE DROPPINGS ARE STILL THERE AT THIS MOMENT.

Members:

Name	Phone Number	Start Date	End Date
STARK, ALICIA		2019-06-01	2029-05-29

Parties Involved:

Name	DOB	Role	Nature of Involvement	Phone No.	Address
GFL ENVIRONMENTAL s.22		SUBJECT OF COMPLAINT COMPLAINANT		s.22	DELTA BC CAN s.22

Sites:

Site	Site Type	Description
1. 2-4; FRASER SOUTH ZONE		DELTA

Notes:

Date	Name	Comments
------	------	----------

Continuation Report:

Date	Time	Name	Report
2019-06-01	14:00	STARK, ALICIA	<p>CO STARK SPOKE WITH THE COM. STARK IDENTIFIED THAT THERE IS A WASTE TRANSFER STATION IN CLOSE PROXIMITY AND WHEN SHE DROVE BY THE OTHER DAY s.22 SAW NUMEROUS EAGLES THERE. THEY MAY BE EATING PLASTIC AT THE DUMP NOT GFL. STARK EXPLAINED SHE WAS GOING TO TALK TO THE SPECIALISTS AT OWL TO GET ADVICE ON HOW WE COULD CURB THIS.</p> <p>s.22 SAID GFL IS LITTERING PLASTIC BAGS WITH THEIR COMPOST AND THAT IS WHAT THE EAGLES ARE EATING. s.2 DEMANDED SOMETHING GETS DONE AND HUNG UP THE PHONE.</p> <p>NO WAY TO PROVE THAT THE BIRDS ARE EATING PLASTIC FROM THIS LOCATION. s.22</p>

Attachments:

Attach#	Description	Photo	File	Attached By	Attached Date
---------	-------------	-------	------	-------------	---------------

Contravention No.2**ENVIRONMENTAL MANAGEMENT ACT 12 (2) : DISCHARGE LITTER****Species:****Est. Incident Date**

2019-05-31 14:00

Party:

GFL ENVIRONMENTAL

Site:1. 2-4; FRASER SOUTH ZONE;
DELTA**Party Address:**

DELTA BC CAN

Enforcement Actions**Enforcement Action No. 1****Type:**

UNFOUNDED

Comments:**Vehicles:**



Case Summary

Details

Case File #:	202100567	Opened Date:	2021-01-25 12:48 PM
Category:	CO SERVICE	Discovery Date:	2021-01-02
Type:	ENVIRONMENTAL	Closed Date:	2021-01-25 01:09 PM
Status:	Closed	Admin Org Unit:	FRASER SOUTH ZONE
Opened By:	GOOLIAFF, HAILEY	Source:	REPORTED
Lead Investigator:	GOOLIAFF, HAILEY	Source Ref #:	20-8457
Lead Investigator's Phone:		Other Source Agency:	
Paper File Created:	No	Transferred to Agency:	
Electronic Case File:	No	Other Transferred Agency:	
Investigation Review Process:	No	Joint Investigation:	No
Investigation Review Date:		Transferred Agency Contact:	
Investigation Start Date:	2021-01-02	Lead Agency:	MINISTRY OF ENVIRONMENT
Joint Agency Contact:		Joint Agency:	MINISTRY OF ENVIRONMENT
Other Joint Agency:		Joint Agency Phone:	
Case Description:	LAFARGE AIR QUALITY	Joint Agency Case No:	

Members:

Name	Phone Number	Start Date	End Date
GOOLIAFF, HAILEY		2021-01-25	2031-01-23

Parties Involved:

Name	DOB	Role	Nature of Involvement	Phone No.	Address
LAFARGE CANADA INC.		SUBJECT OF COMPLAINT.			s.22
s.22		COMPLAINANT.		s.22	

Sites:

Site	Site Type	Description
1. 2-4; FRASER SOUTH ZONE		LAFARGE CANADA - 7611 NO 9 RD., RICHMOND.

Notes:

Date	Name	Comments
------	------	----------

Continuation Report:

Date Printed:2021/10/13
User ID: DAYTON, PAVLINA
Environment:PROD

Page 1 of 2
Report ID: CORS-001

Date	Time	Name	Report
2021-01-25	12:57	GOOLIAFF, HAILEY	CO GOOLIAFF reviewed file. File emailed to Environmental Protection Dan Bings.

Attachments:

Attach#	Description	Photo	File	Attached By	Attached Date
1	ERS 20-8457	No	ERS 20-8457.PDF	GOOLIAFF, HAILEY	2021-01-25

Contravention No.1
ENVIRONMENTAL MANAGEMENT ACT 6 (2) : INTRODUCE WASTE FROM A PRESCRIBED INDUSTRY, TRADE OR BUSINESS
Species:
Est. Incident Date

2021-01-02

Party:

LAFARGE CANADA INC

Site:

1. 2-4; FRASER SOUTH ZONE;
LAFARGE CANADA - 7611 NO 9
RD., RICHMOND

Party Address:

s.22

Enforcement Actions
Enforcement Action No. 1
Type:

ADMINISTRATIVE ACTION

Effective Date:

2021-01-25

End Date:2024-01-25

Admin Action Type:

REFERRED

Comments:

REFERRED TO ENVIRONMENTAL PROTECTION - DAN BINGS

Vehicles:

Close Report	Previous	Next
--------------	----------	------

Enforcement Routing Sheet #20-8457

Complaint Received By: CIARA - OPS 6 (Ciara Doyle-Waters)

Date / Time received:

2021-01-02 10:01

Area: RICHMOND - SURREY - SOUTH COAST REGION

COORS OR#:

CALLER INFORMATION

Caller Name: s.22

Mail / Street NA

Address:

City: s.22

Postal Code:

Referred By:

Contact Numbers

Cellular s.22

VIOLATION DETAILS

Violation Date: 01/02/2021

Violation Time:

Violation in Progress? No

Violation Type: OPEN BURNING

Offense Witnessed:

open burning

Offense Location:

Richmond LaFarge - Cement Plant

Offense Details:

Advises that they are burning garbage and it is causing horrible air pollution and bad fall out. The air is very horrible and hard to breath. This has been going on for a few weeks now, s.22

DESCRIPTION

Name (if known)				
Description	Sex	Race	Height	Weight
	Eyes	Hair	Glasses	Smoker
	Build	Complexion	Distinguishing Features	
Clothing				
Vehicle				
Weapons				
Other Details				
	Sex	Race	Height	Weight
	Eyes	Hair	Glasses	Smoker
	Build	Complexion	Distinguishing Features	
Name (if known)				
Description	Sex	Race	Height	Weight
	Eyes	Hair	Glasses	Smoker
	Build	Complexion	Distinguishing Features	

Description	Sex	Race	Height	Weight
	Eyes	Hair	Glasses	Smoker
	Build	Complexion	Distinguishing Features	
Name (if known)				
Description	Sex	Race	Height	Weight
	Eyes	Hair	Glasses	Smoker
	Build	Complexion	Distinguishing Features	
Clothing				
Vehicle				
Weapons				
Other Details				

Notification:

2021-01-02 10:08 Email to: Fraser South [CHILLIWACK , SURREY] [COS.FraserSouthZone@gov.bc.ca] Sent from SGPEP.ECC1@gov.bc.ca



Case Summary

Details

Case File #:	202012086	Opened Date:	2020-10-20 02:58 PM
Category:	CO SERVICE	Discovery Date:	2020-10-19
Type:	ENVIRONMENTAL	Closed Date:	2020-10-20 03:02 PM
Status:	Closed	Admin Org Unit:	FRASER SOUTH ZONE
Opened By:	MAVIN, MARY	Source:	REPORTED
Lead Investigator:	PLAMONDON, MARC	Source Ref #:	ERS 20-6656
Lead Investigator's Phone:		Other Source Agency:	
		Transferred to Agency:	MINISTRY OF ENVIRONMENT
Paper File Created:	No	Other Transferred Agency:	
Electronic Case File:	No	Joint Investigation:	No
Investigation Review Process:	No	Transferred Agency Contact:	BINGS, DAN
Investigation Review Date:		Lead Agency:	MINISTRY OF ENVIRONMENT
Investigation Start Date:	2020-10-19	Joint Agency:	MINISTRY OF ENVIRONMENT
Joint Agency Contact:		Joint Agency Phone:	
Other Joint Agency:		Joint Agency Case No:	
Case Description:	s.22 AND IS REPORTING THAT WHENEVER THE PLANT CONDUCTS BURNING, DUST OF VARIOUS COLOURS FALLS ONTO s.22 LAST WEEK THE DUST WAS A BRIGHT RED. ADVISED THAT THE AIR QUALITY IS SO BAD TODAY s.22 s.22 TOLD THAT THE AIR SMELLS LIKE CHLORINE AND FERTILIZER. ALSO ADVISED THAT A VERY THICK BLUE SMOKE WAS COMING OUT OF THE STACKS TODAY. AND WAS VISIBLE FROM NEW WESTMINSTER. s.22 s.22		

Members:

Name	Phone Number	Start Date	End Date
PLAMONDON, MARC		2020-10-20	2030-10-18
MAVIN, MARY		2020-10-20	2030-10-18

Parties Involved:

Name	DOB	Role	Nature of Involvement	Phone No.	Address
LAFARGE CANADA INC s.22		SUBJECT OF COMPLAINT COMPLAINANT			s.22

Sites:

Site	Site Type	Description
1. 2-4; FRASER SOUTH ZONE		LAFARGE CANADA - 7611 NO 9 RD., RICHMOND

Notes:

Date	Name	Comments
------	------	----------

Continuation Report:

Date	Time	Name	Report
2020-10-20	10:49	PLAMONDON, MARC	CO PLAMONDON reviews file, refers to Dan BINGS with Environmental Protection.

Attachments:

Attach#	Description	Photo	File	Attached By	Attached Date
1	ERS 20-6656	No	ERS 20-6656.PDF	MAVIN, MARY	2020-10-20

Contravention No.1**ENVIRONMENTAL MANAGEMENT ACT 6 (2) : INTRODUCE WASTE FROM A PRESCRIBED INDUSTRY, TRADE OR BUSINESS****Species:****Est. Incident Date**

2020-10-19

Party:

LAFARGE CANADA INC

Site:1. 2-4; FRASER SOUTH ZONE;
LAFARGE CANADA - 7611 NO 9
RD., RICHMOND**Party Address:**

s.22

Enforcement Actions**Enforcement Action No. 1****Type:**

ADMINISTRATIVE ACTION

Effective Date:

2020-10-20

End Date:**Admin Action Type:**

REFERRED

Comments:

REFERRED TO EP

Vehicles:

◀ Close Report	⬆ Previous	⬇ Next
----------------	------------	--------

Enforcement Routing Sheet #20-6656

Complaint Received By: ILIYA OPS 9 (Iliya Pavlovic)

Date / Time received:

2020-10-19 16:19

Area: RICHMOND - SURREY - SOUTH COAST REGION

COORS OR#:

CALLER INFORMATION

Caller Name: s.22
Mail / Street Address:
City: s.22
Postal Code:
Referred By:
Contact Numbers
Cellular s.22

VIOLATION DETAILS

Violation Date: 10/19/2020

Violation Time: Ongoing

Violation in Progress? No

Violation Type: OPEN BURNING

Offense Witnessed:

See report.

Offense Location:

6911 Graybar Rd. & Lafarge Canada - 7611 No 9 Rd.

Offense Details:

s.22 and is reporting that whenever the plant conducts burning, dust of various colours falls onto
 s.22 Last week the dust was a bright red. Advised that the air quality is so bad today s.22
 s.22 Told that the air smells like chlorine and fertilizer. Also advised that a very thick blue smoke was coming
 out of the stacks today and was visible from New Westminster. s.22
 s.22

DESCRIPTION				
Name (if known)				
Description	Sex	Race	Height	Weight
	Eyes	Hair	Glasses	Smoker
	Build	Complexion	Distinguishing Features	
Clothing				
Vehicle				
Weapons				
Other Details				
	Sex	Race	Height	Weight
	Eyes	Hair	Glasses	Smoker
	Build	Complexion	Distinguishing Features	
Name (if known)				
Description	Sex	Race	Height	Weight
	Eyes	Hair	Glasses	Smoker
	Build	Complexion	Distinguishing Features	

Description	Sex	Race	Height	Weight
	Eyes	Hair	Glasses	Smoker
	Build	Complexion	Distinguishing Features	
Name (if known)				
Description	Sex	Race	Height	Weight
	Eyes	Hair	Glasses	Smoker
	Build	Complexion	Distinguishing Features	
Clothing				
Vehicle				
Weapons				
Other Details				

Notification:

2020-10-19 16:31 Email to: Fraser.South [CHILLIWACK , SURREY] [COS.FraserSouthZone@gov.bc.ca] Sent from SGPEP.ECC1@gov.bc.ca



Case Summary

Details

Case File #: 201900269
Category: CO SERVICE
Type: FISHERIES
Status: Closed
Opened By: SEXTON, DENISE : 3901
Lead Investigator: HUNTER, TODD : 126914
Lead Investigator's Phone:
Opened Date: 2019-01-17 03:52 PM
Discovery Date: 2019-01-09
Closed Date: 2019-01-18 11:08 AM
Admin Org Unit: FRASER NORTH ZONE
Source: REPORTED
Source Ref #: ERS 18-6418
Other Source Agency:
Transferred to Agency: DEPARTMENT OF FISHERIES AND OCEANS
Other Transferred Agency: DFO
Joint Investigation: No
Transferred Agency Contact: KNOOP, DONALD
Lead Agency: MINISTRY OF ENVIRONMENT
Joint Agency: MINISTRY OF ENVIRONMENT
Paper File Created: No
Electronic Case File: No
Investigation Review Process: No
Investigation Review Date:
Investigation Start Date: 2019-01-09
Joint Agency Contact:
Other Joint Agency:
Case Description: ERS 18-6418 REC'D @ 1312 HOURS - POSSIBLE DEPOSIT OF DELETERIOUS SUBSTANCE TO FISH BEARING STREAM
Joint Agency Phone:
Joint Agency Case No:

Members:

Name	Phone Number	Start Date	End Date
HUNTER, TODD : 126914		2019-01-17	2029-01-14
SEXTON, DENISE : 3901		2019-01-17	2029-01-14

Parties Involved:

Name	DOB	Role	Nature of Involvement	Phone No.	Address
ALLARD CONTRACTORS LTD.		SUBJECT OF COMPLAINT	POSSIBLE DEPOSIT OF DELETERIOUS SUBSTANCES	604-944-12556	PO BOX 47, 1520 PIPELINE OAD, COQUITLAM BC, V3C 3V5 CAN
LAFARGE CANADA INC.		SUBJECT OF COMPLAINT	POSSIBLE DEPOSIT OF DELETERIOUS SUBSTANCES	604-526-2796	22 LEEDER STREET, COQUITLAM BC CAN
JACK CEWE LTD.		SUBJECT OF COMPLAINT	POSSIBLE DEPOSIT OF DELETERIOUS SUBSTANCES	604-526-0751	1850 HILLSIDE AVENUE, COQUITLAM BC V3J6Z7 CAN

Parties Involved:

Name	DOB	Role	Nature of Involvement	Phone No.	Address
------	-----	------	-----------------------	-----------	---------

Sites:

Site	Site Type	Description
1. 2-8; FRASER NORTH ZONE		COQUITLAM RIVER, COQUITLAM

Notes:

Date	Name	Comments
2019-01-17	SEXTON, DENISE : 3901	ENTERED AND ATTACHED; LEFT OPEN AS PER SGT. HUNTER'S REQUEST

Continuation Report:

Date	Time	Name	Report
2019-01-18	11:06	HUNTER, TODD : 126914	Sgt. HUNTER attempted to call COM to provide update, but could not reach COM at the number provided. Case closed.
2019-01-18	10:00	HUNTER, TODD : 126914	09:54 Sgt. HUNTER was called by and spoke to DFO habitat specialist Don KNOOP. Both discussed the previous issues in the area. Sgt. HUNTER found that Environment Canada officers were dealing with some similar issues. Sgt. HUNTER was advised that officer KNOOP/ DFO will take over this particular file. Sgt. HUNTER also discussed and outlined a process with similar files. Most rivers within the area concerning Fish habitat will be considered Salmon can either be directly referred or discussed on how to pursue.
2019-01-10	16:00	HUNTER, TODD : 126914	Sgt. HUNTER found and reviewed the details of the report. Sgt. HUNTER noted previous and similar reports may have been taken on by the DFO habitat. Sgt. HUNTER sent file to DFO habitat section at: ReferralsPacific@dfo-mpo.gc.ca inquiring if they could take over file. (ds)

Attachments:

Attach#	Description	Photo	File	Attached By	Attached Date
1	20190109_DOC_s.22 E_ERS 18-6418	No	20190109_DOC_s.22 ERS 18-6418.PDF	_SEXTON, DENISE : 3901	2019-01-17

Contravention No.1**FISHERIES ACT (CANADA) AND REGULATIONS 36 (3) : DEPOSIT
DELETERIOUS SUBSTANCES****Species:****Est. Incident Date**

2019-01-06

Party:ALLARD CONTRACTORS
LTD.**Site:**1. 2-8; FRASER NORTH ZONE;
COQUITLAM RIVER,
COQUITLAM**Party Address:**PO BOX 47 1520 PIPELINE
OAD COQUITLAM BC V3C
3V5 CAN**Enforcement Actions**

Date Printed:2021/10/13

User ID: DAYTON, PAVLINA

Environment:PROD

Page 3 of 4

Report ID: CORS-001

Enforcement Action No. 1

Type: ADMINISTRATIVE ACTION
Effective Date: 2019-01-10 End Date:
Admin Action Type: REFERRED
Comments: TO REFERRALSPACIFIC@DFO-MPO.GC.CA

Contravention No.2**FISHERIES ACT (CANADA) AND REGULATIONS 36 (3) : DEPOSIT
DELETERIOUS SUBSTANCES**

Species:
Est. Incident Date: 2019-01-06 Party: LAFARGE CANADA INC.
Site: 1. 2-8; FRASER NORTH ZONE; Party Address: 22 LEEDER STREET
COQUITLAM RIVER, COQUITLAM BC CAN
COQUITLAM

Enforcement Actions**Enforcement Action No. 2**

Type: ADMINISTRATIVE ACTION
Effective Date: 2019-01-10 End Date:
Admin Action Type: REFERRED
Comments: REFERRALSPACIFIC@DFO-MPO.GC.CA

Contravention No.3**FISHERIES ACT (CANADA) AND REGULATIONS 36 (3) : DEPOSIT
DELETERIOUS SUBSTANCES**

Species:
Est. Incident Date: 2019-01-06 Party: JACK CEWE LTD.
Site: 1. 2-8; FRASER NORTH ZONE; Party Address: 1850 HILLSIDE AVENUE
COQUITLAM RIVER, COQUITLAM BC V3J6Z7
COQUITLAM CAN

Enforcement Actions**Enforcement Action No. 3**

Type: ADMINISTRATIVE ACTION
Effective Date: 2019-01-10 End Date:
Admin Action Type: REFERRED
Comments: TO REFERRALSPACIFIC@DFO-MPO.GC.CA

Vehicles:



Case Summary

Details

Case File #:	202013068	Opened Date:	2020-11-08 01:50 PM
Category:	CO SERVICE	Discovery Date:	2020-10-23
Type:	ENVIRONMENTAL	Closed Date:	2021-01-05 11:38 AM
Status:	Closed	Admin Org Unit:	FRASER SOUTH ZONE
Opened By:	PLAMONDON, MARC	Source:	REPORTED
Lead Investigator:	PLAMONDON, MARC	Source Ref #:	ERS 20-6778
Lead Investigator's Phone:		Other Source Agency:	
Paper File Created:	No	Transferred to Agency:	
Electronic Case File:	No	Other Transferred Agency:	
Investigation Review Process:	No	Joint Investigation:	No
Investigation Review Date:		Transferred Agency Contact:	
Investigation Start Date:	2020-10-23	Lead Agency:	MINISTRY OF ENVIRONMENT
		Joint Agency:	MINISTRY OF ENVIRONMENT
Joint Agency Contact:		Joint Agency Phone:	
Other Joint Agency:		Joint Agency Case No:	
Case Description:	ERS 20-6778 - ADVISES THAT THIS RECYCLING OUTLET MAKE PELLETS OUT OF RECYCLED MATERIAL AND THE PELLETS ARE ALL OVER THE PLACE.		

Members:

Name	Phone Number	Start Date	End Date
PLAMONDON, MARC		2020-11-08	2030-11-06

Parties Involved:

Name	DOB	Role	Nature of Involvement	Phone No.	Address
MERLIN PLASTICS SUPPLY INC.		SUBJECT OF COMPLAINT	PLASTIC PELLETS HAVE BEEN FOUND AROUND PROPERTY.	604-522-6799	917 CLIVEDEN AVE DELTA BC V3M 5R6 CAN
ANONYMOUS, s.22		COMPLAINANT			DELTA BC CAN

Sites:

Site	Site Type	Description
1. 2-4; FRASER SOUTH ZONE		917 CLIVEDEN AVE, DELTA, BC V3M 5R6

Notes:

Date	Name	Comments
------	------	----------

Continuation Report:

Date	Time	Name	Report
2021-01-05	11:30	PLAMONDON, MARC	CO's busy with other higher priority issues at time of call, file unattended.

Attachments:

Attach#	Description	Photo	File	Attached By	Attached Date
1	ERS 20-6778	No	NOTIFICATION OF ERS 20-6778 - SURREY - DELTA.PDF	PLAMONDON, MARC	2020-11-08

Contravention No.1**ENVIRONMENTAL MANAGEMENT ACT 12 (2) : DISCHARGE LITTER****Species:****Est. Incident Date**

2020-10-23

Party:MERLIN PLASTICS
SUPPLY INC**Site:**1. 2-4; FRASER SOUTH ZONE;
917 CLIVEDEN AVE, DELTA, BC
V3M 5R6**Party Address:**917 CLIVEDEN AVE
DELTA BC V3M 5R6 CAN**Enforcement Actions****Enforcement Action No. 1****Type:**

UNATTENDED

Comments:

CO'S BUSY WITH OTHER HIGHER PRIORITY FILES AT TIME OF CALL.

Vehicles:



Case Summary

Details

Case File #:	202101205	Opened Date:	2021-02-22 03:31 PM
Category:	CO SERVICE	Discovery Date:	2021-02-04
Type:	ENVIRONMENTAL	Closed Date:	
Status:	Open	Admin Org Unit:	SEA-TO-SKY ZONE
Opened By:	PRINGLE, AVRIL	Source:	REPORTED
Lead Investigator:	HARBICH, ERICH	Source Ref #:	ERS 20-8981
Lead Investigator's Phone:		Other Source Agency:	
Paper File Created:	No	Transferred to Agency:	
Electronic Case File:	No	Other Transferred Agency:	
Investigation Review Process:	No	Joint Investigation:	No
Investigation Review Date:		Transferred Agency Contact:	
Investigation Start Date:	2021-02-04	Lead Agency:	MINISTRY OF ENVIRONMENT
Joint Agency Contact:		Joint Agency:	MINISTRY OF ENVIRONMENT
Other Joint Agency:		Joint Agency Phone:	
Case Description:	DUMPING OF CHEMICAL AND SOAP DISPENSERS IN DUMPSTER - UBC PHARMACY BUILDING		

Members:

Name	Phone Number	Start Date	End Date
HARBICH, ERICH		2021-02-22	2031-02-20
PRINGLE, AVRIL		2021-02-22	2031-02-20

Parties Involved:

Name	DOB	Role	Nature of Involvement	Phone No.	Address
UNIVERSITY OF BRITISH COLUMBIA		SUBJECT OF COMPLAINT.			6035 NURSERIES ROAD VANCOUVER BC V6T 1W5 CAN
s.22		COMPLAINANT		s.22	

Sites:

Site	Site Type	Description
1. 2-8; SEA-TO-SKY ZONE		VANCOUVER

Notes:

Date	Name	Comments
2021-06-13	HARBICH, ERICH	CR UPDATE
2021-05-17	GRAVEL, SIMON	REVIEWED. REQUESTED UPDATE. DD JUNE 1ST

Continuation Report:

Date	Time	Name	Report
2021-06-13	19:00	HARBICH, ERICH	NO RESPONSE FROM COM TO DETERMINE WHAT KIND OF CHEMICALS WERE DISPOSED OF AND HOW EXACTLY THEY WERE DISPOSED OF.
2021-02-22	14:22	HARBICH, ERICH	HARBICH called COM to determine what kind of substances were improperly disposed of, but no answer, HARBICH left a voice message requesting a call back for more information.

Attachments:

Attach#	Description	Photo	File	Attached By	Attached Date
1	20210222_DOC_ERS 20-8981_HARBICH	No	20210222_DOC_ERS 20-8981_HARBICH.PDF	PRINGLE, AVRIL	2021-02-22

Contravention No.1	ENVIRONMENTAL MANAGEMENT ACT 6 (4) : INTRODUCE WASTE AND CAUSE POLLUTION
---------------------------	---

Species:

Est. Incident Date	2021-02-04 14:22	Party:	UNIVERSITY OF BRITISH COLUMBIA
Site:	1. 2-8; SEA-TO-SKY ZONE; VANCOUVER	Party Address:	6035 NURSERIES ROAD VANCOUVER BC V6T 1W5 CAN

Enforcement Actions
Vehicles:



Case Summary

Details

Case File #:	202107939	Opened Date:	2021-08-26 07:28 AM
Category:	CO SERVICE	Discovery Date:	2021-08-23
Type:	ENVIRONMENTAL	Closed Date:	2021-08-26 07:33 AM
Status:	Closed	Admin Org Unit:	FRASER SOUTH ZONE
Opened By:	MAVIN, MARY	Source:	REPORTED
Lead Investigator:	TRUDGIAN, JACK : 86075	Source Ref #:	ERS 21-4609
Lead Investigator's Phone:		Other Source Agency:	
Paper File Created:	No	Transferred to Agency:	
Electronic Case File:	No	Other Transferred Agency:	
Investigation Review Process:	No	Joint Investigation:	No
Investigation Review Date:		Transferred Agency Contact:	
Investigation Start Date:	2021-08-23	Lead Agency:	MINISTRY OF ENVIRONMENT
		Joint Agency:	MINISTRY OF ENVIRONMENT
Joint Agency Contact:		Joint Agency Phone:	
Other Joint Agency:		Joint Agency Case No:	
Case Description:	COM REPORTS GARBAGE TRUCKS BEING WASHED OUT INTO A LARGE STORM DRAIN NEAR THE FRASER RIVER		

Members:

Name	Phone Number	Start Date	End Date
TRUDGIAN, JACK : 86075		2021-08-26	2031-08-24
MAVIN, MARY		2021-08-26	2031-08-24

Parties Involved:

Name	DOB	Role	Nature of Involvement	Phone No.	Address
URBAN IMPACT RECYCLING LTD.		SUBJECT OF COMPLAINT			NEW WESTMINSTER BC
s.22		COMPLAINANT			CAN s.22

Sites:

Site	Site Type	Description
1. 2-4; FRASER SOUTH ZONE		s.22

Notes:

Date	Name	Comments
------	------	----------

Continuation Report:

Date	Time	Name	Report
2021-08-26	15:26	TRUDGIAN, JACK : 86075	Com called DFO and then DFO forwarded to us, so they are aware. Washing out a truck near a storm drain would most likely have no effect on any nearby watercourse or any harm to fish. Com has a picture of the storm drain, but that doesn't substantiate anything. Also appears to be on the Urban Impact property in New Westminster

Attachments:

Attach#	Description	Photo	File	Attached By	Attached Date
1	ERS 21-4609	No	ERS 21-4609.PDF	MAVIN, MARY	2021-08-26

Contravention No.1**FISHERIES ACT (CANADA) AND REGULATIONS 36 (3) : DEPOSIT
DELETERIOUS SUBSTANCES****Species:****Est. Incident Date**

2021-08-23

Party:URBAN IMPACT
RECYCLING LTD.**Site:**1. 2-4; FRASER SOUTH ZONE;
10 SPRUCE STREET, NEW
WESTMINSTER**Party Address:**NEW WESTMINSTER BC
CAN**Enforcement Actions****Enforcement Action No. 1****Type:**

UNFOUNDED

Comments:**Vehicles:**



Case Summary

Details

Case File #:	201903421	Opened Date:	2019-06-01 01:50 PM
Category:	CO SERVICE	Discovery Date:	2019-06-01
Type:	ENVIRONMENTAL	Closed Date:	2019-06-04 12:34 PM
Status:	Closed	Admin Org Unit:	FRASER SOUTH ZONE
Opened By:	STARK, ALICIA	Source:	CONSERVATION OFFICER FOUND
Lead Investigator:	STARK, ALICIA	Source Ref #:	
Lead Investigator's Phone:		Other Source Agency:	
Paper File Created:	No	Transferred to Agency:	
Electronic Case File:	No	Other Transferred Agency:	
Investigation Review Process:	No	Joint Investigation:	No
Investigation Review Date:		Transferred Agency Contact:	
Investigation Start Date:	2019-06-01	Lead Agency:	MINISTRY OF ENVIRONMENT
Joint Agency Contact:		Joint Agency:	MINISTRY OF ENVIRONMENT
Other Joint Agency:		Joint Agency Phone:	
Case Description:	ERS 19-1131	Joint Agency Case No:	

CALLER IS PARKED NEAR THE GFL SITE AND A LARGE EAGLE JUST CRAPPED ON s.22 VEHICLE. s.22 CONCERN IS THAT THE DROPPINGS ARE FILLED WITH PLASTIC FROM THE DUMP. s.2 HAS TAKEN A PICTURE AND THE EAGLE AND THE DROPPINGS ARE STILL THERE AT THIS MOMENT.

Members:

Name	Phone Number	Start Date	End Date
STARK, ALICIA		2019-06-01	2029-05-29

Parties Involved:

Name	DOB	Role	Nature of Involvement	Phone No.	Address
GFL ENVIRONMENTAL s.22		SUBJECT OF COMPLAINT COMPLAINANT		s.22	DELTA BC CAN

Sites:

Site	Site Type	Description
1. 2-4; FRASER SOUTH ZONE		DELTA

Notes:

Date	Name	Comments
------	------	----------

Continuation Report:

Date	Time	Name	Report
2019-06-01	14:00	STARK, ALICIA	<p>CO STARK SPOKE WITH THE COM. STARK IDENTIFIED THAT THERE IS A WASTE TRANSFER STATION IN CLOSE PROXIMITY AND WHEN SHE DROVE BY THE OTHER DAY SHE SAW NUMEROUS EAGLES THERE. THEY MAY BE EATING PLASTIC AT THE DUMP NOT GFL. STARK EXPLAINED SHE WAS GOING TO TALK TO THE SPECIALISTS AT OWL TO GET ADVICE ON HOW WE COULD CURB THIS.</p> <p>s.22 SAID GFL IS LITTERING PLASTIC BAGS WITH THEIR COMPOST AND THAT IS WHAT THE EAGLES ARE EATING. s.22 DEMANDED SOMETHING GETS DONE AND HUNG UP THE PHONE.</p> <p>NO WAY TO PROVE THAT THE BIRDS ARE EATING PLASTIC FROM THIS LOCATION. s.22</p>

Attachments:

Attach#	Description	Photo	File	Attached By	Attached Date
---------	-------------	-------	------	-------------	---------------

Contravention No.2**ENVIRONMENTAL MANAGEMENT ACT 12 (2) : DISCHARGE LITTER****Species:****Est. Incident Date**

2019-05-31 14:00

Party:

GFL ENVIRONMENTAL

Site:1. 2-4; FRASER SOUTH ZONE;
DELTA**Party Address:**

DELTA BC CAN

Enforcement Actions**Enforcement Action No. 1****Type:**

UNFOUNDED

Comments:**Vehicles:**



Case Summary

Details

Case File #:	201902273	Opened Date:	2019-04-17 01:34 PM
Category:	CO SERVICE	Discovery Date:	2019-04-17
Type:	ENVIRONMENTAL	Closed Date:	2019-04-17 01:37 PM
Status:	Closed	Admin Org Unit:	FRASER SOUTH ZONE
Opened By:	STARK, ALICIA	Source:	
Lead Investigator:	STARK, ALICIA	Source Ref #:	
Lead Investigator's Phone:		Other Source Agency:	
Paper File Created:	No	Transferred to Agency:	
Electronic Case File:	No	Other Transferred Agency:	
Investigation Review Process:	No	Joint Investigation:	No
Investigation Review Date:		Transferred Agency Contact:	
Investigation Start Date:	2019-04-17	Lead Agency:	MINISTRY OF ENVIRONMENT
Joint Agency Contact:		Joint Agency:	MINISTRY OF ENVIRONMENT
Other Joint Agency:		Joint Agency Phone:	
Case Description:	ERS 19-0324	Joint Agency Case No:	

CAPT'N CRUNCH RECYCLING'S DRYWALL AND GARBAGE PILES ARE LEACHING INTO CREEK. GARBAGE AND DRYWALL ARE NOT COVERED SO RAIN WATER RUNS OFF AND INTO A NEARBY CREEK WITH TOXIC CHEMICALS IN IT. PLEASE DO SOMETHING ABOUT THIS TRAVESTY. IT HAS GONE ON TOO LONG. IT APPEARS THE MINISTRY OF ENVIRONMENT DOES NOT CARE.

Members:

Name	Phone Number	Start Date	End Date
STARK, ALICIA		2019-04-17	2029-04-14

Parties Involved:

Name	DOB	Role	Nature of Involvement	Phone No.	Address
CAPT'N CRUNCH RECYCLING		SUBJECT OF COMPLAINT			ABBOTSFORD BC, CAN

Sites:

Site	Site Type	Description
1. 2-4; FRASER SOUTH ZONE		ABBOTSFORD

Notes:

Date Printed:2021/10/13
User ID: DAYTON, PAVLINA
Environment:PROD

Page 1 of 2
Report ID: CORS-001

Date	Name	Comments
------	------	----------

Continuation Report:

Date	Time	Name	Report
------	------	------	--------

Attachments:

Attach#	Description	Photo	File	Attached By	Attached Date
---------	-------------	-------	------	-------------	---------------

Contravention No.1 **ENVIRONMENTAL MANAGEMENT ACT 6 (2) : INTRODUCE WASTE FROM A PRESCRIBED INDUSTRY, TRADE OR BUSINESS**

Species:

Est. Incident Date 2019-04-17 13:30 **Party:** CAPT'N CRUNCH RECYCLING
Site: 1. 2-4; FRASER SOUTH ZONE; **Party Address:** ABBOTSFORD BC CAN
 ABBOTSFORD

Enforcement Actions
Enforcement Action No. 1

Type: ADMINISTRATIVE ACTION
Effective Date: 2019-04-17 **End Date:**
Admin Action Type: REFERRED
Comments: REFERRED TO EP AS THEY ALREADY HAVE A FEW REPORTS ON THIS COMPANY.

Vehicles: