

Fenton, Chrystal TRAN:EX

From: TRAN EMBC OFC SPCO TRAN:EX
Sent: Friday, July 28, 2017 20:36
To: McPhillips, Pat TRAN:EX; §.22 Wacey, Bill TRAN:EX
Subject: FW: SPU's

From: Owens, Rick TRAN:EX
Sent: Friday, July 28, 2017 8:36:13 PM (UTC-08:00) Pacific Time (US & Canada)
To: TRAN EMBC OFC SPCO TRAN:EX
Subject: SPU's

Chris

Gord Schriener is on the Pressy Lake Fire (Green Lake) He has 1 SPU type 2 trailer c/w crew – 1st call
Other SPU trailer they demobbed from Little Fort was Fire Storm # __ and was sent back home

Rick Owens, CFO

Fire Service Advisor

Prov. Structure Protection Program Coordinator

TEL 250-819-2231

Toll-Free 1.888.988.9488 (24hrs)

Emergency Management BC / Office of the Fire Commissioner, 1255 - D Dalhousie Drive, Kamloops, BC, V2C 5Z5

Fenton, Chrystal TRAN:EX

From: firehall@comox.ca
Sent: Friday, July 28, 2017 21:17
To: Wacey, Bill TRAN:EX
Subject: Fwd: C41367 SitRep July 28
Attachments: C41367 SitRep July 28.doc; ATT00001.htm

Sent from my iPhone

Begin forwarded message:

From: Gord Schreiner <firehall@comox.ca>
Date: July 28, 2017 at 21:15:37 PDT
To: Gord Schreiner <firehall@comox.ca>
Cc: s.22
Subject: C41367 SitRep July 28



Incident Information	
Date/Time:	July 28, 2017
Incident Name/Task Number:	C41367
Structure Protection Specialist:	Gord Schreiner, SPS #110

Structure Protection Summary						
Priority Area	Triage Category			Total	Structures Actioned	Comments
	Needs No Attention	Needs Protection	Cannot Be Saved			
A						
B						
C						
Totals						Assessed a couple dozen properties and started triage forms on them.

Resources Summary			
Type	#	Est. Daily Cost (use guide)	Comments
SPS Wage		SPS wages: s.17, s.21 day 1 vehicle SPS s.17 km x s.17 = s.17	
SPU Crews	First Call	s.17, s.21	Name: First Call, Kamloops
SPU Crews			Name:
Pickup Trucks km		1 vehicle total s.1 km x s.1 = \$289.17 1 vehicle total s.1 km x s.1 = \$277.83	Not required for Ministry pickups - Done monthly
SPU Trailers	First Call	\$ s.17, s.2	Closed: Assessments only today
SPU Trailers			
Expenses		SPS Motel \$ s.17	
Estimated Total Daily Costs		\$6730.60	

Comments- SPS Schreiner and SPC First Call went to Pressy Lake Road area to conduct some property inspections and pre-planning we toured close to thirty properties and drove by dozens of more. We sent some time assessing the area for water supply, values and met with several occupants. Crew returned to camp at about 18:00. SPS attended 21:30 Ops meeting.

Structure Protection Specialist Signature: Gord Schreiner, SPS #110, original signed	BCWS Signature (where applicable):
---	------------------------------------

Fenton, Chrystal TRAN:EX

From: firehall@comox.ca
Sent: Wednesday, August 9, 2017 14:26
To: Wacey, Bill TRAN:EX
Subject: s.22
Attachments:

Bill

My SPS stuff for July 1126-292017 for Clearwater and Pressy Lake

Please let me know what changes I need to make and where to send this. Should I be mailing the originals to you or?

Gord

This should be the final of SIX important invoicing emails to you.



Incident Information	
Date/Time:	July 28, 2017
Incident Name/Task Number:	C41367
Structure Protection Specialist:	Gord Schreiner, SPS #110

Structure Protection Summary						
Priority Area	Triage Category			Total	Structures Actioned	Comments
	Needs No Attention	Needs Protection	Cannot Be Saved			
A						
B						
C						
Totals						Assessed a couple dozen properties and started triage forms on them.

Resources Summary			
Type	#	Est. Daily Cost (use guide)	Comments
SPS Wage		SPS wages: \$s.17,s.2 day 1 vehicle SPS ^{s.17} km x s.17 = s.17	
SPU Crews	First Call	s.17,s.21	Name: First Call, Kamloops
SPU Crews			Name:
Pickup Trucks km		1 vehicle total s.1 km s.17 = \$289.17 1 vehicle total s.1 km x s.1 = \$277.83	Not required for Ministry pickups - Done monthly
SPU Trailers	First Call	\$s.17,s.21	Closed: Assessments only today
SPU Trailers			
Expenses		SPS Motel \$ ^{s.17}	
Estimated Total Daily Costs		\$6730.60	

Comments- SPS Schreiner and SPC First Call went to Pressy Lake Road area to conduct some property inspections and pre-planning we toured close to thirty properties and drove by dozens of more. We sent some time assessing the area for water supply, values and met with several occupants. Crew returned to camp at about 18:00. SPS attended 21:30 Ops meeting.

Structure Protection Specialist Signature: Gord Schreiner, SPS #110, <i>original signed</i>	BCWS Signature (where applicable):
--	------------------------------------



Incident Information	
Date/Time:	July 29, 2017
Incident Name/Task Number:	C41367
Structure Protection Specialist:	Gord Schreiner, SPS #110

Structure Protection Summary						
Priority Area	Triage Category			Total	Structures Actioned	Comments
	Needs No Attention	Needs Protection	Cannot Be Saved			
A						
B						
C						
Totals						

Resources Summary			
Type	#	Est. Daily Cost (use guide)	Comments
SPS Wage		SPS wages: s.17, s.21 day 1 vehicle SPS s.17 km x s.1 = s.17	
SPU Crews			
SPU Crews			Name:
Pickup Trucks km			Not required for Ministry pickups - Done monthly
SPU Trailers			
SPU Trailers			
Expenses		SPS Motel s.17	
Estimated Total Daily Costs		\$949.60	

Comments— SPS Schreiner and SPC First Call released from above noted fire and directed to Clinton. SPS dropped off SPC/U first Call at Camp in Clinton and traveled home to comox.c

Structure Protection Specialist Signature: Gord Schreiner, SPS #110, <i>original signed</i>	BCWS Signature (where applicable):
--	------------------------------------

Page 007 to/à Page 014

Withheld pursuant to/removed as

s.22

Owens, Rick TRAN:EX

From: firehall@comox.ca
Sent: Saturday, July 29, 2017 9:31
To: Owens, Rick TRAN:EX
Subject: C41367

Rick

We (SPU and First Call SPU) have been released from C41367 Pressy Lake. I have talked to bill and he is looking at a plan s.22

First Call type 2 is now available. s.22

Gord

Sent from my iPhone

Office of the Fire Commissioner
Structure Protection Standing Offer Drawdown Form
PO Box 9201 Stn Prov. Govt, Victoria BC V8W 9J1
EMBC Kamloops Phone: 250-371-5240 Fax: 250-371-5246

Standing Offer #: SO-SPU17BCWS-003 **Resource Request #:** _____
Contractor Name: First Call Fire Services Ltd. **Contact Name:** Stephen Butchart
Phone: 250-819-3473 **Fax:** N/A

RESOURCES REQUESTED

☐ STRUCTURE PROTECTION 5 PERSON CREW		☐ STRUCTURE PROTECTION UNIT TYPE II	
☐ STANDBY	Date (s):	Start Time:	End Time:
☐ DEPLOYMENT	Date: Friday July 28, 2017	Time: 0700am	
Fire On-Site Contact:		Fire #C41367	
Directions to incident: Highway 24 from Little Fort to 100 Mile camp. Pressy Lake Fire C41367			
Service Requested by:	OFC	Order Date/Time:	Friday July 28, 2017 0700 am
Comments: Leave Clearwater at 0700 am and proceed to Green/Pressy Lake fire C41367 with Type II SPU			

Printed Name	Sign Signature
Ministry Representative: Ron French	
Contractor Representative: Steve Butchart	

Once signed please return via email to SPC@fgov.bc.ca along with manifest

K:\Structure Protection Program\Structure Protection Program 2013\SPS Information Package\Standing Offer Form - Revised May 2013.docx

Ministry of Forests, Lands
and Natural Resource Operations

AUG 17 2017

KAMLOOPS FIRE CENTRE

s.17,s.21

Aug 4

Aug 4

Aug 5

Aug 5

Aug 6

Aug 6

Aug 7

Aug 7

Aug 8

Aug 8

Aug 9

Aug 9

Aug 10

Aug 10

Aug 11

Aug 11

Aug 12

Aug 12

Aug 13

Aug 14

Aug 15

\$75,445.31

s.17,s.21

\$75,445.31

Ministry of Forests, Lands
and Natural Resource Operations

AUG 17 2017

KAMLOOPS FIRE CENTRE

July 28

July 29

July 30

July 31

Aug 1

Aug 2

Aug 3

Aug 4

Aug 5

Aug 6

Aug 7

Aug 8

Aug 9

Aug 10

Aug 11

Aug 12

Aug 13

Aug 14

Aug 15

SPU Total \$63,015.45

GST# 87392 4906 RC0001

5% GST \$6,923.04

SUB TOTAL \$145,383.82

Ministry of Forests, Lands
and Natural Resource Operations

AUG 17 2017

KAMLOOPS FIRE CENTRE



DAILY TIME REPORT

081212

FULL LEGAL COMPANY OR INDIVIDUAL NAME:

First Call Fire ServicesINCIDENT #: 041307DATE: July 28 / 17EVACUATION ☐ ALERT ☐ ORDER

TIME RELEASED FROM INCIDENT:

REHABILITATION: ☐ YES Type:

(i.e. Crown Land, Private, IR etc)

PERSONNEL & EQUIPMENT BILLABLE HOURS

Name/Equipment	Fireline Position	24 Hr Clock		Break Time Taken	Total Work Hours	Total Hours Standby		Vehicle Km/day or standby	Initial
		Start	Stop			POH/Trans port	On - Site		

s.22

EQUIPMENT INFORMATION

Make:	Type:	Unit Assigned #:	Year:
Model/Size :	Operator: (print name)	Point of Hire Location:	

Lowbed Company Used:

Equipment Hauled For:

Equipment Hauled:

ATTACHMENTS/MISCELLANEOUS EQUIPMENT☐ TANK Size ☐ PUMP Size ☐ CHAINS Size # of Sets

List all WMB requested/required attachments and Industry Equipment

2011 Dodge Crew
2007 Ford F350
SPU Type 2

The above noted attachments are billable as per FS101 and Schedule A or other attached forms

FUEL DEDUCTION: # of Ltrs/\$

MINISTRY SUPPLIED

ACCOMMODATION: ☐ YESMEALS: ☐ B ☐ L ☐ D**SIGNATURES**

Contract Rep or Individual	Fireline Supervisor	Time Recorder
Ministry Qualified Receiver	Print Name	Employee Number

Comments

Ministry of Forests, Lands
and Natural Resource Operations

FS 257B Revised Apr 18/2011

SEE REVERSE FOR SAMPLES

AUG 17 2017

Distribution:

White - Fire Centre

Yellow - Fire Centre

Green - Contractor, Attach to invoice

KAMLOOPS FIRE CENTRE

Aug 6/17

Team to go

Coal Beds

Whitewine Drive thru

Check with East Branch

Dalgarno Coal Bed

Info to Scott Rennie

* Call Shane - Good to go
SPC move to Camp

BCWS Needs 5 Hotel Rooms.

Michel to Block A4 rooms.

Eat at Restaurants

Coal Bed info to Hugh

Branch Directors 34012 Tom

Aug 6 Safety Message - All Crews

TFL's + Branch Div to meet with all

TD IF3 - E3 + E18 crews + review
IAP

IF6 E17 + I5

1 Clinton - E2 + E1 12:00

2 pm TF3

Carson - Peachland in Clinton working

(4) North to North Bonanza Rd

- Clearwater to Yang Lake - Assess

(4) Pressy Lake

(12) - Stategic / Lac La Biche + Carson

to Hihume Lake

6 Pumps + Equipment

(5) - Well Lake 1 Pump

Combies radio's

Aug 6/17

99 Back lit on 99
tomorrow night 2 Engines
min. required

Uncontained Fire near Stinking
Lake

Tomorrow

* No work above / North of
Hihum Lake today
South of Hihum better

4 Helos due to size of fire
No more helicopters available

IC - Structures being burned
need coordinates & pics
CN Rail main frame again

Scott NO changes

NW wind tomorrow night
need more night crew

Thurs Wind event plan
accordingly

Hat Creek Ranch being ^{s.22}

s.22

EPS 201: Carson

Young Lake 44 + resort +
ranch all sprinkled

Continued Fire Smarting Green Lake

Do we want to ^{protect} south side of Bonaparte
Road

From North Green Lake Rd to Pressy Lake

Fire Smart properties

* Any other areas we can pull pumps
& sprinklers

Hihum Lake - Protect?

Helicopter in too late

50 Structures Approv

Aug 7/07?

055 Meeting with I.C. - Update each other on crews & status

* Flight Tomorrow for 2 man crew
11:00 am Contact Hugh in morning

11:30 Meeting with Capt. C.F.D. - sprinklers on in town for 1 week - suggestion?
T.D. look to shut them down today given the stale air & localized fire activity. Keep list and fire sprinklers as needed especially if wind event today. Send crew in a pickup so as not to tie up apparatus

1800 106 Thru
7400' $1\frac{1}{2}$ " hose
7 Pumps
Need for Presby Lake
Currently have
1600 Warp sprinklers
87 " brackets
2,000 Sprinklers
40 Boxes Econo 50'
2600' $1\frac{1}{2}$ "
1 Pump

Presby Lake

Horse Ranch back to Clinton
Mand Rand Freshby Pulling

Equipment

we have approx ⁶~~4-5~~ pumps
& equipment - Can we pull all equip.

*
S.22 Single Cabin Near Mt Gant,
→ 1500 Gallon Bladder with
pump MK3 & sprinklers put
equipment on run
Marsh & Timber burnt soil
some fuel

S.22

Ops Meeting

Weather Same as today
Thurs more snow possible weekly
Fri Sat Shift in which
30's + mid teen R.H.

Aug 13th

s.22

Finance - Docs to Rob

Will Lake Full Trailer

Presy - Neil will advise
Hydro + DTM

① Young Lake + Area Filled + Run

② Hutchison Lake + Area

③ Tim Cup

Green Lake - Address Properties as
required.

4pm Mandatory Meeting

09:30 T-5 Blaw Tire Delayed - will
check in when repaired

North Banquette Limer Goods

Presy Lake Power Limer Down

Potential 40% loss

Hutchison No loss.

Olson Ranch - Structures Saved

- Barns Burnt

Sinich - s.22

Blue Goose - s.22

Canyon Ranch - s.22

Wildland Engines into Presy? Tender
needed DTA + DTF
Hydro off

Carson - 1 crew North Banquette

Clearwater 1 - E22 White Rock

- Hutchison - T-7 Carson

- Green Lake La La B. site

- " Will Lake

Pressy Lake Assessment

07/08/17

Primary Structures: ~~|||||~~ ~~|||||~~ ~~|||||~~ ~~|||||~~ ~~|||||~~ ~~|||||~~ ~~|||||~~
total: 71

- South Pressy
- Area 1: 2 pumps for 13 addresses, 2200 feet of line 35 sprinklers
 - Area 2: 2 pumps for 15 primaries, 2000 feet of line 30 sprinklers
 - Area 3: Tied into Area 2 8 primaries, 600 ft for tie in 600 ft to structures 16 sr
- Rayfield Sub. Div.
- Area 4: 2 pumps 21 primaries, 2600 ft of line 40 sprinklers
- North Pressy
- Area 5: 2 pumps for 16 primaries, 2200 ft of line 35 sprinklers
- ~~Cut buildings: ~~|||||~~ ~~|||||~~ ~~|||||~~ ~~|||||~~ ~~|||||~~ ~~|||||~~ ~~|||||~~ ~~|||||~~ ~~|||||~~ ~~|||||~~~~
- Pumps: 8 MK's

None Grouped structures

- Hull Rd. 1 primary (residence) 1 out building
3 sprinklers 600 ft of 1 1/2" to swamp edge to the north
or bladder requires pump
- "West Pielawa" 3 out buildings not assessed as worth resource
- s.22
2 primary structures 1 out building
6 sprinklers 700 ft from water source (Pressy lake) requires pump
- s.22
2 primary 2 out buildings
8 sprinklers 600 ft from source (lesser Pressy lake) Tie into main system
- s.22
2 primary 6 out buildings
10 sprinklers 900 ft from source to longest lay requires pump
- s.22
5 primaries 6 out buil
18 sprinklers 600 ft from source (Rayfield Creek to south) requires pump (people press)

Carson call @ 10:00

Green Lake

Pontoon Boats

1pm Torch Base Carson

Mandatory 2pm Meeting

* Brian - Check-ins + tracking of crews

Carson - E22 White Rock Dwg

T70 Arnsburg

(4) SPC 3 Clearwater

North Bonaparte Rd

Green Lake

(4) SPC 2 L.L.B

(3) SPC 6 Will Lake

T-5 Eric's Delayed

T-11 Chem Creek

E-17 Delta Dwg

Recm Pressy Lake - Approx 30

properties burnt over

Torch Force Assembled to enter Pressy LK

BC Hydro Truck 8214

Cutting Line DTA

TF sent in to Pressy Lake.

T5 + T1 to work with SPC's
at Green Lake installing sprinkler

USRack Trailer 175 on site at
SELVED not opened

TF4 + All crews to withdraw at 16:15
from Pressy/Young Lake area using Little Green
Lake / Watch Lake Rd - Noted severe warning!

All SPC + TFS crews notified of
wind warnings

16:00 Safety check KFC all crews.

Meeting with SELVED, NGLVED + TOMLVED
update on all days proceedings, crews
continue patrols when needed use their
discretion, don't burn crews out.

Rev June 2012

Office of the Fire Commissioner Triage Form

Assessment #: 1

Picture #:

Triage #: ① 2 3 4

1-Prep & Hold Safe Zone Pres. 2-Standalone Safe Zone Pres. 3-Prep & Leave No Safe Zone Pres. 4-Rescue Drive-by No Safe Zone Pres.

s.22

Fire #: C41367	Crew: First Call	Date: July 28	GPS: Lat / Long	s.22
Name: PRESSY CAN BRAND	Contact #:	Street Address: PRESSY LAKE FIRST CANYON N. BONAPARTE RD		
Structures: 3	Primary: 1	Out Building: 2	Access Length: 1m	Width: 4m
Roof: METAL	Siding: WOOD	Power Overhead: Yes No	Natural Gas: Yes No	Type: gravel
Skylight: Yes No	Decks #: 1	Open: Yes No	Fire Wood by House: Yes No	Aspect: N - S - E - W
Fence: Yes No	Wood: Yes No	Propane: Yes No	Location: Side A B C D	Zone 1: _____
			Zone 2: _____	
Water Supply			Special Hazards	
Hydrants: Yes No Pool: Yes No Creek: Yes No				
River: Yes No Lake: Yes No Cistern: Yes No				
Distance from location: 5 METERS				
Notes: - needs 2 roof top S				
Equipment - Used / Required		Site Diagram		
Sprinklers: ☐		PRESSY LAKE		
S: _____ L: _____ BF: _____		SHED HOUSE SHED		
1 1/2" Hose: _____ 5/8" Hose: _____				
3 Ways: _____ Thieves: _____				
Pump: _____ S/N: _____				
Bladder _____				
Notes: _____		N. Bonaparte Rd FIRST CABIN ON		

Office of the Fire Commissioner Triage Form

Assessment #: 2

Picture #:

Triage #: 1 2 3 4

1- Prep & Hold Safe Zone Pres. 2- Standalone Safe Zone Pres. 3- Prep & Leave No Safe Zone Pres. 4- Rescue Drive-by No Safe Zone Pres.
s.22

Fire #: C41367		Crew: First Call Fire	Date: July 28	s.22	GPS: Lat / Long
Name:		Contact #:	Street Address: N. Bonaparte Rd		
Structures: 3	Primary: 1	Out Building: 2	Access Length: 100	Width: 5m	Type: gravel
Roof: Asphalt Siding: Vinyl			Power Overhead: Yes (No)	Natural Gas: Yes (No)	
Skylight: Yes (No)			Fire Wood by House: Yes (No)		
Decks #: 2 Open: Yes (No)			Aspect: N - S - E - W		
Fence: Yes (No) Wood: Yes (No)			Zone 1:		
Propane: Yes (No) Location: Side A B C D			Zone 2:		
Water Supply			Special Hazards		
Hydrants: Yes No Pool: Yes No Creek: Yes No					
River: Yes No Lake: Yes (No) Cistern: Yes No					
Distance from location:					
Notes: 1 roof top sprinkler (Solar power)					
Equipment - Used / Required			Site Diagram		
Sprinklers: ☐					
S: _____ L: _____ BF: _____					
1 1/2" Hose: _____ 5/8" Hose: _____					
3 Ways: _____ Thieves: _____					
Pump: _____ S/N: _____					
Bladder _____					
Notes: _____					

Office of the Fire Commissioner Triage Form

Assessment #: 3 Picture #: _____ Triage #: 1 2 3 4
 1- Prep & Hold Safe Zone Pres. 2- Standalone Safe Zone Pres. 3- Prep & Leave No Safe Zone Pres. 4- Rescue Drive-by No Safe Zone Pres. s.22

Fire #: <u>C41367</u>	Crew: <u>First Call fire</u>	Date: <u>July 28/17</u>	GPS: Lat /Long s.22
Name: _____	Contact #: _____	Street Address: <u>N. Bonaparte Rd</u> s.22	
Structures: <u>4</u>	Primary: <u>2</u>	Out Building: <u>2</u>	Access Length: <u>5</u> Width: <u>3</u> Type: <u>Gravel</u>
Roof: <u>Asphalt</u>	Siding: <u>WOOD</u>	Power Overhead: <u>Yes</u> No	Natural Gas: <u>Yes</u> <u>No</u>
Skylight: <u>Yes</u> <u>No</u>	Decks #: <u>2</u>	Open: <u>Yes</u> No	Fire Wood by House: <u>Yes</u> No
Fence: <u>Yes</u> No	Wood: <u>Yes</u> No	Aspect: <u>N</u> - S - E - W	Zone 1: _____
Propane: <u>Yes</u> No	Location: Side <u>A</u> B C D	Zone 2: _____	
<u>Water Supply</u>		<u>Special Hazards</u>	
Hydrants: Yes No Pool: Yes No Creek: Yes No			
River: Yes No Lake: <u>Yes</u> No Cistern: Yes No			
Distance from location: <u>30 meters</u>			
Notes: <u>NEED 2 ROOF TOP</u>			

<u>Equipment - Used / Required</u> Sprinklers: ☐ S: _____ L: _____ BF: _____ 1½" Hose: _____ 5/8" Hose: _____ 3 Ways: _____ Thieves: _____ Pump: _____ S/N: _____ Bladder: _____ Notes: _____ _____ _____ _____	<u>Site Diagram</u> LAKE CABIN CABIN SHED WOOD SHED NE ← N. BONAPARTE Rd
--	---

Office of the Fire Commissioner Triage Form

Assessment #: 4 Picture #: _____ Triage #: (1) 2 3 4

1- Prep & Hold Safe Zone Pres. 2- Standalone Safe Zone Pres. 3- Prep & Leave No Safe Zone Pres. 4- Rescue Drive/No Safe Zone Pres.

Fire #: <u>C-41367</u>	Crew: <u>FIRST CALL FIRE</u>	Date: <u>July 28</u>	GPS: Lat / Long s.22
Name: _____ s.22	Contact #: _____	Street Address: <u>N. BONAPARTE</u>	
Structures: <u>5</u>	Primary: <u>1</u>	Out Building: <u>4</u>	Access Length: <u>25m</u> Width: <u>4m</u> Type: <u>Gravel</u>
Roof: <u>Asphalt</u> Siding: <u>WOOD</u>	Power Overhead: <u>Yes</u> No Natural Gas: <u>Yes</u> No		
Skylight: Yes <u>No</u>	Fire Wood by House: <u>Yes</u> No		
Decks #: _____ Open: Yes <u>No</u>	Aspect: <u>N - S - E - W</u>		
Fence: Yes <u>No</u> Wood: Yes <u>No</u>	Zone 1: _____		
Propane: <u>Yes</u> No Location: Side <u>A</u> B C D	Zone 2: _____		
<u>Water Supply</u>		<u>Special Hazards</u>	
Hydrants: Yes No Pool: Yes No Creek: Yes No			
River: Yes No Lake: <u>Yes</u> No Cistern: Yes No			
Distance from location: <u>30 m</u>			

Notes:

<u>Equipment - Used / Required</u> Sprinklers: ☐ S: _____ L: _____ BF: _____ 1½" Hose: _____ 5/8" Hose: _____ 3 Ways: _____ Thieves: _____ Pump: _____ S/N: _____ Bladder _____ Notes: _____ _____ _____ _____	<u>Site Diagram</u>
---	-------------------------

1/2 ← N. BONAPARTE Rd.

Office of the Fire Commissioner Triage Form

Assessment #: 5

Picture #:

Triage #: 1 2 3 4

(1-Prep & Hold Safe Zone Pres. 2-Standalone Safe Zone Pres. 3-Prep & Leave No Safe Zone Pres. 4-Rescue Drive-by No Safe Zone Pres. s.22

Fire #: C 41367	Crew: FIRST CALL	Date: July 28	GPS: 1 at 11 on s.22
Name: s.22	Contact #:	Street Address: N. Bonaparte Rd	
Structures: 5	Primary: 1	Out Building: 4	Access Length: 30m Width: 3m Type: GRAVEL
Roof: ASHPLT	Siding: HARPY	Power Overhead: (Yes) No	Natural Gas: Yes (No)
Skylight: Yes (No)		Fire Wood by House: Yes (No)	Aspect: (N) - S - E - W
Decks #: 1	Open: (Yes) No	Zone 1: _____	Zone 2: _____
Fence: Yes (No)	Wood: Yes No		
Propane: Yes (No)	Location: Side A B C D		
<u>Water Supply</u> Hydrants: Yes No Pool: Yes No Creek: Yes No River: Yes No Lake: (Yes) No Cistern: Yes No Distance from location: 30 m		<u>Special Hazards</u>	
Notes: NEED 4 ROOFTOPS			

Equipment – Used / Required

Sprinklers: ☐

S: _____ L: _____ BF: _____


1½" Hose: _____ 5/8" Hose: _____

3 Ways: _____ Thieves: _____

Pump: _____ S/N: _____

Bladder: _____

Notes: _____



Triage #: 1 2 3 4

s.22

Site Diagram

LAKE

CABIN

546A

N. BRUNAPARTÉ

Office of the Fire Commissioner Triage Form

Assessment #: 7

Picture #:

Triage #: 1 2 3 4

1- Prep & Hold Safe Zone Pres. 2- Standalone Safe Zone Pres. 3- Prep & Leave No Safe Zone Pres. 4- Rescue Drive-by No Safe Zone Pres. s.22

Fire #: C41367	Crew: First Call	Date: July 28/17	s.22 GPS: Lat / Long
Name: s.22	Contact #: s.22	Street Address: N. BONAPARTE Rd.	
Structures: 4	Primary: 2	Out Building: 2	Access Length: 25m Width: 4m Type: Gravel
Roof: Asphalt Siding: WOOD	Skylight: Yes No	Decks #: 2	Power Overhead: Yes No Natural Gas: Yes No
Fence: Yes No Wood: Yes No	Propane: Yes No	Location: Side A B C D	Fire Wood by House: Yes No
Water Supply			Aspect: N - S - E - W
Hydrants: Yes No Pool: Yes No Creek: Yes No			Zone 1: _____
River: Yes No Lake: Yes No Cistern: Yes No			Zone 2: _____
Distance from location: 38 m			Special Hazards
Notes: 5 rooftops			

Equipment – Used / Required Sprinklers: ☐ S: _____ L: _____ BF: _____ 1½" Hose: _____ 5/8" Hose: _____ 3 Ways: _____ Thieves: _____ Pump: _____ S/N: _____ Bladder: _____ Notes: _____ _____ _____ _____	Site Diagram
--	-------------------------

Office of the Fire Commissioner Triage Form

Assessment #: 8 Picture #: _____ Triage #: 1 2 3 4

1- Prep & Hold Safe Zone Pres. 2- Standalone Safe Zone Pres. 3- Prep & Leave No Safe Zone Pres. 4- Rescue Drive-by No Safe Zone Pres.

s.22

Fire #: <u>C41367</u>	Crew: <u>First Call Fire</u>	Date: <u>July 28</u>	GPS: Lat /Long
Name: _____	Contact #: _____	Street Address: <u>N. Bonaparte</u>	
Structures: <u>3</u>	Primary: <u>1</u>	Out Building: <u>2</u>	Access Length: <u>30</u> Width: <u>4</u> Type: <u>gravel</u>
Roof: <u>META</u> Siding: <u>wood</u>			Power Overhead: <u>Yes</u> No Natural Gas: Yes No
Skylight: Yes <u>No</u>			Fire Wood by House: <u>Yes</u> No
Decks #: <u>1</u> Open: <u>Yes</u> No			Aspect: <u>N-S-E-W</u>
Fence: Yes <u>No</u> Wood: Yes No			Zone 1: _____
Propane: Yes <u>No</u> Location: Side A B C D			Zone 2: _____
<u>Water Supply</u>		<u>Special Hazards</u>	
Hydrants: Yes No Pool: Yes No Creek: Yes No			
River: Yes No Lake: <u>Yes</u> No Cistern: Yes No			
Distance from location: <u>30</u>			

Notes:

need 2 roofsEquipment - Used / RequiredSprinklers: ☐

S: _____ L: _____ BF: _____


1 1/2" Hose: _____ 5/8" Hose: _____

3 Ways: _____ Thieves: _____

Pump: _____ S/N: _____

Bladder _____

Notes: _____

Site Diagram

Office of the Fire Commissioner Triage Form

Assessment #: 9

Picture #:

Triage #: 1 2 3 4


1- Prep & Hold Safe Zone Pres. 2- Standalone Safe Zone Pres. 3- Prep & Leave No Safe Zone Pres. 4- Rescue Drive-by No Safe Zone Pres. s.22

Fire #: C41367	Crew: First Call Fire	Date: July 28	GDS: Lat 11 min s.22
Name:	Contact #:	Street Address: N. BONAPARTE Rd	
Structures: 4	Primary: 1	Out Building: 3	Access Length: 50 Width: 4 Type: gravel
Roof: Asphalt Siding: wood	Power Overhead: Yes No Natural Gas: Yes No		
Skylight: Yes No	Fire Wood by House: Yes No		
Decks #: 1	Open: Yes No	Aspect: N - S - E - W	
Fence: Yes No Wood: Yes No	Zone 1: _____		
Propane: Yes No Location: Side A B C D	Zone 2: _____		
<u>Water Supply</u>		<u>Special Hazards</u>	
Hydrants: Yes No Pool: Yes No Creek: Yes No		(X) propane by pump house	
River: Yes No Lake: Yes No Cistern: Yes No			
Distance from location: 15 m			
Notes: 3 roofs			

<u>Equipment - Used / Required</u>
Sprinklers: ☐
S: _____ L: _____ BF: _____
1 1/2" Hose: _____ 5/8" Hose: _____
3 Ways: _____ Thieves: _____
Pump: _____ S/N: _____
Bladder: _____
Notes: _____

<u>Site Diagram</u>

Office of the Fire Commissioner Triage Form
 Assessment #: 10 Picture #: Triage #: 1 2 3 4
 1- Prep & Hold Safe Zone Pres. 2- Standalone Safe Zone Pres. 3- Prep & Leave No Safe Zone Pres. 4- Rescue Drive-by No Safe Zone Pres.
 s.22

Fire #: C41367		Grew: First Call Fire	Date: July 28	GPS: Lat / Long s.22
Name: s.22		Contact #:	Street Address: N. BONA PASTE Rd	
Structures: 2	Primary: 1	Out Building: 1	Access Length: 150m Width: 3 Type: gravel	
Roof: METAL Siding: WOOD			Power Overhead: Yes No Natural Gas: Yes No	
Skylight: Yes No			Fire Wood by House: Yes No	
Decks #: Open: Yes No			Aspect: N → S - E - W	
Fence: Yes No Wood: Yes No			Zone 1: _____	
Propane: Yes No Location: Side A B C D			Zone 2: _____	
<u>Water Supply</u> Hydrants: Yes No Pool: Yes No Creek: Yes No River: Yes No Lake: Yes No Cistern: Yes No Distance from location: 20m			<u>Special Hazards</u>	
Notes:				
<u>Equipment - Used / Required</u> Sprinklers: ☐ S: _____ L: _____ BF: _____ 1 1/2" Hose: _____ 5/8" Hose: _____ 3 Ways: _____ Thieves: _____ Pump: _____ S/N: _____ Bladder: _____ Notes: _____ _____ _____ _____			<u>Site Diagram</u> 	

Office of the Fire Commissioner Triage Form

Assessment #: 11

Picture #:

Triage #: 1 2 3 4

1- Prep & Hold Safe Zone Pres. 2- Standalone Safe Zone Pres. 3- Prep & Leave No Safe Zone Pres. 4- Rescue Drive-by No Safe Zone Pres. s.22

Fire #: C41367	Crew: First Call Fire	Date: July 28	GPS: Lat / Long s.22
Name: s.22	Contact #:	Street Address: s.22	N. BONAPARTE Rd
Structures:	Primary:	Out Building:	Access Length: 60m Width: 2.5 Type: CAU2
Roof: METAL	Siding: WOOD	Power Overhead: (Yes) No	Natural Gas: Yes (No)
Skylight: Yes (No)	Decks #: 1	Open: (Yes) No	Fire Wood by House: Yes No
Fence: Yes No	Wood: Yes No	Propane: (Yes) No	Location: Side A B (C) D
Water Supply		Special Hazards	
Hydrants: Yes No Pool: Yes No Creek: Yes No			
River: Yes No Lake: (Yes) No Cistern: Yes No			
Distance from location: 20 m			
Notes:			

Equipment - Used / Required

Sprinklers: ☐

S: _____ L: _____ BF: _____

1 1/2" Hose: _____ 5/8" Hose: _____


3 Ways: _____ Thieves: _____

Pump: _____ S/N: _____

Bladder: _____

Notes: _____

Site Diagram




Office of the Fire Commissioner Triage Form

Assessment #: 12

Picture #:

Triage #: 1 2 3 4

1- Prep & Hold Safe Zone Pres. 2- Standalone Safe Zone Pres. 3- Prep & Leave No Safe Zone Pres. 4- Rescue Drive-by No Safe Zone Pres. s.22

Fire #: C41367		Crew: First Call Fire	Date: July 28/17	GPS: Lat / Long s.22
Name:		Contact #:	Street Address: N. BONAPARTE Rd.	
Structures: 3	Primary: 1	Out Building: 2	Access Length: 100 Width: 15 Type: gravel	
Roof: METAL Siding: WOOD			Power Overhead: Yes No Natural Gas: Yes No	
Skylight: Yes No			Fire Wood by House: Yes No	
Decks #: 1 Open: Yes No			Aspect: N - S - E - W	
Fence: Yes No Wood: Yes No			Zone 1: _____	
Propane: Yes No Location: Side A B C D			Zone 2: _____	
<u>Water Supply</u> Hydrants: Yes No Pool: Yes No Creek: Yes No River: Yes No Lake: Yes No Cistern: Yes No Distance from location: 20			Special Hazards	
Notes:				
<u>Equipment - Used / Required</u> Sprinklers: ☐ S: _____ L: _____ BF: _____ 1 1/2" Hose: _____ 5/8" Hose: _____ 3 Ways: _____ Thieves: _____ Pump: _____ S/N: _____ Bladder: _____ Notes: _____ _____ _____ _____			<u>Site Diagram</u> 	

← NE NORTH BONAPARTE

Office of the Fire Commissioner Triage Form

Assessment #: 13

Picture #:

Triage #: 1 2 3 4

1- Prep & Hold Safe Zone Pres. 2- Standalone Safe Zone Pres. 3- Prep & Leave No Safe Zone Pres. 4- Rescue Drive-by No Safe Zone Pres. s.22

Fire #: C41367		Crew: FIRST CALL Fire	Date: July 28
Name:		Contact #:	Street Address: N. BONAPARTE Rd. s.22
Structures: 4	Primary: 1	Out Building: 3	Access Length: 100m Width: 3m Type: gravel
Roof: METAL	Siding: WOOD		Power Overhead: Yes No Natural Gas: Yes No
Skylight: Yes No			Fire Wood by House: Yes No
Decks #: 2	Open: Yes No		Aspect: N → S - E - W
Fence: Yes No	Wood: Yes No		Zone 1: _____
Propane: Yes No	Location: Side A B C D		Zone 2: _____
Water Supply		Special Hazards	
Hydrants: Yes No Pool: Yes No Creek: Yes No			
River: Yes No Lake: Yes No Cistern: Yes No			
Distance from location: 20 m			
Notes:			
Equipment - Used / Required		Site Diagram	
Sprinklers: ☐		LAKE	
S: _____ L: _____ BF: _____		SHED HOUSE	
1½" Hose: _____ 5/8" Hose: _____			
3 Ways: _____ Thieves: _____			
Pump: _____ S/N: _____			
Bladder _____			
Notes: _____		GARAGE	
		← NE N. BONAPARTE Rd.	

Office of the Fire Commissioner Triage Form

Assessment #: 14 Picture #: _____ Triage #: 1 2 3 4

1- Prep & Hold Safe Zone Pres. 2- Standalone Safe Zone Pres. 3- Prep & Leave No Safe Zone Pres. 4- Rescue Drive-by No Safe Zone Pres.

Fire #: <u>C41367</u>	Crew: <u>FIRST CALL FIRE</u>	Date: <u>July 28</u>	GPS: <u>1</u> at <u>11 min</u> s.22
Name: _____	Contact #: _____	Street Address: s.22 <u>N. BONAPARTE Rd</u>	
Structures: <u>4</u> Primary: <u>1</u> Out Building: <u>3</u>	Access Length: <u>100m</u> Width: <u>5m</u> Type: <u>GRAVEL</u>		
Roof: <u>METAL</u> Siding: <u>WOOD</u>	Power Overhead: <u>Yes</u> No Natural Gas: Yes <u>No</u>		
Skylight: Yes <u>No</u>	Fire Wood by House: <u>Yes</u> No		
Decks #: <u>1</u> Open: <u>Yes</u> No	Aspect: <u>N-S-E-W</u>		
Fence: Yes <u>No</u> Wood: Yes <u>No</u>	Zone 1: _____		
Propane: Yes <u>No</u> Location: Side A B C D	Zone 2: _____		
<u>Water Supply</u>		<u>Special Hazards</u>	
Hydrants: Yes No Pool: Yes No Creek: Yes No			
River: Yes No Lake: <u>Yes</u> No Cistern: Yes No			
Distance from location: <u>20 m</u>			

Notes:

<u>Equipment - Used / Required</u> Sprinklers: ☐ S: _____ L: _____ BF: _____ 1 1/2" Hose: _____ 5/8" Hose: _____ 3 Ways: _____ Thieves: _____ Pump: _____ S/N: _____ Bladder _____ Notes: _____ _____ _____ _____	<u>Site Diagram</u> <u>LAKE</u> <u>HOUSE</u> <u>SHEDS</u> ☐ ☐ ☐ ← NE <u>N. BONAPARTE Rd</u>
---	--

Office of the Fire Commissioner Triage Form

Assessment #: 15

Picture #:

Triage #: ① 2 3 4

1- Prep & Hold Safe Zone Pres. 2- Standalone Safe Zone Pres. 3- Prep & Leave No Safe Zone Pres. 4- Rescue Drive by No Safe Zone Pres.

Fire #: C41367		Crew: First Call Fire	Date: July 28
Name s.22		Contact #:	Street Address s.22 N. BONAPARTE Rd
Structures: 3	Primary: 1	Out Building: 2	Access Length: 100 m Width: 3 Type: gravel
Roof: METAL	Siding: Vyn		Power Overhead: Yes No Natural Gas: Yes No
Skylight: Yes No			Fire Wood by House: Yes No
Decks #: 0	Open: Yes No		Aspect: N - S - E - W
Fence: Yes No	Wood: Yes No		Zone 1: _____
Propane: Yes No	Location: Side A B C D		Zone 2: _____
<u>Water Supply</u>		<u>Special Hazards</u>	
Hydrants: Yes No Pool: Yes No Creek: Yes No			
River: Yes No Lake: Yes No Cistern: Yes No			
Distance from location: 25 m			
Notes:)			
<u>Equipment – Used / Required</u>		<u>Site Diagram</u>	
Sprinklers: ☐		LAKE	
S: _____ L: _____ BF: _____		HOUSE	
1½" Hose: _____ 5/8" Hose: _____		SHEED	
3 Ways: _____ Thieves: _____		WOOD	
Pump: _____ S/N: _____		N. BONAPARTE	
Bladder _____		← NE	
Notes: _____			

Office of the Fire Commissioner Triage Form

Assessment #: 16

Picture #:

Triage #: 1 2 3 41- Prep & Hold Safe Zone Pres. 2- Standalone Safe Zone Pres. 3- Prep & Leave No Safe Zone Pres. 4- Rescue Drive-by No Safe Zone Pres.
s.22

Fire #: <u>C41367</u>	Crew: <u>FIRST CALL FIRE</u>	Date: <u>July 28</u>	s.22
Nar s.22	Contact #:	Street Address: <u>N. BONAPARTE RD</u>	s.22
Structures: <u>3</u>	Primary: <u>2</u>	Out Building: <u>1</u>	Access Length: <u>150</u> Width: <u>3</u> Type: <u>gravel</u>
Roof: <u>METAL/WOOD</u>	Siding: <u>SYNTH/WOOD</u>	Power Overhead: <u>Yes</u> No Natural Gas: <u>Yes</u> <u>No</u>	Fire Wood by House: <u>Yes</u> No
Skylight: Yes <u>No</u>	Decks #: <u>1</u> Open: <u>Yes</u> No	Aspect: <u>N</u> - S - E - W	Zone 1: _____
Fence: Yes <u>No</u> Wood: Yes No	Propane: Yes <u>No</u> Location: Side A B C D	Zone 2: _____	
<u>Water Supply</u>		<u>Special Hazards</u>	
Hydrants: Yes No Pool: Yes No Creek: Yes No			
River: Yes No Lake: Yes No Cistern: Yes No			
Distance from location: <u>15m</u>			
Notes:			

<u>Equipment - Used / Required</u> Sprinklers: ☐ S: _____ L: _____ BF: _____ 1½" Hose: _____ 5/8" Hose: _____ 3 Ways: _____ Thieves: _____ Pump: _____ S/N: _____ Bladder: _____ Notes: _____ _____ _____ _____	<u>Site Diagram</u>
--	-------------------------

Office of the Fire Commissioner Triage Form


Assessment #: 17

Picture #:

Triage #: 1 2 3 4

1- Prep & Hold Safe Zone Pres. 2- Standalone Safe Zone Pres. 3- Prep & Leave No Safe Zone Pres. 4- Rescue Drive No Safe Zone Pres. s.22

Fire #: C41367 First Crew: s.22 Date: July 28		Street Address: N. Bong Partz s.22	
Structures: 11	Primary: 5	Out Building: 6	Access Length: 10m Width: 3m Type: gravel
Roof: METAL	Siding: wood	Power Overhead: Yes No	Natural Gas: Yes No
Skylight: Yes No	Fire Wood by House: Yes No	Aspect: N - S - E - W	Zone 1: _____
Decks #: _____	Open: Yes No	Zone 2: _____	
Fence: Yes No	Wood: Yes No		
Propane: Yes No	Location: Side A B C D		
<u>Water Supply</u> Hydrants: Yes No Pool: Yes No Creek: Yes No River: Yes No Lake: Yes No Cistern: Yes No Distance from location: 200 METERS		<u>Special Hazards</u>	
Notes:			
<u>Equipment – Used / Required</u> Sprinklers: ☐ S: _____ L: _____ BF: _____ 1½" Hose: _____ 5/8" Hose: _____ 3 Ways: _____ Thieves: _____ Pump: _____ S/N: _____ Bladder: _____ Notes: _____ _____ _____ _____ _____		<u>Site Diagram</u> SEE BACK	



Office of the Fire Commissioner Triage Form


Assessment #:

Picture #:

Triage #: ① 2 3 4

1- Prep & Hold Safe Zone Pres. 2- Standalone Safe Zone Pres. 3- Prep & Leave No Safe Zone Pres. 4- Rescue Drive-by No Safe Zone Pres. s.22

Fire #: C41367		Crew: First Call Fire	Date: July 28/17
Name: s.22		Street Address: North Bonaparte s.22	
Structures: 3	Primary: 1	Out Building: 2	Access Length: 30m Width: 4m Type: Gravel
Roof: METAL	Siding: METAL	Power Overhead: Yes No	Natural Gas: Yes No
Skylight: Yes No	Decks #: 1	Open: Yes No	Fire Wood by House: Yes No
Fence: Yes No	Wood: Yes No	Aspect: N - S - E - W	Zone 1: _____
Propane: Yes No	Location: Side A B C D	Zone 2: _____	
Water Supply		Special Hazards	
Hydrants: Yes No Pool: Yes No Creek: Yes No			
River: Yes No Lake: Yes No Cistern: Yes No			
Distance from location: 150 m			
Notes: roof tops on trailer			
Equipment - Used / Required		Site Diagram	
Sprinklers: ☐		CREEK	
S: _____ L: _____ BF: _____		BARN	
1 1/2" Hose: _____ 5/8" Hose: _____		TRAILER	
3 Ways: _____ Thieves: _____		SHED	
Pump: _____ S/N: _____			
Bladder: _____			
Notes: _____		← NE North Bonaparte	



Assessment # 7 Office of the Fire Commissioner Triage Form

Rev June 2012

1- Prep & Hold Safe Zone Pres. 2- Standalone Safe Zone Pres. 3- Prep & Leave No Safe Zone Pres. 4- Rescue Pres. 5- 22

Triage # 1 2 3 4

Fire #:

C41367

Name:

Crew:

First Call

Date:

July 28/17

GPS: Lat & lon

s. 22

Structures:

Primary

Out Building:

Street Address:

N-Bonaparte Rd

Roof:

Asphalt

Siding:

WOOD

Access Length:

25m

Width:

4m

Type:

Gravel

Power Overhead:

Yes

No

Natural Gas:

Yes

No

Fire Wood by House:

Yes

No

Aspect:

N

S

E

W

Zone 1:

Zone 2:

Special Hazards

Water Supply

Hydrants: Yes No

Pool: Yes No

Creek: Yes No

River: Yes No

Lake: Yes No

Cistern: Yes No

Distance from location:

38 m


Notes:


Site Diagram


2017 7.28 1


Used / Required















2017-07-28








2017. 7.28



2017-7-23 1




2017. 7.28 1





2017-7-28-1





2017. 7. 28 1

Assessment # 6

Office of the Fire Commissioner Triage Form

1- Prep & Hold Safe Zone Pres. 2- Standalone Safe Zone Pres. 3- Prep & Leave No Safe Zone Pres. 4- Rescue Drive by No Safe Zone Pres.

Picture #

Triage #: 1 2 3 4

Fire # 41367

Name First Last Fire

Crew

Date

s.22

Contact #

Street Address

s.22

Structures

Primary

Out Building

Roof METAL

Siding

WOOD

Skylight Yes (No)

Decks: 1 Open (Yes) No

Fence Yes (No) Wood Yes No

Propane Yes (No) Location Side A B C D

Access Length 30m

Width 3m

Type GRAVEL

Power Overhead Yes (No)

Natural Gas Yes No

Fire Wood by House Yes (No)

Aspect (N) S - E - W

Zone 1

Zone 2

Special Hazards

Water Supply

Drants: Yes No

Pool: Yes No

Drank: Yes No

er: Yes No

Lake: Yes No

Quarry: Yes No

ance from location

30

100

REED 2 SPRINKLERS

Equipment Used Required


Site Diagram

CAFE

CAFE

2017. 7.28 1






2017. 7. 28. 1



2017 7 28 1





2017. 7. 28



Assessment #: 10 Office of the Fire Commissioner Triage Form

Rev June 2012

Fire #: C41367
 Name: s.22
 Structures: 2
 Primary: 1
 Out Building: 1
 Roof: METAL
 Siding: WOOD
 Skylight: Yes (No)
 Decks #: Open: (Yes) No
 Fence: Yes (No) Wood: Yes No
 Propane: Yes (No) Location: Side A B C D

Picture #:

Triage #: 1 2 3 4

Grew:

Contact #:

Date:

July 28

GPS: Lat / Long

s.22

Street Address:

N BONAPARTE RD

Access Length:

150

Width:

3

Type:

gravel

Power Overhead:

(Yes)

No

Natural Gas:

Yes

No

Fire Wood by House:

Yes

(No)

Aspect:

N - S - E - W

Zone 1:

Zone 2:

Water Supply

Special Hazards

Hydrants: Yes No Pool: Yes No Creek: Yes No

River: Yes No Lake: (Yes) No Cistern: Yes No

Distance from location: 20m

Notes:

Equipment - Used / Required

Site Diagram

LAKE


Sprinklers: ☐

BE

2017. 7.28

1






2017-7-28 1



2017-11-28



2017. 7.28 1



2017. 7. 23. 1

Rev June 20

Office of the Fire Commissioner Triage Form

Assessment #: 8

Picture #:

Triage #: 1 2 3 4

1- Prep & Hold Safe Zone Pres. 2- Standalone Safe Zone Pres. 3- Prep & Leave No Safe Zone Pres. 4- Rescue Drive-by No Safe Zone Pres.

GPS: Lat /Long

Fire #:

C41367

Crew:

FIRST CALL FIRE

Date:

July 28

Name:

Contact #:

Street Address:

Structures:

3

Primary:

1

Out Building:

2

Roof:

META

Siding:

Wood

Skylight:

Yes

No

Decks #:

Open:

Yes

No

Fence:

Yes

No

Wood:

Yes

No

Propane:

Yes

No

Location:

Side

A B C D

Access Length:

Width:

Type:

Power Overhead:

Yes

No

Natural Gas:

Yes

Fire Wood by House:

Yes

No

Aspect: N - S - E - W

Zone 1:

Zone 2:

Water Supply

Hydrants: Yes No

Pool: Yes No

Creek: Yes No

River: Yes No

Lake: Yes No

Cistern: Yes No

Distance from location:

Notes:

Special Hazards

2017. 7.28 1







Rev June 2012

Assessment # 9 Office of the Fire Commissioner Triage Form

Picture #: _____ Triage #: 1 2 3 4
 1-Prep & Hold Safe Zone Pres. 2-Standalone Safe Zone Pres. 3-Prep & Leave No Safe Zone Pres. 4-Rescue Drive-by No Safe Zone Pres. s.22

Fire #: C41367 Crew: First Call Fire Date: July 28 GPS: Lat: _____ Lon: _____ s.22

Name: _____ Contact #: _____ Street Address: N. Bonaventure Rd

Structures: 4 Primary: 1 Out Building: 3 Access Length: 50 Width: 4 Type: gravel

Roof: Asph/Flt Siding: Wood Power Overhead: Yes No Natural Gas: Yes No

Skylight: Yes No Fire Wood by House: Yes No Aspect: N-S-E-W

Decks #: _____ Open: Yes No Zone 1: _____

Fence: Yes No Wood: Yes No Zone 2: _____

Propane: Yes No Location: Side A B C D

Water Supply Special Hazards: (X) Propane by pump house

Hydrants: Yes No Pool: Yes No Creek: Yes No

River: Yes No Lake: Yes No Cistern: Yes No

Distance from location: 15m

Notes: 3 roofs

Equipment - Used / Required

Sprinklers: ☐ _____

S. _____ L. _____ BF. _____

1 1/4" Hose _____ 5/8" Hose _____

3 Ways _____ Thieves _____

Site Diagram

LAKE

HOUSE

2017-7-28

(X)

172




2017. 7. 28







2017 7 28




2017-7-28



OFFICIALS
GRANDPA
PARKING
ONLY









Rev June 2013

Picture #: _____ Triage #: 1 2 3

Equipment—Used / Required


Sprinklers: ☒
 S: _____ L: _____ GF: _____
 1 1/2" Hose: _____ 5/8" Hose: _____
 3 Ways: _____ Thieves: _____
 Pump: _____ S/N: _____
 Bladder: _____
 Notes: _____

See Diagram

2017


2001 7 28

72



2017. 7.28 1





Fire #:

041367

Name:

s.22

Crew:

First Call Fire

Date:

July 28

Contact #:

Triage #:

1 2 3 4

Rev June 2012

Structures:

Primary:

Out Building:

Roof: METAL

Siding: WOOD

Skylight: Yes ☒ No

Decks #: 1 Open: ☒ Yes No

Fence: Yes No Wood: Yes No

Propane: ☒ Yes No Location: Side A B ☒ C D

Street #:

s.22

GP:

s.22

Access Length: 100m Width: 25 Type: GRAVEL

Power Overhead: ☒ Yes No Natural Gas: Yes ☒ No

Fire Wood by House: Yes No

Aspect: N-S-E-W

Zone 1:

Zone 2:

Special Hazards

Water Supply

Hydrants: Yes No Pool: Yes No Creek: Yes No

River: Yes No Lake: ☒ Yes No Cistern: Yes No

Distance from location: 20 m

Notes:

Equipment - Used / Required

Sprinklers: ☐

BF:

5/8" Hose:

Thieves:

S/N:

3 Ways:

Pump:

Bladder:


Notes:


Site Diagram


LAKE

HOUSE

SHED







2017 7 28 1

Rev June 2012

Office of the Fire Commissioner Triage Form

Incident # 12

Picture #

Triage # 1 2 3 4

1- Safe Zone Pres. 2- Standalone Safe Zone Pres. 3- Prep & Leave No Safe Zone Pres. 4- Rescue Drive-by No Safe Zone Pres.

Crew:

Date:

s.22

Contact #:

Street Address:

s.22

Out Building:

Access Length:

Width:

Type:

Power Overhead: Yes No Natural Gas: Yes No

Fire Wood by House: Yes No

Aspect: N-S-E-W

Zone 1:

Zone 2:

Special Hazards

No Creek: Yes No

No Cistern: Yes No

2017. 7.28 1









Assessment #: 13 Office of the Fire Commissioner Triage Form
 1- Prep & Hold Safe Zone Pres. 2- Standalone Safe Zone Pres. 3- Prep & Leave No Safe Zone Pres. 4- Rescue Drive-by No Safe Zone Pres.

Rev June 2012

Fire #

C41367

Picture #

Triage #: 1 2 3 4

Name

First Call Fire

Date: July 28

s. 22

Crew

Contact #

Structures

Primary

Out Building

Roof: METAL

Siding

WOOD

Skylight: Yes ☒ No

Decks #

Open

Yes ☒ No

Fence: Yes ☒ No

Wood

Yes ☒ No

Propane: Yes ☒ No

Location: Side A B C D

Access Length: 100m Width: 3m Type: gravel

Power Overhead: Yes ☒ No

Natural Gas: Yes ☒ No

Fire Wood by House: Yes ☒ No

Aspect: N S E W

Zone 1

Zone 2

Special Hazards

Water Supply

Hydrants: Yes No

Pool: Yes No

Creek: Yes No

River: Yes No

Lake: Yes ☒ No

Cistern: Yes No

Distance from location:

20 m

Notes

Equipment - Used / Required

Sprinklers: ☐

S: _____ L: _____ BF: _____

1 1/2" Hose: _____ 5/8" Hose: _____

3 Ways: _____ Thieves: _____

Pump: _____ S/N: _____


Site Diagram


Lake

SHED

HOUSE


2017. 7. 28 1






2017. 7.28 1





2017-7-28



2017. 7. 28 1

Rev June 2012

Office of the Fire Commissioner Triage Form

Assessment #: 18

Picture #:

Triage #: 1 2 3 4

1-Prep & Hold Safe Zone Pres. 2-Standalone Safe Zone Pres. 3-Prep & Leave No Safe Zone Pres. 4-Rescue Drive-by No Safe Zone Pres.

Crew:

Date:

GPS: Lat /Long

First Call Fire July 28/17

Contact #:

Street Address:

s.22

s.22

North Bonaparte

Primary:

Out Building:

Access Length:

Width:

Type:

Power Overhead: Yes No Natural Gas: Yes No

Fire Wood by House: Yes No

Aspect: N - S - E - W

Zone 1: _____

Zone 2: _____

Roof: METAL Siding: METAL

Skylight: Yes No

Decks #: Open: Yes No

ence: Yes No Wood: Yes No

opane: Yes No Location: Side A B C D

Special Hazards

er Supply

nts: Yes No Pool: Yes No Creek: Yes No

Yes No Lake: Yes No Cistern: Yes No

from location: 150 m


2017. 7. 28




Page 110

Withheld pursuant to/removed as


DUPLICATE




2017 28




2017-7-28 11:12



2017 7.28





Assessment #: 15 Office of the Fire Commissioner Triage Form

Rev June 2012

1- Prep & Hold Safe Zone Pres. 2- Standalone Safe Zone Pres. 3- Prep & Leave No Safe Zone Pres. 4- Rescue Data Only

41367

s.22

Crew: First Call Fire

Date: July 28

s.22

Contact #:

Street Address: s.22

N. Bonaparte Rd

Primary:

Out Building:

METAL

Siding: VINYL

nt: Yes ☒ No

s #: Open: Yes No

e: Yes No Wood: Yes No

ane: Yes No Location: Side A B C D

Access Length: 100 ft Width: 3 Type:

Power Overhead: Yes No Natural Gas: Yes No

Fire Wood by House: Yes No

Aspect: N-S-E-W

Zone 1:

Zone 2:

Special Hazards

er Supply

drants: Yes No Pool: Yes No Creek: Yes No

ver: Yes No Lake: Yes No Cistern: Yes No

distance from location:

otes:

See Diagram

LIST

Equipment - Used / Required

Sprinklers: ☐

2017 7:28
1 1/2" Hose

BF: _____


5/8" Hose: _____

Thieves: _____


SIN: _____

Hose






2017-07-28 11



2017-7-22



2017. 7.28 1

Office of the Fire Commissioner Triage Form

Rev June 2012


File # C41367
 Assessment # 16
 1. Prep & Hold Safe Zone Pres. 2. Standalone Safe Zone Pres. 3. Prep & Leave No Safe Zone Pres. 4. Rescue Drive-by No Safe Zone Pres.

Picture # First Call Fire
 Date July 28
 GPS: Lat / Long RD

Structures: 2 Primary 2 Siding syn / wood
 Roof: metal Open: Yes No
 Skylight: Yes No
 Decks #: 1 Wood: Yes No
 Fence: Yes No Location: Side A B
 Propane: Yes No
 Water Supply
 Hydrants: Yes No Pool: Yes No Creek
 River: Yes No Lake: Yes No
 Distance from location
 Notes

Street Address: N Bona Parte
 Access Length: 28 Width: 10
 Power Overhead: Yes No
 Intersected by House: Yes No
 Intersected by: S-E-W Natural Gas: Yes No

2017. 7.28




2017. 7. 28 1



2017 7-20



2017. 7.29 1





2017-07-29 14










2017. 7.29 1





2017. 7.29 1







Rev June 2012

Office of the Fire Commissioner Triage Form

Assessment #: 17

Picture #:

Triage # 1 2 3 4

1-Hold Safe Zone Pres. 2-Standalone Safe Zone Pres. 3-Prep & Leave No Safe Zone Pres. 4-Rescue Drive-by No Safe Zone Pres.

Crew: First Call

Date: July 28

GPS: Lat / Long

s.22

s.22

s.22

ital
c

Street Address:

N. Bong Part 2

Primary: Out Building

Siding:

Access Length: Width: Type:
Power Overhead: Yes No Natural Gas: Yes No
Fire Wood by House: Yes No

Open: Yes No

Aspect: N - S - E - W

Wood: Yes No

Zone 1: _____
Zone 2: _____


Location: Side A B C D

Special Hazards

bl: Yes No Creek: Yes No


e: Yes No Cistern: Yes No

2017. 7.28




2017. 7.28






2017 7 23







2017-7-20 11

























2017-7-30-11





2017-7-30 1



















Incident Information	
Date/Time:	Aug. 7, 2017
Incident Name/Task Number:	K20637
Structure Protection Specialist:	SPS 108 /115/107/114/116

Structure Protection Summary						
Priority Area	Triage Category			Total	Structures Actioned	Comments
	Needs No Attention	Needs Protection	Cannot Be Saved			
A	10	159		169	169	Sprinklers installed on structures on all areas of the fire
B		40		40	40	Clinton, West Fraser Mill, 70 mile, Hwy 99 and Hwy 1 corridor
C		50		50	50	High Hume Lake
D		44		44	44	Young Lake
Totals	10	293		303	303	

Resources Summary				
Type	#	Est. Daily Cost (use guide)	Est. Daily Cost - BCWS	
☐ Ministry ☐ FD SPS & Command	s.17,s.21	\$1,800	\$3,990	
SPU Crews			\$26,137.41	
Pickup Trucks Kms		\$2365		
SPU Trailers			Type 1 s.17,s.21 - day 6 Type 1 - day 7 Type 1 - day 3 Type 2 Type 2	
Mobile Communications		\$4,228		
Engines		\$152,592	1 Engine 24hr – Chasm Mill Site \$s.17,s.21	
Tenders		\$38,664	1 Tender 24 hr. - Chasm Mill \$s.17,s.21	
Expenses		\$8,400	\$2,000	
Estimated Total Daily Costs		\$208,049	\$88,526	
		Total Cost OFC and WMB \$296,575		

Comments– The Structure Protection Task Force continued Daytime and Night time Patrols.

44 Structures were actioned by three sprinkler crews at Young Lake yesterday. 50 Structures were actioned today at High Hume Lake

Strike Teams assisted in backburn activity.

Planning activities were continued for the Chasm Mill Site and New Crews were checked and given an orientation tour.

The Incident Command Post technical and logistics staff were cycled out today and transition complete early this evening.

Structure Protection Signature:
Rob Owens



BCWS Signature (where applicable):

Revised May 2016



Incident Information	
Date/Time:	Aug. 8, 2017
Incident Name/Task Number:	K20637
Structure Protection Specialist:	SPS 108 /115/107/114/116

Structure Protection Summary						
Priority Area	Triage Category			Total	Structures Actioned	Comments
	Needs No Attention	Needs Protection	Cannot Be Saved			
A	10	159		169	169	Sprinklers installed on structures on all areas of the fire
B		40		40	40	Clinton, West Fraser Mill, 70 mile, Hwy 99 and Hwy 1 corridor
C		50		50	50	High Hume Lake
D		44		44	44	Young Lake
Totals	10	293		303	303	

Resources Summary			
Type	#	Est. Daily Cost (use guide)	Est. Daily Cost - BCWS
☐ Ministry ☐ FD SPS & Command	s.17,s.21	\$1,800	\$3,990
SPU Crews			\$26,137.41
Pickup Trucks Kms		\$2365	
SPU Trailers			Type 1 s.17,s.21 - day 6 Type 1 - day 7 Type 1 - day 3 Type 2) Type 2
Mobile Communications		\$4,228	
Engines		\$152,592	1 Engine 24hr – Chasm Mill Site s.17,s.21
Tenders		\$38,664	1 Tender 24 hr. - Chasm Mill s.17,s.2
Expenses		\$8,400	\$2,000
Estimated Total Daily Costs		\$208,049 Total Cost OFC and WMB \$296,575	\$88,526

Comments— The Structure Protection Task Force continued Daytime and Night time Patrols. Hume Lake Properties were finished up today and a few ranches along Young Lake road were actioned with pumps and sprinklers. Structure Protection Crews coordinated with BCWS for possible controlled burns today. The Chasm Mill Action Plan is continuing to be developed. A new SPS for the north sector and a new operations supervisor arrived today.

Structure Protection Signature: Rob Owens 	BCWS Signature (where applicable):
--	---

Revised May 2016



Incident Information	
Date/Time:	Aug. 9, 2017
Incident Name/Task Number:	K20637
Structure Protection Specialist:	SPS 108 /115/107/114/116

Structure Protection Summary						
Priority Area	Triage Category			Total	Structures Actioned	Comments
	Needs No Attention	Needs Protection	Cannot Be Saved			
A	10	159		169	169	Sprinklers installed on structures on all areas of the fire
B		40		40	40	Clinton, West Fraser Mill, 70 mile, Hwy 99 and Hwy 1 corridor
C		50		50	50	High Hume Lake
D		44		44	44	Young Lake
Totals	10	293		303	303	

Resources Summary				
Type	#	Est. Daily Cost (use guide)	Est. Daily Cost - BCWS	
☐ Ministry ☐ FD SPS & Command	s.17,s.21	\$1,800	\$3,990	
SPU Crews			\$26,137.41	
Pickup Trucks Kms		\$2365		
SPU Trailers			Type 1 s.17,s.21 day 6 Type 1 day 7 Type 1 - day 3 Type 2 Type 2	
Mobile Communications		\$4,228		
Engines		\$152,592	1 Engine 24hr – Chasm Mill Site s.17,s.21	
Tenders		\$38,664	1 Tender 24 hr. - Chasm Mill s.17,s.21	
Expenses		\$8,400	\$2,000	
Estimated Total Daily Costs		\$208,049	\$88,526	
		Total Cost OFC and WMB \$296,575		


Comments– The Structure Protection Task Force continued Daytime and Night time Patrols.

Properties above Young Lake were looked at today in order to get an idea of what protection might be required dependent on Fire Behavior.

Structure Protection Crews coordinated with BCWS for possible controlled burns today. Loon Lake Rd is still active and will require engines and tenders for the next few days.

The Chasm Mill was moved from an evacuation order to an evacuation alert today. Mill will start operating tomorrow.

Crew have done some familiarization and planning in the 70 mile area .

Structure Protection Signature: Rob Owens 	BCWS Signature (where applicable):
---	---

Revised May 2016



Incident Information	
Date/Time:	Aug. 10, 2017
Incident Name/Task Number:	K20637
Structure Protection Specialist:	SPS 108 /115/107/114/116

Structure Protection Summary						
Priority Area	Triage Category			Total	Structures Actioned	Comments
	Needs No Attention	Needs Protection	Cannot Be Saved			
A						Sprinklers installed on structures on all areas of the fire
B						Clinton, West Fraser Mill, 70 mile, Hwy 99 and Hwy 1 corridor
C						High Hume Lake
D						Young Lake
Totals						

Resources Summary				
Type	#	Est. Daily Cost (use guide)	Est. Daily Cost - BCWS	
☐ Ministry ☐ FD SPS & Command	s.17,s.21	\$1,800	\$3,990	
SPU Crews			\$26,137.41	
Pickup Trucks Kms		\$2365		
SPU Trailers			Type 1 s.17,s.21 day 6 Type 1 day 7 Type 1 - day 3 Type 2) Type 2	
Mobile Communications		\$4,228		
Engines		\$152,592	1 Engine 24hr – Chasm Mill Site s.17,s.21	
Tenders		\$38,664	1 Tender 24 hr. - Chasm Mill s.17,s.21	
Expenses		\$8,400	\$2,000	
Estimated Total Daily Costs		\$208,049	\$78,526	
		Total Cost OFC and WMB \$286,575		


Comments– The Structure Protection Task Force continued Daytime and Night time Patrols.

Properties above Young Lake were looked at today in order to get an idea of what protection might be required dependent on Fire Behavior.

Structure Protection Crews coordinated with BCWS for possible controlled burns today. Fire at the hatchery on Loon Lake Rd, our engine, tender and SPU Crews assisted BCWS in protecting hydro lines and getting sprinklers running on the Hatchery. Loon Lake Rd is still active and will require engines and tenders for the next few days

Skoocumchuk Ranch was being threatened by spot fires. Engine Crew from Kitimat attended and rearranged some sprinkler sets. They stayed on scene until BCWS had the spot fires contained.

Crews continue to some familiarization and planning in the 70 mile area .

Structure Protection Signature: Rob Owens 	BCWS Signature (where applicable):
--	---

Revised May 2016



Incident Information	
Date/Time:	Aug.11, 2017
Incident Name/Task Number:	K20637
Structure Protection Specialist:	SPS 108 /115/107/114/116

Structure Protection Summary						
Priority Area	Triage Category			Total	Structures Actioned	Comments
	Needs No Attention	Needs Protection	Cannot Be Saved			
A				169	169	Sprinklers installed on structures on all areas of the fire
B						
C				50	50	High Hume Lake
D				44	44	Young Lake
Totals				263	263	


Resources Summary				
Type	#	Est. Daily Cost (use guide)	Est. Daily Cost - BCWS	
☐ Ministry ☐ FD SPS & Command	s.17,s.21	\$1,800	\$3,990	
SPU Crews			\$28,137	
Pickup Trucks Kms		\$2365		
SPU Trailers			Type 1 s.17,s.21 day 6 Type 1 day 7 Type 1 day 3 Type 2 Type 2	
Mobile Communications		\$4,228		
Engines		\$145,572		
Tenders		\$47,256		
Expenses		\$8,400	\$2,000	
Estimated Total Daily Costs		\$209,621	\$57,052	
		Total Cost OFC and WMB \$266,673		

Comments— The Structure Protection Task Force continued Daytime and Night time Patrols along Hwy 99, 97 and Loon Lake Rd

Properties above Young Lake were looked at today in order to get an idea of what protection might be required dependent on Fire Behavior.

Structure Protection Crews coordinated with BCWS for possible controlled burns today

10 Engines and 4 Tenders returned to home Base today.

Structure Protection Signature: Rob Owens 	BCWS Signature (where applicable):
--	------------------------------------

Revised May 2016




Incident Information	
Date/Time:	Aug.12, 2017
Incident Name/Task Number:	K20637
Structure Protection Specialist:	SPS 108 /115/107/114/116

Structure Protection Summary						
Priority Area	Triage Category			Total	Structures Actioned	Comments
	Needs No Attention	Needs Protection	Cannot Be Saved			
A						Tactical Deployment of Sprinklers at Green Lake
B						
C						
D						
Totals						

Resources Summary				
Type	#	Est. Daily Cost (use guide)	Est. Daily Cost - BCWS	
☐ Ministry ☐ FD SPS & Command	s.17,s.21	\$1,800	\$3,990	
SPU Crews			\$28,137	
Pickup Trucks Kms		\$2365		
SPU Trailers			Type 1 s.17,s.21 day 6 Type 1 day 7 Type 1 day 3 Type 2 Type 2	
Mobile Communications		\$4,228		
Engines		\$76,296 Travel 40,000		
Tenders		\$ 21,480 Travel 16,000		
Expenses		\$8,400	\$2,000	
Estimated Total Daily Costs		\$168,204	\$57,052	
		Total Cost OFC and WMB \$225,256		

Comments— Structure Protection crews maintains sets at Young/Hihium Lake

2 Engines and 1 Tender (Chilliwack, Merritt, Pender Island) sent to Nazko this afternoon.
Tactical Deployment of Sprinkler Sets at South Green Lake

Structure Protection Signature: Rob Owens 	BCWS Signature (where applicable):
--	---

Revised May 2016




Incident Information	
Date/Time:	Aug.13, 2017
Incident Name/Task Number:	K20637
Structure Protection Specialist:	SPS 108 /115/107/114/116

Structure Protection Summary						
Priority Area	Triage Category			Total	Structures Actioned	Comments
	Needs No Attention	Needs Protection	Cannot Be Saved			
A						Tactical Deployment of Sprinklers at Green Lake
B						
C						
D						
Totals						

Resources Summary				
Type	#	Est. Daily Cost (use guide)	Est. Daily Cost - BCWS	
☐ Ministry ☐ FD SPS & Command	s.17,s.21	\$1,800	\$3,990	
SPU Crews			\$28,137	
Pickup Trucks Kms		\$2365		
SPU Trailers			Type 1 s.17,s.21 day 6 Type 1 day 7 Type 1 - day 4 Type 2 Type 2	
Mobile Communications		\$4,228		
Engines		\$76,296		
Tenders		\$ 21,480		
Expenses		\$8,400	\$2,000	
Estimated Total Daily Costs		\$106,176	\$62,052	
		Total Cost OFC and WMB \$ 168,228		

Comments– Structure Protection crews maintain sets at Young/Hihium Lake

Tactical Deployment of Sprinkler Sets at South Green Lake continues. Some demob along Mound Rd. to recover equipment needed

Structure Protection Signature: Rob Owens 	BCWS Signature (where applicable):
--	---

Revised May 2016