

## View Work Order Detail - C220465

Fields marked with an \* are required.

\* Enter Work Order Number:

[View Order](#)

### Work Order Location

St, City:  
CA, BC, SAANICH

Building:  
4216 Wilkinson Rd-Corr Ctr

Floor:  
F01

Area:  
1-Custody-

Location within Area:  
LI Unit - Stairs

Location Phone:  
**s.15**

Contact Name:  
Garth Fraser

Contact Phone:

### Important Dates

Entered:  
8/10/2020 6:51:43 AM PST

Response Target:  
8/10/2020 2:51:44 PM PST

Completion Target:  
8/11/2020 10:52:44 PM PST

Date Dispatched:  
8/10/2020 6:51:43 AM PST

Next Arrival:

Completed:  
8/12/2020 1:25:00 PM PST

### Work Order

Work Order Number:  
C220465 feedback

Problem Description:  
General Building Maintenance:>The flooring at the top of the stairs is lifting. Please re-secure it ...

Completion Description:  
Apoxy glued back down the lifted edge

### General Information