

**National Safety Code (NSC)
Compliance Review**

NSC #:	200300205	Event #:	89321	Date:	September 11, 2014
Compliance Review Period:	September 1, 2013	to	September 11, 2014		
Carrier Name:	Stryder Motorfreight Canada Ltd.				
Records Address:	7167 Progress Way				
City:	Delta	Province:	BC	Postal Code:	V4G 1K8
Principal:	Daniel Howard Saam	DL # & Jur.:	s.22	BC	
Principal:		DL # & Jur.:			
Authorized Rep.:	GILLIAN PHILLIPS	DL # & Jur.:			
Authorized Rep. Title:	MANAGER SAFETY & COMPLIANCE				
Office Phone:	604-233-1205	ext.		Fax:	(604) -270-9244
Cell Phone	s.22	Email:	compliancego-stryder.com		

Scope of Operations

Fleet Size (Power Units Only):	77	Number of Drivers:	80
☒ Within 160 km	☒ Outside 160 km		
☒ Intra-Provincial	☒ Extra-Provincial (inside Canada)	☒ Outside Canada	
☐ Dangerous Goods	☐ No vehicles over 11,794 kg (except passenger vehicles)		

Service Types*Passenger Services:*

☐ Taxi/Limousine	☐ Bus - Community Group	☐ Passenger - Other
☐ Bus - School	☐ Bus - Public Transit	
☐ Bus - Charter/Tour	☐ Bus - Shuttle	

Non-Passenger Services:

☐ Artisan	☒ General Freight	☐ Towing Service
☐ Bulk - Dry	☐ Government Vehicle	☐ TDG - Explosives (Class 1)
☐ Bulk - Liquid	☐ Household Mover	☐ TDG - Compressed Gases (Class 2)
☐ Bulk - Other	☐ Heavy Equipment	☐ TDG - Flammable/Combustible Liquids (Class 3)
	☐ Local Delivery	
☐ Catering Food Services	☐ Logs/Poles	☐ TDG - Corrosives (Class 8)
☐ Container	☐ Lumber/Building Supplies	☐ TDG - Other
☐ Courier Services	☐ Mobile Equipment	
☐ Dump Truck	☐ Oil Well Field Services	☐ Waste Removal
☐ Emergency Vehicle	☐ Perishables	☐ Other
☐ Farm Products	☐ Rental	



National Safety Code (NSC) Compliance Review

Number of Driver Files Reviewed:

Driver Records

2

Driver File

1. Does the carrier have a separate file for each driver operating under its Safety Certificate? ☒ Yes ☐ No ☐ N/A

Driver Abstract

2. Does the carrier obtain and review a current driver abstract for every driver at the time of hire? ☒ Yes ☐ No ☐ N/A

You must obtain a driver abstract whenever you hire a new driver (MVAR 37.29(1)(a)). Obtaining a current "N" print driver abstract will allow you to verify that a driver is properly licensed and alerts you to any commercial contraventions, criminal code convictions, prohibitions, etc.

As part of your driver application process, each new driver should complete the *National Safety Code Abstract Personal Request Form* (found in Section 4 of the Carrier Safety Guide) in order to allow you to request their abstract.

3. Does the carrier obtain and review driver abstracts for every driver at least once every 12 months? ☐ Yes ☒ No ☐ N/A

Develop a system to remind yourself of due dates. This includes the dates your drivers' licences must be renewed and the dates you need to request a new driver abstract (MVAR 37.29(1)(a)(ii)).

Abstracts can be requested from ICBC using the *National Safety Code Abstract Request Form* (found in Section 4 of the Carrier Safety Guide).

Driving Incident Records

4. Does the carrier receive driver contraventions, accident reports, etc. within 15 days of an incident? ☒ Yes ☐ No ☐ N/A

Record-keeping

5. Does the carrier follow the NSC record-keeping requirements for:
- a. Employment application and signed company policy ☒ Yes ☐ No ☐ N/A
 - b. Driver abstracts ☒ Yes ☐ No ☐ N/A
 - c. TDG Certificate is applicable ☒ Yes ☐ No ☐ N/A
 - d. Driving incident records, violation tickets, Notice and Orders, Level 3 CVSA inspections, training records/certificates, and any disciplinary action ☒ Yes ☐ No ☐ N/A

e. Accident reports

☒ Yes ☐ No ☐ N/A

You must keep the following records for every driver who operates under your safety certificate:

- driver's licence to be copied at time of hire and upon renewal (retained for term of employment);
- the driver's job application, including information about the driver's experience and skills (retained for term of employment);
- current and historical abstracts, obtained at the time of hire and annually thereafter (retained for the current year plus 4 years)(MVAR 37.30);
- driver-related roadside inspection reports, violation tickets, accident reports to be received within 15 days of the incident (retained for current year plus 4 years)(MVAR37.30); and
- transportation of dangerous goods certificate, if applicable, received at time of hire or when certified (retained for current year and 2 years after expiry)(TDGR 6.6).



Number of Daily Logs Reviewed:

Hours of Service

2

Daily Logs

1. Do the contents of the daily logs and/or time records meet regulatory requirements? ☐ Yes ☒ No ☐ N/A

For drivers who are exempt from the completion of a daily log, you must develop and implement a system for recording hours of service.

A driver that is exempt from the completion of a Daily Log under MVAR 37.18.01(2) is not required to use Schedule 2, and may use another method of record keeping, provided that:

- the driver operates within a radius of 160 km of the home terminal;
- the driver returns to the home terminal each day to begin a minimum of 8 consecutive hours of off-duty time;
- and the carrier maintains accurate and legible records showing, for each day, the driver's duty status and elected cycle, the start and finish times of each duty status, and the total number of hours spent in each duty status.

2. Does the carrier monitor their drivers to ensure compliance with daily on-duty time? ☒ Yes ☐ No ☐ N/A

You are responsible for ensuring your drivers obey the hours of service regulations. Your obligations are to:

- ensure your drivers do not drive after accumulating 13 hours of driving in a day (MVAR 37.13.01(1))
- ensure your drivers do not drive after accumulating 14 hours of on-duty time in a day (MVAR 37.13.01(2))
- keep accurate records that show your drivers are working within the legal limits; and
- ensure your drivers who travel into other provinces or territories know and follow the federal hours of service regulations as found in the federal Commercial Vehicle Drivers Hours of Service Regulations (<http://laws.justice.gc.ca/en/SOR-2005-313/>).

On-duty time begins when a driver begins to work or when a carrier requires a driver to be ready to start work; includes any driving time; and ends when the driver stops work. The following is considered to be on-duty:

- fueling, inspecting, servicing, repairing, conditioning or starting a commercial vehicle;
- traveling as one of two drivers and not resting in the sleeper berth;
- participating in the loading or unloading of a commercial vehicle;
- inspecting or checking the load;
- waiting for the vehicle or load to be inspected;
- waiting along the route because of an accident or other unanticipated events;
- waiting for a commercial vehicle to be serviced, loaded or unloaded; and
- performing any work for any carrier.

3. Does the carrier monitor their drivers to ensure compliance with off- ☒ Yes ☐ No ☐ N/A

duty time?

You must monitor your drivers' hours of rest to ensure that they comply with the daily hours of rest as defined in the Motor Vehicle Act Regulations.

According to MVAR 37.13.02 and 37.13.03, the minimum amounts of off-duty time for drivers are:

Mandatory off-duty time

You must ensure that your drivers do not drive:

- after 13 hours of driving unless the driver takes 8 consecutive hours of off-duty time (MVAR 37.13.02(1));
- after 14 hours of on-duty time unless the driver takes 8 consecutive hours of off-duty time (MVAR 37.13.02(2));
- after 16 hours of elapsed time between 2 off-duty periods of at least 8 consecutive hours (MVAR 37.13.02(3)); or
- unless the driver has taken at least 24 hours off-duty in the previous 14 days (MVAR 37.13.02(4)).

Daily off-duty time

You must ensure that:

- your drivers take at least 10 hours of off-duty time in a day (MVAR 37.13.03(1));
- off-duty time other than the 8 consecutive hours may be taken throughout the day in blocks of no fewer than 30 minutes (MVAR 37.13.03(2)); and
- the total amount of off-duty time taken by a driver in a day must include at least 2 hours of off-duty time that isn't part of the mandatory 8 consecutive hours of off-duty time (MVAR 37.13.03(3)).

4. **Does the carrier monitor their drivers to ensure compliance with hours of service cumulative cycles?** ☐ Yes ☒ No ☐ N/A

Drivers must keep track of their time using one of two cycles (MVAR 37.16.02). Each cycle has a maximum number of hours of on-duty. You must choose one of two cycles for your drivers to follow:

- Cycle 1 - Drivers must not drive after completing 70 on-duty hours in 7 days (MVAR 37.16.03).
- Cycle 2 - Drivers must not drive after completing 120 on-duty hours in 14 days, and must take at least 24 consecutive hours off-duty prior to accumulating 70 hours of on-duty time (MVAR 37.16.04).

A cycle can be reset at any time by taking:

- 36 consecutive hours off to reset Cycle 1 (MVAR 37.16.05(1)(a))
- 72 consecutive hours off to reset Cycle 2 (MVAR 37.16.05(1)(b))

5. **Does the carrier monitor their drivers to ensure compliance with work-shift regulations?** ☒ Yes ☐ No ☐ N/A

You must monitor your drivers to ensure that no driver drives after 16 hours of time has elapsed between two off-duty periods of 8 or more consecutive hours (MVAR 37.13.02(3)).

Every off-duty period of 8 or more consecutive hours resets the work-shift.

6. Does the carrier review the supporting documents to substantiate the information on the daily logs? ☐ Yes ☒ No ☐ N/A

Drivers are required to retain all supporting documents per driver for their current trip with their daily logs. You are obligated to ensure these documents are accurate and to retain them with the logs. Supporting documents may include, but are not limited to:

- fuel receipts,
- bills of lading and shipping documents,
- mill slips,
- interchange receipts,
- accommodation receipts,
- meal receipts,
- customs documents,
- toll payments,
- copies of co-driver's logbook (even if the co-driver is no longer with the driver), and
- any other documents to support the entries in the daily log.

Supporting documents must verify the information shown on the driver's log. You must:

- receive supporting documents from your drivers within 20 days (MVAR 37.18.05(1));
- monitor your drivers' logs against Bills of lading, trip records, border times, license plate readers, fuel times, dispatch, payroll records and any other document that can support the hours of service records;
- file these documents in your driver files within 30 days of when you receive them (MVAR 37.18.05(3)(a)); and
- keep these documents in your files for at least 6 months (MVAR 37.18.05(3)(b)).

7. Does the carrier utilize a corrective progressive disciplinary policy? ☒ Yes ☐ No ☐ N/A

Where you have found non-compliance, you should be able to show that you have taken immediate remedial action such as meaningful training or progressive discipline (MVAR 37.19(2)). Meaningful training and progressive discipline could include:

- a certificate training course
- reinforced direction noted in writing on the driver's file, and
- a progressive company policy, for example:
 - First infraction = verbal warning with notation on driver file
 - Second infraction = written warning with training
 - Third infraction = written warning with 3 day suspension
 - Fourth infraction = written warning with longer suspension up to and including termination
 - Serious infractions (theft/drugs/alcohol) = immediate dismissal

No matter what kind of progressive disciplinary action is used, you must have the driver acknowledge receipt by way of date and signature.

8. Does the carrier receive daily logs and supporting documents from the driver within 20 days? ☒ Yes ☐ No ☐ N/A

You are required to receive the original daily logs from your drivers within 20 days (MVAR 37.18.05(1)). Once received, you should:

- monitor and review the logs to ensure compliance (MVAR 37.15.01); and
- inform drivers of any non-compliance, record the date of the occurrence and document the action taken with the driver (MVAR37.19(3)).

Record-keeping

9. Does the carrier follow the NSC record-keeping requirements for:

- | | |
|--|---|
| a. Daily logs | ☒ Yes ☐ No ☐ N/A |
| b. Supporting documents | ☒ Yes ☐ No ☐ N/A |
| c. Time records when exempt from a daily log | ☐ Yes ☒ No ☐ N/A |

Within 30 days of receiving your drivers' daily logs and/or time records and supporting documents, you must file them in chronological order for each driver at your principal place of business (MVAR 37.18.05(3)(a)). You must keep each of the daily logs and supporting documents in your files for at least 6 months.



Vehicle Maintenance

Number of Vehicle Files Reviewed: 2

Trip Inspections

1. Are defects noted on the trip inspection reports?

☒ Yes ☐ No ☐ N/A

A complete trip inspection must be done on every vehicle before its first trip each day. A post-trip inspection must be done at the end of the final trip of the day. The driver can do this inspection, or you can name someone else to do it (MVAR 37.23(2)).

A properly completed written trip inspection report must provide specific information (MVAR 37.23(4)). Each report must include:

- the licence plate or unit number for the vehicle and/or trailer;
- the date of the inspection;
- the signature of the driver or other person making the report;
- a statement that no defect was discovered, should that be the case;
- a statement about any defect that may affect the operation of any of the following (MVAR 37.22(2)):
 - service brakes, brake adjustments, including trailer connections,
 - parking brakes,
 - steering mechanism,
 - lighting devices and reflectors,
 - tires,
 - horn,
 - windshield wipers,
 - rear-view mirrors,
 - coupling devices,
 - wheels and rims,
 - emergency equipment, or
 - load securement device; and
- a statement about any defect, other than those listed above, that may affect the safe operation of the vehicle.

2. Does the person responsible for repairs to defects sign and date the trip inspection reports, verifying that repairs were completed or not required before the first trip of the day?

☒ Yes ☐ No ☐ N/A

If defects are found during a trip inspection, you or your agent (who may be the driver) must either correct the defects and sign the report to say this correction was done; or sign the report to certify that the defect did not need to be corrected (MVAR 37.26).

Vehicle Maintenance

3. Does the carrier have a recall system to ensure the vehicles are inspected and maintained?

☒ Yes ☐ No ☐ N/A

You are responsible for ensuring the vehicles are maintained and inspections are completed on time. Set up

a simple system to remind yourself when CVIP inspections are due. Decide on a regular maintenance program for each of your vehicles. Schedule each maintenance visit according to a set number of engine hours, kilometers driven, and/or time passed.

4. Are the vehicles inspected, maintained and repaired in accordance with the regulations:

- a. Vehicles are driven with a valid CVIP decal ☒ Yes ☐ No ☐ N/A
- b. Vehicle defects as noted on trip inspections, CVIP or CVSA inspections are addressed in a reasonable time or as directed on CVSA ☐ Yes ☒ No ☐ N/A
- c. Vehicles have not received an Out of Service CVSA inspection for mechanical defects within the last 12 months ☐ Yes ☒ No ☐ N/A
- d. Vehicles have not received a Box 1 or 2 Notice & Order within the last 12 months ☐ Yes ☒ No ☐ N/A
- e. No defects identified during CVIP inspections that should have been repaired during regular maintenance ☐ Yes ☒ No ☐ N/A
- f. Following a preventative maintenance plan ☒ Yes ☐ No ☐ N/A

5. Does the carrier receive CVSAs and Notice & Orders from the driver within 15 days? ☒ Yes ☐ No ☐ N/A

You are responsible for ensuring your drivers are aware of the requirement to deliver all CVSA Inspections and Notice and Orders to you within 15 days of receipt (MVAR 37.29(2)). Checking your carrier profile on a regular basis will provide you with evidence as to whether or not your drivers are complying with this requirement.

Record-keeping

6. Does the carrier follow the NSC record-keeping requirements for:

- a. Manufacturer recall notices ☒ Yes ☐ No ☐ N/A
- b. Vehicle Inspections – CVIP, CVSA, N & O ☒ Yes ☐ No ☐ N/A
- c. Maintenance and repair records/receipts ☒ Yes ☐ No ☐ N/A
- d. Vehicles sold/disposed of from the carrier fleet ☒ Yes ☐ No ☐ N/A
- e. Trip inspection reports ☒ Yes ☐ No ☐ N/A

You must keep the following records for every vehicle operating under your safety certificate:

- a copy of all manufacturer recall notices that affect vehicles operating under your NSC certificate (MVAR 37.29(1)(c)(ii)) (retained for current year plus 4 years);
- all records that show these defects have been corrected (retained for current year plus 4 years);
- all CVSA inspection reports and Notice & Orders (retained for current year plus 4 years);
- all CVIP vehicle inspection reports (MVAR 37.29(1)(c)(i)) (retained for 3 years (MVAR 25.18(1))); and
- records of all repairs done and parts replaced because of an inspection report (MVAR 37.29(1)(c)(ii)) (retained for 3 years (MVAR 25.18(1))).

You must also keep:

- all records (or copies of records) for at least 6 months after you no longer have the vehicle (MVAR 25.18(1)); and
- any safety plan and any scheduled maintenance plan (MVAR 37.29(1)(d)).



Safety Practices

Safety Plan

1. Has the carrier developed a safety plan that demonstrates the ability to maintain practices and procedures necessary to ensure compliance with the regulations and NSC requirements?

a. Company Policy

- i. Hiring policy for drivers ☒ Yes ☐ No ☐ N/A
- ii. Monitoring process for driver performance ☒ Yes ☐ No ☐ N/A
- iii. Monitoring process for hours of service ☒ Yes ☐ No ☐ N/A
- iv. Monitoring process for trip inspection ☒ Yes ☐ No ☐ N/A
- v. Monitoring process for vehicle maintenance ☒ Yes ☐ No ☐ N/A
- vi. Monitoring process for dangerous goods (if applicable) ☐ Yes ☐ No ☒ N/A
- vii. Driver signature and date in agreement with policy ☒ Yes ☐ No ☐ N/A

b. Driver Policy

- i. Driver licensing ☒ Yes ☐ No ☐ N/A
- ii. Obtaining driver abstracts (N print) at least every 12 months ☒ Yes ☐ No ☐ N/A
- iii. Handing in violation tickets, Notices & Orders, roadside inspections and accident reports ☒ Yes ☐ No ☐ N/A
- iv. Hours of service ☒ Yes ☐ No ☐ N/A
- v. Corrective progressive disciplinary policy ☒ Yes ☐ No ☐ N/A
- vi. Driver signature and date in agreement with policy ☒ Yes ☐ No ☐ N/A

c. Vehicle Maintenance Policy

- i. Schedule of maintenance ☒ Yes ☐ No ☐ N/A
- ii. Check sheets for each schedule ☒ Yes ☐ No ☐ N/A
- iii. Trip inspection report ☒ Yes ☐ No ☐ N/A

d. Dangerous Goods/Required Certificates

- i. Defensive driver training certificates ☒ Yes ☐ No ☐ N/A
- ii. First aid training certificates ☒ Yes ☐ No ☐ N/A
- iii. Certificates of Training for Dangerous Goods ☐ Yes ☐ No ☒ N/A

All carriers are required to have a safety plan and scheduled vehicle maintenance plan (MVAR 37.29(d)). A good plan will assist in you meeting your obligations with National Safety Code requirements. At minimum, a good Safety Plan should cover each of the areas listed above. A more detailed breakdown is available in

the training materials provided by your Carrier Safety Inspector.

2. **Is the carrier following their safety plan?**

☒ Yes ☐ No ☐ N/A

As a carrier, you are responsible for all the vehicles that operate under your NSC Safety Certificate and all drivers who drive the vehicles. Following your safety plan will assist you in meeting your obligations under NSC.

As a carrier, you must:

- educate yourself and all drivers who work under your Safety Certificate regarding the applicable regulations;
- ensure that all vehicles that are operated under your Safety Certificate are properly maintained;
- ensure that only competent and qualified drivers drive your vehicles;
- establish policies for tracking hours of service, vehicle maintenance, safety programs; and
- ensure your safety policies are followed.

3. **Does the carrier understand and regularly review their Carrier Profile?**

☒ Yes ☐ No ☐ N/A

The Carrier Profile is a measurement of your on-road performance. It is a summary of all accidents, driver and carrier contraventions, CVSA roadside inspections, and audit results. Regular review of your carrier profile gives you a comprehensive picture of the on-road performance of your drivers and vehicles as well as providing you with a list of documents that must be retained with your records.

Your Carrier Profile is available online through the NSC program website at http://www.th.gov.bc.ca/cvse/national_safety_code/carrier_profile.htm. Additional information regarding how to obtain a BCeID User ID and password in order to access your profile is also available through this website.

Dangerous Goods

4. **Do the shipping papers that accompany Dangerous Goods loads contain all the required information?**

☐ Yes ☐ No ☒ N/A

5. **Does the carrier monitor to ensure that all Transport of Dangerous Goods documentation is complete for each shipment?**

☐ Yes ☐ No ☒ N/A

Record Keeping

6. **Does the carrier maintain all records relating to NSC at the records location address on file with the NSC program office?**

☒ Yes ☐ No ☐ N/A



National Safety Code (NSC) Compliance Review

Action Plan

Implementation Date: 2014-09-30

Carrier should implement a system of recording local hours of service as per MVAR 37.18.01. Carrier should revise their Safety Plan to include reference to the proper name Stryder Motor Freight Canada. Carrier should set up a comprehensive maintenance program for all of their vehicles and utilize check sheets to ensure vehicle is maintained to minimum standards at all times. When auditing log pages for accuracy and compliance, it is suggested comparison is made with all supporting documents.

General Remarks

Carrier is in the business of hauling General Freight through out the Lower Mainland, US and Alberta. Carrier currently has 77 vehicle licenced to their fleet. Carrier was previously operating as AP Transport and recently changed their name to Stryder Motor Freight. This Compliance Review was requested due to false logs found during routine stops at the scales.

September 11, 2014

Authorized Representative Signature

Date

Inspector Signature

Inspector Name, Badge Number, Phone Number and Email Address:

Ted Nager, MV604, 604-575-3438, Ted.Nager@gov.bc.ca

If you have any questions regarding the National Safety Code, please contact your Carrier Safety Inspector using the contact information provided above, or contact the NSC program office in Victoria by phone (250-952-0576) or email (NSC@gov.bc.ca).

NSC #: 00000200300205

NAME: STRYDER MOTORFREIGHT CANADA LTD

Carrier's Safety Performance

Your NSC Carrier Profile is a record that keeps track of indicators of your on-road safety performance. These indicators are:

- * the number and type of at-fault accidents involving the vehicle(s) operating under your Safety Certificate (NSC points are removed from the profile for accidents if it can be determined that the driver was less than 50% at fault);
- * roadside (CVSA) vehicle inspections that put a vehicle or driver out-of-service;
- * contraventions (e.g. violation tickets) which have been deemed guilty; and
- * an overall total of accidents, out-of-service CVSA inspections, and contraventions.

The above items may have occurred while operating in BC or other North American jurisdictions.

Most items recorded on a Carrier Profile are assigned NSC profile points. The following chart indicates your point scores in each of the above categories.

PROFILE SCORES	FLEET SIZE	CONTRA- VENTIONS	OUT OF SERVICE CVSA	ACCIDENTS	OVERALL
STRYDER MOTORFREIGHT	73.85	0.35	1.06	0.05	1.46
ANNUAL PROVIN MEDIAN	20.01 -	0.37	0.19	0.10	0.53

The chart compares your scores to the provincial average for carriers with the same or similar fleet size. Fleet size is determined by the number of days that your vehicle(s) have been operating under your NSC certificate over a 12-month period. Each 365 vehicle licenced days, or portion thereof, is considered to be one vehicle.

For your information, a copy of your Carrier Profile report is enclosed. The report shows information for each of the incidents recorded for your fleet. Please review the profile. If you find any inconsistencies, please report them to the NSC program office by mail, or by faxing a copy of the profile page(s) to (250) 952-0578. Indicate the discrepancy(s) and reason(s) why. If NSC points appear for an accident for which you were not considered to be 50% or more at fault, please provide a copy of this information from your insurance provider. The NSC program office will investigate and, where applicable, make the necessary corrections as promptly as possible.

To monitor your on-road safety performance, you may request a copy of your Carrier Profile on a regular basis. Send a letter, fax, or e-mail to the NSC program office requesting a copy of your Carrier Profile report.

NSC CARRIER: BC 00000200300205

RECIPIENT ADDRESS:
BAMORRIS
REQUESTED ONLINE AND E-MAILED TO
<BARBARA.MORRIS@GOV.BC.CA>

STRYDER MOTORFREIGHT CANADA LTD
7271 NELSON RD
RICHMOND, BC, CAN, V6W 1G3

TOTAL NUMBER OF CURRENTLY LICENSED VEHICLES: 63.00

CARRIER SAFETY RATING

PROFILE STATUS:	SATISFACTORY
AUDIT STATUS:	UNAUDITED
CARRIER SAFETY RATING:	SAT-UNAUDITED

INTERVENTIONS	DATE
WARNING LETTER	2014-11-01
REQUESTED COMPLIANCE REVIEW	2014-09-03
WARNING LETTER	2013-10-01
WARNING LETTER	2012-09-01
TRIGGERED INTERVIEW	2012-09-01
WARNING LETTER	2011-08-01
TRIGGERED INTERVIEW	2011-08-01
TRIGGERED INTERVIEW	2010-07-01
WARNING LETTER	2009-11-01
TRIGGERED INTERVIEW	2008-07-01
WARNING LETTER	2007-07-01

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
PROFILE SCORES AS OF APRIL 2015

NSC CARRIER: BC 00000200300205

MONTH	NUMBER OF VEHICLE DAYS	12 MONTHS TOTAL DAYS	AVERAGE FLEET SIZE	CONTRAVENTIONS PROFILE	CVSA PROFILE	ACCIDENT PROFILE	TOTAL PROFILE SCORE
2015-04	1913	26954	73.85	0.35	1.06	0.05	1.46 **
2015-03	2005	27546	75.47	0.45	1.15	0.05	1.65
2015-02	1822	28137	77.09	0.47	1.13	0.05	1.65
2015-01	2278	28463	77.98	0.46	1.04	0.05	1.55
2014-12	2360	28450	77.95	0.42	1.08	0.05	1.55
2014-11	2126	28529	78.16	0.58	1.04	0.08	1.70
2014-10	2262	28863	79.08	0.61	0.99	0.13	1.73
2014-09	2310	29175	79.93	0.66	0.90	0.10	1.66
2014-08	2432	29318	80.32	0.65	0.78	0.10	1.53
2014-07	2359	29418	80.60	0.65	0.67	0.10	1.42
2014-06	2467	29761	81.54	0.54	0.63	0.10	1.27
2014-05	2620	29828	81.72	0.61	0.66	0.10	1.37
2014-04	2505	29789	81.61	0.64	0.70	0.10	1.44
2014-03	2596	29788	81.61	0.53	0.66	0.10	1.29
2014-02	2148	29807	81.66	0.51	0.77	0.15	1.43
2014-01	2265	30109	82.49	0.58	0.73	0.15	1.46
2013-12	2439	30742	84.22	0.57	0.78	0.14	1.49
2013-11	2460	31294	85.74	0.51	0.87	0.12	1.50
2013-10	2574	31175	85.41	0.49	1.09	0.07	1.65
2013-09	2453	31011	84.96	0.45	1.20	0.09	1.74
2013-08	2532	30830	84.47	0.46	1.31	0.09	1.86
2013-07	2702	30349	83.15	0.49	1.37	0.10	1.96
2013-06	2534	29764	81.55	0.48	1.40	0.10	1.98
2013-05	2581	29209	80.02	0.49	1.46	0.12	2.07
2013-04	2504	28523	78.15	0.52	1.42	0.13	2.07
2013-03	2615	27948	76.57	0.64	1.53	0.16	2.33
2013-02	2450	27303	74.80	0.67	1.52	0.11	2.30
2013-01	2898	26719	73.20	0.60	1.68	0.11	2.39
2012-12	2991	25631	70.22	0.61	1.62	0.09	2.32
2012-11	2341	24463	67.02	0.52	1.61	0.09	2.22
2012-10	2410	23990	65.73	0.53	1.46	0.12	2.11
2012-09	2272	23620	64.71	0.53	1.39	0.09	2.01
2012-08	2051	23409	64.13	0.48	1.31	0.09	1.88
2012-07	2117	23473	64.31	0.44	1.35	0.09	1.88
2012-06	1979	23600	64.66	0.46	1.44	0.15	2.05
2012-05	1895	23848	65.34	0.37	1.24	0.15	1.76
2012-04	1929	24283	66.53	0.42	1.35	0.15	1.92
2012-03	1970	24633	67.49	0.40	1.20	0.12	1.72
2012-02	1866	24813	67.98	0.50	1.24	0.15	1.89
2012-01	1810	24839	68.05	0.54	1.15	0.24	1.93
2011-12	1823	25196	69.03	0.59	1.26	0.23	2.08
2011-11	1868	25503	69.87	0.70	1.37	0.23	2.30
2011-10	2040	25401	69.59	0.70	1.38	0.20	2.28
2011-09	2061	25163	68.94	0.71	1.44	0.20	2.35
2011-08	2115	24864	68.12	0.87	1.50	0.23	2.60

SECTION 2

PAGE: 2

NSC CARRIER: BC 00000200300205

MONTH	NUMBER OF VEHICLE DAYS	12 MONTHS TOTAL DAYS	AVERAGE FLEET SIZE	CONTRAVENTIONS PROFILE	CVSA PROFILE	ACCIDENT PROFILE	TOTAL PROFILE SCORE
2011-07	2244	24527	67.20	0.91	1.52	0.27	2.70
2011-06	2227	24017	65.80	0.87	1.46	0.21	2.54
2011-05	2330	23391	64.08	0.95	1.64	0.19	2.78

**NOTE: THE CARRIER PROFILE STATUS IS DETERMINED BY YOUR PROFILE SCORES IN RELATION TO THRESHOLD LEVELS FOR FLEETS OF SIMILAR SIZE. THE TABLE BELOW SHOWS THE THRESHOLD VALUES AND CORRESPONDING PROFILE STATUS BASED ON YOUR CURRENT FLEET SIZE FOR THE CURRENT MONTH:

	PROFILE STATUS		
	SATISFACTORY	CONDITIONAL	UNSATISFACTORY
CONTRAVENTIONS	< 3.44	3.44- 7.93	> 7.93
CVSA	< 1.71	1.71- 3.70	> 3.70
ACCIDENTS	< 1.64	1.64- 2.63	> 2.63
TOTALS	< 4.10	4.10- 8.09	> 8.09

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CURRENT VEHICLE LIST

NSC CARRIER: BC 00000200300205

VEHICLE REG #	VEHICLE PLATE #	VEH YEAR	VEHICLE MAKE	VEHICLE MODEL	EFFECTIVE DATE	OWNER NAME	GVW	INSPECTION DECAL	DECAL EXPIRY DATE
00187999	HV7772	2000	VOLVO		2014-11-18	s.22	00046500	EQ41594	2014-12-31
00219747	15700P	2007	KENWORTH		2014-08-01	STRYDER MOTORFREIGHT CANADA	00046500	EP76082	2014-09-30
00263666		2000	KENWORTH		2015-03-02	STRYDER MOTORFREIGHT CANADA	00046500	ER40049	2015-04-30
00343911	11841P	2000	KENWORTH		2014-08-01	STRYDER MOTORFREIGHT CANADA	00046500	EQ08694	2014-11-30
00597447	01353P	2007	FREIGHTLIN		2014-08-01	STRYDER MOTORFREIGHT CANADA	00046500	EQ09892	2014-12-31
00967378	17948P	2008	KENWORTH		2015-02-28	STRYDER MOTORFREIGHT CANADA	00046500	EP34881	2015-08-31
01065757	20446P	2008	FREIGHTLIN		2015-01-02	STRYDER MOTORFREIGHT CANADA	00046500	ER80691	2015-06-30
01358658	P87530	2003	KENWORTH		2014-08-01	STRYDER MOTORFREIGHT CANADA	00046500	EP74999	2014-10-31
01833965		2004	PETERBILT		2015-04-09	STRYDER MOTORFREIGHT CANADA	00046500	ES17326	2015-07-31
01846874	18531P	2004	PETERBILT		2014-08-01	STRYDER MOTORFREIGHT CANADA	00046500	EP77608	2014-09-30
02209430	17593P	2000	KENWORTH		2014-11-27	STRYDER MOTORFREIGHT CANADA	00063500	AB32823	2015-02-28
02211029	03999P	2003	FREIGHTLIN		2014-08-01	STRYDER MOTORFREIGHT CANADA	00046500	EQ77770	2015-01-31
02485930		2005	PETERBILT		2015-03-29	STRYDER MOTORFREIGHT CANADA	00046500	ER80914	2015-06-30
02777288	08688P	2005	FREIGHTLIN		2014-08-01	STRYDER MOTORFREIGHT CANADA	00046500	EQ78120	2015-01-31
03031384	17613P	2006	FREIGHTLIN		2014-08-05	STRYDER MOTORFREIGHT CANADA	00046500	EP50318	2014-08-31
03091059	17610P	2008	FREIGHTLIN		2014-08-01	STRYDER MOTORFREIGHT CANADA	00046500	EQ09835	2014-11-30
03264597	17941P	2005	KENWORTH		2014-08-01	STRYDER MOTORFREIGHT CANADA	00046500	EP65225	2014-09-30
03382914	JE7195	2009	INTERNATNA	2WHDR	2015-03-20	PENSKE TRUCK LEASING CANADA	00046500	PL05576	2016-02-29
03446085	23736P	2009	FREIGHTLIN		2015-02-02	STRYDER MOTORFREIGHT CANADA	00046500	ER05618	2015-02-28
03526127		2006	FREIGHTLIN		2015-03-06	STRYDER MOTORFREIGHT CANADA	00046500	ER38394	2015-03-31
03589084	17954P	2006	FREIGHTLIN		2014-08-01	STRYDER MOTORFREIGHT CANADA	00046500	EQ09833	2014-11-30
03618114	17590P	2007	FREIGHTLIN		2014-08-01	BODKIN LEASING CORPORATION	00046500	EQ77785	2015-01-31
03654597	HB9363	2003	FORD		2014-08-01	STRYDER MOTORFREIGHT CANADA	00007700		
03747713		2007	FREIGHTLIN		2015-02-24	BODKIN LEASING CORPORATION	00046500	ES32495	2015-08-31
03773135	10468P	2007	KENWORTH		2014-08-01	STRYDER MOTORFREIGHT CANADA	00046500	EP42168	2014-09-30
03919308	12991P	2007	KENWORTH		2014-08-01	STRYDER MOTORFREIGHT CANADA	00046500	EP42208	2014-10-31
03922480	JB8957	2009	FREIGHTLIN		2014-12-09	PENSKE TRUCK LEASING CANADA	00046500	ER32379	2015-04-30
06944009	1084WL	1990	KENWORTH		2014-08-13	STRYDER MOTORFREIGHT CANADA	00029500	EQ79924	2015-02-28
08618565	11838P	2007	PETERBILT		2014-08-01	STRYDER MOTORFREIGHT CANADA	00046500	EQ56064	2015-01-31
09845578	P93885	2007	FREIGHTLIN		2014-08-01	STRYDER MOTORFREIGHT CANADA	00046500	EP51381	2014-08-31
09861648		2006	VOLVO		2015-02-05	STRYDER MOTORFREIGHT CANADA	00046500	EQ79991	2015-08-31
10070282	08677P	2006	FREIGHTLIN		2014-08-01	STRYDER MOTORFREIGHT CANADA	00046500	EQ02722	2014-10-31
10299186	21781P	2012	KENWORTH		2014-08-01	COAST CAPITAL SAVINGS	00046500	EQ55617	2014-12-31
10302250	22260P	2007	FREIGHTLIN		2014-10-09	STRYDER MOTORFREIGHT CANADA	00046500	EQ09878	2014-12-31
10392576	HX5509	2012	FREIGHTLIN		2014-12-09	PENSKE TRUCK LEASING CANADA	00047500	PK33208	2015-09-30
10566182	24623P	2013	FREIGHTLIN		2015-04-13	STRYDER MOTORFREIGHT CANADA	00046500	ER66812	2015-08-31
10581669		2013	PETERBILT		2015-04-18	STRYDER MOTORFREIGHT CANADA	00046500	ES41357	2015-09-30
10589942	21943P	2013	FREIGHTLIN		2015-01-05	PENSKE TRUCK LEASING CANADA	00046500	PK33205	2015-09-30
10618315	10926P	2012	INTERNATNA		2015-03-13	ROYAL BANK OF CANADA (LSR)	00046500	EQ80006	2015-09-30
10618690	10928P	2012	INTERNATNA		2014-08-01	ROYAL BANK OF CANADA (LSR)	00046500	EP46680	2014-09-30
10618844	23067P	2012	INTERNATNA		2014-11-19	ROYAL BANK OF CANADA (LSR)	00046500	EQ79918	2015-02-28
10627033	16145P	2013	FREIGHTLIN		2014-08-01	CANADIAN WESTERN BANK	00046500	EP74973	2014-09-30
10691202		2005	FREIGHTLIN		2015-03-06	STRYDER MOTORFREIGHT CANADA	00046500	ER67067	2015-06-30
10693340	21789P	2008	KENWORTH		2014-08-01	STRYDER MOTORFREIGHT CANADA	00046500	EP40129	2014-11-30
10700488	23502P	2008	FREIGHTLIN		2015-01-05	PENSKE TRUCK LEASING CANADA	00046500	PK13524	2015-08-31

SECTION 3

PAGE: 4

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CURRENT VEHICLE LIST

NSC CARRIER: BC 00000200300205

VEHICLE REG #	VEHICLE PLATE #	VEH YEAR	VEHICLE MAKE	VEHICLE MODEL	EFFECTIVE DATE	OWNER NAME	GVW	INSPECTION DECAL	DECAL EXPIRY DATE
10754387	JG1596	2014	FREIGHTLIN		2015-03-06	PENSKE TRUCK LEASING CANADA	00063500	PK01630	2015-03-31
10763020	HF4977	2014	FREIGHTLIN		2014-12-10	PENSKE TRUCK LEASING CANADA	00063500	PK13455	2015-03-31
10804310	23069P	2014	FREIGHTLIN		2014-11-20	CANADIAN WESTERN BANK	00046500	EQ77844	2015-02-28
10864127	23046P	2008	FREIGHTLIN		2014-10-14	STRYDER MOTORFREIGHT CANADA	00046500	EP85388	2014-11-30
10875610		2007	FREIGHTLIN		2015-04-08	STRYDER MOTORFREIGHT CANADA	00046500	ES36740	2015-08-31
10890783	21792P	2003	PETERBILT		2014-12-16	2258756 ONTARIO LIMITED LSR	00046500	ER05364	2015-02-28
10925112	16580P	2007	FREIGHTLIN		2014-08-01	STRYDER MOTORFREIGHT CANADA	00046500	EP42179	2014-09-30
10955643	20426P	2014	FREIGHTLIN		2015-02-27	PENSKE TRUCK LEASING CANADA	00046500	PK13486	2015-11-30
11018738	19098P	2007	KENWORTH		2014-08-01	STRYDER MOTORFREIGHT CANADA	00046500	EP40017	2014-08-31
11080667	20447P	2014	FREIGHTLIN		2015-01-05	PENSKE TRUCK LEASING CANADA	00047000	AA	
11101840	09174P	2015	FREIGHTLIN		2014-08-11	STRYDER MOTORFREIGHT CANADA	00046500	EQ50066	2015-02-28
11155793	JB8967	2015	FREIGHTLIN		2015-03-20	PENSKE TRUCK LEASING CANADA	00046500	S	
11177916	24067P	2015	FREIGHTLIN		2015-03-02	MERCEDES-BENZ FIN SERVIC	00046500	ER13267	2015-07-31
11265691	20439P	2014	INTERNATNA		2014-12-19	PENSKE TRUCK LEASING CANADA	00046500	PK27099	2015-05-31
11313757	20443P	2013	FREIGHTLIN		2015-01-01	PENSKE TRUCK LEASING CANADA	00047000	AB24131	2015-06-30
11313780	20444P	2013	FREIGHTLIN		2015-01-01	PENSKE TRUCK LEASING CANADA	00047000	AB24128	2015-06-30
11401751		2016	VOLVO		2015-04-08	CANADIAN WESTERN BANK	00046500	AB19988	2015-09-30
11428433		2016	FREIGHTLIN		2015-05-01	STRYDER MOTORFREIGHT CANADA	00046500	EQ80040	2015-10-31

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 00025509 PLATE 21326P 00 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-05-24	CVIP	S5716	EQ10708	9623964	INSPECTION PASSED
2014-05-24	CVIP	S5716		9623963	VEHICLE INSPECTION REJECTED
2013-11-28	CVIP	S5716	EP03755	9250644	INSPECTION PASSED
2013-11-28	CVIP	S5716		9250643	VEHICLE INSPECTION REJECTED
2013-10-30	CVSA				INSPECTION PASSED
2013-08-21	CVSA			8206877	INSPECTION PASSED
2013-07-11	CVSA				VIOLATIONS PRESENT
2013-05-23	CVIP	S5716	EM41769	8943621	INSPECTION PASSED
2013-05-23	CVIP	S5716		8943599	VEHICLE INSPECTION REJECTED
2013-05-01	CVSA				INSPECTION PASSED
2013-02-26	CVSA				INSPECTION PASSED
2013-01-25	CVSA			8123581	VIOLATIONS PRESENT
2012-11-27	CVSA				INSPECTION PASSED
2012-11-24	CVIP	S5716	EL42047	8716071	INSPECTION PASSED
2012-11-24	CVIP	S5716		8716065	VEHICLE INSPECTION REJECTED
2012-08-01	CVSA			8102221	VIOLATIONS PRESENT
2012-05-31	CVIP	S5716	EJ59370	8519186	INSPECTION PASSED
2012-05-26	CVSA				INSPECTION PASSED

VEHICLE REGISTRATION: 00027586 PLATE 6371GM 00 INTERNATNA

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-08-16	CVIP	S6978	EQ79927	9819344	INSPECTION PASSED
2014-02-18	CVIP	S6978	EN42529	9407775	INSPECTION PASSED
2014-02-18	CVIP	S6978		9407774	VEHICLE INSPECTION REJECTED
2014-02-04	CVIP	S6978	RD04009	9379049	VEHICLE INSPECTION REJECTED
2013-07-03	CVIP	S6978	EL41861	9009170	INSPECTION PASSED
2012-12-20	CVIP	S6978	EL40240	8743782	INSPECTION PASSED
2012-06-23	CVIP	S6978	EJ39978	8546751	INSPECTION PASSED

VEHICLE REGISTRATION: 00042508 PLATE 08695P 2007 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-09-18	CVSA			8106633	VIOLATIONS PRESENT
2012-09-15	CVIP	S5944	EK87868	8639325	INSPECTION PASSED

VEHICLE REGISTRATION: 00131214 PLATE 07 KENWORTH

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-05-07	CVIP	S6268	EP40112	9588437	INSPECTION PASSED
2014-05-07	CVIP	S6268		9588436	VEHICLE INSPECTION REJECTED
2014-01-22	CVSA			8272224	INSPECTION PASSED
2013-11-23	CVIP	S4683	EN85963	9232329	INSPECTION PASSED
2013-11-23	CVIP	S4683		9232328	VEHICLE INSPECTION REJECTED
2013-07-25	CVSA			8195323	INSPECTION PASSED

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 00187999 PLATE HV7772 00 VOLVO

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-12-27	CVIP	S7076	ES07753	10109244	INSPECTION PASSED
2014-12-27	CVIP	S7076		10109243	VEHICLE INSPECTION REJECTED

VEHICLE REGISTRATION: 00190625 PLATE P84508 02 VOLVO

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-12-02	CVIP	S6978	EQ79971	10064238	INSPECTION PASSED
2014-12-02	CVIP	S6978		10064237	VEHICLE INSPECTION REJECTED
2014-07-25	CVSA				VIOLATIONS PRESENT
2014-05-25	CVIP	S6978	EP88676	9624005	INSPECTION PASSED
2014-03-11	CVSA				VIOLATIONS PRESENT
2013-12-28	CVSA				INSPECTION PASSED
2013-10-10	CVIP	S6978	EN42424	9155512	INSPECTION PASSED
2013-10-10	CVIP	S6978		9155500	VEHICLE INSPECTION REJECTED
2013-03-31	CVIP	S6978	EL41733	8859922	INSPECTION PASSED
2013-02-19	CVIP	S6978	RD04009	8806670	VEHICLE INSPECTION REJECTED
2012-08-31	CVSA			8104829	VIOLATIONS PRESENT
2012-07-27	CVIP	S6978	EK17526	8586263	INSPECTION PASSED

VEHICLE REGISTRATION: 00193960 PLATE 07 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-11-02	CVIP	S5708	EL42344	8694242	INSPECTION PASSED
2012-05-18	CVSA			8094795	INSPECTION PASSED

VEHICLE REGISTRATION: 00211494 PLATE 27161D 2007 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-12-11	CVSA			8115204	INSPECTION PASSED

VEHICLE REGISTRATION: 00219747 PLATE 15700P KENS

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-04-06	CVSA				INSPECTION PASSED
2015-03-12	CVIP	S4168	ES54006	10258316	INSPECTION PASSED
2015-03-11	CVSA				INSPECTION PASSED
2014-09-24	CVIP	S5716	ER13502	9909146	INSPECTION PASSED
2014-05-27	CVSA				INSPECTION PASSED
2014-03-04	CVSA			8292740	INSPECTION PASSED
2014-03-03	CVIP	S5708	EP76082	9434861	INSPECTION PASSED
2014-03-03	CVIP	S5708		9434860	VEHICLE INSPECTION REJECTED
2013-12-10	CVSA				INSPECTION PASSED
2013-09-12	CVIP	S5708	EN66628	9117433	INSPECTION PASSED
2013-09-12	CVIP	S5708		9117430	VEHICLE INSPECTION REJECTED
2013-07-09	CVSA				INSPECTION PASSED

CVSE-NSCSP351 (P)
2015-05-11

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 00239977 PLATE P86209 2000 KENWORTH

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-03-25	CVSA			8144028	VIOLATIONS PRESENT
2012-11-29	CVSA				INSPECTION PASSED
2012-11-28	CVSA				INSPECTION PASSED
2012-11-24	CVIP	S5716	EL42048	8716076	INSPECTION PASSED
2012-11-24	CVIP	S5716		8716074	VEHICLE INSPECTION REJECTED
2012-11-20	CVSA				INSPECTION PASSED
2012-11-16	CVSA				INSPECTION PASSED
2012-10-17	CVSA				INSPECTION PASSED
2012-07-30	CVSA				INSPECTION PASSED
2012-07-26	CVSA				INSPECTION PASSED
2012-07-19	CVSA				INSPECTION PASSED
2012-06-27	CVSA				INSPECTION PASSED
2012-06-05	CVSA				VIOLATIONS PRESENT
2012-05-30	CVSA				INSPECTION PASSED
2012-05-30	CVIP	S5716	EJ59368	8517306	INSPECTION PASSED
2012-05-30	CVIP	S5716		8517287	VEHICLE INSPECTION REJECTED

VEHICLE REGISTRATION: 00263666 PLATE 00 KENWORTH

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-04-26	CVIP	S7076		10352865	VEHICLE INSPECTION REJECTED
2015-04-26	CVIP	S7076	ES91480	10352866	INSPECTION PASSED
2015-04-06	CVSA				VIOLATIONS PRESENT
2014-10-31	CVIP	S4676	ER40049	10000430	INSPECTION PASSED
2014-10-31	CVIP	S4676		10000429	VEHICLE INSPECTION REJECTED
2014-08-28	CVSA			8372163	INSPECTION PASSED
2014-08-08	CVSA				INSPECTION PASSED
2014-05-12	CVSA				VIOLATIONS PRESENT
2014-04-26	CVIP	S4676	EQ09131	9557737	INSPECTION PASSED
2014-04-21	CVSA				INSPECTION PASSED
2014-02-18	CVSA				INSPECTION PASSED
2013-12-06	CVSA				INSPECTION PASSED
2013-10-18	CVIP	S4676	EN87030	9163699	INSPECTION PASSED
2013-10-16	CVIP	S4676	EN87023	9160955	INSPECTION PASSED
2013-06-04	CVSA				INSPECTION PASSED
2012-05-23	CVSA			8099252	INSPECTION PASSED

VEHICLE REGISTRATION: 00327002 PLATE 18729B 2000 WABASH

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-02-13	CVSA			8129560	INSPECTION PASSED

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 00327083 PLATE 16585P 2007 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-05-02	CVSA			8323016	INSPECTION PASSED
2013-08-29	CVIP	S6948	EN28213	9099792	INSPECTION PASSED
2013-05-19	CVSA			8166361	VIOLATIONS PRESENT
2013-04-24	CVSA				INSPECTION PASSED
2013-03-21	CVSA			8142640	VIOLATIONS PRESENT
2013-02-06	CVIP	S6948	EL92934	8793501	INSPECTION PASSED
2012-10-18	CVSA				INSPECTION PASSED
2012-08-24	CVIP	S6978	EK17566	8614934	INSPECTION PASSED

VEHICLE REGISTRATION: 00343911 PLATE 11841P 00 KENWORTH

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-05-06	CVIP	S1005	ES66593	10379287	INSPECTION PASSED
2015-05-06	CVIP	S1005		10379286	VEHICLE INSPECTION REJECTED
2014-11-04	CVIP	S1005	ER52626	10007951	INSPECTION PASSED
2014-11-04	CVIP	S1005		10007950	VEHICLE INSPECTION REJECTED
2014-05-01	CVIP	S1005	EQ08694	9574043	INSPECTION PASSED
2014-05-01	CVIP	S1005		9574042	VEHICLE INSPECTION REJECTED
2013-10-18	CVIP	S6978	EN42431	9163904	INSPECTION PASSED
2013-10-18	CVIP	S6978		9163278	VEHICLE INSPECTION REJECTED
2013-04-27	CVIP	S4676	EM58208	8899845	INSPECTION PASSED
2013-01-10	CVSA				INSPECTION PASSED

VEHICLE REGISTRATION: 00356628 PLATE 08690P KW

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-01-07	CVSA				VIOLATIONS PRESENT
2012-11-13	CVIP	S6266	EL02866	8703568	INSPECTION PASSED
2012-11-13	CVIP	S6266		8703565	VEHICLE INSPECTION REJECTED
2012-09-21	CVSA				INSPECTION PASSED
2012-08-31	CVSA			8104790	INSPECTION PASSED

VEHICLE REGISTRATION: 00413629 PLATE 16150P FRHT

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-03-25	CVSA				INSPECTION PASSED
2014-02-21	CVSA				VIOLATIONS PRESENT
2014-01-22	CVSA				VIOLATIONS PRESENT
2014-01-08	CVIP	S6285	EP36744	9325041	INSPECTION PASSED
2014-01-08	CVIP	S6285		9325039	VEHICLE INSPECTION REJECTED
2013-11-18	CVSA				INSPECTION PASSED
2013-11-13	CVSA				INSPECTION PASSED
2013-08-16	CVSA			8204051	VIOLATIONS PRESENT
2013-08-12	CVSA				INSPECTION PASSED
2013-07-18	CVSA				INSPECTION PASSED

CVSE-NSCSP351 (P)
2015-05-11

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 00414882 PLATE 22499P 07 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-09-20	CVIP	S4438	ER06032	9900275	INSPECTION PASSED
2014-07-14	CVSA				INSPECTION PASSED
2014-03-10	CVIP	S4438	EP79243	9450208	INSPECTION PASSED
2014-03-10	CVIP	S4438		9450207	VEHICLE INSPECTION REJECTED
2014-02-05	CVSA			8280013	INSPECTION PASSED
2013-09-25	CVSA				INSPECTION PASSED
2013-09-21	CVIP	S6978	EN42412	9131337	INSPECTION PASSED
2013-09-21	CVIP	S6978		9131319	VEHICLE INSPECTION REJECTED
2013-09-11	CVSA				INSPECTION PASSED
2013-08-27	CVSA				INSPECTION PASSED
2013-08-01	CVSA			8199010	INSPECTION PASSED
2013-03-21	CVIP	S4438	EM35738	8846797	INSPECTION PASSED

VEHICLE REGISTRATION: 00457095 PLATE DEALER 2000 SUZUKI

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-12-19	CVSA			8430960	INSPECTION PASSED

VEHICLE REGISTRATION: 00547686 PLATE 05 PETERBILT

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-11-01	CVIP	S4676	ER40063	10000443	INSPECTION PASSED
2014-10-09	CVSA			8389511	VIOLATIONS PRESENT
2014-04-30	CVIP	S6268	EP40101	9568118	INSPECTION PASSED
2014-04-30	CVIP	S6268		9568116	VEHICLE INSPECTION REJECTED
2014-01-26	CVSA			8273942	VIOLATIONS PRESENT
2013-10-25	CVIP	S6268	EN28127	9174626	INSPECTION PASSED
2013-04-26	CVIP	S6268	EL95411	8899785	INSPECTION PASSED
2013-04-26	CVIP	S6268		8899780	VEHICLE INSPECTION REJECTED
2013-04-12	CVSA			8152060	VIOLATIONS PRESENT
2012-10-12	CVIP	S6268	EK87397	8670137	INSPECTION PASSED
2012-10-12	CVIP	S6268		8670131	VEHICLE INSPECTION REJECTED
2012-08-13	CVSA			8103159	INSPECTION PASSED

VEHICLE REGISTRATION: 00582523 PLATE 12998P FRHT

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-12-19	CVSA				INSPECTION PASSED
2013-09-27	CVIP	S7079	EN35500	9137375	INSPECTION PASSED
2013-07-26	CVSA				INSPECTION PASSED
2013-07-13	CVSA				INSPECTION PASSED
2013-06-12	CVSA				INSPECTION PASSED
2013-05-23	CVSA			8168223	VIOLATIONS PRESENT
2013-03-12	CVSA			8138960	INSPECTION PASSED
2013-03-02	CVIP	S6948	EL92964	8823309	INSPECTION PASSED
2012-09-17	CVSA				INSPECTION PASSED
2012-06-16	CVIP	S6948	EJ60592	8538705	INSPECTION PASSED

SECTION 5

PAGE: 10

CVSE-NSCSP351 (P)
2015-05-11

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 00582523 PLATE 05748P 2001 FRTLINER (CONTINUED)
2012-05-26 CVSA 8095429 VIOLATIONS PRESENT
2012-05-11 CVSA INSPECTION PASSED

VEHICLE REGISTRATION: 00594526 PLATE 10659P 01 PETERBILT

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-06-05	CVIP	S6903	EJ60459	8525868	INSPECTION PASSED

VEHICLE REGISTRATION: 00597447 PLATE 01353P 2007 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-04-19	CVSA			8437429	INSPECTION PASSED
2014-12-22	CVIP	S6948	ER66760	10104320	INSPECTION PASSED
2014-12-22	CVIP	S6948		10104319	VEHICLE INSPECTION REJECTED
2014-09-10	CVSA			8376410	INSPECTION PASSED
2014-09-10	CVSA			8376463	INSPECTION PASSED
2014-07-13	CVSA				INSPECTION PASSED
2014-06-20	CVIP	S6948	EQ09892	9689711	INSPECTION PASSED
2014-06-20	CVIP	S6948		9689710	VEHICLE INSPECTION REJECTED
2013-12-24	CVIP	S6948	EP04476	9304558	INSPECTION PASSED
2013-08-16	CVSA				INSPECTION PASSED
2013-08-11	CVSA			8201580	VIOLATIONS PRESENT
2013-06-29	CVIP	S6948	EN00426	9005513	INSPECTION PASSED
2013-05-31	CVSA				INSPECTION PASSED
2013-05-14	CVSA			8164330	OUT OF SERVICE
2013-04-21	CVSA			8155510	VIOLATIONS PRESENT
2013-04-03	CVSA				INSPECTION PASSED
2012-12-21	CVSA				INSPECTION PASSED
2012-12-20	CVIP	S6948	EL42239	8744150	INSPECTION PASSED
2012-11-20	CVSA				INSPECTION PASSED
2012-11-15	CVSA				OUT OF SERVICE
2012-09-14	CVSA				INSPECTION PASSED
2012-08-15	CVSA				INSPECTION PASSED
2012-08-01	CVSA			8102216	INSPECTION PASSED
2012-06-10	CVSA				INSPECTION PASSED
2012-06-09	CVIP	S6948	EJ60587	8531001	INSPECTION PASSED
2012-06-06	CVSA				VIOLATIONS PRESENT
2012-06-05	CVSA			8096503	OUT OF SERVICE
2012-05-24	CVSA				INSPECTION PASSED

VEHICLE REGISTRATION: 00719501 PLATE 00507P FRHT

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-01-08	CVSA				INSPECTION PASSED
2014-01-07	CVIP	S6978		9321611	VEHICLE INSPECTION REJECTED
2014-01-07	CVIP	S6978	EN42490	9321612	INSPECTION PASSED
2013-10-24	CVSA				INSPECTION PASSED
2013-09-05	CVSA				INSPECTION PASSED
2013-09-04	CVSA			8212632	VIOLATIONS PRESENT

SECTION 5

PAGE: 11

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 00719501		PLATE 21335P	07 FREIGHTLIN	(CONTINUED)	
2013-06-21	CVIP	S6948	EN00412	8991828	INSPECTION PASSED
2013-03-08	CVSA				INSPECTION PASSED
2012-12-18	CVSA				OUT OF SERVICE
2012-12-15	CVIP	S6948	EL42237	8738760	INSPECTION PASSED
2012-12-14	CVSA				INSPECTION PASSED
2012-10-17	CVSA				INSPECTION PASSED
2012-10-16	CVSA				INSPECTION PASSED
2012-10-09	CVSA				INSPECTION PASSED
2012-08-23	CVSA				INSPECTION PASSED
2012-07-05	CVSA			8099727	VIOLATIONS PRESENT
2012-06-27	CVIP	S6948	EJ60606	8552106	INSPECTION PASSED

VEHICLE REGISTRATION: 00864260 PLATE 84833C 2008 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-04-19	CVSA			8437429	INSPECTION PASSED
2013-04-12	CVSA			8152060	VIOLATIONS PRESENT
2013-01-07	CVSA			8118330	INSPECTION PASSED

VEHICLE REGISTRATION: 00871139 PLATE 19889P 2008 VOLVO

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-09-30	CVSA			8385401	INSPECTION PASSED
2013-12-02	CVIP	S4168	EP15385	9259450	INSPECTION PASSED
2013-12-02	CVIP	S4168		9259446	VEHICLE INSPECTION REJECTED
2013-08-26	CVSA			8210010	INSPECTION PASSED
2013-08-20	CVSA			8206221	VIOLATIONS PRESENT
2013-05-21	CVIP	S4168	EM98714	8937222	INSPECTION PASSED
2013-05-21	CVIP	S4168		8937217	VEHICLE INSPECTION REJECTED
2013-03-23	CVSA			8143700	VIOLATIONS PRESENT
2013-02-28	CVSA			8135092	VIOLATIONS PRESENT
2013-01-06	CVSA			8118064	INSPECTION PASSED
2012-11-29	CVIP	S4168	EL18686	8721771	INSPECTION PASSED
2012-11-29	CVIP	S4168		8721766	VEHICLE INSPECTION REJECTED
2012-09-06	CVSA			8105270	INSPECTION PASSED
2012-08-15	CVSA			8103336	VIOLATIONS PRESENT

VEHICLE REGISTRATION: 00950178 PLATE 19875P 02 KENWORTH

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-04-24	CVIP	S6978	EL41772	8899669	INSPECTION PASSED
2013-04-24	CVIP	S6978		8899651	VEHICLE INSPECTION REJECTED
2012-11-19	CVSA				VIOLATIONS PRESENT
2012-10-20	CVIP	S6978	EK18168	8678115	INSPECTION PASSED
2012-10-04	CVSA				VIOLATIONS PRESENT
2012-07-09	CVSA				INSPECTION PASSED

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 00967378 PLATE 17948P KENS

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-04-06	CVSA				INSPECTION PASSED
2015-02-21	CVIP	S7225	ES35052	10217977	INSPECTION PASSED
2015-02-03	CVSA				INSPECTION PASSED
2014-09-06	CVSA			8375070	INSPECTION PASSED
2014-08-14	CVIP	S6865	EQ54823	9815211	INSPECTION PASSED
2013-11-14	CVSA			8240271	INSPECTION PASSED
2013-10-15	CVSA				INSPECTION PASSED
2013-07-01	CVSA				INSPECTION PASSED
2013-06-01	CVIP	S6865	EL80070	8958967	INSPECTION PASSED
2013-05-04	CVSA			8160010	INSPECTION PASSED
2013-02-26	CVSA			8133854	INSPECTION PASSED
2012-12-16	CVIP	S6865	EK36298	8739120	INSPECTION PASSED
2012-10-24	CVSA				INSPECTION PASSED
2012-10-16	CVSA			8109593	INSPECTION PASSED
2012-06-28	CVIP	S6865	EJ66581	8553799	INSPECTION PASSED
2012-05-14	CVSA			8094003	INSPECTION PASSED

VEHICLE REGISTRATION: 01065757 PLATE 20446P FRHT

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-01-24	CVSA				INSPECTION PASSED
2015-01-19	CVSA				VIOLATIONS PRESENT
2014-11-01	CVSA			8397110	VIOLATIONS PRESENT
2014-07-21	CVSA				INSPECTION PASSED
2014-06-10	CVIP	S5688		9665886	VEHICLE INSPECTION REJECTED
2014-06-10	CVIP	S5688	EQ40426	9665887	INSPECTION PASSED
2014-06-05	CVSA				INSPECTION PASSED
2014-05-26	CVSA				INSPECTION PASSED

VEHICLE REGISTRATION: 01192322 PLATE 21331P 03 KENWORTH

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-04-17	CVIP	S4438	EQ05410	9538978	INSPECTION PASSED
2014-04-17	CVIP	S4438		9538977	VEHICLE INSPECTION REJECTED
2014-01-16	CVSA				INSPECTION PASSED
2013-11-15	CVSA				INSPECTION PASSED
2013-10-15	CVIP	S7079	EN35455	9159002	INSPECTION PASSED
2013-10-15	CVIP	S7079		9158981	VEHICLE INSPECTION REJECTED
2013-09-12	CVSA				INSPECTION PASSED
2013-08-19	CVSA			8205268	INSPECTION PASSED
2013-06-11	CVSA				INSPECTION PASSED
2013-05-28	CVSA			8170311	INSPECTION PASSED
2013-05-08	CVSA				VIOLATIONS PRESENT
2013-04-21	CVIP	S6978	EL41766	8889458	INSPECTION PASSED
2012-12-19	CVSA				INSPECTION PASSED
2012-10-26	CVSA				INSPECTION PASSED

SECTION 5

PAGE: 13

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 01192322	PLATE 21331P	03 KENWORTH	(CONTINUED)
2012-10-04 CVIP S6978	EK18149	8662244	INSPECTION PASSED
2012-10-04 CVIP S6978		8662189	VEHICLE INSPECTION REJECTED
2012-10-03 CVSA		8108321	VIOLATIONS PRESENT

VEHICLE REGISTRATION: 01206824	PLATE 13888Y	2003 GREAT DANE	
DATE	ACTION	FACILITY#	DECAL #
2014-05-15	CVSA		
		MICROFILM #	OUTCOME
		8327663	VIOLATIONS PRESENT

VEHICLE REGISTRATION: 01310072	PLATE P93888	07 FREIGHTLIN	
DATE	ACTION	FACILITY#	DECAL #
2012-05-22	CVIP	S6978	EJ39924
2012-05-22	CVIP	S6978	
		MICROFILM #	OUTCOME
		8508758	INSPECTION PASSED
		8508725	VEHICLE INSPECTION REJECTED

VEHICLE REGISTRATION: 01326848	PLATE 02949D	2008 UTILITY	
DATE	ACTION	FACILITY#	DECAL #
2013-09-05	CVSA		
		MICROFILM #	OUTCOME
		8213152	VIOLATIONS PRESENT

VEHICLE REGISTRATION: 01358658	PLATE P87530	03 KENWORTH	
DATE	ACTION	FACILITY#	DECAL #
2015-04-17	CVIP	S7076	
2015-04-17	CVIP	S7076	ES74084
2014-10-31	CVIP	S4676	ER40047
2014-04-26	CVIP	S6903	EP74999
2014-01-08	CVSA		
2013-10-26	CVIP	S6903	EN28787
2013-10-20	CVSA		
2013-09-05	CVSA		
2013-04-29	CVIP	S6903	EM40728
2012-10-07	CVIP	S6903	EK03538
2012-06-13	CVSA		
		MICROFILM #	OUTCOME
		10333084	VEHICLE INSPECTION REJECTED
		10333085	INSPECTION PASSED
		9998308	INSPECTION PASSED
		9557798	INSPECTION PASSED
		8264890	INSPECTION PASSED
		9174902	INSPECTION PASSED
		8228696	INSPECTION PASSED
		8213152	VIOLATIONS PRESENT
		8902480	INSPECTION PASSED
		8664728	INSPECTION PASSED
		8097527	INSPECTION PASSED

VEHICLE REGISTRATION: 01421888	PLATE 23100Y	2004 GREAT DANE	
DATE	ACTION	FACILITY#	DECAL #
2012-10-10	CVSA		
		MICROFILM #	OUTCOME
		8108811	INSPECTION PASSED

VEHICLE REGISTRATION: 01486441	PLATE 55520B	2004 GREAT DANE	
DATE	ACTION	FACILITY#	DECAL #
2013-06-01	CVSA		
		MICROFILM #	OUTCOME
		8172110	VIOLATIONS PRESENT

VEHICLE REGISTRATION: 01518770	PLATE 55521B	2004 GREAT DANE	
DATE	ACTION	FACILITY#	DECAL #
2013-01-06	CVSA		
		MICROFILM #	OUTCOME
		8118064	OUT OF SERVICE

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 01624943 PLATE 84852C 2004 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-01-09	CVSA			8265150	INSPECTION PASSED

VEHICLE REGISTRATION: 01632101 PLATE 03 KENWORTH

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-02-26	CVIP	S5708	ES32553	10229121	INSPECTION PASSED
2015-02-26	CVIP	S5708		10229120	VEHICLE INSPECTION REJECTED
2014-09-19	CVSA				INSPECTION PASSED
2014-07-21	CVIP	S6912	EP41615	9794990	INSPECTION PASSED
2014-07-21	CVIP	S6912		9794959	VEHICLE INSPECTION REJECTED
2014-03-12	CVSA			8297212	INSPECTION PASSED
2014-02-13	CVSA				INSPECTION PASSED
2014-01-17	CVIP	S5935	EN24967	9372143	INSPECTION PASSED
2014-01-17	CVIP	S5935		9372142	VEHICLE INSPECTION REJECTED
2013-12-03	CVSA				INSPECTION PASSED
2013-10-25	CVSA				INSPECTION PASSED
2013-07-11	CVIP	S5935	EM55334	9022869	INSPECTION PASSED
2013-07-11	CVIP	S5935		9022864	VEHICLE INSPECTION REJECTED
2013-07-10	CVSA				INSPECTION PASSED
2013-05-30	CVSA			8171300	INSPECTION PASSED
2013-04-19	CVSA				VIOLATIONS PRESENT
2013-04-16	CVSA			8153861	VIOLATIONS PRESENT
2013-04-02	CVSA			8147060	VIOLATIONS PRESENT
2013-02-13	CVSA			8129199	VIOLATIONS PRESENT
2013-01-18	CVIP	S6948	EL92902	8771435	INSPECTION PASSED
2012-11-28	CVSA				INSPECTION PASSED
2012-07-23	CVIP	S6948	EJ60637	8580963	INSPECTION PASSED
2012-07-21	CVSA			8101263	INSPECTION PASSED

VEHICLE REGISTRATION: 01645562 PLATE 29215D 2008 GREAT DANE

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-06-01	CVSA			8172390	VIOLATIONS PRESENT

VEHICLE REGISTRATION: 01656713 PLATE 98782C 2008 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-02-21	CVSA			8430992	INSPECTION PASSED
2014-06-03	CVSA			8333731	VIOLATIONS PRESENT
2013-02-08	CVSA			8128361	INSPECTION PASSED

VEHICLE REGISTRATION: 01656900 PLATE 61629D 2008 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-09-10	CVSA			8376410	INSPECTION PASSED
2014-02-24	CVSA			8288411	INSPECTION PASSED
2013-03-07	CVSA			8137690	OUT OF SERVICE

CVSE-NSCSP351 (P)
2015-05-11

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 01657426 PLATE 98779C 2008 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-07-13	CVSA			8100560	VIOLATIONS PRESENT

VEHICLE REGISTRATION: 01657644 PLATE 98777C 2008 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-10-16	CVSA			8391750	INSPECTION PASSED

VEHICLE REGISTRATION: 01660398 PLATE 07187C 2004 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-12-04	CVSA			8114459	VIOLATIONS PRESENT

VEHICLE REGISTRATION: 01739012 PLATE 10416D 2005 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-03-15	CVSA			8140753	OUT OF SERVICE
2012-11-15	CVSA			8112862	INSPECTION PASSED

VEHICLE REGISTRATION: 01741341 PLATE 84813C 2005 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-11-27	CVSA			8248261	INSPECTION PASSED

VEHICLE REGISTRATION: 01846874 PLATE 18531P 04 PETERBILT

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-03-19	CVIP	S2225	ES22745	10272577	INSPECTION PASSED
2014-10-20	CVSA				INSPECTION PASSED
2014-09-23	CVIP	S2225	EQ93459	9905139	INSPECTION PASSED
2014-09-02	CVSA				INSPECTION PASSED
2014-08-20	CVSA			8367841	INSPECTION PASSED
2014-05-01	CVSA			8322290	INSPECTION PASSED
2014-03-29	CVIP	S2225	EP77608	9494581	INSPECTION PASSED
2014-03-29	CVIP	S2225		9494580	VEHICLE INSPECTION REJECTED
2013-10-22	CVSA				INSPECTION PASSED
2013-10-03	CVSA				INSPECTION PASSED
2013-09-17	CVIP	S2225	EN63853	9122370	INSPECTION PASSED
2013-09-13	CVSA				INSPECTION PASSED
2013-08-16	CVSA				VIOLATIONS PRESENT
2013-03-21	CVIP	S2225	EM13166	8846997	INSPECTION PASSED
2013-03-21	CVIP	S2225		8846983	VEHICLE INSPECTION REJECTED
2012-11-20	CVSA				INSPECTION PASSED
2012-10-18	CVSA			8109781	VIOLATIONS PRESENT
2012-10-09	CVSA				INSPECTION PASSED
2012-09-24	CVIP	S2225	EK93815	8647870	INSPECTION PASSED
2012-09-24	CVIP	S2225		8647868	VEHICLE INSPECTION REJECTED
2012-07-24	CVSA				INSPECTION PASSED

CVSE-NSCSP351 (P)
2015-05-11

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 01862766 PLATE 90144B 2008 GREAT DANE

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-11-26	CVSA			8113869	INSPECTION PASSED

VEHICLE REGISTRATION: 01862844 PLATE 29212D 2008 GREAT DANE

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-08-19	CVSA			8368068	INSPECTION PASSED
2013-01-17	CVSA			8121050	INSPECTION PASSED

VEHICLE REGISTRATION: 01896963 PLATE 04 VOLVO

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-04-06	CVIP	S7254	ER74370	10351060	INSPECTION PASSED
2015-04-06	CVIP	S7254		10351059	VEHICLE INSPECTION REJECTED
2014-09-14	CVIP	S6978	EQ79949	9885342	INSPECTION PASSED
2014-07-17	CVSA			8351141	VIOLATIONS PRESENT
2014-05-22	CVSA				INSPECTION PASSED
2014-03-01	CVIP	S5935	EP46907	9435518	INSPECTION PASSED
2014-03-01	CVIP	S5935		9435517	VEHICLE INSPECTION REJECTED
2013-08-09	CVIP	S6978	EN42350	9066907	INSPECTION PASSED
2013-08-09	CVIP	S6978		9066901	VEHICLE INSPECTION REJECTED
2013-02-20	CVIP	S6978	EL40311	8808021	INSPECTION PASSED
2013-02-13	CVSA			8129560	VIOLATIONS PRESENT
2013-02-13	N&O			8129560	NOTICE & ORDER 2
2012-09-24	CVSA			8107254	INSPECTION PASSED
2012-06-01	CVIP	S6978	EJ39945	8521650	INSPECTION PASSED

VEHICLE REGISTRATION: 01922108 PLATE 29209D 2008 GREAT DANE

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-06-18	CVSA			8181811	OUT OF SERVICE

VEHICLE REGISTRATION: 01957154 PLATE 29213D 2008 GREAT DANE

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-01-27	CVSA			8123933	OUT OF SERVICE

VEHICLE REGISTRATION: 01963378 PLATE 98783C 2008 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-09-05	CVSA			8374770	INSPECTION PASSED

VEHICLE REGISTRATION: 01963539 PLATE 98786C 2008 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-07-07	CVSA			8346445	VIOLATIONS PRESENT
2013-06-06	CVSA			8175970	VIOLATIONS PRESENT
2013-01-23	CVSA			8122885	INSPECTION PASSED
2012-09-25	CVSA			8107453	VIOLATIONS PRESENT

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 01963601 PLATE 98787C 2008 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-05-29	CVSA			8170750	INSPECTION PASSED

VEHICLE REGISTRATION: 01963688 PLATE 98788C 2008 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-07-27	CVSA			8196510	VIOLATIONS PRESENT

VEHICLE REGISTRATION: 01970155 PLATE 29287D 2008 GREAT DANE

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-06-25	CVSA			8185240	INSPECTION PASSED

VEHICLE REGISTRATION: 02063636 PLATE HH0136 03 PETERBILT

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-07-31	CVIP	S5708	EK22185	8590444	INSPECTION PASSED

VEHICLE REGISTRATION: 02134044 PLATE 11823P 04 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-10-27	CVIP	S6948	EL42187	8686449	INSPECTION PASSED
2012-09-23	CVSA			8107159	VIOLATIONS PRESENT

VEHICLE REGISTRATION: 02172581 PLATE P97126 08 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-08-12	CVIP	S6978	EQ79923	9808335	INSPECTION PASSED
2014-02-03	CVSA				INSPECTION PASSED
2013-11-20	CVIP	S6978	EN42456	9220879	INSPECTION PASSED
2013-04-13	CVSA				INSPECTION PASSED
2013-04-04	CVIP	S6978	EL41743	8866707	INSPECTION PASSED
2012-09-04	CVIP	S6978	EK17576	8626172	INSPECTION PASSED
2012-07-18	CVSA				INSPECTION PASSED
2012-07-04	CVSA				INSPECTION PASSED
2012-06-06	CVSA				VIOLATIONS PRESENT
2012-06-05	CVSA				INSPECTION PASSED

VEHICLE REGISTRATION: 02172601 PLATE 07250P 08 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-06-29	CVIP	S6978	EP88708	9710115	INSPECTION PASSED
2013-12-11	CVIP	S6978	EN42473	9278125	INSPECTION PASSED
2013-12-11	CVIP	S6978		9278124	VEHICLE INSPECTION REJECTED
2013-10-12	CVSA				VIOLATIONS PRESENT
2013-05-25	CVIP	S6978	EL41802	8945098	INSPECTION PASSED
2013-02-11	CVSA				INSPECTION PASSED
2012-11-01	CVIP	S6978	EK18185	8692684	INSPECTION PASSED

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 02190954 PLATE JA4489 08 KENWORTH

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-03-29	CVIP	S6903	EP74983	9494274	INSPECTION PASSED
2014-03-29	CVIP	S6903		9494272	VEHICLE INSPECTION REJECTED
2014-02-24	CVSA			8288411	VIOLATIONS PRESENT
2013-09-27	CVIP	S6903	EN28763	9137017	INSPECTION PASSED
2013-03-27	CVIP	S6903	EL59688	8855509	INSPECTION PASSED
2013-01-07	CVSA			8118330	INSPECTION PASSED
2012-09-24	CVIP	S6903	EK03525	8648544	INSPECTION PASSED

VEHICLE REGISTRATION: 02196631 PLATE 07266P 04 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-08-09	CVIP	S6978	EK17546	8599097	INSPECTION PASSED
2012-05-15	CVSA				INSPECTION PASSED

VEHICLE REGISTRATION: 02209430 PLATE 17593P KENWORTH

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-03-19	CVSA				VIOLATIONS PRESENT

VEHICLE REGISTRATION: 02210468 PLATE 29219D 2008 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-02-13	CVSA			8129199	INSPECTION PASSED

VEHICLE REGISTRATION: 02210544 PLATE 29217D 2008 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-11-25	CVSA			8245960	INSPECTION PASSED
2012-08-31	CVSA			8104765	VIOLATIONS PRESENT

VEHICLE REGISTRATION: 02210558 PLATE 02950D 2008 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-07-21	CVSA			8101263	VIOLATIONS PRESENT

VEHICLE REGISTRATION: 02211029 PLATE 03999P FRHT

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-03-17	CVSA				INSPECTION PASSED
2015-02-02	CVIP	S6948	ER66808	10183623	INSPECTION PASSED
2015-02-02	CVIP	S6948		10183622	VEHICLE INSPECTION REJECTED
2014-07-02	CVIP	S6948	EQ77770	9716504	INSPECTION PASSED
2014-07-02	CVIP	S6948		9716503	VEHICLE INSPECTION REJECTED
2014-05-22	CVSA				INSPECTION PASSED
2014-01-28	CVSA				VIOLATIONS PRESENT
2013-12-18	CVSA				INSPECTION PASSED
2013-12-05	CVIP	S6948	EP04461	9267425	INSPECTION PASSED
2013-06-22	CVSA				INSPECTION PASSED
2013-05-01	CVIP	S6948	EM39839	8907000	INSPECTION PASSED
2013-03-15	CVSA			8140753	OUT OF SERVICE

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 02211029		PLATE 03999P	FRHT	(CONTINUED)
2013-03-05	CVSA			VIOLATIONS PRESENT
2013-02-07	CVSA		8127930	INSPECTION PASSED
2012-10-30	CVSA		8110946	VIOLATIONS PRESENT
2012-10-03	CVIP	S6978	8660766	INSPECTION PASSED
2012-09-17	CVSA	EK18147		OUT OF SERVICE

VEHICLE REGISTRATION: 02227341		PLATE P93693	2005 KENWORTH		
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-06-01	CVSA			8172110	VIOLATIONS PRESENT
2013-01-21	CVSA			8122081	VIOLATIONS PRESENT
2013-01-16	CVSA			8120482	VIOLATIONS PRESENT
2012-10-23	CVIP	S5708	EL42284	8680723	INSPECTION PASSED

VEHICLE REGISTRATION: 02231582		PLATE 12401P	2005 KENWORTH		
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-05-29	CVSA			8170750	INSPECTION PASSED
2013-05-02	CVIP	S5708	EM73735	8909407	INSPECTION PASSED
2012-10-27	CVIP	S5708	EL42313	8686495	INSPECTION PASSED

VEHICLE REGISTRATION: 02245144		PLATE P97125	05 INTERNATNA		
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-03-03	CVIP	S6978	EN42542	9434661	INSPECTION PASSED
2013-11-17	CVSA				INSPECTION PASSED
2013-09-24	CVSA				VIOLATIONS PRESENT
2013-07-30	CVIP	S6978	EL41901	9050076	INSPECTION PASSED
2013-05-08	CVSA				VIOLATIONS PRESENT
2013-01-09	CVIP	S6978	EL40263	8760984	INSPECTION PASSED
2012-09-11	CVSA				INSPECTION PASSED
2012-06-01	CVIP	S6978	EJ39946	8521776	INSPECTION PASSED
2012-05-22	CVSA				INSPECTION PASSED

VEHICLE REGISTRATION: 02252296		PLATE P97124	05 INTERNATNA		
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-09-29	CVIP	S6978	ER79954	9919226	INSPECTION PASSED
2014-07-30	CVSA				OUT OF SERVICE
2014-03-12	CVIP	S6978	EN42553	9453693	INSPECTION PASSED
2013-08-23	CVIP	S6978	EN42368	9092531	INSPECTION PASSED
2013-08-23	CVIP	S6978		9092524	VEHICLE INSPECTION REJECTED
2013-03-27	CVIP	S6978	EL41725	8854956	INSPECTION PASSED
2012-12-05	CVSA			8114575	INSPECTION PASSED
2012-10-09	CVSA			8108774	VIOLATIONS PRESENT
2012-09-09	CVIP	S6978	EK17587	8631881	INSPECTION PASSED
2012-07-04	CVSA			8099697	VIOLATIONS PRESENT

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 02273417 PLATE 05 INTERNATNA

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-11-29	CVIP	S6978	EL40212	8722384	INSPECTION PASSED
2012-05-30	CVIP	S6978	EJ39936	8516701	INSPECTION PASSED

VEHICLE REGISTRATION: 02288472 PLATE 63030C 2008 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-11-14	CVSA			8402050	VIOLATIONS PRESENT
2012-05-26	CVSA			8095429	INSPECTION PASSED

VEHICLE REGISTRATION: 02292069 PLATE 84811C 2004 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-02-24	CVSA			8431238	INSPECTION PASSED

VEHICLE REGISTRATION: 02406481 PLATE 19256P 06 VOLVO

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-10-11	CVIP	S6978	EN42427	9156439	INSPECTION PASSED
2013-10-11	CVIP	S6978		9156438	VEHICLE INSPECTION REJECTED
2013-09-29	CVIP	S6978	RD04178	9139088	VEHICLE INSPECTION REJECTED
2013-08-09	CVSA			8201310	INSPECTION PASSED

VEHICLE REGISTRATION: 02439273 PLATE 13000P 2008 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-03-07	CVSA			8137690	INSPECTION PASSED

VEHICLE REGISTRATION: 02449936 PLATE 84807C 2005 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-08-31	CVSA			8104790	INSPECTION PASSED

VEHICLE REGISTRATION: 02450053 PLATE 84854C 2005 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-11-12	CVSA			8427006	INSPECTION PASSED
2013-01-07	CVSA			8118141	INSPECTION PASSED

VEHICLE REGISTRATION: 02485930 PLATE 05 PETERBILT

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-12-24	CVIP	S4676	ER80914	10108116	INSPECTION PASSED
2014-11-03	CVSA			8397560	OUT OF SERVICE
2014-06-10	CVIP	S4168	EQ47830	9668660	INSPECTION PASSED
2013-12-20	CVIP	S4168	EP36593	9298622	INSPECTION PASSED
2013-06-14	CVIP	S4168	EN16044	8989565	INSPECTION PASSED
2013-01-23	CVSA			8122885	VIOLATIONS PRESENT
2012-12-27	CVIP	S5874	EL10247	8748129	INSPECTION PASSED
2012-12-27	CVIP	S5874		8748120	VEHICLE INSPECTION REJECTED
2012-06-13	CVIP	S4168	EK06677	8538923	INSPECTION PASSED

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 02503028 PLATE 84806C 2005 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-02-07	CVSA			8127930	INSPECTION PASSED
2012-12-05	CVSA			8114575	INSPECTION PASSED

VEHICLE REGISTRATION: 02503032 PLATE 84808C 2005 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-10-16	CVSA			8391330	INSPECTION PASSED

VEHICLE REGISTRATION: 02503098 PLATE 07012D 2005 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-11-27	CVSA			8113970	INSPECTION PASSED

VEHICLE REGISTRATION: 02505981 PLATE 55516B 2005 GREAT DANE

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-01-05	CVSA			8263633	VIOLATIONS PRESENT
2013-08-02	CVSA			8199271	INSPECTION PASSED

VEHICLE REGISTRATION: 02512166 PLATE 16121C 2005 GREAT DANE

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-10-27	CVSA			8395751	OUT OF SERVICE

VEHICLE REGISTRATION: 02516377 PLATE 07 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-08-30	CVIP	S5708	ER12615	9854845	INSPECTION PASSED

VEHICLE REGISTRATION: 02517167 PLATE 55518B 2005 GREAT DANE

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-06-17	CVSA			8097835	VIOLATIONS PRESENT

VEHICLE REGISTRATION: 02522233 PLATE 63036C 2008 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-01-05	CVSA			8263660	INSPECTION PASSED

VEHICLE REGISTRATION: 02523262 PLATE 63040C 2009 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-07-24	CVSA			8354711	VIOLATIONS PRESENT

VEHICLE REGISTRATION: 02523281 PLATE 33589D 2009 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-06-05	CVSA			8354072	INSPECTION PASSED
2013-11-13	CVSA			8239760	INSPECTION PASSED

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 02523317 PLATE 63039C 2009 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-04-11	CVSA			8314150	INSPECTION PASSED

VEHICLE REGISTRATION: 02523521 PLATE 10462D 2009 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-11-29	CVSA			8407690	VIOLATIONS PRESENT

VEHICLE REGISTRATION: 02523641 PLATE 63034C 2009 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-08-26	CVSA			8209840	VIOLATIONS PRESENT

VEHICLE REGISTRATION: 02531026 PLATE 16123C 2005 GREAT DANE

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-10-30	CVSA			8110946	VIOLATIONS PRESENT
2012-08-13	CVSA			8103159	INSPECTION PASSED

VEHICLE REGISTRATION: 02596157 PLATE 55523B 2005 GREAT DANE

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-09-24	CVSA			8107254	VIOLATIONS PRESENT

VEHICLE REGISTRATION: 02602609 PLATE 04776P 05 PETERBILT

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-10-20	CVIP	S6268		8678362	VEHICLE INSPECTION REJECTED
2012-10-20	CVIP	S6268	EK87409	8678368	INSPECTION PASSED
2012-06-06	CVSA			8096583	INSPECTION PASSED

VEHICLE REGISTRATION: 02730189 PLATE 14356P 2007 VOLVO

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-06-25	CVSA			8185240	VIOLATIONS PRESENT
2013-06-11	CVSA			8179221	INSPECTION PASSED

VEHICLE REGISTRATION: 02734856 PLATE 12460D 2005 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-10-16	CVSA			8109593	OUT OF SERVICE

VEHICLE REGISTRATION: 02777288 PLATE 08688P 05 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-01-21	CVIP	S1005	ER85689	10160489	INSPECTION PASSED
2015-01-21	CVIP	S1005		10160488	VEHICLE INSPECTION REJECTED
2014-07-19	CVIP	S1005	EQ78120	9755402	INSPECTION PASSED
2014-07-19	CVIP	S1005		9755401	VEHICLE INSPECTION REJECTED
2014-02-26	CVSA				INSPECTION PASSED
2014-01-05	CVIP	S6978	EN42489	9318751	INSPECTION PASSED
2014-01-05	CVIP	S6978		9318750	VEHICLE INSPECTION REJECTED
2013-11-27	CVSA			8248320	VIOLATIONS PRESENT

CVSE-NSCSP351 (P)
2015-05-11

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 02777288	PLATE 08688P	05	FREIGHTLIN	(CONTINUED)
2013-06-25	CVIP S6948		8996822	INSPECTION PASSED
2013-03-14	CVSA			INSPECTION PASSED
2013-01-09	CVSA			INSPECTION PASSED
2012-12-22	CVSA			INSPECTION PASSED
2012-12-11	CVIP S6948		EL42233 8734693	INSPECTION PASSED
2012-11-29	CVSA			INSPECTION PASSED
2012-06-05	CVSA		8096263	INSPECTION PASSED

VEHICLE REGISTRATION: 02778723	PLATE 12456D	2005	UTILITY		
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-12-12	CVSA			8115273	INSPECTION PASSED
2012-09-27	CVSA			8107626	INSPECTION PASSED

VEHICLE REGISTRATION: 02815689	PLATE P90970	05	STERLING		
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-08-16	CVIP	S6978	EQ79928	9819353	INSPECTION PASSED
2014-02-25	CVIP	S6978	EN42539	9422171	INSPECTION PASSED
2013-07-20	CVIP	S0104	EM19533	9033883	INSPECTION PASSED
2013-07-20	CVIP	S0104		9033875	VEHICLE INSPECTION REJECTED
2013-05-08	CVSA			8161790	VIOLATIONS PRESENT
2013-01-30	CVIP	S6978	EL40286	8783970	INSPECTION PASSED
2012-07-12	CVIP	S6978	EJ40007	8568384	INSPECTION PASSED
2012-05-19	CVSA			8094831	VIOLATIONS PRESENT

VEHICLE REGISTRATION: 02921756	PLATE 96700C	2005	UTILITY		
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-05-28	CVSA			8170311	INSPECTION PASSED

VEHICLE REGISTRATION: 02951036	PLATE 36512B	2005	UTILITY		
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-06-04	CVSA			8335092	INSPECTION PASSED

VEHICLE REGISTRATION: 02971193	PLATE 96216B	2006	UTILITY		
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-07-25	CVSA			8195323	INSPECTION PASSED

VEHICLE REGISTRATION: 02989579	PLATE	06	VOLVO		
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-09-22	CVIP	S6948	EK03936	8646954	INSPECTION PASSED
2012-06-09	CVSA				INSPECTION PASSED

CVSE-NSCSP351 (P)
2015-05-11

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 03011599			PLATE 24887C	2006 DOEPKER	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-05-23	CVSA			8099252	INSPECTION PASSED
VEHICLE REGISTRATION: 03025705			PLATE 10907P	2008 FREIGHTLIN	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-11-27	CVSA			8113970	VIOLATIONS PRESENT
2012-11-03	CVIP	S5716	EL42012	8694968	INSPECTION PASSED
VEHICLE REGISTRATION: 03031384			PLATE 17613P	06 FREIGHTLIN	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-02-27	CVIP	S6750		10231885	VEHICLE INSPECTION REJECTED
2015-02-27	CVIP	S6750	ES36733	10231886	INSPECTION PASSED
2014-11-12	CVSA			8427006	OUT OF SERVICE
2014-08-30	CVIP	S6750	ER05367	9854923	INSPECTION PASSED
2014-08-30	CVIP	S6750		9854922	VEHICLE INSPECTION REJECTED
2014-06-05	CVSA			8335598	VIOLATIONS PRESENT
2014-02-01	CVIP	S6750	EP50318	9374639	INSPECTION PASSED
2013-11-27	CVSA			8248261	VIOLATIONS PRESENT
VEHICLE REGISTRATION: 03046575			PLATE 42425B	2006 GREAT DANE	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-01-14	CVSA			8267321	INSPECTION PASSED
VEHICLE REGISTRATION: 03046632			PLATE 40625B	2006 GREAT DANE	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-06-05	CVSA			8098616	INSPECTION PASSED
VEHICLE REGISTRATION: 03050962			PLATE 84817C	2006 UTILITY	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-01-14	CVSA			8119941	INSPECTION PASSED
VEHICLE REGISTRATION: 03050967			PLATE 84823C	2006 UTILITY	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-05-02	CVSA			8323016	INSPECTION PASSED
2013-09-19	CVSA			8218100	VIOLATIONS PRESENT
2013-05-19	CVSA			8166361	VIOLATIONS PRESENT
VEHICLE REGISTRATION: 03050980			PLATE 48966C	2006 UTILITY	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-08-01	CVSA			8102221	VIOLATIONS PRESENT

CVSE-NSCSP351 (P)
2015-05-11

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 03060614 PLATE 40627B 2006 GREAT DANE

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-06-06	CVSA			8096583	VIOLATIONS PRESENT

VEHICLE REGISTRATION: 03066182 PLATE 30445C 2006 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-05-16	CVSA			8165881	INSPECTION PASSED

VEHICLE REGISTRATION: 03082366 PLATE 36288D 2009 HYUNDAI

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-03-12	CVSA			8433391	VIOLATIONS PRESENT
2012-06-05	CVSA			8098586	INSPECTION PASSED

VEHICLE REGISTRATION: 03082453 PLATE 16178C 2009 HYUNDAI

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-11-16	CVSA			8113115	VIOLATIONS PRESENT

VEHICLE REGISTRATION: 03082508 PLATE 36291D 2009 HYUNDAI

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-10-19	CVSA			8228502	INSPECTION PASSED

VEHICLE REGISTRATION: 03082537 PLATE 36287D 2009 HYUNDAI

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-10-08	CVSA			8388381	VIOLATIONS PRESENT

VEHICLE REGISTRATION: 03091059 PLATE 17610P 08 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-12-01	CVIP	S6948	ER66736	10062448	INSPECTION PASSED
2014-12-01	CVIP	S6948		10062447	VEHICLE INSPECTION REJECTED
2014-11-21	CVSA				INSPECTION PASSED
2014-08-15	CVSA				INSPECTION PASSED
2014-07-22	CVSA				INSPECTION PASSED
2014-05-10	CVIP	S6948	EQ09835	9595566	INSPECTION PASSED
2014-05-10	CVIP	S6948		9595565	VEHICLE INSPECTION REJECTED
2014-03-31	CVSA				INSPECTION PASSED
2014-03-13	CVSA				VIOLATIONS PRESENT

VEHICLE REGISTRATION: 03251800 PLATE 84819C 2006 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-12-14	CVSA			8115479	INSPECTION PASSED

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 03253842 PLATE 07013D 2006 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-03-12	CVSA			8297212	INSPECTION PASSED
2013-12-03	CVSA			8252830	INSPECTION PASSED

VEHICLE REGISTRATION: 03254103 PLATE 84821C 2006 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-01-31	CVSA			8124940	INSPECTION PASSED

VEHICLE REGISTRATION: 03264597 PLATE 17941P 05 KENWORTH

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-03-27	CVIP	S7076	ES66179	10288381	INSPECTION PASSED
2015-03-27	CVIP	S7076		10288380	VEHICLE INSPECTION REJECTED
2015-02-19	CVSA				INSPECTION PASSED
2014-09-12	CVIP	S5716	ER13463	9884697	INSPECTION PASSED
2014-08-14	CVSA				INSPECTION PASSED
2014-06-24	CVSA				INSPECTION PASSED
2014-04-25	CVSA				INSPECTION PASSED
2014-04-07	CVSA				INSPECTION PASSED
2014-03-01	CVIP	S4168	EP65225	9432202	INSPECTION PASSED

VEHICLE REGISTRATION: 03267214 PLATE 84818C 2006 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-04-28	CVSA			8319440	INSPECTION PASSED

VEHICLE REGISTRATION: 03267342 PLATE 17599P 2006 PETERBILT

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-11-23	CVSA			8405220	INSPECTION PASSED
2014-09-13	CVIP	S5716	ER13464	9884704	INSPECTION PASSED
2014-08-19	CVSA			8368068	INSPECTION PASSED
2014-01-14	CVSA			8267321	INSPECTION PASSED
2013-08-08	CVIP	S6978	EN42346	9063867	INSPECTION PASSED
2013-02-20	CVIP	S5708	EL94741	8809016	INSPECTION PASSED
2013-02-20	CVIP	S5708		8809014	VEHICLE INSPECTION REJECTED
2013-02-20	CVIP	S5708	EL94741	8808974	INSPECTION PASSED
2013-02-20	CVIP	S5708		8808967	VEHICLE INSPECTION REJECTED
2012-12-15	CVSA			8115547	INSPECTION PASSED
2012-12-05	CVSA			8114592	VIOLATIONS PRESENT
2012-08-27	CVIP	S4438	EK62111	8617580	INSPECTION PASSED
2012-06-05	CVSA			8098616	INSPECTION PASSED

CVSE-NSCSP351 (P)
2015-05-11

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 03289924 PLATE 84822C 2006 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-11-01	CVSA			8397110	VIOLATIONS PRESENT
2013-11-14	CVSA			8240271	INSPECTION PASSED
2013-05-25	CVSA			8169442	INSPECTION PASSED

VEHICLE REGISTRATION: 03446085 PLATE 23736P 09 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-02-25	CVIP	S5708	ES32541	10225397	INSPECTION PASSED
2015-02-25	CVIP	S5708		10225395	VEHICLE INSPECTION REJECTED
2014-11-07	CVSA			8399571	VIOLATIONS PRESENT
2014-09-11	CVSA			8377292	VIOLATIONS PRESENT
2014-08-27	CVIP	S5708	ER05618	9846214	INSPECTION PASSED
2014-08-27	CVIP	S5708		9846213	VEHICLE INSPECTION REJECTED
2014-02-26	CVIP	S5708	EP75386	9425230	INSPECTION PASSED

VEHICLE REGISTRATION: 03455550 PLATE 17163P 06 VOLVO

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-06-11	CVIP	S6268	EP40158	9668761	INSPECTION PASSED
2014-06-02	CVSA			8333394	INSPECTION PASSED
2013-12-30	CVIP	S6268	EN28198	9309227	INSPECTION PASSED

VEHICLE REGISTRATION: 03458597 PLATE 10937P 2006 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-01-27	CVSA			8123933	VIOLATIONS PRESENT
2013-01-21	CVSA			8122072	INSPECTION PASSED

VEHICLE REGISTRATION: 03506574 PLATE 19253P 06 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-12-30	CVIP	S6948	EP04480	9309917	INSPECTION PASSED
2013-12-03	CVSA			8252200	INSPECTION PASSED
2013-07-11	CVIP	S6948	EN00437	9020735	INSPECTION PASSED
2012-12-04	CVSA			8114459	VIOLATIONS PRESENT
2012-07-17	CVIP	S6978	EK17504	8572962	INSPECTION PASSED

VEHICLE REGISTRATION: 03526127 PLATE 06 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-03-26	CVIP	S6948		10287091	VEHICLE INSPECTION REJECTED
2015-03-26	CVIP	S6948	ES33001	10287092	INSPECTION PASSED
2014-09-20	CVIP	S6948	ER38394	9899960	INSPECTION PASSED
2014-09-20	CVIP	S6948		9899959	VEHICLE INSPECTION REJECTED
2014-06-10	CVSA				INSPECTION PASSED
2014-05-10	CVSA				INSPECTION PASSED
2014-03-22	CVIP	S6948	EP42180	9477044	INSPECTION PASSED
2014-03-22	CVIP	S6948		9477043	VEHICLE INSPECTION REJECTED
2014-01-16	CVSA				INSPECTION PASSED

SECTION 5

PAGE: 28

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 03526127		PLATE 09165P	2006 FREIGHTLIN	(CONTINUED)
2014-01-09	CVSA		8265150	INSPECTION PASSED
2013-10-19	CVSA		8228502	INSPECTION PASSED
2013-09-24	CVIP	S6948	9131926	INSPECTION PASSED
2013-07-29	CVSA		8197200	VIOLATIONS PRESENT
2013-03-16	CVIP	S6948	8840808	INSPECTION PASSED
2013-01-21	CVSA		8121902	INSPECTION PASSED
2012-11-27	CVSA			INSPECTION PASSED
2012-09-27	CVIP	S6948	8653392	INSPECTION PASSED
2012-09-11	CVSA			INSPECTION PASSED
2012-08-31	CVSA		8104765	INSPECTION PASSED

VEHICLE REGISTRATION: 03565565		PLATE 21334P	06 FREIGHTLIN		
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-05-31	CVIP	S6948	EQ09871	9642792	INSPECTION PASSED
2014-05-31	CVIP	S6948		9642791	VEHICLE INSPECTION REJECTED
2014-05-22	CVSA				INSPECTION PASSED
2014-04-15	CVSA				INSPECTION PASSED
2014-03-25	CVSA				INSPECTION PASSED
2014-02-12	CVSA				INSPECTION PASSED
2014-01-10	CVSA			8265722	INSPECTION PASSED
2013-11-28	CVIP	S6948	EP04450	9245785	INSPECTION PASSED
2013-07-01	CVSA				VIOLATIONS PRESENT
2013-05-25	CVSA				INSPECTION PASSED
2013-05-22	CVSA				INSPECTION PASSED
2013-05-14	CVIP	S6948	EM39855	8928596	INSPECTION PASSED
2012-11-24	CVIP	S6948	EL42215	8715948	INSPECTION PASSED
2012-11-07	CVSA				INSPECTION PASSED
2012-07-27	CVSA				INSPECTION PASSED
2012-07-24	CVSA				INSPECTION PASSED
2012-05-26	CVSA				INSPECTION PASSED
2012-05-19	CVIP	S6948	EJ60554	8504858	INSPECTION PASSED

VEHICLE REGISTRATION: 03566648		PLATE 10908P	FRHT		
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-11-09	CVSA				VIOLATIONS PRESENT
2012-10-31	CVIP	S6903	EK03556	8691085	INSPECTION PASSED
2012-10-18	CVSA				INSPECTION PASSED
2012-09-19	CVSA				INSPECTION PASSED

VEHICLE REGISTRATION: 03589084		PLATE 17954P	06 FREIGHTLIN		
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-05-09	CVIP	S6948	ES66464	10386660	INSPECTION PASSED
2015-05-09	CVIP	S6948		10386659	VEHICLE INSPECTION REJECTED
2014-11-25	CVSA				INSPECTION PASSED
2014-11-08	CVIP	S6948	ER38461	10015621	INSPECTION PASSED
2014-11-08	CVIP	S6948		10015620	VEHICLE INSPECTION REJECTED

SECTION 5

PAGE: 29

CVSE-NSCSP351 (P)
2015-05-11

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION:	03589084	PLATE	17954P	FRHT	(CONTINUED)
2014-06-30	CVSA				INSPECTION PASSED
2014-05-09	CVIP	S6948	EQ09833	9594712	INSPECTION PASSED
2014-05-09	CVIP	S6948		9594711	VEHICLE INSPECTION REJECTED
2014-03-01	CVSA			8291360	INSPECTION PASSED
2013-12-02	CVSA			8251300	INSPECTION PASSED
2013-11-07	CVIP	S6948	EN28301	9194085	INSPECTION PASSED
2013-09-20	CVSA				INSPECTION PASSED
2013-09-19	CVSA			8218543	VIOLATIONS PRESENT
2013-07-16	CVSA				OUT OF SERVICE
2013-05-11	CVIP	S6948	EM39850	8924252	INSPECTION PASSED
2013-04-25	CVSA				OUT OF SERVICE
2013-04-02	CVSA				INSPECTION PASSED
2012-11-30	CVSA				INSPECTION PASSED
2012-11-01	CVIP	S6948	EL42195	8693129	INSPECTION PASSED
2012-10-16	CVSA				INSPECTION PASSED
2012-09-27	CVSA			8107626	INSPECTION PASSED
2012-07-10	CVSA				INSPECTION PASSED

VEHICLE REGISTRATION:	03618114	PLATE	17590P	2007 FREIGHTLIN	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-02-25	CVSA			8431516	VIOLATIONS PRESENT
2015-01-15	CVIP	S6948	ER66784	10153138	INSPECTION PASSED
2015-01-15	CVIP	S6948		10153137	VEHICLE INSPECTION REJECTED
2014-07-19	CVIP	S6948	EQ77785	9755397	INSPECTION PASSED
2014-07-19	CVIP	S6948		9755396	VEHICLE INSPECTION REJECTED
2014-06-04	CVSA			8335092	INSPECTION PASSED

VEHICLE REGISTRATION:	03622451	PLATE		07 PETERBILT	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-09-28	CVIP	S5708	ER29310	9918353	INSPECTION PASSED
2013-08-10	CVIP	S5708	EN27824	9067900	INSPECTION PASSED
2013-07-24	CVSA				INSPECTION PASSED
2013-07-04	CVSA				INSPECTION PASSED
2013-03-08	CVSA				INSPECTION PASSED
2013-02-27	CVSA			8134791	VIOLATIONS PRESENT
2013-02-09	CVIP	S5708	EL94704	8796840	INSPECTION PASSED
2013-01-31	CVSA			8124940	INSPECTION PASSED
2013-01-07	CVSA				INSPECTION PASSED
2012-08-04	CVIP	S5708	EK22203	8595692	INSPECTION PASSED

VEHICLE REGISTRATION:	03647208	PLATE		06 FREIGHTLIN	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-03-15	CVIP	S6948	EP42166	9461750	INSPECTION PASSED
2014-03-15	CVIP	S6948		9461749	VEHICLE INSPECTION REJECTED
2013-09-17	CVSA			8217475	INSPECTION PASSED
2013-08-31	CVIP	S6978	EN42383	9103622	INSPECTION PASSED

SECTION 5

PAGE: 30

CVSE-NSCSP351 (P)
2015-05-11

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 03647208	PLATE	06	FREIGHTLIN	(CONTINUED)
2013-08-31	CVIP	S6978	9102593	VEHICLE INSPECTION REJECTED
2013-03-28	CVSA		8146065	INSPECTION PASSED

VEHICLE REGISTRATION: 03700736 PLATE 10484P PTRB

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-11-27	CVSA				INSPECTION PASSED
2012-10-26	CVSA				INSPECTION PASSED
2012-10-24	CVIP	S6632	EK68633	8682417	INSPECTION PASSED
2012-10-11	CVSA			8109008	INSPECTION PASSED
2012-10-08	CVSA				OUT OF SERVICE

VEHICLE REGISTRATION: 03707629 PLATE 17945P 2007 FRTLNR

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-04-29	CVSA			8352953	INSPECTION PASSED
2014-03-21	CVIP	S6948		9475499	VEHICLE INSPECTION REJECTED
2014-03-21	CVIP	S6948	EP42177	9475510	INSPECTION PASSED
2014-02-18	CVSA			8285170	INSPECTION PASSED
2013-09-19	CVIP	S6948	EN28239	9126019	INSPECTION PASSED
2013-03-23	CVIP	S6948	EM39781	8849407	INSPECTION PASSED
2013-02-12	CVSA			8128998	VIOLATIONS PRESENT

VEHICLE REGISTRATION: 03720173 PLATE 84824C 2007 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-03-12	CVSA			8138960	INSPECTION PASSED
2013-01-16	CVSA			8120482	INSPECTION PASSED
2013-01-06	CVSA			8118010	INSPECTION PASSED
2012-07-05	CVSA			8099727	INSPECTION PASSED

VEHICLE REGISTRATION: 03733087 PLATE 21667P 06 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-04-28	CVIP	S6903	EP75001	9561646	INSPECTION PASSED
2014-04-28	CVIP	S6903		9561645	VEHICLE INSPECTION REJECTED
2014-01-28	CVSA			8275560	INSPECTION PASSED
2014-01-28	CVSA			8275551	INSPECTION PASSED
2013-10-26	CVIP	S6903	EN28784	9174841	INSPECTION PASSED
2013-05-16	CVSA			8165881	INSPECTION PASSED
2013-04-27	CVIP	S6903	EM40724	8900145	INSPECTION PASSED
2013-04-12	CVSA			8152141	VIOLATIONS PRESENT
2012-10-11	CVIP	S6903	EK03541	8668538	INSPECTION PASSED
2012-06-17	CVSA			8097835	VIOLATIONS PRESENT

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 03742033 PLATE 02965D 2007 GREAT DANE

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-09-03	CVSA			8212491	VIOLATIONS PRESENT

VEHICLE REGISTRATION: 03745644 PLATE 02966D 2007 GREAT DANE

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-12-03	CVSA			8252200	VIOLATIONS PRESENT

VEHICLE REGISTRATION: 03773135 PLATE 10468P 07 KENWORTH

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-03-12	CVIP	S4168	ES54005	10258309	INSPECTION PASSED
2014-12-04	CVSA				INSPECTION PASSED
2014-11-07	CVSA				INSPECTION PASSED
2014-10-14	CVSA				INSPECTION PASSED
2014-09-23	CVIP	S5716	ER13501	9906155	INSPECTION PASSED
2014-03-24	CVSA				INSPECTION PASSED
2014-03-15	CVIP	S6948	EP42168	9462279	INSPECTION PASSED
2014-03-15	CVIP	S6948		9462278	VEHICLE INSPECTION REJECTED
2014-02-10	CVSA				INSPECTION PASSED
2013-10-07	CVSA				INSPECTION PASSED
2013-09-12	CVIP	S5708	EN66627	9117425	INSPECTION PASSED
2013-09-12	CVIP	S5708		9117424	VEHICLE INSPECTION REJECTED
2013-06-02	CVSA				INSPECTION PASSED
2013-03-21	CVIP	S6978	EL41714	8846936	INSPECTION PASSED
2013-03-21	CVIP	S6978		8846902	VEHICLE INSPECTION REJECTED
2013-03-14	CVSA				VIOLATIONS PRESENT
2013-02-11	CVSA				VIOLATIONS PRESENT
2012-11-15	CVSA			8112862	INSPECTION PASSED
2012-09-19	CVIP	S5708	EK87545	8643498	INSPECTION PASSED

VEHICLE REGISTRATION: 03773812 PLATE 84827C 2007 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-09-28	CVSA			8220870	INSPECTION PASSED
2013-02-04	CVSA			8126420	VIOLATIONS PRESENT

VEHICLE REGISTRATION: 03845693 PLATE 12403P 09 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-12-21	CVIP	S6948	EP04474	9300639	INSPECTION PASSED
2013-12-03	CVSA			8252830	VIOLATIONS PRESENT
2013-06-22	CVIP	S6948	EN00414	8992318	INSPECTION PASSED
2013-05-13	CVSA				INSPECTION PASSED
2013-03-05	CVSA				INSPECTION PASSED
2013-02-14	CVSA				INSPECTION PASSED
2013-01-22	CVSA				INSPECTION PASSED

CVSE-NSCSP351 (P)
2015-05-11

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 03847220 PLATE 09161P 2007 KENWORTH

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-02-01	CVSA			8125602	VIOLATIONS PRESENT
2013-01-13	CVSA			8119645	INSPECTION PASSED
2012-12-24	CVIP	S0621	EL15733	8746859	INSPECTION PASSED
2012-06-21	CVSA			8098465	VIOLATIONS PRESENT

VEHICLE REGISTRATION: 03876943 PLATE 04756P 07 KENWORTH

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-11-22	CVIP	S6948	EL42209	8713609	INSPECTION PASSED
2012-10-18	CVSA				INSPECTION PASSED
2012-07-13	CVSA			8100560	INSPECTION PASSED
2012-06-28	CVSA				VIOLATIONS PRESENT
2012-06-12	CVSA				INSPECTION PASSED

VEHICLE REGISTRATION: 03883752 PLATE 12818P 07 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-07-03	CVIP	S4168	EK32701	8559916	INSPECTION PASSED

VEHICLE REGISTRATION: 03912952 PLATE 05 PETERBILT

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-06-02	CVIP	S6948	EJ60579	8522717	INSPECTION PASSED

VEHICLE REGISTRATION: 03919308 PLATE 12991P 07 KENWORTH

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-04-25	CVIP	S6948	ES66441	10352074	INSPECTION PASSED
2014-10-04	CVIP	S6948	ER38420	9936674	INSPECTION PASSED
2014-05-24	CVSA			8330225	INSPECTION PASSED
2014-04-12	CVIP	S6948	EP42208	9527776	INSPECTION PASSED
2014-04-12	CVIP	S6948		9527775	VEHICLE INSPECTION REJECTED
2013-10-24	CVIP	S6948	EN28282	9171230	INSPECTION PASSED
2013-05-25	CVSA			8169442	INSPECTION PASSED
2013-05-02	CVSA				INSPECTION PASSED
2013-04-06	CVIP	S6948	EM39804	8869551	INSPECTION PASSED
2013-03-20	CVSA			8142560	INSPECTION PASSED
2012-10-22	CVSA				INSPECTION PASSED
2012-10-05	CVIP	S6948	EK03960	8663753	INSPECTION PASSED

VEHICLE REGISTRATION: 03922480 PLATE JB8957 09 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-04-26	CVIP	S5242	ER26752	10352728	INSPECTION PASSED
2015-02-21	CVSA			8431011	OUT OF SERVICE

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 04142170 PLATE 12124P 09 VOLVO

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-01-11	CVIP	S6978	EL40270	8763451	INSPECTION PASSED

VEHICLE REGISTRATION: 04180780 PLATE 12123P 2009 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-01-24	CVSA			8123220	INSPECTION PASSED

VEHICLE REGISTRATION: 04276109 PLATE 17947P 2009 KENWORTH

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-06-03	CVSA			8333731	VIOLATIONS PRESENT
2014-04-12	CVIP	S7225	EQ12958	9527188	INSPECTION PASSED
2014-04-12	CVIP	S7225		9527187	VEHICLE INSPECTION REJECTED
2013-10-05	CVIP	S7225	EN83809	9148379	INSPECTION PASSED
2013-09-28	CVSA			8220870	INSPECTION PASSED
2013-08-01	CVSA				INSPECTION PASSED
2013-05-03	CVSA				INSPECTION PASSED
2013-04-06	CVIP	S6266	EM20914	8869179	INSPECTION PASSED
2013-04-06	CVIP	S6266		8869177	VEHICLE INSPECTION REJECTED

VEHICLE REGISTRATION: 04502550 PLATE 09175P 05 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-12-01	CVIP	S6978		9253144	VEHICLE INSPECTION REJECTED
2013-12-01	CVIP	S6978	EN42464	9253145	INSPECTION PASSED
2013-07-27	CVSA			8196510	VIOLATIONS PRESENT
2013-05-01	CVIP	S6978	EL41777	8907889	INSPECTION PASSED
2013-05-01	CVIP	S6978		8907744	VEHICLE INSPECTION REJECTED
2013-03-21	CVSA			8143131	INSPECTION PASSED
2012-12-05	CVSA			8114694	INSPECTION PASSED
2012-10-06	CVIP	S6285	EL07745	8664541	INSPECTION PASSED
2012-10-06	CVIP	S6285		8664534	VEHICLE INSPECTION REJECTED
2012-08-13	CVSA			8103134	VIOLATIONS PRESENT

VEHICLE REGISTRATION: 04937980 PLATE 12979P 1998 PETERBILT

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-06-06	CVSA			8175970	VIOLATIONS PRESENT
2013-01-11	CVIP	S6632	EL60485	8763944	INSPECTION PASSED
2012-10-17	CVSA			8109544	VIOLATIONS PRESENT
2012-07-16	CVIP	S6903	EJ60508	8572769	INSPECTION PASSED
2012-07-16	CVIP	S6903		8572766	VEHICLE INSPECTION REJECTED
2012-06-05	CVSA			8098586	VIOLATIONS PRESENT

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 06432738 PLATE 09 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-05-08	CVIP	S5944	EM42416	8920355	INSPECTION PASSED
2013-05-08	CVIP	S5944		8920329	VEHICLE INSPECTION REJECTED

VEHICLE REGISTRATION: 06461671 PLATE 13825P 05 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-06-12	CVIP	S6948	EJ60588	8533806	INSPECTION PASSED
2012-05-17	CVSA				VIOLATIONS PRESENT

VEHICLE REGISTRATION: 06944009 PLATE 1084WL 90 KENWORTH

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-08-12	CVIP	S6978	EQ79924	9810262	INSPECTION PASSED
2013-10-02	CVIP	S6978	EN42416	9143592	INSPECTION PASSED
2013-10-02	CVIP	S6978		9143576	VEHICLE INSPECTION REJECTED
2013-03-06	CVIP	S6978	EL40325	8828361	INSPECTION PASSED
2013-02-06	CVIP	S6978	RD04009	8793911	VEHICLE INSPECTION REJECTED
2012-07-13	CVIP	S6978	EJ40009	8571085	INSPECTION PASSED

VEHICLE REGISTRATION: 07238242 PLATE 07228P 2007 KENWORTH

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-12-03	CVSA			8409551	INSPECTION PASSED
2014-08-30	CVIP	S6978	EQ79938	9855172	INSPECTION PASSED
2014-03-17	CVIP	S6978	EN42559	9467083	INSPECTION PASSED
2013-08-13	CVIP	S6978	EN42351	9071516	INSPECTION PASSED
2013-08-13	CVIP	S6978		9071478	VEHICLE INSPECTION REJECTED
2013-05-24	CVSA			8169396	VIOLATIONS PRESENT
2013-05-09	CVSA			8162030	VIOLATIONS PRESENT
2013-02-14	CVIP	S6978	EL40307	8801675	INSPECTION PASSED
2013-02-14	CVIP	S6978		8801649	VEHICLE INSPECTION REJECTED
2013-01-03	CVSA			8117450	VIOLATIONS PRESENT
2012-11-20	CVSA				INSPECTION PASSED
2012-08-25	CVIP	S6978	EK17456	8615918	INSPECTION PASSED
2012-06-29	CVSA				VIOLATIONS PRESENT

VEHICLE REGISTRATION: 08618565 PLATE 11838P 2007 PETERBILT

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-05-08	CVSA			8440435	VIOLATIONS PRESENT
2015-01-23	CVIP	S5708	ES09655	10165917	INSPECTION PASSED
2014-09-08	CVSA			8375582	OUT OF SERVICE
2014-08-18	CVSA			8366371	INSPECTION PASSED
2014-07-01	CVIP	S5708	EQ56064	9713525	INSPECTION PASSED
2014-07-01	CVIP	S5708		9713524	VEHICLE INSPECTION REJECTED
2014-02-04	CVSA				VIOLATIONS PRESENT
2014-01-07	CVSA				INSPECTION PASSED
2013-12-01	CVIP	S5708	EP36221	9253393	INSPECTION PASSED

CVSE-NSCSP351 (P)
2015-05-11

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 08618565 PLATE 11838P 07 PETERBILT (CONTINUED)
2013-05-01 CVIP S6978 EL41776 8906117 INSPECTION PASSED
2013-05-01 CVIP S6978 8906097 VEHICLE INSPECTION REJECTED
2012-11-16 CVSA 8113115 VIOLATIONS PRESENT
2012-10-29 CVIP S6268 EK87438 8689452 INSPECTION PASSED

VEHICLE REGISTRATION: 09488094 PLATE EM1001 96 INTERNATNA

DATE ACTION FACILITY# DECAL # MICROFILM # OUTCOME
2014-07-06 CVIP S6978 EP88726 9727635 INSPECTION PASSED
2013-12-22 CVIP S6978 EN42482 9302526 INSPECTION PASSED
2013-12-22 CVIP S6978 9302525 VEHICLE INSPECTION REJECTED
2013-05-28 CVIP S6978 EL41851 9000858 INSPECTION PASSED
2013-05-28 CVIP S6978 9000835 VEHICLE INSPECTION REJECTED
2012-11-13 CVIP S6978 EK18212 8703090 INSPECTION PASSED

VEHICLE REGISTRATION: 09582853 PLATE 10 PETERBILT

DATE ACTION FACILITY# DECAL # MICROFILM # OUTCOME
2014-07-12 CVIP S3817 EQ69531 9739314 INSPECTION PASSED
2014-07-12 CVIP S3817 9739313 VEHICLE INSPECTION REJECTED
2014-04-30 CVSA INSPECTION PASSED
2014-04-23 CVSA INSPECTION PASSED
2014-01-31 CVSA INSPECTION PASSED
2014-01-02 CVIP S3817 EP34365 9316475 INSPECTION PASSED
2013-09-19 CVSA 8218100 INSPECTION PASSED
2013-07-31 CVSA INSPECTION PASSED
2013-06-15 CVIP S3817 EN07826 8981828 INSPECTION PASSED
2013-06-15 CVIP S3817 8981826 VEHICLE INSPECTION REJECTED
2013-02-12 CVSA 8128924 INSPECTION PASSED
2012-12-14 CVSA 8115479 INSPECTION PASSED
2012-12-11 CVSA INSPECTION PASSED
2012-12-01 CVIP S3817 EL79573 8724564 INSPECTION PASSED
2012-07-20 CVSA 8101227 INSPECTION PASSED

VEHICLE REGISTRATION: 09649734 PLATE P93686 2009 VOLVO

DATE ACTION FACILITY# DECAL # MICROFILM # OUTCOME
2015-01-11 CVSA 8422420 VIOLATIONS PRESENT
2015-01-11 N&O 8422420 NOTICE & ORDER 2
2014-10-27 CVSA 8395751 INSPECTION PASSED
2014-10-16 CVSA 8391330 VIOLATIONS PRESENT
2014-09-16 CVSA INSPECTION PASSED
2014-06-02 CVIP S6978 EP88687 9649475 INSPECTION PASSED
2014-02-04 CVSA INSPECTION PASSED
2013-11-21 CVIP S6605 EN11835 9225925 INSPECTION PASSED
2013-11-21 CVIP S6605 9225924 VEHICLE INSPECTION REJECTED
2013-01-14 CVSA 8119941 INSPECTION PASSED

SECTION 5

PAGE: 36

CVSE-NSCSP351 (P)
2015-05-11

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 09760484 PLATE 84832C 2007 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-03-20	CVSA			8142560	INSPECTION PASSED

VEHICLE REGISTRATION: 09845578 PLATE P93885 07 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-04-24	CVIP	S4438	ES96853	10351547	INSPECTION PASSED
2015-04-24	CVIP	S4438		10351546	VEHICLE INSPECTION REJECTED
2015-03-12	CVSA			8433391	VIOLATIONS PRESENT
2014-10-04	CVIP	S4438	ER29632	9936888	INSPECTION PASSED
2014-10-04	CVIP	S4438		9936887	VEHICLE INSPECTION REJECTED
2014-09-21	CVIP	S6735	RD02362	9900711	VEHICLE INSPECTION REJECTED
2014-09-21	CVSA			8381182	VIOLATIONS PRESENT
2014-09-21	N&O			8381182	NOTICE & ORDER 2
2014-09-05	N&O			8374770	NOTICE & ORDER 2
2014-08-21	CVIP	S4438	EQ85635	9834371	INSPECTION PASSED
2014-08-21	CVIP	S4438		9834370	VEHICLE INSPECTION REJECTED
2014-05-14	CVSA			8326960	VIOLATIONS PRESENT
2014-04-11	CVSA			8314150	INSPECTION PASSED
2014-02-22	CVIP	S4438	EP51381	9415266	INSPECTION PASSED
2014-02-22	CVIP	S4438		9415265	VEHICLE INSPECTION REJECTED
2013-08-15	CVIP	S4438	EN23898	9075647	INSPECTION PASSED
2013-05-04	CVSA			8160040	VIOLATIONS PRESENT
2013-02-22	CVIP	S4438	EL88680	8811548	INSPECTION PASSED
2013-02-22	CVIP	S4438		8811536	VEHICLE INSPECTION REJECTED
2013-02-04	CVSA			8126420	VIOLATIONS PRESENT
2012-08-23	CVIP	S4438	EK62101	8613049	INSPECTION PASSED
2012-08-23	CVIP	S4438		8613026	VEHICLE INSPECTION REJECTED

VEHICLE REGISTRATION: 09861648 PLATE JJ2912 2006 VOLVO

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-03-01	CVSA			8431847	INSPECTION PASSED

VEHICLE REGISTRATION: 09861668 PLATE 20239P 07 VOLVO

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-05-21	CVIP	S6912	EP41572	9623781	INSPECTION PASSED
2014-05-21	CVIP	S6912		9623780	VEHICLE INSPECTION REJECTED
2013-11-18	CVIP	S6912	EN66509	9225643	INSPECTION PASSED
2013-11-13	CVSA			8239760	INSPECTION PASSED
2013-06-05	CVSA			8174953	INSPECTION PASSED
2013-04-15	CVIP	S6912	EM42189	8917055	INSPECTION PASSED
2013-04-15	CVIP	S6912		8917027	VEHICLE INSPECTION REJECTED
2013-03-24	CVSA			8143832	VIOLATIONS PRESENT
2012-10-27	CVIP	S6266	EL02820	8685760	INSPECTION PASSED
2012-10-27	CVIP	S6266		8685754	VEHICLE INSPECTION REJECTED
2012-10-10	CVSA			8108811	INSPECTION PASSED

SECTION 5

PAGE: 37

CVSE-NSCSP351 (P)
2015-05-11

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 09868148 PLATE 18907P 04 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-08-31	CVIP	S6978		9102569	VEHICLE INSPECTION REJECTED
2013-08-31	CVIP	S6978	EN42382	9102578	INSPECTION PASSED
2013-06-05	CVSA			8175763	VIOLATIONS PRESENT
2013-04-18	CVSA			8154832	VIOLATIONS PRESENT

VEHICLE REGISTRATION: 09874313 PLATE 10 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-08-30	CVIP	S6266	EQ91784	9855016	INSPECTION PASSED
2014-08-30	CVIP	S6266		9855015	VEHICLE INSPECTION REJECTED
2014-08-06	CVSA			8360031	VIOLATIONS PRESENT
2014-08-06	CVSA			8360053	OUT OF SERVICE
2014-02-14	CVIP	S6948	EP42121	9398422	INSPECTION PASSED
2014-01-09	CVSA			8265173	INSPECTION PASSED
2013-11-25	CVSA			8245960	VIOLATIONS PRESENT
2013-09-17	CVSA			8217231	INSPECTION PASSED
2013-08-31	CVIP	S6266	EN07152	9102559	INSPECTION PASSED
2013-08-31	CVIP	S6266		9102556	VEHICLE INSPECTION REJECTED
2013-05-13	CVSA				INSPECTION PASSED
2013-05-06	CVSA			8160382	INSPECTION PASSED

VEHICLE REGISTRATION: 09955897 PLATE 15697P VOLV

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-07-20	CVSA				INSPECTION PASSED
2014-07-09	CVSA				INSPECTION PASSED
2014-06-30	CVIP	S6978	EP88714	9716132	INSPECTION PASSED
2013-12-05	CVIP	S0134	EN54295	9266971	INSPECTION PASSED
2013-12-05	CVIP	S0134		9266985	VEHICLE INSPECTION REJECTED
2013-10-05	CVSA			8223410	INSPECTION PASSED
2013-08-27	CVSA			8210530	VIOLATIONS PRESENT
2013-06-26	CVIP	S6605	EM47773	8997739	INSPECTION PASSED

VEHICLE REGISTRATION: 09973332 PLATE 10954P FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-04-06	CVSA				VIOLATIONS PRESENT

VEHICLE REGISTRATION: 10005562 PLATE 71827C 2011 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-06-13	CVSA			8097527	VIOLATIONS PRESENT

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 10013446 PLATE 08648P 2007 PETERBILT

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-10-17	CVSA			8109576	INSPECTION PASSED
2012-09-01	CVIP	S4438	EK62597	8625038	INSPECTION PASSED

VEHICLE REGISTRATION: 10022141 PLATE 15698P VOLVO

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-12-02	CVSA				OUT OF SERVICE
2014-09-11	CVSA				VIOLATIONS PRESENT
2013-11-17	CVIP	S6978	EN42454	9213293	INSPECTION PASSED
2013-08-28	CVSA				INSPECTION PASSED
2013-08-22	CVSA				INSPECTION PASSED
2013-01-07	CVSA			8118141	INSPECTION PASSED

VEHICLE REGISTRATION: 10042150 PLATE 84837C 2010 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-05-30	CVSA			8332487	INSPECTION PASSED
2013-05-06	CVSA			8160382	OUT OF SERVICE

VEHICLE REGISTRATION: 10042360 PLATE 73568C 2011 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-11-28	CVSA			8249410	INSPECTION PASSED

VEHICLE REGISTRATION: 10070282 PLATE 08677P 06 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-04-23	CVIP	S1441	ES73059	10347672	INSPECTION PASSED
2015-03-22	CVSA			8434371	VIOLATIONS PRESENT
2015-02-12	CVSA				VIOLATIONS PRESENT
2014-10-21	CVSA			8393142	INSPECTION PASSED
2014-10-10	CVIP	S6285	ER38838	9951809	INSPECTION PASSED
2014-09-09	CVSA			8375810	INSPECTION PASSED
2014-07-23	CVSA				INSPECTION PASSED
2014-06-10	CVSA			8336846	INSPECTION PASSED
2014-04-12	CVIP	S7076	EQ02722	9530535	INSPECTION PASSED
2013-12-21	CVSA				INSPECTION PASSED
2013-10-08	CVIP	S6978	EN42421	9151066	INSPECTION PASSED
2013-10-08	CVIP	S6978		9150907	VEHICLE INSPECTION REJECTED
2013-07-05	CVSA				INSPECTION PASSED
2013-06-14	CVSA				VIOLATIONS PRESENT
2013-04-11	CVIP	S6948	EM39808	8876667	INSPECTION PASSED
2013-03-01	CVSA				INSPECTION PASSED
2013-02-08	CVSA			8128361	INSPECTION PASSED
2012-10-05	CVIP	S6948	EK03961	8664358	INSPECTION PASSED
2012-07-12	CVSA				INSPECTION PASSED

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 10097522	PLATE 10946P	VOLV			
DATE 2012-12-02	ACTION CVSA	FACILITY#	DECAL #	MICROFILM #	OUTCOME INSPECTION PASSED
VEHICLE REGISTRATION: 10102067	PLATE 73557C	2011 UTILITY			
DATE 2013-06-05	ACTION CVSA	FACILITY#	DECAL #	MICROFILM # 8174953	OUTCOME VIOLATIONS PRESENT
VEHICLE REGISTRATION: 10104464	PLATE 12386P	2011 VOLVO			
DATE 2013-01-25	ACTION CVSA	FACILITY#	DECAL #	MICROFILM # 8123584	OUTCOME VIOLATIONS PRESENT
2012-12-13	CVIP	S6978	EL40230	8736840	INSPECTION PASSED
VEHICLE REGISTRATION: 10109897	PLATE 12389P	2011 VOLVO			
DATE 2013-01-06	ACTION CVSA	FACILITY#	DECAL #	MICROFILM # 8118010	OUTCOME VIOLATIONS PRESENT
2012-12-28	CVIP	S6978	EL40245	8748826	INSPECTION PASSED
2012-12-28	CVIP	S6978		8748750	VEHICLE INSPECTION REJECTED
VEHICLE REGISTRATION: 10117468	PLATE	11 FREIGHTLIN			
DATE 2014-06-23	ACTION CVIP	FACILITY# S4438	DECAL # EQ35879	MICROFILM # 9697137	OUTCOME INSPECTION PASSED
2014-06-23	CVIP	S4438		9697136	VEHICLE INSPECTION REJECTED
2014-05-07	CVSA				INSPECTION PASSED
VEHICLE REGISTRATION: 10146233	PLATE 17171P	2012 FREIGHTLIN			
DATE 2014-10-16	ACTION CVSA	FACILITY#	DECAL #	MICROFILM # 8391750	OUTCOME VIOLATIONS PRESENT
2014-09-24	CVIP	S6750	ER06433	9909278	INSPECTION PASSED
2014-09-18	CVSA			8380201	INSPECTION PASSED
2014-04-28	CVSA			8319440	VIOLATIONS PRESENT
2014-03-13	CVIP	S6750	EP78351	9458175	INSPECTION PASSED
2014-01-05	CVSA			8263660	VIOLATIONS PRESENT
VEHICLE REGISTRATION: 10149384	PLATE 84835C	2008 UTILITY			
DATE 2013-02-27	ACTION CVSA	FACILITY#	DECAL #	MICROFILM # 8134791	OUTCOME VIOLATIONS PRESENT
2013-02-12	CVSA			8128998	INSPECTION PASSED
VEHICLE REGISTRATION: 10154257	PLATE 19869P	2007 FREIGHTLIN			
DATE 2014-10-08	ACTION CVSA	FACILITY#	DECAL #	MICROFILM # 8388381	OUTCOME VIOLATIONS PRESENT
2014-06-24	CVSA			8341980	VIOLATIONS PRESENT

CVSE-NSCSP351 (P)
2015-05-11

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 10163691	PLATE	11	VOLVO		
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-04-26	CVIP	S6978		8899608	VEHICLE INSPECTION REJECTED
2013-04-26	CVIP	S6978	EL41771	8899616	INSPECTION PASSED
2012-12-05	CVSA				INSPECTION PASSED
2012-10-31	CVIP	S4168	EL17708	8690319	INSPECTION PASSED
2012-10-21	CVSA			8110022	VIOLATIONS PRESENT
VEHICLE REGISTRATION: 10164538	PLATE 10417D		2005 UTILITY		
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-04-18	CVSA			8154832	INSPECTION PASSED
2012-10-11	CVSA			8109008	INSPECTION PASSED
VEHICLE REGISTRATION: 10175467	PLATE 84843C		2012 UTILITY		
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-05-04	CVSA			8160010	INSPECTION PASSED
VEHICLE REGISTRATION: 10186432	PLATE 80441C		2012 UTILITY		
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-10-18	CVSA			8392391	VIOLATIONS PRESENT
2012-10-21	CVSA			8110022	VIOLATIONS PRESENT
VEHICLE REGISTRATION: 10186436	PLATE 80442C		2012 UTILITY		
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-09-04	CVSA			8212632	INSPECTION PASSED
2013-01-25	CVSA			8123581	INSPECTION PASSED
2012-08-01	CVSA			8102212	VIOLATIONS PRESENT
VEHICLE REGISTRATION: 10195074	PLATE 86656C		2012 UTILITY		
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-02-12	CVSA			8128924	INSPECTION PASSED
2012-06-05	CVSA			8098674	INSPECTION PASSED
VEHICLE REGISTRATION: 10195084	PLATE 86657C		2012 UTILITY		
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-03-01	CVSA			8431847	INSPECTION PASSED
VEHICLE REGISTRATION: 10195118	PLATE 86659C		2012 UTILITY		
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-01-23	CVSA			8123120	OUT OF SERVICE
2012-10-18	CVSA			8109781	INSPECTION PASSED

CVSE-NSCSP351 (P)
2015-05-11

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION:	10206113	PLATE	86589C	2012 UTILITY	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-04-09	CVSA			8436305	VIOLATIONS PRESENT
VEHICLE REGISTRATION:	10208028	PLATE	86613C	2012 UTILITY	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-09-25	CVSA			8107429	OUT OF SERVICE
VEHICLE REGISTRATION:	10208038	PLATE	86618C	2012 UTILITY	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-09-17	CVSA			8217475	INSPECTION PASSED
2013-01-21	CVSA			8122072	INSPECTION PASSED
VEHICLE REGISTRATION:	10208068	PLATE	86615C	2012 UTILITY	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-09-08	CVSA			8375582	INSPECTION PASSED
VEHICLE REGISTRATION:	10208076	PLATE	86614C	2012 UTILITY	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-09-18	CVSA			8106633	VIOLATIONS PRESENT
VEHICLE REGISTRATION:	10208509	PLATE	07259P	FRHT	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-01-30	CVSA				INSPECTION PASSED
2014-01-21	CVSA				INSPECTION PASSED
2013-11-30	CVIP	S6978	EN42462	9251304	INSPECTION PASSED
2013-11-30	CVIP	S6978		9251303	VEHICLE INSPECTION REJECTED
2013-11-27	CVSA				INSPECTION PASSED
2013-08-28	CVSA				INSPECTION PASSED
2013-05-22	CVIP	S6978	EL41796	8939066	INSPECTION PASSED
2013-05-14	CVSA			8164296	VIOLATIONS PRESENT
2013-04-23	CVSA				INSPECTION PASSED
2013-03-26	CVSA				OUT OF SERVICE
2013-01-26	CVSA				INSPECTION PASSED
2012-11-23	CVIP	S6978	EL40203	8714903	INSPECTION PASSED
2012-11-23	CVIP	S6978		8714819	VEHICLE INSPECTION REJECTED
2012-10-03	CVSA				INSPECTION PASSED
2012-07-04	CVSA			8099672	VIOLATIONS PRESENT
2012-06-22	CVSA				VIOLATIONS PRESENT
2012-06-06	CVSA				VIOLATIONS PRESENT
2012-06-04	CVSA				INSPECTION PASSED
2012-05-26	CVIP	S6978	EE45018	8512119	INSPECTION PASSED
2012-05-26	CVIP	S6978		8512110	VEHICLE INSPECTION REJECTED

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 10212350	PLATE 88765C	2007 UTILITY
DATE 2012-07-04	ACTION CVSA	FACILITY# DECAL # MICROFILM # OUTCOME 8099697 OUT OF SERVICE
VEHICLE REGISTRATION: 10234609	PLATE 86558C	2012 UTILITY
DATE 2012-05-18	ACTION CVSA	FACILITY# DECAL # MICROFILM # OUTCOME 8094795 INSPECTION PASSED
VEHICLE REGISTRATION: 10234635	PLATE 86559C	2012 UTILITY
DATE 2013-03-25	ACTION CVSA	FACILITY# DECAL # MICROFILM # OUTCOME 8144028 INSPECTION PASSED
VEHICLE REGISTRATION: 10247109	PLATE 21787P	FRHT
DATE 2015-02-09	ACTION CVSA	FACILITY# DECAL # MICROFILM # OUTCOME INSPECTION PASSED
2014-12-06	CVIP	S4438 ER85295 10074308 INSPECTION PASSED
2014-12-06	CVIP	S4438 10074307 VEHICLE INSPECTION REJECTED
2014-11-20	CVSA	INSPECTION PASSED
2014-09-09	CVSA	8375970 INSPECTION PASSED
2014-09-08	CVSA	8375450 VIOLATIONS PRESENT
VEHICLE REGISTRATION: 10287216	PLATE 12120P	2007 FREIGHTLIN
DATE 2012-12-04	ACTION CVSA	FACILITY# DECAL # MICROFILM # OUTCOME 8114449 VIOLATIONS PRESENT
VEHICLE REGISTRATION: 10299186	PLATE 21781P	2012 KENWORTH
DATE 2015-04-09	ACTION CVSA	FACILITY# DECAL # MICROFILM # OUTCOME 8436305 VIOLATIONS PRESENT
2015-01-02	CVIP	S5708 ER85571 10118635 INSPECTION PASSED
VEHICLE REGISTRATION: 10302250	PLATE 22260P	07 FREIGHTLIN
DATE 2014-12-27	ACTION CVIP	FACILITY# DECAL # MICROFILM # OUTCOME 10109164 VEHICLE INSPECTION REJECTED
2014-12-27	CVIP	S6948 ER66764 10109165 INSPECTION PASSED
2014-12-03	CVSA	8409587 INSPECTION PASSED
VEHICLE REGISTRATION: 10338714	PLATE 98814C	2012 UTILITY
DATE 2013-03-24	ACTION CVSA	FACILITY# DECAL # MICROFILM # OUTCOME 8143832 INSPECTION PASSED
VEHICLE REGISTRATION: 10346220	PLATE 12116P	2012 VOLVO
DATE 2013-01-23	ACTION CVSA	FACILITY# DECAL # MICROFILM # OUTCOME 8123120 VIOLATIONS PRESENT
2013-01-17	CVSA	8121050 INSPECTION PASSED

CVSE-NSCSP351 (P)
2015-05-11

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
VEHICLE REGISTRATION: 10350135 PLATE 15699P VOLV					
2014-11-28	CVSA				INSPECTION PASSED
2014-11-09	CVSA				INSPECTION PASSED
2014-10-12	CVIP	S6978	EQ79960	9957830	INSPECTION PASSED
2014-04-28	CVIP	S6978	EN42632	9560902	INSPECTION PASSED
2014-04-28	CVIP	S6978		9560901	VEHICLE INSPECTION REJECTED
2014-01-20	CVSA				INSPECTION PASSED
2013-12-23	CVSA				INSPECTION PASSED
2013-11-05	CVSA				INSPECTION PASSED
2013-10-29	CVIP	S6978	EN42440	9178305	INSPECTION PASSED
2013-10-29	CVIP	S6978		9178128	VEHICLE INSPECTION REJECTED
2013-10-23	CVSA				INSPECTION PASSED
2013-04-09	CVIP	S6978	EL14748	8873075	INSPECTION PASSED
2013-04-09	CVIP	S6978		8873018	VEHICLE INSPECTION REJECTED
2013-01-24	CVSA			8123490	INSPECTION PASSED
VEHICLE REGISTRATION: 10383700 PLATE 05244D 2012 UTILITY					
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-01-28	CVSA			8275560	INSPECTION PASSED
2014-01-28	CVSA			8275551	INSPECTION PASSED
VEHICLE REGISTRATION: 10383711 PLATE 05246D 2012 UTILITY					
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-05-07	CVSA			8440228	INSPECTION PASSED
2013-01-25	CVSA			8123584	INSPECTION PASSED
VEHICLE REGISTRATION: 10383723 PLATE 05248D 2012 UTILITY					
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-03-22	CVSA			8434371	INSPECTION PASSED
2013-05-30	CVSA			8171300	INSPECTION PASSED
2012-06-05	CVSA			8096503	INSPECTION PASSED
VEHICLE REGISTRATION: 10390303 PLATE 05262D 2012 UTILITY					
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-02-05	CVSA			8280013	OUT OF SERVICE
VEHICLE REGISTRATION: 10390315 PLATE 05265D 2012 UTILITY					
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-09-30	CVSA			8385401	INSPECTION PASSED
2012-05-19	CVSA			8094831	INSPECTION PASSED

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 10390317		PLATE 05266D		2012 UTILITY	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-06-10	CVSA			8336846	INSPECTION PASSED
2014-05-01	CVSA			8322290	VIOLATIONS PRESENT
2014-01-03	CVSA			8263380	INSPECTION PASSED
VEHICLE REGISTRATION: 10392576		PLATE 20427P		2012 FREIGHTLIN	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-02-15	CVSA			8430053	VIOLATIONS PRESENT
VEHICLE REGISTRATION: 10406308		PLATE 12122P		09 MACK	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-06-07	CVIP	S6978	EL41824	8969112	INSPECTION PASSED
VEHICLE REGISTRATION: 10449708		PLATE 10420D		2012 UTILITY	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-05-06	CVSA			8323701	INSPECTION PASSED
2013-04-12	CVSA			8152141	INSPECTION PASSED
2012-06-05	CVSA			8096263	INSPECTION PASSED
VEHICLE REGISTRATION: 10472597		PLATE 10422D		2012 PACESETTER	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-09-08	CVSA			8375561	INSPECTION PASSED
VEHICLE REGISTRATION: 10498892		PLATE 10470D		2012 UTILITY	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-11-07	CVSA			8399571	VIOLATIONS PRESENT
2014-08-21	CVSA			8369070	VIOLATIONS PRESENT
2013-06-06	CVSA			8176451	INSPECTION PASSED
VEHICLE REGISTRATION: 10505157		PLATE 12125P		2010 FREIGHTLIN	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2012-12-12	CVSA			8115273	INSPECTION PASSED
VEHICLE REGISTRATION: 10549828		PLATE 16144P		2007 FREIGHTLIN	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-05-06	CVSA			8323701	INSPECTION PASSED
2014-04-07	CVSA			8311380	INSPECTION PASSED
2014-03-01	CVIP	S6285	EP42009	9431845	INSPECTION PASSED
2013-12-23	CVSA				INSPECTION PASSED
2013-10-24	CVSA			8233626	INSPECTION PASSED
2013-09-25	CVSA				VIOLATIONS PRESENT

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 10564421 PLATE 10910P FRHT

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-01-09	CVSA				INSPECTION PASSED
2012-11-23	CVSA				INSPECTION PASSED
2012-10-25	CVSA				INSPECTION PASSED
2012-10-24	CVSA			8110352	VIOLATIONS PRESENT
2012-10-24	CVSA				VIOLATIONS PRESENT
2012-10-16	CVSA				INSPECTION PASSED

VEHICLE REGISTRATION: 10566182 PLATE 24623P 13 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-02-04	CVIP	S6948	ER66812	10189708	INSPECTION PASSED
2015-02-04	CVIP	S6948		10189707	VEHICLE INSPECTION REJECTED
2014-08-07	CVIP	S6948	EQ77809	9799495	INSPECTION PASSED
2014-08-07	CVIP	S6948		9799494	VEHICLE INSPECTION REJECTED
2014-02-18	CVIP	S6948	EP42130	9404775	INSPECTION PASSED
2014-02-18	CVIP	S6948		9404743	VEHICLE INSPECTION REJECTED
2014-01-03	CVSA			8263380	INSPECTION PASSED
2013-08-13	CVIP	S6268	EM42069	9072677	INSPECTION PASSED
2013-02-08	CVIP	S6268	EL18460	8796498	INSPECTION PASSED

VEHICLE REGISTRATION: 10572840 PLATE 13 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-02-13	CVIP	S6333	ES00397	10202858	INSPECTION PASSED
2015-02-08	CVIP	S6647	RD04251	10195277	VEHICLE INSPECTION REJECTED
2014-09-08	CVSA			8375531	INSPECTION PASSED
2014-08-21	CVIP	S6654	EQ48056	9831411	INSPECTION PASSED
2014-08-21	CVIP	S6654		9831410	VEHICLE INSPECTION REJECTED
2014-08-21	CVSA			8369070	VIOLATIONS PRESENT
2014-03-12	CVSA			8297650	INSPECTION PASSED
2014-02-08	CVIP	S6654	EN86747	9387648	INSPECTION PASSED
2013-07-30	CVIP	S6654	EN16440	9050183	INSPECTION PASSED
2013-07-30	CVIP	S6654		9050169	VEHICLE INSPECTION REJECTED
2013-01-21	CVIP	S6647	EL57533	8773576	INSPECTION PASSED
2012-12-11	CVSA			8115204	INSPECTION PASSED

VEHICLE REGISTRATION: 10580984 PLATE 20099D 2013 WABASH

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-08-18	CVSA			8366277	INSPECTION PASSED

VEHICLE REGISTRATION: 10580990 PLATE 20097D 2013 WABASH

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-04-02	CVSA			8147060	INSPECTION PASSED

CVSE-NSCSP351 (P)
2015-05-11

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 10581669	PLATE 24655P	2013 PETERBILT			
DATE 2015-05-06	ACTION CVSA	FACILITY#	DECAL #	MICROFILM # 8439954	OUTCOME INSPECTION PASSED
VEHICLE REGISTRATION: 10585421	PLATE 22901D	2013 VANGUARD			
DATE 2015-02-21	ACTION CVSA	FACILITY#	DECAL #	MICROFILM # 8431011	OUTCOME VIOLATIONS PRESENT
2014-08-28	CVSA			8372163	INSPECTION PASSED
VEHICLE REGISTRATION: 10585429	PLATE 22902D	2013 VANGUARD			
DATE 2014-10-21	ACTION CVSA	FACILITY#	DECAL #	MICROFILM # 8393142	OUTCOME INSPECTION PASSED
VEHICLE REGISTRATION: 10589942	PLATE 20437P	2013 FREIGHTLIN			
DATE 2015-03-31	ACTION CVSA	FACILITY#	DECAL #	MICROFILM # 8435493	OUTCOME VIOLATIONS PRESENT
VEHICLE REGISTRATION: 10590974	PLATE 22900D	2013 VANGUARD			
DATE 2012-10-24	ACTION CVSA	FACILITY#	DECAL #	MICROFILM # 8110352	OUTCOME INSPECTION PASSED
VEHICLE REGISTRATION: 10603519	PLATE 10950P	2013 FREIGHTLIN			
DATE 2012-09-25	ACTION CVSA	FACILITY#	DECAL #	MICROFILM # 8107429	OUTCOME VIOLATIONS PRESENT
VEHICLE REGISTRATION: 10603916	PLATE	07 FREIGHTLIN			
DATE 2014-11-15	ACTION CVIP	FACILITY# S5708	DECAL # ER66240	MICROFILM # 10026838	OUTCOME INSPECTION PASSED
2014-10-19	CVSA				INSPECTION PASSED
VEHICLE REGISTRATION: 10604227	PLATE 22380P	13 FREIGHTLIN			
DATE 2013-05-11	ACTION CVIP	FACILITY# S6978	DECAL # EL41783	MICROFILM # 8923807	OUTCOME INSPECTION PASSED
2013-04-13	CVSA				INSPECTION PASSED
2013-02-13	CVSA				INSPECTION PASSED
2013-01-17	CVSA				INSPECTION PASSED
VEHICLE REGISTRATION: 10614290	PLATE	13 FREIGHTLIN			
DATE 2015-01-24	ACTION CVIP	FACILITY# S6948	DECAL # ER66792	MICROFILM # 10167471	OUTCOME INSPECTION PASSED
2015-01-24	CVIP	S6948		10167470	VEHICLE INSPECTION REJECTED

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 10618315 PLATE 10926P 12 INTERNATNA

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-03-10	CVIP	S6978	EQ80006	10254935	INSPECTION PASSED

VEHICLE REGISTRATION: 10618690 PLATE 10928P 12 INTERNATNA

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-03-29	CVIP	S6978	EQ80022	10294111	INSPECTION PASSED
2015-03-29	CVIP	S6978		10294110	VEHICLE INSPECTION REJECTED
2014-09-29	CVIP	S6978	EQ79955	9920104	INSPECTION PASSED
2014-08-15	CVSA			8365380	OUT OF SERVICE
2014-03-19	CVIP	S5325	EP46680	9484510	INSPECTION PASSED
2014-03-19	CVIP	S5325		9484509	VEHICLE INSPECTION REJECTED
2014-02-11	CVSA				INSPECTION PASSED
2013-09-16	CVIP	S6978	EN42401	9121045	INSPECTION PASSED
2013-08-28	CVSA			8210692	INSPECTION PASSED
2013-03-14	CVSA				INSPECTION PASSED
2013-03-01	CVIP	S6978	EL40319	8821416	INSPECTION PASSED
2013-02-22	CVSA				INSPECTION PASSED
2012-10-29	CVSA				INSPECTION PASSED

VEHICLE REGISTRATION: 10618844 PLATE 23067P 12 INTERNATNA

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-03-04	CVIP	S6978	EQ80000	10240729	INSPECTION PASSED
2014-11-29	CVSA			8407690	VIOLATIONS PRESENT
2014-08-05	CVIP	S6978	EQ79918	9796465	INSPECTION PASSED
2013-08-14	CVSA				INSPECTION PASSED
2013-07-06	CVIP	S6978	EL41871	9015229	INSPECTION PASSED
2013-06-18	CVSA				INSPECTION PASSED
2013-05-01	CVSA				INSPECTION PASSED

VEHICLE REGISTRATION: 10619217 PLATE 01619P 2013 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-01-05	CVSA			8263633	INSPECTION PASSED
2013-11-23	CVIP	S6903	EN28800	9229981	INSPECTION PASSED
2013-05-02	CVIP	S6647	EM16751	8909307	INSPECTION PASSED
2013-04-17	CVSA				INSPECTION PASSED
2013-01-06	CVSA			8118038	INSPECTION PASSED

VEHICLE REGISTRATION: 10627033 PLATE 16145P 13 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-03-20	CVIP	S6903	ES10055	10275142	INSPECTION PASSED
2015-03-20	CVIP	S6903		10275141	VEHICLE INSPECTION REJECTED
2014-09-19	CVIP	S6903	ER10761	9898461	INSPECTION PASSED
2014-09-08	CVSA			8375561	INSPECTION PASSED
2014-06-23	CVSA			8341950	INSPECTION PASSED
2014-06-05	CVSA			8354072	INSPECTION PASSED

CVSE-NSCSP351 (P)
2015-05-11

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION:	10627033	PLATE	16145P	13	FREIGHTLIN	(CONTINUED)
2014-03-21	CVIP	S6903	EP74973	9474025	INSPECTION PASSED	
2013-09-14	CVIP	S6903	EN28751	9119640	INSPECTION PASSED	

VEHICLE REGISTRATION:	10628426	PLATE	22942D	2013	UTILITY	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME	
2013-05-14	CVSA			8164330	INSPECTION PASSED	

VEHICLE REGISTRATION:	10628433	PLATE	22943D	2013	UTILITY	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME	
2014-04-01	CVSA			8308581	OUT OF SERVICE	

VEHICLE REGISTRATION:	10678954	PLATE	20417P		FRHT	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME	
2014-10-13	CVSA				INSPECTION PASSED	

VEHICLE REGISTRATION:	10691202	PLATE		05	FREIGHTLIN	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME	
2014-12-31	CVIP	S6285	ER67067	10115278	INSPECTION PASSED	
2014-08-18	CVSA				INSPECTION PASSED	

VEHICLE REGISTRATION:	10693340	PLATE	21789P	08	KENWORTH	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME	
2014-11-26	CVIP	S6268		10051136	VEHICLE INSPECTION REJECTED	
2014-11-26	CVIP	S6268	ER13214	10051137	INSPECTION PASSED	
2014-11-14	CVSA			8402050	VIOLATIONS PRESENT	

VEHICLE REGISTRATION:	10695252	PLATE	19257P	13	FREIGHTLIN	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME	
2014-07-31	CVIP	S5716	ER10570	9788027	INSPECTION PASSED	
2014-04-12	CVSA			8314760	INSPECTION PASSED	
2014-01-11	CVIP	S6948	EP04489	9330617	INSPECTION PASSED	
2013-07-19	CVIP	S6978	EL41887	9032644	INSPECTION PASSED	
2013-03-27	CVSA			8145323	INSPECTION PASSED	

VEHICLE REGISTRATION:	10713889	PLATE	12999P	2007	FREIGHTLIN	
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME	
2014-06-05	CVSA			8335730	INSPECTION PASSED	
2014-02-21	CVIP	S6268	EP40009	9413679	INSPECTION PASSED	
2014-02-21	CVIP	S6268		9413678	VEHICLE INSPECTION REJECTED	
2014-01-18	CVSA			8269750	OUT OF SERVICE	
2013-12-08	CVSA			8255239	VIOLATIONS PRESENT	
2013-08-24	CVIP	S6268	EN28021	9092092	INSPECTION PASSED	
2013-08-24	CVIP	S6268		9092090	VEHICLE INSPECTION REJECTED	
2013-06-01	CVSA			8172390	VIOLATIONS PRESENT	

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 10719198 PLATE 21557P 07 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-09-13	CVIP	S6285	ER12772	9884509	INSPECTION PASSED
2014-08-18	CVSA			8366277	OUT OF SERVICE
2014-06-25	CVSA			8342420	INSPECTION PASSED
2014-05-30	CVSA			8332487	INSPECTION PASSED

VEHICLE REGISTRATION: 10728527 PLATE 12997P 2013 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-10-05	CVSA			8387240	INSPECTION PASSED
2014-09-02	CVIP	S4223	EQ80414	9856815	INSPECTION PASSED
2014-07-17	CVSA			8351500	INSPECTION PASSED
2014-02-15	CVIP	S4223	EP47321	9399419	INSPECTION PASSED
2013-10-07	CVSA			8224044	INSPECTION PASSED
2013-08-21	CVIP	S4223	EN25191	9086767	INSPECTION PASSED
2013-08-02	CVSA			8199271	INSPECTION PASSED

VEHICLE REGISTRATION: 10734502 PLATE 07 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-03-31	CVIP	S7076	ES73134	10299058	INSPECTION PASSED
2014-10-02	CVSA				INSPECTION PASSED
2014-09-28	CVIP	S6285	ER38674	9918466	INSPECTION PASSED
2014-09-28	CVIP	S6285		9918465	VEHICLE INSPECTION REJECTED
2014-09-19	CVSA				INSPECTION PASSED
2014-09-14	CVSA			8378111	VIOLATIONS PRESENT

VEHICLE REGISTRATION: 10752365 PLATE 44805D 2014 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-09-17	CVSA			8217231	INSPECTION PASSED

VEHICLE REGISTRATION: 10752466 PLATE 44804D 2014 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-06-24	CVSA			8341980	OUT OF SERVICE

VEHICLE REGISTRATION: 10752602 PLATE 44802D 2014 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-10-05	CVSA			8387240	INSPECTION PASSED

VEHICLE REGISTRATION: 10752661 PLATE 44739D 2014 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-09-11	CVSA			8377292	INSPECTION PASSED

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 10754387	PLATE JG1596	14	FREIGHTLIN		
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-03-06	CVIP	S5241	EQ91475	10285991	INSPECTION PASSED
VEHICLE REGISTRATION: 10755004	PLATE 44737D	2014	UTILITY		
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-06-05	CVSA			8335730	INSPECTION PASSED
VEHICLE REGISTRATION: 10755031	PLATE 44735D	2014	UTILITY		
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-03-04	CVSA			8292740	INSPECTION PASSED
2014-02-18	CVSA			8285170	INSPECTION PASSED
VEHICLE REGISTRATION: 10755054	PLATE 44733D	2014	UTILITY		
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2013-12-02	CVSA			8251300	INSPECTION PASSED
VEHICLE REGISTRATION: 10755073	PLATE 44732D	2014	UTILITY		
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-04-07	CVSA			8311790	INSPECTION PASSED
VEHICLE REGISTRATION: 10755105	PLATE 44731D	2014	UTILITY		
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-10-21	CVSA			8393300	INSPECTION PASSED
VEHICLE REGISTRATION: 10755114	PLATE 44730D	2014	UTILITY		
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-09-14	CVSA			8378111	INSPECTION PASSED
VEHICLE REGISTRATION: 10755806	PLATE 44808D	2014	UTILITY		
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-09-06	CVSA			8375070	INSPECTION PASSED
VEHICLE REGISTRATION: 10755842	PLATE 44809D	2014	UTILITY		
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-09-08	CVSA			8375450	INSPECTION PASSED
VEHICLE REGISTRATION: 10755906	PLATE 44811D	2014	UTILITY		
DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-03-12	CVSA			8297650	INSPECTION PASSED
2014-01-08	CVSA			8264890	INSPECTION PASSED

CVSE-NSCSP351 (P)
2015-05-11

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 10763020 PLATE HF4977 14 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-03-25	CVIP	S5241	EQ91474	10283743	INSPECTION PASSED

VEHICLE REGISTRATION: 10764690 PLATE JH4801 07 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-04-26	CVIP	S4438	EQ05436	9557881	INSPECTION PASSED
2014-04-26	CVIP	S4438		9557880	VEHICLE INSPECTION REJECTED
2014-01-17	CVSA			8269680	VIOLATIONS PRESENT
2013-10-18	CVIP	S4438	EN56184	9164408	INSPECTION PASSED
2013-10-18	CVIP	S4438		9164407	VEHICLE INSPECTION REJECTED
2013-09-03	CVSA			8212491	VIOLATIONS PRESENT
2013-08-05	CVSA				INSPECTION PASSED
2013-07-20	CVSA				INSPECTION PASSED

VEHICLE REGISTRATION: 10795651 PLATE 16588P 2009 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-04-28	CVSA			8319640	INSPECTION PASSED
2014-03-08	CVIP	S6978	EN42547	9447897	INSPECTION PASSED
2013-12-04	CVSA			8253451	INSPECTION PASSED
2013-09-16	CVIP	S6978	EN42402	9121980	INSPECTION PASSED
2013-09-16	CVIP	S6978		9121970	VEHICLE INSPECTION REJECTED
2013-06-18	CVSA			8181811	INSPECTION PASSED

VEHICLE REGISTRATION: 10795975 PLATE 44744D 2014 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-05-24	CVSA			8330225	INSPECTION PASSED

VEHICLE REGISTRATION: 10795991 PLATE 44741D 2014 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-03-01	CVSA			8291360	INSPECTION PASSED

VEHICLE REGISTRATION: 10796174 PLATE 44723D 2014 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-08-15	CVSA			8365380	INSPECTION PASSED

VEHICLE REGISTRATION: 10796192 PLATE 44724D 2014 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-01-17	CVSA			8269680	INSPECTION PASSED

VEHICLE REGISTRATION: 10796225 PLATE 44726D 2014 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-02-25	CVSA			8431516	VIOLATIONS PRESENT
2013-08-16	CVSA			8204051	INSPECTION PASSED
2013-08-09	CVSA			8201310	INSPECTION PASSED

CVSE-NSCSP351 (P)
2015-05-11

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 10796261	PLATE 44742D	2014 UTILITY
DATE 2014-11-23	ACTION CVSA	FACILITY# DECAL # MICROFILM # OUTCOME 8405220 INSPECTION PASSED
VEHICLE REGISTRATION: 10796267	PLATE 44747D	2014 UTILITY
DATE 2014-01-09	ACTION CVSA	FACILITY# DECAL # MICROFILM # OUTCOME 8265173 INSPECTION PASSED
VEHICLE REGISTRATION: 10804310	PLATE 23069P	14 FREIGHTLIN
DATE 2015-02-23	ACTION CVIP	FACILITY# DECAL # MICROFILM # OUTCOME 10220810 VEHICLE INSPECTION REJECTED
2015-02-23	CVIP	S6948 ES32936 10220811 INSPECTION PASSED
2014-08-27	CVIP	S6948 EQ77844 9847817 INSPECTION PASSED
2014-04-07	CVSA	8311790 VIOLATIONS PRESENT
2013-08-26	CVSA	8209840 VIOLATIONS PRESENT
VEHICLE REGISTRATION: 10810535	PLATE 16148P	2006 FREIGHTLIN
DATE 2014-06-04	ACTION CVSA	FACILITY# DECAL # MICROFILM # OUTCOME 8334828 OUT OF SERVICE
2014-04-01	CVSA	INSPECTION PASSED
2014-02-23	CVIP	S6978 9415571 VEHICLE INSPECTION REJECTED
2014-02-23	CVIP	S6978 EN42530 9415572 INSPECTION PASSED
2013-11-28	CVSA	8249410 INSPECTION PASSED
VEHICLE REGISTRATION: 10840702	PLATE 44778D	2014 UTILITY
DATE 2013-11-27	ACTION CVSA	FACILITY# DECAL # MICROFILM # OUTCOME 8248320 OUT OF SERVICE
VEHICLE REGISTRATION: 10840709	PLATE 44779D	2014 UTILITY
DATE 2015-04-27	ACTION CVSA	FACILITY# DECAL # MICROFILM # OUTCOME 8438626 INSPECTION PASSED
VEHICLE REGISTRATION: 10840727	PLATE 44781D	2014 UTILITY
DATE 2014-03-20	ACTION CVSA	FACILITY# DECAL # MICROFILM # OUTCOME 8302052 VIOLATIONS PRESENT
VEHICLE REGISTRATION: 10841754	PLATE 44787D	2014 UTILITY
DATE 2014-06-25	ACTION CVSA	FACILITY# DECAL # MICROFILM # OUTCOME 8342420 VIOLATIONS PRESENT
VEHICLE REGISTRATION: 10841761	PLATE 44788D	2014 UTILITY
DATE 2015-03-31	ACTION CVSA	FACILITY# DECAL # MICROFILM # OUTCOME 8435493 VIOLATIONS PRESENT

CVSE-NSCSP351 (P)
2015-05-11

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 10861227 PLATE 46093D 2014 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-05-06	CVSA			8439954	OUT OF SERVICE
2013-09-19	CVSA			8218543	INSPECTION PASSED
2013-08-27	CVSA			8210530	INSPECTION PASSED

VEHICLE REGISTRATION: 10864127 PLATE 23046P 08 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-05-08	CVIP	S4676	ES72972	10386937	INSPECTION PASSED
2015-05-08	CVIP	S4676		10386936	VEHICLE INSPECTION REJECTED
2015-05-05	CVIP	S6647	RD04604	10378062	VEHICLE INSPECTION REJECTED
2014-11-19	CVIP	S6978	EQ79967	10034629	INSPECTION PASSED
2014-11-19	CVIP	S6978		10034628	VEHICLE INSPECTION REJECTED
2014-07-24	CVSA			8354711	OUT OF SERVICE

VEHICLE REGISTRATION: 10866931 PLATE 46105D 2014 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-09-10	CVSA			8376463	INSPECTION PASSED

VEHICLE REGISTRATION: 10879872 PLATE 16170P KW

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-10-24	CVSA				INSPECTION PASSED
2014-10-21	CVSA			8393300	VIOLATIONS PRESENT
2014-08-25	CVIP	S7076	ER01323	9849950	INSPECTION PASSED
2014-05-23	CVSA				INSPECTION PASSED
2014-02-21	CVIP	S6948	EP42136	9413388	INSPECTION PASSED
2014-02-21	CVIP	S6948		9413386	VEHICLE INSPECTION REJECTED
2013-10-02	CVSA				INSPECTION PASSED
2013-08-20	CVSA			8205623	INSPECTION PASSED

VEHICLE REGISTRATION: 10890783 PLATE 21792P 03 PETERBILT

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-02-14	CVIP	S6750	ER86020	10204847	INSPECTION PASSED
2015-02-14	CVIP	S6750		10204845	VEHICLE INSPECTION REJECTED
2014-09-08	CVSA			8375603	VIOLATIONS PRESENT
2014-08-29	CVIP	S6750	ER05364	9853476	INSPECTION PASSED
2014-08-29	CVIP	S6750		9853475	VEHICLE INSPECTION REJECTED
2014-07-07	CVSA			8346445	VIOLATIONS PRESENT
2014-02-26	CVIP	S5708	EP75384	9423237	INSPECTION PASSED
2014-01-26	CVSA			8273896	VIOLATIONS PRESENT

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 10897850 PLATE 48865D 2014 UTILITY

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-01-11	CVSA			8422420	INSPECTION PASSED

VEHICLE REGISTRATION: 10925112 PLATE 16580P 07 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-03-13	CVIP	S6948		10260887	VEHICLE INSPECTION REJECTED
2015-03-13	CVIP	S6948	ES32971	10260888	INSPECTION PASSED
2015-01-09	CVSA				VIOLATIONS PRESENT
2014-10-14	CVSA				INSPECTION PASSED
2014-09-26	CVIP	S6285	ER38647	9917767	INSPECTION PASSED
2014-06-02	CVSA				INSPECTION PASSED
2014-03-22	CVIP	S6948	EP42179	9476703	INSPECTION PASSED
2014-03-22	CVIP	S6948		9476702	VEHICLE INSPECTION REJECTED
2013-11-13	CVSA				VIOLATIONS PRESENT

VEHICLE REGISTRATION: 10952434 PLATE 21786P FRHT

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-10-23	CVSA				INSPECTION PASSED

VEHICLE REGISTRATION: 10955643 PLATE 20426P FRHT

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-03-23	CVSA				INSPECTION PASSED

VEHICLE REGISTRATION: 11008218 PLATE 20623P 14 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2014-04-26	CVIP	S7079	EP61840	9557758	INSPECTION PASSED

VEHICLE REGISTRATION: 11018738 PLATE 19098P KW

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-03-03	CVSA				INSPECTION PASSED
2015-02-20	CVIP	S4432		10218777	VEHICLE INSPECTION REJECTED
2015-02-20	CVIP	S4432	ES14529	10218778	INSPECTION PASSED
2014-12-29	CVSA				INSPECTION PASSED
2014-10-18	CVSA			8392391	OUT OF SERVICE
2014-10-15	CVSA				INSPECTION PASSED
2014-09-03	CVSA				INSPECTION PASSED
2014-08-23	CVIP	S6948	EQ77837	9835711	INSPECTION PASSED

VEHICLE REGISTRATION: 11080667 PLATE 20447P 14 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-04-25	CVIP	P5239	PL16090	10352047	INSPECTION PASSED
2015-02-24	CVSA			8431238	VIOLATIONS PRESENT
2015-02-21	CVSA			8430992	INSPECTION PASSED

CVSE-NSCSP351 (P)
2015-05-11

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
VEHICLE INSPECTION HISTORY
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REGISTRATION: 11101840 PLATE 09174P 15 FREIGHTLIN

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-02-28	CVIP	S6647	ER86367	10232449	INSPECTION PASSED
2014-12-09	CVSA				INSPECTION PASSED
2014-09-18	CVSA				INSPECTION PASSED
2014-08-27	CVSA				INSPECTION PASSED

VEHICLE REGISTRATION: 11265691 PLATE 20439P 14 INTERNATNA

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-03-20	CVIP	S5240	ER70701	10275287	INSPECTION PASSED
2015-03-20	CVIP	S5240		10275286	VEHICLE INSPECTION REJECTED
2015-03-19	CVIP	S5240		10272411	VEHICLE CONDEMNED
2015-03-17	CVSA				INSPECTION PASSED
2015-01-22	CVSA				INSPECTION PASSED

VEHICLE REGISTRATION: 11401751 PLATE 24100P 2016 VOLVO

DATE	ACTION	FACILITY#	DECAL #	MICROFILM #	OUTCOME
2015-05-07	CVSA			8440228	INSPECTION PASSED
2015-04-27	CVSA			8438626	VIOLATIONS PRESENT

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CARRIER CONTRAVENTIONS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VIOLATION DATE	ACT SECTION TIME	EQUI DESCRIPTION CODE	LOCATION	JR TICKET#	PLATE	JR PTS	DISP DATE
2014-08-13	01:20 MVA 129.1	0104 RED LIGHT AT INTERSECTION	VANCOUVER	BC ST011189931	s.22	3	2014-09-19
2014-05-27	07:22 MVA 129.1	0104 RED LIGHT AT INTERSECTION	DELTA	BC ST010437281		3	2014-09-07
2013-08-06	11:37 MVA 129.1	0104 RED LIGHT AT INTERSECTION	SURREY	BC ST008005091		3	2013-08-16
TOTALS		NUMBER OF CONTRAVENTIONS	NUMBER OF NSC POINTS				
		3	9				

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
DRIVERS CONTRAVENTIONS
ISSUED WHILE OPERATING FOR THE CARRIER
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VIOLATION DATE	ACT SECTION TIME	EQUI DESCRIPTION CODE	LOCATION	JR TICKET#	PLATE	JR PTS	DISP	DATE
2012-06-07	05:06	121/0910(9)	0213 CARRIER FAIL TO KEEP COPY OF A	EDSON	AB 0654623	s.22	3	2012-08-03
s.22		DL#: s.22	CLASS: 100	STATUS: NORMAL				
2012-05-22	09:02	MVR 37.18011	0401 FAIL TO FILL OUT DAILY LOG	LANGLEY	BC AH714580061	s.22	2	2012-06-14
s.22		DL#: s.22	CLASS: 100	STATUS: NORMAL				
2014-03-01	18:26	MVA 151.A	0300 UNSAFE LANE CHANGE	HOPE	BC AH812385891	s.22	3	2014-04-01
s.22		DL#: s.22	CLASS: 100	STATUS: NORMAL				
2014-03-25	21:10	MVA 125	0317 DISOBEY TRAFFIC CONTROL DEVICE	REVELSTOKE	BC AH516532201	s.22	3	2014-04-25
s.22		DL#: s.22	CLASS: 100	STATUS: NORMAL				
2013-06-04	12:23	MVA 219.1	0604 IMPROPERLY EQUIPPED M.V.	HOPE	BC AH716259021	s.22	3	2013-06-18
s.22		DL#: s.22	CLASS: 100	STATUS: NORMAL				
2013-02-06	22:55	MVA 146.3	0004 SPEED AGAINST HIGHWAY SIGN	SALMON ARM	BC AH733645081	s.22	1	2013-03-09
s.22		DL#: s.22	CLASS: 100	STATUS: NORMAL				
2013-10-01	01:55	MVR 4.1	0324 DRIVE W/O REQ'D/LIGHTED LAMP	KELOWNA	BC AH791181991	s.22	2	2014-03-27
2012-05-04	09:02	MVA 146.3	0004 SPEED AGAINST HIGHWAY SIGN	GOLDEN	BC AH675214951		1	2013-01-07
s.22		DL#: s.22	CLASS: 100	STATUS: NORMAL				
2014-06-17	09:30	MVA 125	0317 DISOBEY TRAFFIC CONTROL DEVICE	NEW WESTMI	BC AH822841931	s.22	3	2014-07-18
2013-10-23	23:25	MVA 125	0317 DISOBEY TRAFFIC CONTROL DEVICE	REVELSTOKE	BC AH803540631		3	2013-11-23
s.22		DL#: s.22	CLASS: 100	STATUS: NORMAL				
2012-09-05	09:54	MVR 39.2C	0212 OPER VEH/PERSON NOT SEATED	MERRITT	BC AH734962861	s.22	2	2013-06-13
s.22		DL#: s.22	CLASS: 100	STATUS: NORMAL				
2015-02-10	13:12	CTA 12.1B	0705 VEHICLE EXCEEDS AXLE WEIGHT	DELTA	BC AH744306711	s.22	0	2015-02-21
s.22		DL#: s.22	CLASS: 100	STATUS: NORMAL				
2013-02-10	00:05	MVA 125	0317 DISOBEY TRAFFIC CONTROL DEVICE	REVELSTOKE	BC AH735657841	s.22	3	2013-02-12
s.22		DL#: s.22	CLASS: 100	STATUS: NORMAL				
2011-11-20	09:31	MVR 37.233	0500 NO INSPECTION REPORT	DELTA	BC AH582487191	s.22	2	2012-12-19
s.22		DL#: s.22	CLASS: 100	STATUS: NORMAL				
2013-10-26	20:00	MVA 219.1	0604 IMPROPERLY EQUIPPED M.V.	GOLDEN	BC AH750585051	s.22	3	2013-10-28
s.22		DL#: s.22	CLASS: 160	STATUS: NORMAL				
2014-12-08	19:20	MVA 146.3	0004 SPEED AGAINST HIGHWAY SIGN	KAMLOOPS	BC AH839951791	s.22	1	2015-01-08

SECTION 8

PAGE: 58

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
DRIVERS CONTRAVENTIONS
ISSUED WHILE OPERATING FOR THE CARRIER
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VIOLATION DATE	ACT TIME	SECTION	EQUI CODE	DESCRIPTION	LOCATION	JR TICKET#	PLATE	JR PTS	DISP	DATE

s.22				DL#: s.22		CLASS: 100	STATUS: NORMAL			
2013-11-16	20:52	MVA 219.1	0604	IMPROPERLY EQUIPPED M.V.	GOLDEN	BC AH750531171	s.22	3		2013-12-17
2013-11-15	15:00	MVA 146.3	0004	SPEED AGAINST HIGHWAY SIGN	AGASSIZ	BC AH728589321		1		2013-12-16
s.22				DL#: s.22		CLASS: 100	STATUS: NORMAL			
2013-04-30	20:56	MVR 37.236	0502	FAIL TO PRODUCE INSPECT REPORT	PARKSVILLE	BC AH714981431	P90970 BC	1		2013-05-06
s.22				DL#: s.22		CLASS: 160	STATUS: NORMAL			
2012-08-01	12:03	MVR 6.22B	0601	IMPROPER BRAKE PERFORMANCE	DELTA	BC AH670947311	s.22	3		2012-09-01
2012-08-01	12:03	MVR 37.222	0506	UNSAFE VEHICLE	DELTA	BC AH670947312		3		2012-09-01
s.22				DL#: s.22		CLASS: 100	STATUS: NORMAL			
2011-08-21	15:25	MVA 146.3	0004	SPEED AGAINST HIGHWAY SIGN	MERRITT	BC AH663303261	s.22	1		2012-07-12
s.22				DL#: s.22		CLASS: 100	STATUS: NORMAL			
2013-01-17	17:00	MVA 125	0317	DISOBEY TRAFFIC CONTROL DEVICE	ABBOTSFORD	BC AH746240341	s.22	3		2013-02-17
s.22				DL#: s.22		CLASS: 500	STATUS: HOLD			
2012-11-25	13:30	MVR 37.221	0500	PRE/POST TRIP INSPECTIONS	HOPE	BC AH750289541	s.22	2		2012-12-26
2012-11-25	13:30	MVA 219.1	0604	IMPROPERLY EQUIPPED M.V.	HOPE	BC AH750289542		3		2012-12-26
s.22				DL#: s.22		CLASS: 100	STATUS: NORMAL			
2014-06-23	20:41	MVA 219.1	0604	IMPROPERLY EQUIPPED M.V.	GOLDEN	BC AH824889431	s.22	3		2014-07-23
2014-05-29	14:14	CTA 12.1B	0705	VEHICLE EXCEEDS AXLE WEIGHT	DELTA	BC AH823739961		0		2014-06-18
s.22				DL#: s.22		CLASS: 100	STATUS: NORMAL			
2013-11-19	17:25	MVA 125	0317	DISOBEY TRAFFIC CONTROL DEVICE	HOPE	BC AH654242031	s.22	3		2013-12-18
2013-11-19	17:25	MVR 37.18062	0402	FAIL TO MAINTAIN ACCURATE LOGS	HOPE	BC AH654242032		3		2013-12-18
s.22				DL#: s.22		CLASS: 500	STATUS: SURNDR			
2013-05-20	12:05	MVA 146.3	0004	SPEED AGAINST HIGHWAY SIGN	POPKUM	BC AH584075471	s.22	1		2013-06-07
s.22				DL#: s.22		CLASS: 100	STATUS: NORMAL			
2012-05-09	23:46	MVA 146.3	0004	SPEED AGAINST HIGHWAY SIGN	ABBOTSFORD	BC AH654529231	s.22	1		2012-06-09
s.22				DL#: s.22		CLASS:	STATUS:			
2013-04-06	07:20	121/092,22 (L)	0620	DEFECTIVE AIR SUSPENSION.	AIRDRIE	AB 0710732	s.22	1		2013-05-10
s.22				DL#: s.22		CLASS: 100	STATUS: NORMAL			
2012-09-19	10:16	MVA 187.2	0218	OBSTRUCT TRAFFIC BY PARKING	PENTICTON	BC AH734473701	s.22	1		2012-10-24

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
DRIVERS CONTRAVENTIONS
ISSUED WHILE OPERATING FOR THE CARRIER
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VIOLATION DATE	ACT TIME	SECTION	EQUI DESCRIPTION CODE	LOCATION	JR TICKET#	PLATE	JR PTS	DISP	DATE
s.22			DL#: s.22	CLASS: 100	STATUS: NORMAL				
2013-07-04	15:00	MVA 146.3	0004 SPEED AGAINST HIGHWAY SIGN	ROGERS PAS BC	AH678544081	s.22	1		2013-07-12
s.22			DL#: s.22	CLASS: 100	STATUS: NORMAL				
2013-12-08	14:40	MVA 146.3	0004 SPEED AGAINST HIGHWAY SIGN	MERRITT BC	AH663542351	s.22	1		2014-01-08
s.22			DL#: s.22	CLASS: 100	STATUS: NORMAL				
2014-12-02	01:05	304/0253(1)	0105 FAIL TO STOP AT YELLOW LIGHT	CALGARY AB	0809933	s.22	3		2015-01-08
2014-03-24	19:15	MVA 219.1	0604 IMPROPERLY EQUIPPED M.V.	GOLDEN BC	AH824965581		3		2014-04-24
s.22			DL#: s.22	CLASS: 100	STATUS: NORMAL				
2013-09-28	14:47	MVA 146.3	0004 SPEED AGAINST HIGHWAY SIGN	FIELD BC	AH810431521	s.22	1		2013-10-29
2013-08-31	13:30	MVA 151.A	0300 UNSAFE LANE CHANGE	SURREY BC	AH768542091		3		2013-09-29
2013-08-26	14:31	MVR 37.18011	0401 FAIL TO FILL OUT DAILY LOG	HOPE BC	AH728555821		2		2013-09-26
2012-11-30	10:25	MVA 146.3	0004 SPEED AGAINST HIGHWAY SIGN	WESTWOLD BC	AH663572891		1		2012-12-31
2012-10-03	01:00	CTA 12.1C2	0707 VEH DIM W/O LOAD DO NOT CONFRM	KAMLOOPS BC	AH673264231		1		2012-11-03
s.22			DL#: s.22	CLASS: 100	STATUS: NORMAL				
2013-05-14	09:40	MVR 37.18061	0402 MAINTAIN MORE THAN ONE LOG	HOPE BC	AH333437741	s.22	3		2014-07-11
2013-05-14	09:40	MVR 37.21	0403 OBSTRUCT/HINDER DIR OR OFFICER	HOPE BC	AH333437742		3		2014-07-07
s.22			DL#: s.22	CLASS: 100	STATUS: NORMAL				
2012-07-04	08:00	MVA 220.4	0212 FAIL TO WEAR SEAT BELT	RICHMOND BC	AH613789751	(s.22)	2		2012-08-04
s.22			DL#: s.22	CLASS: 100	STATUS: NORMAL				
2013-06-16	07:26	MVR 37.13023	0414 DRIVE AFTER 16 HRS ELAPSED	AGASSIZ BC	AH765152231	s.22	3		2014-08-14
s.22			DL#: s.22	CLASS: 100	STATUS: NORMAL				
2012-06-28	10:39	MVA 146.3	0004 SPEED AGAINST HIGHWAY SIGN	YALE BC	AH674410811	s.22	1		2012-07-29
s.22			DL#: s.22	CLASS:	STATUS:				
2015-01-11	23:14	121/092,22(L)	0620 DEFECTIVE AIR SUSPENSION.	AIRDRIE AB	0826088	s.22	1		2015-04-14
s.22			DL#: s.22	CLASS: 100	STATUS: NORMAL				
2013-11-28	23:50	MVA 168.A	0329 UNSAFE U-TURN	KAMLOOPS BC	AH810867801	s.22	2		2013-12-29
s.22			DL#: s.22	CLASS: 100	STATUS: NORMAL				
2013-06-24	14:59	CTR 7.32	0702 BYPASS WEIGH SCALE	DELTA BC	AH744384271	s.22	3		2013-07-04
s.22			DL#: s.22	CLASS: 100	STATUS: NORMAL				
2013-10-13	13:37	MVR 37.236	0502 FAIL TO PRODUCE INSPECT REPORT	RICHMOND BC	AH801635391	s.22	1		2013-10-18

SECTION 8

PAGE: 60

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
DRIVERS CONTRAVENTIONS
ISSUED WHILE OPERATING FOR THE CARRIER
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VIOLATION DATE	ACT TIME	SECTION	EQUI DESCRIPTION CODE	LOCATION	JR TICKET#	PLATE	JR PTS	DISP	DATE

s.22 2012-06-05	11:20	MVR 6.22B	0601 IMPROPER BRAKE PERFORMANCE	DL#: s.22 CLASS: 100 LAIDLAW	STATUS: NORMAL BC AH674495801 s.22		3		2012-06-19

TOTALS		NUMBER OF CONTRAVENTIONS	NUMBER OF NSC POINTS						
		52	106						

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
DRIVERS CONTRAVENTIONS PENDING
ISSUED WHILE OPERATING FOR THE CARRIER
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VIOLATION DATE	ACT SECTION TIME	EQUI DESCRIPTION CODE	LOCATION	JR TICKET#	PLATE	JR
s.22		DL#: s.22	CLASS: 100	STATUS: NORMAL		
2014-07-28	19:50 MVA 129.1	0104 RED LIGHT AT INTERSECTION	VANCOUVER	BC AH366551761	s.22	
s.22		DL#: s.22	CLASS: 100	STATUS: NORMAL		
2014-08-23	17:05 MVA 185.3A	0113 DISOBEY RAILWAY STOP SIGN	DELTA	BC AH823793321	s.22	
s.22		DL#: s.22	CLASS: 100	STATUS: NORMAL		
2013-05-09	11:30 MVA 146.3	0004 SPEED AGAINST HIGHWAY SIGN	GOLDEN	BC AH736661101	s.22	
s.22		DL#: s.22	CLASS: 100	STATUS: NORMAL		
2014-01-26	00:40 MVR 37.18021	0401 FAIL TO FILL OUT LOG	DELTA	BC AH801641651	s.22	
s.22		DL#: s.22	CLASS: 100	STATUS: NORMAL		
2014-06-13	23:50 MVR 47.2	0316 SLOW DOWN/MOVE OVER	ABBOTSFORD	BC AH833048091	s.22	
s.22		DL#: s.22	CLASS: 100	STATUS: NORMAL		
2014-05-06	07:19 CTA 12.1B	0705 VEHICLE EXCEEDS AXLE WEIGHT	HOPE	BC AH764218341	s.22	:
s.22		DL#: s.22	CLASS: 100	STATUS: NORMAL		
2014-04-27	12:25 MVA 146.7	0004 SPEED AGAINST MUNICIPAL SIGN	DELTA	BC AH823778991	s.22	
s.22		DL#: s.22	CLASS: 100	STATUS: NORMAL		
2014-09-29	15:38 MVA 146.3	0004 SPEED AGAINST HIGHWAY SIGN	ROGERS PAS	BC AH824735801	s.22	
s.22		DL#: s.22	CLASS: 100	STATUS: NORMAL		
2014-08-06	08:20 MVR 37.18062	0402 FAIL TO MAINTAIN ACCURATE LOGS	ABBOTSFORD	BC AH728690541	s.22	
s.22		DL#: s.22	CLASS: 100	STATUS: NORMAL		
2014-08-06	07:03 MVR 37.18022	0401 FAIL TO RECORD HOURS	ABBOTSFORD	BC AH728690381	s.22	
s.22		DL#: s.22	CLASS: 100	STATUS: NORMAL		
2013-12-31	09:40 MVA 214.21	0226 USE ELECTRONIC DEVICE/DRIVING	SURREY	BC AH769128331	s.22	
s.22		DL#: s.22	CLASS: 100	STATUS: NORMAL		
2013-02-11	12:11 MVA 146.3	0004 SPEED AGAINST HIGHWAY SIGN	DELTA	BC AH775430671	s.22	
s.22		DL#: s.22	CLASS: 100	STATUS: NORMAL		
2014-06-17	13:15 MVA 125	0317 DISOBEY TRAFFIC CONTROL DEVICE	NEW WESTMI	BC AH798720681	s.22	
s.22		DL#: s.22	CLASS: 100	STATUS: NORMAL		
2014-08-29	01:10 MVA 146.3	0004 SPEED AGAINST HIGHWAY SIGN	GOLDEN	BC AH836648231	s.22	

SECTION 9

PAGE: 62

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
DRIVERS CONTRAVENTIONS PENDING
ISSUED WHILE OPERATING FOR THE CARRIER
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VIOLATION DATE	ACT TIME	SECTION	EQUI DESCRIPTION CODE	LOCATION	JR TICKET#	PLATE	JR
s.22							
2014-07-24	10:18	MVA 146.3	0004 SPEED AGAINST HIGHWAY SIGN	GOLDEN	BC AH813933411		s.22
s.22							
2014-08-15	12:41	MVR 37.18062	0402 FAIL TO MAINTAIN ACCURATE LOGS	SURREY	BC AH716277341		s.22
s.22							
2014-08-15	12:41	MVR 37.362A	0509 MAKE FALSE STATEMENT/REPORT	SURREY	BC AH716277342		s.22
s.22							
2014-08-15	12:41	MVR 37.18051	0442 FAIL TO FORWARD LOG/DOCUMENTS	SURREY	BC AH716277343		s.22
s.22							
2014-03-20	19:05	CTR 7.112	0700 ILLEGAL LIFT AXLE	SURREY	BC AH716296151		s.22
s.22							
2014-03-12	18:10	MVA 214.21	0226 USE ELECTRONIC DEVICE/DRIVING	DELTA	BC AH845908951		s.22
s.22							
2014-09-05	12:42	MVA 219.1	0604 IMPROPERLY EQUIPPED M.V.	QUILCHENA	BC AH797074711		s.22
s.22							
2014-06-17	10:48	MVA 125	0317 DISOBEY TRAFFIC CONTROL DEVICE	DELTA	BC AH827203451		s.22
s.22							
2014-06-17	10:48	MVR 37.18011	0401 FAIL TO FILL OUT DAILY LOG	DELTA	BC AH827203452		s.22
TOTALS							
		NUMBER OF PENDING CONTRAVENTIONS					

23

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION ITEM	DEFECT(S)
2015-05-08	18:28	1	8440435	0	KAMLOOPS	s.22		s.22
POWER UNIT	11838P	BC	08618565	2007 PETERBILT		FAIL	44 45 49 55	
TRAILER 1	Z38426	AB		2007 UTILITY		FAIL	41 55	
2015-05-07	10:26	3	8440228	0	HUNTER CRE	s.22		s.22
POWER UNIT	24100P	BC	11401751	2016 VOLVO		PASS		
TRAILER 1	05246D	BC	10383711	2012 UTILITY		PASS		
2015-05-06	11:03	1	8439954	3	LAIDLAW	s.22		s.22
POWER UNIT	24655P	BC	10581669	2013 PETERBILT		PASS		
TRAILER 1	46093D	BC	10861227	2014 UTILITY		OOS	46	
2015-04-27	12:24	3	8438626	0	LAIDLAW	s.22		s.22
POWER UNIT	24100P	BC	11401751	2016 VOLVO		FAIL	40	
TRAILER 1	44779D	BC	10840709	2014 UTILITY		PASS		
2015-04-19	10:07	3	8437429	0	HUNTER CRE	s.22		s.22
POWER UNIT	01353P	BC	00597447	2007 FREIGHTLIN		PASS		
TRAILER 1	84833C	BC	00864260	2008 UTILITY		PASS		
2015-04-09	14:25	1	8436305	0	HUNTER CRE	s.22		s.22
POWER UNIT	21781P	BC	10299186	2012 KENWORTH		FAIL	41 44 46	
TRAILER 1	86589C	BC	10206113	2012 UTILITY		FAIL	44	
2015-04-06	09:02	3	2638748	0	SR	s.22		s.22
POWER UNIT	15700P	BC	00219747	KENS		PASS		
SEMI TRAILER	22619C	BC		UTIL		PASS		
2015-04-06	08:18	3	2638747	0	SR	s.22		s.22
POWER UNIT	17948P	BC	00967378	KENS		PASS		
SEMI TRAILER	46135D	BC		UTIL		PASS		
2015-04-06	07:22	2	2572454	0	SC33 BOW	s.22		s.22
POWER UNIT	24069P	BC	00263666	KW		FAIL	44	
SEMI TRAILER	86657C	BC		UTIL		PASS		
2015-03-31	21:15	1	8435493	0	GOLDEN	s.22		s.22
POWER UNIT	20437P	BC	10589942	2013 FREIGHTLIN		FAIL	42 44	
TRAILER 1	44788D	BC	10841761	2014 UTILITY		FAIL	44	
2015-03-30	16:37	1	8435321	3	HUNTER CRE	s.22		s.22
POWER UNIT	20421P	BC	10603916	2007 FREIGHTLIN		OOS	44	
						FAIL	40 43	
TRAILER 1	86589C	BC	10206113	2012 UTILITY		OOS	44	
						FAIL	41 47	

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION	ITEM DEFECT(S)
2015-03-23	09:30	2	2519360	0	SR 9 MP 73	s.22		s.22
POWER UNIT	20426P	BC	10955643	FRHT		PASS		
SEMI TRAILER	44780D	BC		UTIL		PASS		
2015-03-22	12:27	1	8434371	0	HUNTER CRE	s.22		s.22
POWER UNIT	08677P	BC	10070282	2006 FREIGHTLIN		FAIL	41	
TRAILER 1	05248D	BC	10383723	2012 UTILITY		PASS		
2015-03-21	02:35	2	2444808	0	SC33 BOW	s.22		s.22
POWER UNIT	20425P	BC		FRHT		FAIL	40	
SEMI TRAILER	46136D	BC		UTIL		PASS		
2015-03-19	15:45	2	0822342	0	AIRDRIE -	s.22		s.22
POWER UNIT	17593P	BC	02209430	KENWORTH		FAIL	40 41 44	
ELECTRICITY	4WN784	AB		CIMC		PASS		
SEMI TRAILER	06924D	BC		UTILITY		PASS		
SEMI TRAILER	64798C	BC		UTILITY		PASS		
2015-03-17	17:33	2	2404673	0	SC33 BOW	s.22		s.22
POWER UNIT	03999P	BC	02211029	FRHT		PASS		
SEMI TRAILER	05223D	BC		UTIL		PASS		
2015-03-17	09:02	3	2519565	0	DEMING	s.22		s.22
POWER UNIT	20439P	BC	11265691	INTL		PASS		
SEMI TRAILER	48865D	BC		UTIL		PASS		
2015-03-12	18:41	1	8433391	0	KAMLOOPS	s.22		s.22
POWER UNIT	P93885	BC	09845578	2007 FREIGHTLIN		FAIL	41 44 49	
TRAILER 1	36288D	BC	03082366	2009 HYUNDAI		FAIL	44 46	
2015-03-11	10:23	3	2377329	0	EB	s.22		s.22
POWER UNIT	15700P	BC	00219747	KW		PASS		
SEMI TRAILER	4WX576	AB		UTIL		PASS		
2015-03-03	07:45	3	2262413	0	SC33 BOW	s.22		s.22
POWER UNIT	19098P	BC	11018738	KW		PASS		
SEMI TRAILER	44740D	BC		UTIL		PASS		
2015-03-01	09:54	3	8431847	0	HUNTER CRE	s.22		s.22
POWER UNIT	JJ2912	BC	09861648	2006 VOLVO		PASS		
TRAILER 1	86657C	BC	10195084	2012 UTILITY		PASS		
2015-02-25	15:31	1	8431516	0	GOLDEN	s.22		s.22
POWER UNIT	17590P	BC	03618114	2007 FREIGHTLIN		FAIL	41 44	
TRAILER 1	44726D	BC	10796225	2014 UTILITY		FAIL		

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION	ITEM DEFECT(S)
2015-02-25	12:30	3	2234895	0	SC33 BOW	s.22	BC	s.22
POWER UNIT	20438P	BC		FRHT		FAIL	40	
SEMI TRAILER	86614C	BC		UTIL		PASS		
2015-02-24	08:08	3	8431238	0	DELTA	s.22	BC	s.22
POWER UNIT	20447P	BC	11080667	2014 FREIGHTLIN		FAIL	40 50	
TRAILER 1	84811C	BC	02292069	2004 UTILITY		PASS		
2015-02-21	12:14	1	8431011	3	HUNTER CRE	s.22	BC	s.22
POWER UNIT	23075P	BC	03922480	2009 FREIGHTLIN		OOS	44	
TRAILER 1	22901D	BC	10585421	2013 VANGUARD		FAIL	44	
2015-02-21	08:35	3	8430992	0	HUNTER CRE	s.22	BC	s.22
POWER UNIT	20447P	BC	11080667	2014 FREIGHTLIN		PASS		
TRAILER 1	98782C	BC	01656713	2008 UTILITY		PASS		
2015-02-19	19:51	1	2185214	0	COTTONWOOD	s.22	BC	s.22
POWER UNIT	17941P	BC	03264597	KW		PASS		
SEMI TRAILER	33589D	BC		UTIL		PASS		
2015-02-19	09:08	2	2182162	3	BOW HILL P	s.22	BC	s.22
POWER UNIT	23718P	BC		VOLV		PASS		
SEMI TRAILER	05378D	BC		UTIL		OOS	47	
2015-02-15	15:03	1	8430053	0	LAIDLAW	s.22	BC	s.22
POWER UNIT	20427P	BC	10392576	2012 FREIGHTLIN		FAIL	55	
TRAILER 1	4VG437	AB		2015 UTIL		FAIL	45	
2015-02-12	10:20	1	2101009	0	13800 24 S	s.22	BC	s.22
POWER UNIT	08677P	BC	10070282	FRHT		FAIL	44 49	
SEMI TRAILER	84819C	BC		UTIL		FAIL	44	
2015-02-09	16:44	3	2072339	0	BOW HILL P	s.22	BC	s.22
POWER UNIT	20427P	BC		FRHT		PASS		
SEMI TRAILER	05265D	BC		UTIL		PASS		
2015-02-09	13:10	2	2072435	3	COOK RD &	s.22	BC	s.22
POWER UNIT	21787P	BC	10247109	FRHT		PASS		
SEMI TRAILER	05263D	BC		UTIL		OOS	47	
						FAIL	44	
2015-02-03	14:42	3	2234992	0	NB	s.22	BC	s.22
POWER UNIT	17948P	BC	00967378	KW		PASS		
SEMI TRAILER	86657C	BC		UTIL		PASS		

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION	ITEM DEFECT(S)
2015-01-24	07:02	3	1927273	0	SC38 STA	s.22		s.22
POWER UNIT	20446P	BC	01065757	FRHT		PASS		
SEMI TRAILER	SZ5010	BC		UTIL		PASS		
2015-01-22	06:12	3	1899379	0	BOW HILL P	s.22	:	s.22
POWER UNIT	20439P	BC	11265691	INTL		PASS		
SEMI TRAILER	10471D	BC		UTIL		PASS		
2015-01-19	19:55	2	1864488	0	SC53 CLE	s.22		s.22
POWER UNIT	20446P	BC	01065757	FRHT		FAIL	40	
SEMI TRAILER	SZ7391	MB		UTIL		PASS		s.22
2015-01-16	22:45	3	1875310	0	BOW HILL P	s.22		s.22
POWER UNIT	20416P	BC		FRHT		PASS		
SEMI TRAILER	20095D	BC		WANC		PASS		s.22
2015-01-11	23:14	2	0811279	3	AIRDRIE -	s.22		s.22
POWER UNIT	17593P	BC		KENWORTH		PASS		
SEMI TRAILER	4PS117	AB		UTILITY		FAIL	50	
SEMI TRAILER	4PS120	AB		UTILITY		OOS	44 46	
ELECTRICITY	999999	BC				PASS		
2015-01-11	09:23	3	8422420	0	SURREY	s.22		s.22
POWER UNIT	P93686	BC	09649734	2009 VOLVO		FAIL	55	
TRAILER 1	48865D	BC	10897850	2014 UTILITY		PASS		
2015-01-09	10:16	2	1785075	0	EB	s.22		s.22
POWER UNIT	16580P	BC	10925112	FRHT		FAIL	41	
SEMI TRAILER	7572XE	WA		WANC		PASS		
2014-12-29	13:58	3	1709838	0	ACME, WA	s.22		s.22
POWER UNIT	19098P	BC	11018738	KW		PASS		
SEMI TRAILER	44807D	BC		UTIL		PASS		
2014-12-19	12:24	5	8430960	0	SURREY	s.22		s.22
POWER UNIT	DEALER	BC	00457095	2000 SUZUKI		PASS		
2014-12-09	20:42	1	1569862	0	DUNSMUIR G	s.22		s.22
POWER UNIT	09174P	BC	11101840	PTRB		PASS		
SEMI TRAILER	61995D	BC		UTIL		PASS		
2014-12-04	09:15	3	1785029	0	EB	s.22		s.22
POWER UNIT	10468P	BC	03773135	KW		PASS		
SEMI TRAILER	4TS177	AB		UTIL		PASS		

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION ITEM	DEFECT(S)
2014-12-03	11:25	3	8409587	0	HUNTER CRE	s.22	BC	s.22
POWER UNIT	22260P	BC	10302250	2007 FREIGHTLIN		PASS		I
TRAILER 1	Z64130	AB		2008 UTILITY		PASS		
2014-12-03	11:11	3	8409551	0	GOLDEN	s.22	BC	s.22
POWER UNIT	07228P	BC	07238242	2007 KENWORTH		PASS		
2014-12-02	10:15	2	0807158	3	AIRDRIE -	s.22	AB	s.22
POWER UNIT	15698P	BC	10022141	VOLVO		OOS	40	
SEMI TRAILER	22904D	BC		VANGUARD		PASS		
2014-11-29	10:19	1	8407690	0	SURREY	s.22	BC	s.22
POWER UNIT	23067P	BC	10618844	2012 INTERNATNA		FAIL	41 44	
TRAILER 1	10462D	BC	02523521	2009 UTILITY		FAIL		
2014-11-28	14:18	3	1464700	0	SB	s.22	BC	s.22
POWER UNIT	15699P	BC	10350135	VOLV		PASS		
SEMI TRAILER	44808D	BC		UTIL		PASS		
2014-11-25	08:29	1	1442106	0	SC33 BOW H	s.22	BC	s.22
POWER UNIT	17954P	BC	03589084	FRHT		PASS		
SEMI TRAILER	44733D	BC		UTIL		PASS		
2014-11-23	11:39	3	8405220	0	LAILDLAW	s.22	BC	s.22
POWER UNIT	17599P	BC	03267342	2006 PETERBILT		PASS		
TRAILER 1	44742D	BC	10796261	2014 UTILITY		PASS		
2014-11-21	05:48	3	1421346	0	SC33 BOW H	s.22	BC	s.22
POWER UNIT	17610P	BC	03091059	FRHT		PASS		
SEMI TRAILER	46091D	BC		UTIL		PASS		
2014-11-20	10:30	3	1464685	0	SB	s.22	BC	s.22
POWER UNIT	21787P	BC	10247109	FRHT		PASS		
SEMI TRAILER	10420D	BC		UTIL		PASS		
2014-11-14	14:30	1	8402050	0	KAMLOOPS	s.22	BC	s.22
POWER UNIT	21789P	BC	10693340	2008 KENWORTH		FAIL	41 44 45 55	
TRAILER 1	63030C	BC	02288472	2008 UTILITY		FAIL	44	
2014-11-13	08:48	3	1392687	0	SR101 MP28	s.22	BC	s.22
POWER UNIT	10928P	BC		INTL		PASS		
SEMI TRAILER	48901D	BC		UTIL		PASS		
2014-11-12	09:30	1	8427006	3	KAMLOOPS	s.22	BC	s.22
POWER UNIT	17613P	BC	03031384	2006 FREIGHTLIN		OOS	44	
TRAILER 1	84854C	BC	02450053	2005 UTILITY		PASS		

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE VEH TYPE	TIME PLATE#	LEVEL JR	MICRO# VEH REG	NSC PTS VEHICLE DESC	LOCATION	DL# PASS/FAIL	DLJR INSPECTION ITEM	DRIVER NAME DEFECT(S)
2014-11-09 POWER UNIT SEMI TRAILER	23:19 15699P 44811D	2 BC BC	1292675 10350135	0 VOLV UTIL	SC33 BOW H	s.22 PASS PASS	s.22	
2014-11-07 POWER UNIT TRAILER 1	14:45 17175P 10470D	1 BC BC	8399571 03446085 10498892	0 2009 FREIGHTLIN 2012 UTILITY	LAIDLAW	s.22 FAIL FAIL	s.22 44 44	
2014-11-07 POWER UNIT SEMI TRAILER	09:45 10468P 44812D	3 BC BC	1292913 03773135	0 KW UTIL	SC33 BOW H	s.22 PASS PASS	s.22	
2014-11-03 POWER UNIT TRAILER 1	15:06 08649P 98779C	1 BC BC	8397560 02485930 01657426	3 2005 PETERBILT 2008 UTILITY	GOLDEN	s.22 OOS OOS FAIL	s.22 41 41 44	
2014-11-01 POWER UNIT TRAILER 1	10:37 19106P 84822C	1 BC BC	8397110 01065757 03289924	0 2008 FREIGHTLIN 2006 UTILITY	LAIDLAW	s.22 FAIL FAIL	s.22 45 45	
2014-10-27 POWER UNIT TRAILER 1	12:50 P93686 16121C	2 BC BC	8395751 09649734 02512166	3 2009 VOLVO 2005 GREAT DANE	DELTA	s.22 PASS OOS	s.22 44	
2014-10-24 POWER UNIT SEMI TRAILER	08:36 16170P 61949D	3 BC BC	1189870 10879872	0 KW UTIL	SC33 BOW H	s.22 PASS PASS	s.22	
2014-10-23 POWER UNIT SEMI TRAILER	19:13 21786P 29288D	3 BC BC	1162636 10952434	0 FRHT GDAN	COTTONWOOD	s.22 PASS PASS	s.22	
2014-10-21 POWER UNIT TRAILER 1	10:24 16170P 44731D	3 BC BC	8393300 10879872 10755105	0 2004 KENWORTH 2014 UTILITY	ABBOTSFORD	s.22 FAIL PASS	s.22 40	
2014-10-21 POWER UNIT TRAILER 1	08:09 08677P 22902D	3 BC BC	8393142 10070282 10585429	0 2006 FREIGHTLIN 2013 VANGUARD	ABBOTSFORD	s.22 PASS PASS	s.22	
2014-10-20 POWER UNIT	10:20 18531P	3 BC	1464528 01846874	0 PTRB	WB	s.22 PASS	s.22	

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION	ITEM DEFECT(S)
2014-10-19	07:45	2	1103025	0	SC33 BOW H	s.22	BC	s.22
POWER UNIT	20421P	BC	10603916	FRHT		PASS		
SEMI TRAILER	05244D	BC		UTIL		PASS		
2014-10-18	15:11	1	8392391	3	SURREY	s.22	BC	s.22
POWER UNIT	19098P	BC	11018738	2007 KENWORTH		OOS	44	
TRAILER 1	80441C	BC	10186432	2012 UTILITY		FAIL	44 51	
2014-10-16	15:28	1	8391750	0	KAMLOOPS	s.22	BC	s.22
POWER UNIT	17171P	BC	10146233	2012 FREIGHTLIN		FAIL	40	
TRAILER 1	98777C	BC	01657644	2008 UTILITY		PASS		
2014-10-16	08:07	4	8391330	0	MERRITT	s.22	BC	s.22
POWER UNIT	P93686	BC	09649734	2009 VOLVO		FAIL	47 51	
TRAILER 1	84808C	BC	02503032	2005 UTILITY		PASS		
2014-10-15	07:24	3	1064131	0	ACME, WA	s.22	BC	s.22
POWER UNIT	19098P	BC	11018738	KW		PASS		
SEMI TRAILER	80442C	BC		UTIL		PASS		
2014-10-14	08:28	3	1035746	0	SC33 BOW	s.22	BC	s.22
POWER UNIT	10468P	BC	03773135	KW		PASS		
SEMI TRAILER	44726D	BC		UTIL		PASS		
2014-10-14	07:35	3	1035722	0	SC33 BOW	s.22	BC	s.22
POWER UNIT	16580P	BC	10925112	FRHT		PASS		
SEMI TRAILER	44744D	BC		UTIL		PASS		
2014-10-13	11:26	3	1035691	0	SC33 BOW	s.22	BC	s.22
POWER UNIT	20417P	BC	10678954	FRHT		PASS		
SEMI TRAILER	44784D	BC		UTIL		PASS		
2014-10-09	18:56	1	8389511	3	GOLDEN	s.22	BC	s.22
POWER UNIT	03488P	BC	00547686	2005 PETERBILT		FAIL	45	
TRAILER 1	29287D	BC	01970155	2008 GREAT DANE		OOS	41	
						FAIL	44	
2014-10-09	08:18	3	1009610	0	ASHLAND SB	s.22	BC	s.22
POWER UNIT	22147P	BC		FRHT		PASS		
SEMI TRAILER	4MB3-5	AB		VANR		PASS		
2014-10-08	08:27	3	8388381	0	HUNTER CRE	s.22	BC	s.22
POWER UNIT	19869P	BC	10154257	2007 FREIGHTLIN		FAIL	40	
TRAILER 1	36287D	BC	03082537	2009 HYUNDAI		FAIL	55	

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE VEH TYPE	TIME PLATE#	LEVEL JR	MICRO# VEH REG	NSC PTS VEHICLE DESC	LOCATION	DL# PASS/FAIL	DLJR INSPECTION ITEM	DRIVER NAME DEFECT(S)
2014-10-05 POWER UNIT TRAILER 1	10:34 12997P 44802D	3 BC BC	8387240 10728527 10752602	0 2013 FREIGHTLIN 2014 UTILITY	NORTH DELT	s.22 PASS PASS	BC	s.22
2014-10-02 POWER UNIT SEMI TRAILER	06:29 20416P 98784C	1 BC BC	0987829 10734502	0 FRHT UTIL	SC33 BOW	s.22 PASS PASS	BC	s.22
2014-10-01 POWER UNIT SEMI TRAILER	09:18 17948P 86618C	3 BC BC	0934612	0 KW UTIL	STATE ROUT	s.22 PASS PASS	BC	s.22
2014-09-30 POWER UNIT TRAILER 1	21:23 19889P 05265D	3 BC BC	8385401 00871139 10390315	0 2008 VOLVO 2012 UTILITY	LAIDLAW	s.22 PASS PASS	BC	s.22
2014-09-23 POWER UNIT SEMI TRAILER SEMI TRAILER ELECTRICITY	16:01 11823P 4DX595 4EN335 4JN287	2 BC AB AB AB	0789640	3 FREIGHTLIN VANGUARD VANGUARD ITD	LEDUC - VI	s.22 FAIL OOS PASS PASS	AB 40 44 41	s.22
2014-09-21 POWER UNIT	13:21 P93885	2 BC	8381182 09845578	0 2007 FREIGHTLIN	KAMLOOPS	s.22 FAIL	BC 40	s.22
2014-09-19 POWER UNIT SEMI TRAILER	20:01 08689P 44780D	3 BC BC	0905438 01632101	0 KW UTIL	SC33 BOW H	s.22 PASS PASS	BC	s.22
2014-09-19 POWER UNIT SEMI TRAILER	10:57 20416P 44749D	3 BC BC	0853048 10734502	0 FRHT UNK	CONWAY	s.22 PASS PASS	BC	s.22
2014-09-18 POWER UNIT SEMI TRAILER	20:30 09174P 4EY659	2 BC AB	0919466 11101840	0 FRHT TRLR	DOUGLAS CO	s.22 PASS PASS	BC	s.22
2014-09-18 POWER UNIT SEMI TRAILER	12:15 19869P 48901D	3 BC BC	0944008	0 FRHT UTIL	NB	s.22 FAIL PASS	BC 40	s.22
2014-09-18 POWER UNIT	11:16 17171P	3 BC	8380201 10146233	0 2012 FREIGHTLIN	LAIDLAW	s.22 PASS	BC	s.22

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE VEH TYPE	TIME PLATE#	LEVEL JR	MICRO# VEH REG	NSC PTS VEHICLE DESC	LOCATION	DL# PASS/FAIL	DLJR INSPECTION ITEM	DRIVER NAME DEFECT(S)
2014-09-16 POWER UNIT SEMI TRAILER	05:44 P93686 55517B	3 BC BC	0767549 09649734	0 VOLV GDAN	SC33 BOW H	s.22 PASS PASS	BC	s.22
2014-09-14 POWER UNIT TRAILER 1	11:52 20416P 44730D	3 BC BC	8378111 10734502 10755114	0 2007 FREIGHTLIN 2014 UTILITY	HUNTER CRE	s.22 FAIL PASS	BC 40 55	s.22
2014-09-11 POWER UNIT TRAILER 1	12:05 17175P 44739D	4 BC BC	8377292 03446085 10752661	0 2009 FREIGHTLIN 2014 UTILITY	DELTA	s.22 FAIL PASS	BC 44	s.22
2014-09-11 POWER UNIT SEMI TRAILER	08:20 15698P 05248D	1 BC BC	0789286 10022141	3 VOLVO UTILITY	BALZAC - V	s.22 FAIL OOS FAIL	AB 40 46 47 44	s.22
2014-09-10 POWER UNIT TRAILER 1	10:39 01353P 46105D	4 BC BC	8376463 00597447 10866931	0 2007 FREIGHTLIN 2014 UTILITY	ABBOTSFORD	s.22 PASS PASS	BC	s.22
2014-09-10 POWER UNIT TRAILER 1	07:43 01353P 61629D	3 BC BC	8376410 00597447 01656900	0 2007 FREIGHTLIN 2008 UTILITY	LIDLAW	s.22 PASS PASS	BC	s.22
2014-09-09 POWER UNIT	11:49 21787P	1 BC	8375970 10247109	0 2008 FREIGHTLIN	HUNTER CRE	s.22 PASS	BC	s.22
2014-09-09 POWER UNIT	07:23 08677P	3 BC	8375810 10070282	0 2006 FREIGHTLIN	LIDLAW	s.22 PASS	BC	s.22
2014-09-08 POWER UNIT	13:08 21792P	3 BC	8375603 10890783	0 2003 PETERBILT	LIDLAW	s.22 FAIL	BC 40	s.22
2014-09-08 POWER UNIT TRAILER 1	11:06 11838P 86615C	1 BC BC	8375582 08618565 10208068	3 2007 PETERBILT 2012 UTILITY	LIDLAW	s.22 OOS PASS	BC 44	s.22
2014-09-08 POWER UNIT TRAILER 1	10:55 16145P 10422D	3 BC BC	8375561 10627033 10472597	0 2013 FREIGHTLIN 2012 PACESETTER	LIDLAW	s.22 PASS PASS	BC	s.22
2014-09-08 POWER UNIT	10:24 16581P	3 BC	8375531 10572840	0 2013 FREIGHTLIN	LIDLAW	s.22 PASS	BC	s.22

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION ITEM	DEFECT(S)
2014-09-08	08:01	1	8375450	0	HUNTER CRE	s.22	BC	s.22
POWER UNIT	21787P	BC	10247109	2008 FREIGHTLIN		FAIL	40 41	
TRAILER 1	44809D	BC	10755842	2014 UTILITY		PASS		
2014-09-06	09:56	1	8375070	0	HUNTER CRE	s.22	BC	s.22
POWER UNIT	17948P	BC	00967378	2008 KENWORTH		PASS		
TRAILER 1	44808D	BC	10755806	2014 UTILITY		PASS		
2014-09-05	12:42	2	8374770	3	QUILCHENA	s.22	BC	s.22
POWER UNIT	P93885	BC	09845578	2007 FREIGHTLIN		OOS	43	
TRAILER 1	98783C	BC	01963378	2008 UTILITY		FAIL	41 44 49 55	
						PASS		
2014-09-03	10:16	3	0669461	0	ROADSIDE	s.22	BC	s.22
POWER UNIT	19098P	BC	11018738	KW		PASS		
SEMI TRAILER	44739D	BC		UHAU		PASS		
2014-09-02	14:10	3	0943903	0	SB	s.22	BC	s.22
POWER UNIT	18531P	BC	01846874	PTRB		PASS		
SEMI TRAILER	80439C	BC		UTIL		PASS		
2014-08-28	11:17	1	8372163	0	HUNTER CRE	s.22	BC	s.22
POWER UNIT	P93675	BC	00263666	2000 KENWORTH		PASS		
TRAILER 1	22901D	BC	10585421	2013 VANGUARD		PASS		
2014-08-27	14:14	3	0579940	0	LACEY	s.22	BC	s.22
POWER UNIT	09174P	BC	11101840	FRHT		PASS		
SEMI TRAILER	44737D	BC		UTIL		PASS		
2014-08-21	16:11	1	8369070	0	HUNTER CRE	s.22	BC	s.22
POWER UNIT	16581P	BC	10572840	2013 FREIGHTLIN		FAIL	42	
TRAILER 1	10470D	BC	10498892	2012 UTILITY		FAIL	44	
2014-08-20	11:16	3	8367841	0	ABBOTSFORD	s.22	BC	s.22
POWER UNIT	18531P	BC	01846874	2004 PETERBILT		PASS		
2014-08-19	20:12	3	8368068	0	HUNTER CRE	s.22	BC	s.22
POWER UNIT	17599P	BC	03267342	2006 PETERBILT		PASS		
TRAILER 1	29212D	BC	01862844	2008 GREAT DANE		PASS		
2014-08-18	23:25	3	0497486	0	N/B	s.22	BC	s.22
POWER UNIT	19884P	BC	10691202	FRHT		PASS		
SEMI TRAILER	02965D	BC		GDAN		PASS		

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE VEH TYPE	TIME PLATE#	LEVEL JR	MICRO# VEH REG	NSC PTS VEHICLE DESC	LOCATION	DL# PASS/FAIL	DLJR INSPECTION ITEM	DRIVER NAME DEFECT(S)
2014-08-18 POWER UNIT SEMI TRAILER	13:02 17947P 44749D	3 BC BC	0482083	0 KW UTIL	SC38 STA	s.22 PASS PASS	BC	s.22
2014-08-18 POWER UNIT	10:52 11838P	3 BC	8366371 08618565	0 2007 PETERBILT	LAIDLAW	s.22 PASS	BC	s.22
2014-08-18 POWER UNIT TRAILER 1	09:53 19062P 20099D	3 BC BC	8366277 10719198 10580984	3 2007 FREIGHTLIN 2013 WABASH	ABBOTSFORD	s.22 OOS PASS	BC 40	s.22
2014-08-15 POWER UNIT TRAILER 1	12:41 10928P 44723D	3 BC BC	8365380 10618690 10796174	3 2012 INTERNATNA 2014 UTILITY	SURREY	s.22 OOS PASS	BC 40	s.22
2014-08-15 POWER UNIT SEMI TRAILER	08:13 17610P 46131D	3 BC BC	0482394 03091059	0 FRHT UTIL	SC33 BOW	s.22 PASS PASS	BC	s.22
2014-08-14 POWER UNIT SEMI TRAILER	04:52 17941P 22852D	1 BC BC	0473872 03264597	0 KW UTIL	DUNSMUIR G	s.22 PASS PASS	BC	s.22
2014-08-08 POWER UNIT SEMI TRAILER	07:34 P93675 05245D	3 BC BC	0440171 00263666	0 KW UTIL	CASTLE ROC	s.22 PASS PASS	BC	s.22
2014-08-06 POWER UNIT	08:20 P93187	4 BC	8360053 09874313	3 2010 FREIGHTLIN	ABBOTSFORD	s.22 OOS	BC 40	s.22
2014-08-06 POWER UNIT	07:03 P93187	3 BC	8360031 09874313	0 2010 FREIGHTLIN	ABBOTSFORD	s.22 FAIL	BC 40	s.22
2014-08-04 POWER UNIT SEMI TRAILER	06:35 21778P 29214D	2 BC BC	0418626	3 KW GDAN	SC33 BOW	s.22 FAIL OOS FAIL	BC 41 46 44	s.22
2014-07-30 POWER UNIT SEMI TRAILER	20:15 P97124 44786D	2 BC BC	0335366 02252296	3 INTL UTIL	SC33 BOW	s.22 OOS PASS	BC 48	s.22
2014-07-26 POWER UNIT SEMI TRAILER	06:10 21778P 23135Y	3 BC BC	0287769	0 KW GDAN	SC33 BOW	s.22 PASS PASS	BC	s.22

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION ITEM	DEFECT(S)
2014-07-25	18:31	2	0287747	0	SC33 BOW	s.22	BC	s.22
POWER UNIT	P84508	BC	00190625	VOLV		FAIL	44	
SEMI TRAILER	02967D	BC		GDAN		PASS		
2014-07-24	16:43	1	8354711	3	KAMLOOPS	s.22	BC	s.22
POWER UNIT	19866P	BC	10864127	2008 FREIGHTLIN		OOS	44	
TRAILER 1	63040C	BC	02523262	2009 UTILITY		FAIL	44 45	
2014-07-23	08:45	3	0567639	0	SC15 POR	s.22	BC	s.22
POWER UNIT	08677P	BC	10070282	FRHT		PASS		
SEMI TRAILER	22915D	BC		UTIL		PASS		
2014-07-22	10:12	3	0232464	0	N/B	s.22	BC	s.22
POWER UNIT	17610P	BC	03091059	FRHT		PASS		
SEMI TRAILER	44780D	BC		UTIL		PASS		
2014-07-21	15:01	1	0261020	0	COTTONWOOD	s.22	BC	s.22
POWER UNIT	09174P	BC		PTRB		PASS		
SEMI TRAILER	4ER156	AB		UNK		PASS		
2014-07-21	13:38	3	0232338	0	SC33 BOW	s.22	BC	s.22
POWER UNIT	19106P	BC	01065757	FRHT		PASS		
SEMI TRAILER	36288D	BC		HYTR		PASS		
2014-07-20	15:40	3	0222121	0	SC33 BOW	s.22	BC	s.22
POWER UNIT	15697P	BC	09955897	VOLV		PASS		
SEMI TRAILER	55519B	BC		GDAN		PASS		
2014-07-17	19:48	3	8351500	0	LAIDLAW	s.22	BC	s.22
POWER UNIT	12997P	BC	10728527	2013 FREIGHTLIN		PASS		
2014-07-17	13:20	3	8351141	0	DELTA	s.22	BC	s.22
POWER UNIT	05727P	BC	01896963	2004 VOLVO		FAIL	40	
2014-07-14	07:28	3	0172424	0	SC33 BOW	s.22	BC	s.22
POWER UNIT	11824P	BC	00414882	FRHT		PASS		
SEMI TRAILER	22915D	BC		UTIL		PASS		
2014-07-13	12:35	3	0172414	0	SC33 BOW	s.22	BC	s.22
POWER UNIT	01353P	BC	00597447	FRHT		PASS		
SEMI TRAILER	98785C	BC		UTIL		PASS		
2014-07-09	04:40	2	0131568	0	SC33 BOW	s.22	BC	s.22
POWER UNIT	15697P	BC	09955897	VOLV		PASS		
SEMI TRAILER	4HM921	BC		VANR		PASS		

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION ITEM	DEFECT(S)
2014-07-07	19:49	1	8346445	0	KAMLOOPS	s.22	BC	s.22
POWER UNIT	16142P	BC	10890783	2003 PETERBILT		FAIL	41	
TRAILER 1	98786C	BC	01963539	2008 UTILITY		FAIL	44	
2014-06-30	12:35	1	0068448	0	SC38 STA	s.22	BC	s.22
TRUCK	17954P	BC	03589084	FRHT		PASS		
SEMI TRAILER	S41852	AB		GDAN		PASS		
2014-06-25	03:42	2	8342420	0	SURREY	s.22	BC	s.22
POWER UNIT	19062P	BC	10719198	2007 FREIGHTLIN		PASS		
TRAILER 1	44787D	BC	10841754	2014 UTILITY		FAIL	55	
2014-06-24	13:15	3	0602658	0	SB SR9 57	s.22	BC	s.22
POWER UNIT	17941P	BC	03264597	KW		PASS		
SEMI TRAILER	61949D	BC		UTIL		PASS		
2014-06-24	03:52	2	8341980	3	SURREY	s.22	BC	s.22
POWER UNIT	19869P	BC	10154257	2007 FREIGHTLIN		FAIL	40	
TRAILER 1	44804D	BC	10752466	2014 UTILITY		OOS	41	
2014-06-23	21:01	2	8341950	3	GOLDEN	s.22	BC	s.22
POWER UNIT	16145P	BC	10627033	2013 FREIGHTLIN		PASS		
TRAILER 1	4ER339	AB		2012 VANGUARD		OOS	46	
2014-06-16	18:21	3	9931147	0	ROADSIDE	s.22	BC	s.22
POWER UNIT	19062P	BC		FRHT		PASS		
SEMI TRAILER	84818C	BC		UTIL		PASS		
2014-06-10	14:17	3	9855466	0	SUMAS, WA	s.22	BC	s.22
POWER UNIT	09165P	BC	03526127	FRHT		PASS		
SEMI TRAILER	44724D	BC		UTIL		PASS		
2014-06-10	10:56	3	8336846	0	HUNTER CRE	s.22	BC	s.22
POWER UNIT	08677P	BC	10070282	2006 FREIGHTLIN		PASS		
TRAILER 1	05266D	BC	10390317	2012 UTILITY		PASS		
2014-06-10	09:56	3	9855437	0	ACME, WA	s.22	BC	s.22
POWER UNIT	P79528	BC		FRHT		PASS		
SEMI TRAILER	44810D	BC		UTIL		PASS		
2014-06-05	20:54	1	8335730	0	LIDLAW	s.22	BC	s.22
POWER UNIT	12999P	BC	10713889	2007 FREIGHTLIN		PASS		
TRAILER 1	44737D	BC	10755004	2014 UTILITY		PASS		

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION	ITEM DEFECT(S)
2014-06-05	17:36	1	9820462	0	SC38 STA	s.22	BC	s.22
POWER UNIT	19102P	BC		FRHT		FAIL	40 41	
SEMI TRAILER	22852D	BC		UTIL		FAIL	44	
2014-06-05	17:05	1	8335598	0	Laidlaw	s.22	BC	s.22
POWER UNIT	17613P	BC	03031384	2006 FREIGHTLIN		FAIL	50	
TRAILER 1	E7622B	ON		2008 TRAIL		PASS		
2014-06-05	16:30	2	9820465	0	SC38 STA	s.22	BC	s.22
POWER UNIT	17945P	BC		FRHT		PASS		
SEMI TRAILER	84807C	BC		UTIL		PASS		
2014-06-05	14:47	1	9802063	0	SC38 STA	s.22	BC	s.22
POWER UNIT	19106P	BC	01065757	FRHT		PASS		
SEMI TRAILER	4CK964	AB		VANR		PASS		
2014-06-05	12:48	1	8354072	0	HOPE	s.22	BC	s.22
POWER UNIT	16145P	BC	10627033	2013 FREIGHTLIN		PASS		
TRAILER 1	33589D	BC	02523281	2009 UTILITY		PASS		
2014-06-04	22:47	1	8335092	0	HUNTER CRE	s.22	BC	s.22
POWER UNIT	17590P	BC	03618114	2007 FREIGHTLIN		PASS		
TRAILER 1	36512B	BC	02951036	2005 UTILITY		PASS		
2014-06-04	13:53	1	8334828	3	HUNTER CRE	s.22	BC	s.22
POWER UNIT	16148P	BC	10810535	2006 FREIGHTLIN		OOS	44	
TRAILER 1	4ER333	AB		2012 VANGUARD		PASS		
2014-06-03	09:37	1	8333731	0	Laidlaw	s.22	BC	s.22
POWER UNIT	17947P	BC	04276109	2009 KENWORTH		FAIL	40 44 45	
TRAILER 1	98782C	BC	01656713	2008 UTILITY		FAIL	47	
2014-06-02	21:34	3	8333394	0	KAMLOOPS	s.22	BC	s.22
POWER UNIT	17163P	BC	03455550	2006 VOLVO		PASS		
TRAILER 1	4TS064	AB		2015 UTILITY		PASS		
2014-06-02	08:40	3	9820394	0	SC33 BOW	s.22	BC	s.22
POWER UNIT	16580P	BC	10925112	FRHT		PASS		
SEMI TRAILER	46129D	BC		UTIL		PASS		
2014-05-30	11:26	2	8332487	0	CHILLIWACK	s.22	BC	s.22
POWER UNIT	19062P	BC	10719198	2007 FREIGHTLIN		PASS		
TRAILER 1	84837C	BC	10042150	2010 UTILITY		PASS		

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION	ITEM DEFECT(S)
2014-05-27	10:10	1	9708090	0	SC33 BOW	s.22	BC	s.22
POWER UNIT	15700P	BC	00219747	KW		PASS		
SEMI TRAILER	44787D	BC		UTIL		PASS		
2014-05-26	13:25	3	9707752	0	SC33 BOW	s.22	BC	s.22
POWER UNIT	19106P	BC	01065757	FRHT		PASS		
SEMI TRAILER	34070D	BC		UTIL		PASS		s.22
2014-05-24	10:01	3	8330225	0	SURREY	s.22	BC	
POWER UNIT	12991P	BC	03919308	2007 KENWORTH		PASS		
TRAILER 1	44744D	BC	10795975	2014 UTILITY		PASS		
2014-05-23	08:33	3	9944078	0	SC33 BOW	s.22	BC	s.22
POWER UNIT	16170P	BC	10879872	KW		PASS		
2014-05-22	21:48	3	9674088	0	SC33 BOW	s.22	BC	s.22
POWER UNIT	03999P	BC	02211029	FRHT		PASS		
SEMI TRAILER	05245D	BC		UTIL		PASS		
2014-05-22	10:51	3	9674352	0	EVERETT	s.22	BC	s.22
POWER UNIT	05727P	BC	01896963	VOLV		PASS		
SEMI TRAILER	4ER156	AB		TRLR		PASS		
2014-05-22	10:24	3	9663703	0	ROADSIDE	s.22	BC	s.22
POWER UNIT	12409P	BC	03565565	FRHT		PASS		
SEMI TRAILER	34070D	BC		UTIL		PASS		
2014-05-15	15:44	1	8327663	3	GOLDEN	s.22	AB	s.22
POWER UNIT	08649P	BC	02485930	2005 PETERBILT		OOS	47	
						FAIL	43 44 45	
TRAILER 1	13888Y	BC	01206824	2003 GREAT DANE		FAIL	41 46	
							s.22	
2014-05-14	07:35	1	8326960	0	HUNTER CRE	s.22	BC	s.22
POWER UNIT	P93885	BC	09845578	2007 FREIGHTLIN		FAIL	44 55	
TRAILER 1	4EY652	AB		2012 VANGARD		PASS		
2014-05-12	13:14	1	9551802	0	SC07 FT	s.22	BC	s.22
POWER UNIT	P93675	BC	00263666	KW		FAIL	44 45	
SEMI TRAILER	22900D	BC		VANR		PASS		
2014-05-10	06:47	2	9581079	0	SC33 BOW	s.22	BC	s.22
POWER UNIT	09165P	BC	03526127	FRHT		PASS		
SEMI TRAILER	4ER332	AB		TRLR		PASS		

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION	ITEM DEFECT(S)
2014-05-07	14:46	3	9535260	0	LACEY	s.22	BC	s.22
POWER UNIT	19102P	BC	10117468	FRHT		PASS		
SEMI TRAILER	4CK964	AB		VANR		PASS		
2014-05-07	14:05	1	9523257	3	ROADSIDE	s.22	BC	
POWER UNIT	11838P	BC	08618565	PTRB		OOS	49	
SEMI TRAILER	84833C	BC		UTIL		FAIL	44 4	
						PASS		
2014-05-06	07:19	3	8323701	0	HUNTER CRE	s.22	BC	
POWER UNIT	16144P	BC	10549828	2007 FREIGHTLIN		PASS		
TRAILER 1	10420D	BC	10449708	2012 UTILITY		PASS		
2014-05-05	10:15	2	9581323	0	SC38 STA	s.22	BC	
POWER UNIT	16585P	BC		FRHT		PASS		
SEMI TRAILER	44736D	BC		UTIL		PASS		
2014-05-02	10:23	1	8323016	0	HUNTER CRE	s.22	BC	
POWER UNIT	16585P	BC	00327083	2007 FREIGHTLIN		PASS		
TRAILER 1	84823C	BC	03050967	2006 UTILITY		PASS		
2014-05-01	10:56	1	8322290	0	HUNTER CRE	s.22	BC	
POWER UNIT	18531P	BC	01846874	2004 PETERBILT		PASS		
TRAILER 1	05266D	BC	10390317	2012 UTILITY		FAIL	41	
2014-04-30	13:48	1	9469112	0	COTTONWOOD	s.22	BC	
POWER UNIT	09174P	BC	09582853	PTRB		PASS		
SEMI TRAILER	4ER156	AB		VANR		PASS		
2014-04-29	08:55	3	8352953	0	DELTA	s.22	BC	
POWER UNIT	17945P	BC	03707629	2007 FRTLNR		PASS		
TRAILER 1	4DY972	AB		2012 VANGUARD		PASS		
2014-04-28	17:42	3	8319640	0	LIDLAW	s.22	BC	
POWER UNIT	16588P	BC	10795651	2009 FREIGHTLIN		PASS		
2014-04-28	13:18	1	8319440	0	LIDLAW	s.22	BC	
POWER UNIT	17171P	BC	10146233	2012 FREIGHTLIN		FAIL	41 4	
TRAILER 1	84818C	BC	03267214	2006 UTILITY		PASS		
2014-04-25	18:45	2	9408888	3	SC33 BOW	s.22	BC	
POWER UNIT	17941P	BC	03264597	KW		PASS		
SEMI TRAILER	08389Y	BC		UTIL		OOS	46	

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION ITEM	DEFECT(S)
2014-04-23	16:06	3	9381105	0	NB	s.22	BC	s.22
POWER UNIT	09174P	BC	09582853	PTRB		PASS		
SEMI TRAILER	4ER338	AB		VANR		PASS		
2014-04-21	07:45	2	9341932	0	SC33 BOW	s.22	BC	
POWER UNIT	P93675	BC	00263666	KW		PASS		
SEMI TRAILER	T71697	TN		TRLR		FAIL	41	
2014-04-15	13:30	2	9286907	0	NB	s.22	BC	
POWER UNIT	12409P	BC	03565565	FRHT		PASS		
SEMI TRAILER	36288D	BC		HYTR		PASS		
2014-04-12	14:13	3	8314760	0	HUNTER CRE	s.22	BC	
POWER UNIT	12407P	BC	10695252	2013 FREIGHTLIN		PASS		
TRAILER 1	B7883S	ON		2005 MANA		PASS		
2014-04-11	06:34	3	8314150	0	HUNTER CRE	s.22	BC	
POWER UNIT	P93885	BC	09845578	2007 FREIGHTLIN		PASS		
TRAILER 1	63039C	BC	02523317	2009 UTILITY		PASS		
2014-04-07	14:05	3	9218401	0	SC33 BOW	s.22	BC	
POWER UNIT	17941P	BC	03264597	KW		PASS		
SEMI TRAILER	44806D	BC		UTIL		PASS		
2014-04-07	13:58	2	8311790	0	LAIDLAW	s.22	BC	
POWER UNIT	17592P	BC	10804310	2014 FREIGHTLIN		FAIL	40	
TRAILER 1	44732D	BC	10755073	2014 UTILITY		PASS		
2014-04-07	07:15	3	8311380	0	HUNTER CRE	s.22	BC	
POWER UNIT	16144P	BC	10549828	2007 FREIGHTLIN		PASS		
TRAILER 1	4703XH	WA		1999 GREAT		PASS		
2014-04-07	06:30	2	9218620	3	N/B	s.22	BC	
POWER UNIT	18572P	BC		FRHT		FAIL	40	
SEMI TRAILER	43609D	BC		UTIL		OOS	44 4	
2014-04-01	16:21	1	8308581	3	KAMLOOPS	s.22	BC	
POWER UNIT	P87530	BC	01358658	2003 KENWORTH		OOS	47	
						FAIL	44	
TRAILER 1	22943D	BC	10628433	2013 UTILITY		OOS	47	
2014-04-01	13:23	2	9169406	0	SC53 CLE	s.22	BC	
POWER UNIT	16148P	BC	10810535	FRHT		PASS		
SEMI TRAILER	44738D	BC		UTIL		PASS		

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION	ITEM DEFECT(S)
2014-03-31	06:55	3	9152036	0	SC33 BOW	s.22	BC	s.22
POWER UNIT	17610P	BC	03091059	FRHT		PASS		
SEMI TRAILER	20095D	BC		WANC		PASS		
2014-03-25	14:24	3	9091120	0	BOW HILL P	s.22	BC	
POWER UNIT	16150P	BC	00413629	FRHT		PASS		
SEMI TRAILER	61629D	BC		UTIL		PASS		
2014-03-25	08:00	2	9076894	0	SC33 BOW	s.22	BC	
POWER UNIT	12409P	BC	03565565	FRHT		PASS		
SEMI TRAILER	36290D	BC		HYTR		PASS		
2014-03-24	08:45	1	9076881	0	SC33 BOW	s.22	BC	
POWER UNIT	10468P	BC	03773135	KW		PASS		
SEMI TRAILER	80439C	BC		UTIL		PASS		
2014-03-20	19:05	2	8302052	3	SURREY	s.22	BC	
POWER UNIT	17610P	BC	03091059	2008 FREIGHTLIN		OOS	44	
						FAIL	40	55
TRAILER 1	44781D	BC	10840727	2014 UTILITY		FAIL	55	
2014-03-17	12:59	1	9041165	0	NORTHBOUND	s.22	BC	
POWER UNIT	12998P	BC		FRHT		PASS		
SEMI TRAILER	46106D	BC		UTIL		PASS		
2014-03-13	14:20	2	8975451	0	SC33 BOW	s.22	BC	
POWER UNIT	17610P	BC	03091059	FRHT		FAIL	44	
SEMI TRAILER	36290D	BC		HYTR		PASS		
2014-03-12	20:36	3	8297650	0	KAMLOOPS	s.22	BC	
POWER UNIT	16581P	BC	10572840	2013 FREIGHTLIN		PASS		
TRAILER 1	44811D	BC	10755906	2014 UTILITY		PASS		
2014-03-12	10:32	1	8297212	0	LIDLAW	s.22	BC	
POWER UNIT	08689P	BC	01632101	2003 KENWORTH		PASS		
TRAILER 1	07013D	BC	03253842	2006 UTILITY		PASS		
2014-03-11	09:08	2	8940738	0	SB	s.22	BC	
POWER UNIT	P84508	BC	00190625	VOLV		FAIL	41	
SEMI TRAILER	55524B	BC		GDAN		PASS		
2014-03-04	13:49	3	8292740	0	HUNTER CRE	s.22	BC	
POWER UNIT	15700P	BC	00219747	2007 KENWORTH		PASS		
TRAILER 1	44735D	BC	10755031	2014 UTILITY		PASS		

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION	ITEM DEFECT(S)
2014-03-01	09:09	3	8291360	0	HUNTER CRE	s.22	BC	s.22
POWER UNIT	17954P	BC	03589084	2006 FRGHT L		PASS		
TRAILER 1	44741D	BC	10795991	2014 UTILITY		PASS		
2014-02-26	17:39	3	8833145	0	SC33 BOW H	s.22	BC	
POWER UNIT	08688P	BC	02777288	FRHT		PASS		
SEMI TRAILER	46102D	BC		UTIL		PASS		
2014-02-24	14:42	2	8288411	0	KAMLOOPS	s.22	BC	
POWER UNIT	10477P	BC	02190954	2008 KENWORTH		FAIL	41 42	
TRAILER 1	98781C	BC	01656900	2008 UTILITY		PASS		
2014-02-21	10:16	2	8792011	0	SB	s.22	BC	
POWER UNIT	16150P	BC	00413629	FRHT		FAIL	40 41	
SEMI TRAILER	4HM921	AB		VANA		PASS		
2014-02-18	14:26	3	8735891	0	SC38 STA	s.22	BC	
POWER UNIT	P93675	BC	00263666	KW		PASS		
SEMI TRAILER	84836C	BC		UNK		PASS		
2014-02-18	08:05	3	8285170	0	HUNTER CRE	s.22	BC	
POWER UNIT	17945P	BC	03707629	2007 FREIGHTLIN		PASS		
TRAILER 1	44735D	BC	10755031	2014 UTILITY		PASS		
2014-02-13	04:50	3	8702090	0	SC33 BOW H	s.22	BC	
POWER UNIT	08689P	BC	01632101	KW		PASS		
SEMI TRAILER	84820C	BC		UTIL		PASS		
2014-02-12	07:57	2	8692089	0	SC33 BOW H	s.22	BC	
POWER UNIT	12409P	BC	03565565	FRHT		PASS		
SEMI TRAILER	63036C	BC		UTIL		FAIL	46	
2014-02-11	10:32	2	8702033	0	SB	s.22	BC	
POWER UNIT	10928P	BC	10618690	INTL		PASS		
SEMI TRAILER	36290D	BC		HYTR		PASS		
2014-02-10	16:53	3	8681816	0	SC26 FEDE	s.22	BC	
POWER UNIT	10468P	BC	03773135	KW		PASS		
SEMI TRAILER	05248D	BC		UTIL		PASS		
2014-02-05	18:14	2	8280013	3	DELTA	s.22	BC	
POWER UNIT	11824P	BC	00414882	2007 FREIGHTLIN		PASS		
TRAILER 1	05262D	BC	10390303	2012 UTILITY		OOS	41	

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE VEH TYPE	TIME PLATE#	LEVEL JR	MICRO# VEH REG	NSC PTS VEHICLE DESC	LOCATION	DL# PASS/FAIL	DLJR INSPECTION ITEM	DRIVER NAME DEFECT(S)
2014-02-04 POWER UNIT SEMI TRAILER	10:30 P93686 4PH706	2 BC BC	8629583 09649734	0 VOLV VANR	US/CANADA	s.22 PASS PASS	BC	s.22
2014-02-04 POWER UNIT SEMI TRAILER	08:46 11838P 4ER338	3 BC AB	8629678 08618565	0 PTRB UNK	SC33 BOW	s.22 FAIL PASS	BC 40	
2014-02-03 POWER UNIT	04:10 P97126	3 BC	8606625 02172581	0 FRHT	SC33 BOW H	s.22 PASS	BC	
2014-01-31 POWER UNIT SEMI TRAILER	14:59 09174P S41918	1 BC AB	8610299 09582853	0 PTRB GDAN	COTTONWOOD	s.22 PASS PASS	BC	
2014-01-30 POWER UNIT SEMI TRAILER	04:15 07259P 05247D	2 BC BC	8576352 10208509	0 FRHT UTIL	SC33 BOW H	s.22 PASS PASS	BC	
2014-01-28 POWER UNIT TRAILER 1	22:00 01372P 05244D	3 BC BC	8275560 03733087 10383700	0 2006 FREIGHTLIN 2012 UTILITY	HUNTER CRE	s.22 PASS PASS	BC	
2014-01-28 POWER UNIT TRAILER 1	22:00 01372P 05244D	4 BC BC	8275551 03733087 10383700	0 2006 FREIGHTLIN 2012 UTILITY	HUNTER CRE	s.22 PASS PASS	BC	
2014-01-28 POWER UNIT SEMI TRAILER	17:23 03999P 10417D	2 BC BC	8564269 02211029	0 FRHT UTIL	SC33 BOW H	s.22 FAIL PASS	BC 41	
2014-01-26 POWER UNIT TRAILER 1	12:34 03488P 4HM830	3 BC AB	8273942 00547686	0 2005 PETERBILT 2013 VANGUARD	DELTA	s.22 FAIL PASS	BC 40 4	
2014-01-26 POWER UNIT	09:40 16142P	3 BC	8273896 10890783	0 2003 PETERBILT	DELTA	s.22 FAIL	BC 40 4	
2014-01-22 POWER UNIT TRAILER 1	20:06 15129P 4EY676	1 BC AB	8272224 00131214	0 2007 KENWORTH 2012 VANGUARD	GOLDEN	s.22 PASS PASS	BC	
2014-01-22 POWER UNIT SEMI TRAILER	09:38 16150P 80440C	2 BC BC	8500888 00413629	0 FRHT UTIL	US/CANADA	s.22 FAIL PASS	BC 41	

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE VEH TYPE	TIME PLATE#	LEVEL JR	MICRO# VEH REG	NSC PTS VEHICLE DESC	LOCATION	DL# PASS/FAIL	DLJR INSPECTION ITEM	DRIVER NAME DEFECT(S)
2014-01-21 POWER UNIT SEMI TRAILER	10:35 07259P 20098D	2 BC BC	8641632 10208509	0 FRHT WANC	NB	s.22 PASS PASS	BC	s.22
2014-01-20 POWER UNIT SEMI TRAILER	01:55 15699P 4FX309	3 BC AB	8486438 10350135	0 VOLV UTIL	SC33 BOW H	s.22 PASS PASS	BC	
2014-01-18 POWER UNIT	10:44 12999P	2 BC	8269750 10713889	3 2007 FREIGHTLIN	GOLDEN	s.22 OOS	BC	46
2014-01-17 POWER UNIT TRAILER 1	21:58 16146P 44724D	3 BC BC	8269680 10764690 10796192	0 2007 FREIGHTLIN 2014 UTILITY	SURREY	s.22 FAIL PASS	BC	40
2014-01-16 TRUCK SEMI TRAILER	10:46 09165P 85159C	3 BC BC	8463650 03526127	0 FRHT UTIL	SB	s.22 PASS PASS	BC	
2014-01-16 POWER UNIT SEMI TRAILER	10:10 08642P 10470D	3 BC BC	8463648 01192322	0 KW UTIL	SB	s.22 PASS PASS	BC	
2014-01-14 POWER UNIT TRAILER 1	11:29 07261P 42425B	2 BC BC	8267321 03267342 03046575	0 2006 PETERBILT 2006 GREAT DANE	SICAMOUS	s.22 PASS PASS	BC	
2014-01-14 POWER UNIT SEMI TRAILER	04:30 04166P 85159C	2 BC BC	8426694	3 PTRB UTIL	SC33 BOW H	s.22 PASS OOS	BC	47
2014-01-10 POWER UNIT TRAILER 1	08:14 12409P T66086	4 BC AB	8265722 03565565	0 2006 FREIGHTLIN 2012 GREAT DANE	ABBOTSFORD	s.22 PASS PASS	BC	
2014-01-09 POWER UNIT TRAILER 1	09:19 P93187 44747D	4 BC BC	8265173 09874313 10796267	0 2010 FREIGHTLIN 2014 UTILITY	ABBOTSFORD	s.22 PASS PASS	BC	
2014-01-09 POWER UNIT TRAILER 1	08:58 09165P 84852C	4 BC BC	8265150 03526127 01624943	0 2006 FREIGHTLIN 2004 UTILITY	ABBOTSFORD	s.22 PASS PASS	BC	
2014-01-08 POWER UNIT TRAILER 1	15:25 P87530 44811D	3 BC BC	8264890 01358658 10755906	0 2003 KENWORTH 2014 UTILITY	LAIDLAW	s.22 PASS PASS	BC	

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION ITEM	DEFECT(S)
2014-01-08	08:52	3	8373152	0	SC33 BOW	s.22	BC	s.22
POWER UNIT	00507P	BC	00719501	FRHT		PASS		
SEMI TRAILER	20097D	BC		WANC		PASS		
2014-01-07	16:01	3	8387027	0	BOW	s.22	BC	
POWER UNIT	11838P	BC	08618565	PTRB		PASS		
SEMI TRAILER	44723D	BC		UNK		PASS		
2014-01-05	18:16	3	8263660	0	HUNTER CRE	s.22	BC	
POWER UNIT	17171P	BC	10146233	2012 FREIGHT		FAIL	40	
TRAILER 1	63036C	BC	02522233	2008 UTILITY		PASS		
2014-01-05	13:30	1	8263633	0	LAILDLAW	s.22	BC	
POWER UNIT	01619P	BC	10619217	2013 FREIGHTLIN		PASS		
TRAILER 1	55516B	BC	02505981	2005 GREAT DANE		FAIL	44	
2014-01-03	21:21	3	8263380	0	HUNTER CRE	s.22	BC	
POWER UNIT	11837P	BC	10566182	2013 FREIGHTLIN		PASS		
TRAILER 1	05266D	BC	10390317	2012 UTILITY		PASS		
2013-12-28	03:10	3	8305198	0	SC33 BOW	s.22	BC	
POWER UNIT	P84508	BC	00190625	VOLV		PASS		
SEMI TRAILER	22901D	BC		VANR		PASS		
2013-12-23	09:05	3	8280960	0	SC15 POR	s.22	BC	
POWER UNIT	16144P	BC	10549828	FRHT		PASS		
SEMI TRAILER	4473D	BC		UTIL		PASS		
2013-12-23	08:30	3	8262724	0	SC15 POR	s.22	BC	
POWER UNIT	15699P	BC	10350135	VOLV		PASS		
SEMI TRAILER	44735D	BC		UTIL		PASS		
2013-12-21	05:07	3	8262809	0	SC33 BOW H	s.22	BC	
POWER UNIT	08677P	BC	10070282	FRHT		PASS		
SEMI TRAILER	05246D	BC		UTIL		PASS		
2013-12-19	13:20	3	8239358	0	SC15 POR	s.22	BC	
POWER UNIT	12998P	BC	00582523	FRHT		PASS		
SEMI TRAILER	86241B	BC		UTIL		PASS		
2013-12-18	07:04	3	8280941	0	NB	s.22	BC	
POWER UNIT	03999P	BC	02211029	FRHT		PASS		
SEMI TRAILER	44740D	BC		UTIL		PASS		

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE VEH TYPE	TIME PLATE#	LEVEL JR	MICRO# VEH REG	NSC PTS VEHICLE DESC	LOCATION	DL# PASS/FAIL	DLJR INSPECTION ITEM	DRIVER NAME DEFECT(S)
2013-12-10 POWER UNIT SEMI TRAILER	13:25 15700P 44730D	3 BC BC	8195652 00219747	0 KW UTIL	NB	s.22 PASS PASS	BC	s.22
2013-12-08 POWER UNIT TRAILER 1	13:36 12999P T72244	2 BC AB	8255239 10713889	0 2007 FREIGHTLIN 2006 UTILITY	MERRITT	s.22 FAIL FAIL	BC 44 44	
2013-12-06 POWER UNIT SEMI TRAILER	06:45 P93675 45146B	3 BC BC	8136026 00263666	0 KW UTIL	SC33 BOW H	s.22 PASS PASS	BC	
2013-12-04 POWER UNIT	06:48 16588P	3 BC	8253451 10795651	0 2009 FREIGHTLIN	LAIDLAW	s.22 PASS	BC	
2013-12-03 POWER UNIT TRAILER 1	21:26 12403P 07013D	3 BC BC	8252830 03845693 03253842	0 2009 FREIGHTLIN 2006 UTILITY	KAMLOOPS	s.22 FAIL PASS	BC 40	
2013-12-03 POWER UNIT SEMI TRAILER	18:03 08689P 46120D	3 BC BC	8093977 01632101	0 KW GDAN	SC33 BOW H	s.22 PASS PASS	BC	
2013-12-03 POWER UNIT TRAILER 1	10:35 15701P 02966D	2 BC BC	8252200 03506574 03745644	0 2006 FREIGHTLIN 2007 GREAT DANE	KAMLOOPS	s.22 PASS FAIL	BC 55	
2013-12-02 POWER UNIT TRAILER 1	09:36 09172P 44733D	3 BC BC	8251300 03589084 10755054	0 2006 FREIGHTLIN 2014 UTILITY	ABBOTSFORD	s.22 PASS PASS	BC	
2013-11-28 POWER UNIT TRAILER 1	22:26 16148P 73568C	3 BC BC	8249410 10810535 10042360	0 2006 FREIGHTLIN 2011 UTILITY	HUNTER CRE	s.22 PASS PASS	BC	
2013-11-27 POWER UNIT TRAILER 1	19:34 08688P 44778D	2 BC BC	8248320 02777288 10840702	3 2005 FREIGHTLIN 2014 UTILITY	HUNTER CRE	s.22 FAIL OOS	BC 55 41	
2013-11-27 POWER UNIT TRAILER 1	17:07 16582P 84813C	2 BC BC	8248261 03031384 01741341	0 2006 FREIGHTLIN 2005 UTILITY	KAMLOOPS	s.22 FAIL PASS	BC 41	
2013-11-27 POWER UNIT SEMI TRAILER	04:18 07259P 84811C	3 BC BC	8048991 10208509	0 FRHT UTIL	SC33 BOW H	s.22 PASS PASS	BC	

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE VEH TYPE	TIME PLATE#	LEVEL JR	MICRO# VEH REG	NSC PTS VEHICLE DESC	LOCATION	DL# PASS/FAIL	DLJR INSPECTION ITEM	DRIVER NAME DEFECT(S)
2013-11-25 POWER UNIT TRAILER 1	07:23 P93187 29217D	3 BC BC	8245960 09874313 02210544	0 2010 FREIGHTLIN 2008 UTILITY	HUNTER CRE	s.22 FAIL PASS	BC 40	s.22
2013-11-18 POWER UNIT SEMI TRAILER	19:10 16150P 98783C	3 BC BC	7965262 00413629	0 FRHT UTIL	SC33 BOW H	s.22 PASS PASS	BC	
2013-11-17 POWER UNIT	12:20 P97125	2 BC	7952880 02245144	0 INTL	SC33 BOW H	s.22 PASS	BC	
2013-11-15 POWER UNIT SEMI TRAILER	12:49 08642P X41671	3 BC AB	8068984 01192322	0 KW GDAN	NB	s.22 PASS PASS	BC	
2013-11-14 POWER UNIT TRAILER 1	07:31 03459P 84822C	3 BC BC	8240271 00967378 03289924	0 2008 KENWORTH 2006 UTILITY	HUNTER CRE	s.22 PASS PASS	BC	
2013-11-13 POWER UNIT TRAILER 1	12:48 01375P 33589D	3 BC BC	8239760 09861668 02523281	0 2007 VOLVO 2009 UTILITY	LAIDLAW	s.22 PASS PASS	BC	
2013-11-13 POWER UNIT SEMI TRAILER	08:50 16580P 12510D	3 BC BC	8069549 10925112	0 FRHT UTIL	SB	s.22 FAIL PASS	BC 40	
2013-11-13 POWER UNIT	08:27 16150P	2 BC	7908127 00413629	0 FRHT	PORT ANGEL	s.22 PASS	BC	
2013-11-05 POWER UNIT SEMI TRAILER	03:50 15699P 05261D	3 BC BC	7843780 10350135	0 VOLV UTIL	SC33 BOW H	s.22 PASS PASS	WA	
2013-11-01 POWER UNIT SEMI TRAILER	08:15 16585P 4DX595	3 BC AB	7805886	0 FRHT VANR	DUNSMUIR G	s.22 PASS PASS	BC	
2013-10-30 POWER UNIT SEMI TRAILER	08:00 P79528 05201D	1 BC BC	7779573 00025509	0 FRHT GDAN	SC33 BOW H	s.22 PASS PASS	BC	
2013-10-25 POWER UNIT SEMI TRAILER	18:11 08689P 98786C	3 BC BC	7756549 01632101	0 KW UTIL	SC33 BOW	s.22 PASS PASS	BC	

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE VEH TYPE	TIME PLATE#	LEVEL JR	MICRO# VEH REG	NSC PTS VEHICLE DESC	LOCATION	DL# PASS/FAIL	DLJR INSPECTION ITEM	DRIVER NAME DEFECT(S)
2013-10-24 POWER UNIT	11:16 16144P	3 BC	8233626 10549828	0 2007 FREIGHTLIN	ABBOTSFORD	s.22 PASS	BC	s.22
2013-10-24 POWER UNIT SEMI TRAILER	10:57 00507P 46107D	3 BC BC	7739392 00719501	0 FRHT UTIL	SC33 BOW	s.22 PASS PASS	BC	
2013-10-23 POWER UNIT SEMI TRAILER	13:49 03459P 22943D	3 BC BC	7798680	0 KW UTIL	SR9 MP58	s.22 PASS PASS	BC	
2013-10-23 POWER UNIT SEMI TRAILER	03:58 15699P 4PH701	3 BC AB	7713316 10350135	0 VOLV VANR	SC33 BOW H	s.22 PASS PASS	BC	
2013-10-22 POWER UNIT SEMI TRAILER	11:47 P89317 98792C	3 BC BC	7713544 01846874	0 PTRB UTIL	ACME, WA	s.22 PASS PASS	BC	
2013-10-20 POWER UNIT TRAILER 1	12:48 P87530 V88861	1 BC AB	8228696 01358658	0 2003 KENWORTH 2012 GRT DANE	LAIDLAW	s.22 PASS PASS	BC	
2013-10-19 POWER UNIT TRAILER 1	08:00 09165P 36291D	3 BC BC	8228502 03526127 03082508	0 2006 FREIGHTLIN 2009 HYUNDAI	HUNTER CRE	s.22 PASS PASS	BC	
2013-10-15 POWER UNIT SEMI TRAILER	13:55 03459P 4DY975	3 BC AB	7684501 00967378	0 KW VW	NB	s.22 PASS PASS	BC	
2013-10-12 POWER UNIT SEMI TRAILER	05:30 07250P 86658C	2 BC BC	7607524 02172601	0 FRHT UTIL	EB	s.22 FAIL PASS	BC 41	
2013-10-07 POWER UNIT	14:10 12997P	3 BC	8224044 10728527	0 2013 FREIGHTLIN	LAIDLAW	s.22 PASS	BC	
2013-10-07 POWER UNIT SEMI TRAILER	11:35 10468P 44730D	3 BC BC	7562107 03773135	0 KW UTIL	NORTH	s.22 PASS PASS	BC	
2013-10-05 POWER UNIT TRAILER 1	10:20 15697P 98788C	2 BC BC	8223410 09955897 01963688	3 2011 VOLVO 2008 UTILITY	CASSIDY	s.22 PASS OOS FAIL	BC 47 44	

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE VEH TYPE	TIME PLATE#	LEVEL JR	MICRO# VEH REG	NSC PTS VEHICLE DESC	LOCATION	DL# PASS/FAIL	DLJR INSPECTION ITEM	DRIVER NAME DEFECT(S)
2013-10-03 POWER UNIT SEMI TRAILER	09:50 P89317 86659C	3 BC BC	7607417 01846874	0 PTRB UTIL	NB	s.22 PASS PASS	BC	s.22
2013-10-02 POWER UNIT SEMI TRAILER	09:15 16170P 44726D	3 BC BC	7521035 10879872	0 KW UTIL	SC33 BOW H	s.22 PASS PASS	BC	
2013-09-28 POWER UNIT TRAILER 1	07:52 P93671 84827C	3 BC BC	8220870 04276109 03773812	0 2009 KENWORTH 2007 UTILITY	HUNTER CRE	s.22 PASS PASS	BC	
2013-09-25 POWER UNIT SEMI TRAILER	10:55 16144P 44745D	3 BC BC	7520756 10549828	0 FRHT UTIL	SB	s.22 FAIL PASS	BC	40
2013-09-25 POWER UNIT SEMI TRAILER	10:42 11824P 80442C	3 BC BC	7520755 00414882	0 FRHT UTIL	SB	s.22 PASS PASS	BC	
2013-09-24 POWER UNIT	03:22 P97125	2 BC	7417386 02245144	0 INTL	SC33 BOW H	s.22 FAIL	BC	41
2013-09-20 POWER UNIT SEMI TRAILER	16:32 09172P 44783D	1 BC BC	7401517 03589084	0 FRHT UTIL	SC33 BOW H	s.22 PASS PASS	BC	
2013-09-19 POWER UNIT TRAILER 1	10:53 09172P 46093D	1 BC BC	8218543 03589084 10861227	0 2006 FRTLNR 2014 UTILITY	LAIDLAW	s.22 FAIL PASS	BC	41 4
2013-09-19 POWER UNIT TRAILER 1	08:39 09174P 84823C	1 BC BC	8218100 09582853 03050967	0 2010 PETERBILT 2006 UTILITY	HUNTER CRE	s.22 PASS FAIL	BC	44
2013-09-17 POWER UNIT TRAILER 1	15:36 12976P 86618C	1 BC BC	8217475 03647208 10208038	0 2006 FREIGHTLIN 2012 UTILITY	GOLDEN	s.22 PASS PASS	BC	
2013-09-17 POWER UNIT SEMI TRAILER	09:35 12403P X68560	2 BC AB	7339829	0 FRHT GDAN	SC33 BOW	s.22 PASS FAIL	BC	44
2013-09-17 POWER UNIT TRAILER 1	09:01 P93187 44805D	3 BC BC	8217231 09874313 10752365	0 2010 FREIGHTLIN 2014 UTILITY	HUNTER CRE	s.22 PASS PASS	BC	

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION	ITEM DEFECT(S)
2013-09-16	04:18	2	7324054	3	SC33 BOW H	s.22	BC	s.22
POWER UNIT	P97126	BC		FRHT		PASS		
SEMI TRAILER	X41674	AB		GDAN		OOS	41	
2013-09-13	10:50	1	7364705	0	SC38 STA	s.22	BC	
POWER UNIT	P89317	BC	01846874	PTRB		PASS		
SEMI TRAILER	44744D	BC		UTIL		PASS		
2013-09-12	01:45	1	7294609	0	SC33 BOW H	s.22	BC	
POWER UNIT	08642P	BC	01192322	KW		PASS		
SEMI TRAILER	84820C	BC		UTIL		PASS		
2013-09-11	13:05	1	7417345	0	SC40 GRAN	s.22	BC	
POWER UNIT	09165P	BC		FRHT		PASS		
SEMI TRAILER	46129D	BC		UTIL		PASS		
2013-09-11	05:40	1	7279376	0	SC33 BOW	s.22	BC	
POWER UNIT	11824P	BC	00414882	FRHT		PASS		
SEMI TRAILER	84855C	BC		UTIL		PASS		
2013-09-05	15:09	1	8213152	0	KAMLOOPS	s.22	BC	
POWER UNIT	P87530	BC	01358658	2003 KENWORTH		FAIL	41	
TRAILER 1	02949D	BC	01326848	2008 UTILITY		FAIL	46	
2013-09-05	08:58	2	7217201	0	SUMAS, WA	s.22	BC	
POWER UNIT	00507P	BC	00719501	FRHT		PASS		
SEMI TRAILER	84808C	BC		UTIL		PASS		
2013-09-04	11:17	2	8212632	0	SURREY	s.22	BC	
POWER UNIT	00507P	BC	00719501	2007 FREIGHTLIN		FAIL	55	
TRAILER 1	80442C	BC	10186436	2012 UTILITY		PASS		
2013-09-03	19:25	2	8212491	0	SURREY	s.22	BC	
POWER UNIT	P93683	BC	10764690	2007 FREIGHTLIN		FAIL	40	
TRAILER 1	02965D	BC	03742033	2007 GREAT DANE		FAIL	41	
2013-08-28	10:36	3	8210692	0	ABBOTSFORD	s.22	BC	
POWER UNIT	10928P	BC	10618690	2012 INTERNATNA		PASS		
2013-08-28	08:40	1	7141101	0	SC15 POR	s.22	BC	
POWER UNIT	15698P	BC	10022141	VOLV		PASS		
SEMI TRAILER	98778C	BC		UTIL		FAIL	44	
2013-08-28	03:46	3	7141358	0	SC33 BOW H	s.22	BC	
POWER UNIT	07259P	BC	10208509	FRHT		PASS		
SEMI TRAILER	55522B	BC		GDAN		PASS		

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION ITEM	DEFECT(S)
2013-08-27	18:03	1	8210530	0	GOLDEN	s.22	BC	s.22
POWER UNIT	15697P	BC	09955897	2011 VOLVO		FAIL	40 41	
TRAILER 1	46093D	BC	10861227	2014 UTILITY		PASS		
2013-08-27	17:53	2	0736982	0	HWY. 40/T.	s.22	BC	
POWER UNIT	12130P	BC		FREIGHTLIN		PASS		
SEMI TRAILER	22903D	BC		VANGUARD		PASS		
2013-08-27	14:03	2	7141285	0	ROADSIDE	s.22	BC	
POWER UNIT	11824P	BC	00414882	FRHT		PASS		
SEMI TRAILER	40627B	BC		GDAN		PASS		
2013-08-26	20:44	3	8210010	0	LAIDLAW	s.22	BC	
POWER UNIT	10453P	BC	00871139	2008 VOLVO		PASS		
2013-08-26	13:29	1	8209840	0	LAIDLAW	s.22	BC	
POWER UNIT	14361P	BC	10804310	2014 FREIGHTLIN		FAIL	40 41	
TRAILER 1	63034C	BC	02523641	2009 UTILITY		FAIL	44	
2013-08-23	14:07	2	7108536	0	SC38 STA	s.22	BC	
POWER UNIT	P93687	BC		FRHT		PASS		
SEMI TRAILER	4ER331	AB		VANR		PASS		
2013-08-22	15:41	1	8208150	3	GOLDEN	s.22	AB	
POWER UNIT	08649P	BC	02485930	2005 PETERBILT		OOS	44	
						FAIL	40 41	
TRAILER 1	4CK965	AB		2012 VANGUARD		FAIL	41 44	
2013-08-22	07:49	3	7091049	0	SC33 BOW H	s.22	BC	
POWER UNIT	15698P	BC	10022141	VOLV		PASS		
SEMI TRAILER	29213D	BC		GDAN		PASS		
2013-08-21	12:08	3	8206877	0	SURREY	s.22	BC	
POWER UNIT	P79528	BC	00025509	2000 FREIGHTLIN		PASS		
2013-08-20	12:25	3	8206221	0	LAIDLAW	s.22	BC	
POWER UNIT	10453P	BC	00871139	2008 VOLVO		FAIL	40	
2013-08-20	09:45	3	8205623	0	ALDERGROVE	s.22	BC	
POWER UNIT	16170P	BC	10879872	2004 KENWORTH		PASS		
2013-08-19	14:45	3	8205268	0	SURREY	s.22	BC	
POWER UNIT	08642P	BC	01192322	2003 KENWORTH		PASS		

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION	ITEM DEFECT(S)
2013-08-16	17:05	3	7051726	0	SB	s.22	BC	s.22
POWER UNIT	01353P	BC	00597447	FRHT		PASS		
SEMI TRAILER	29218D	BC		UTIL		PASS		
2013-08-16	11:33	3	7051725	0	NB	s.22	BC	
POWER UNIT	P89317	BC	01846874	PTRB		FAIL	40	
SEMI TRAILER	X41669	AB		GDAN		PASS		
2013-08-16	08:43	3	8204051	0	HUNTER CRE	s.22	BC	
POWER UNIT	16150P	BC	00413629	2001 FREIGHTLIN		FAIL	40	
TRAILER 1	44726D	BC	10796225	2014 UTILITY		PASS		
2013-08-14	20:20	2	7006393	0	SC33 BOW	s.22	BC	
POWER UNIT	10929P	BC	10618844	INTL		PASS		
SEMI TRAILER	63036C	BC		UTIL		FAIL	44	
2013-08-12	08:05	2	6980424	0	SC33 BOW H	s.22	BC	
POWER UNIT	16150P	BC	00413629	FRHT		PASS		
SEMI TRAILER	4ER333	AB		TRLR		PASS		
2013-08-11	07:24	3	8201580	0	SURREY	s.22	BC	
POWER UNIT	01353P	BC	00597447	2007 FREIGHTLIN		FAIL	40	
TRAILER 1	4ER330	AB		2012 VANGUARD		PASS		
2013-08-09	14:53	1	8201310	0	LAIDLAW	s.22	BC	
POWER UNIT	15702P	BC	02406481	2006 VOLVO		PASS		
TRAILER 1	44726D	BC	10796225	2014 UTILITY		PASS		
2013-08-05	05:50	3	6898320	0	SC33 BOW H	s.22	BC	
POWER UNIT	P93683	BC	10764690	FRHT		PASS		
SEMI TRAILER	SX2563	MB		UTIL		PASS		
2013-08-02	14:52	3	8199271	0	HUNTER CRE	s.22	BC	
POWER UNIT	12997P	BC	10728527	2013 FREIGHTLIN		PASS		
TRAILER 1	55516B	BC	02505981	2005 GREAT DANE		PASS		
2013-08-01	23:03	2	8199010	0	SURREY	s.22	BC	
POWER UNIT	11824P	BC	00414882	2007 FREIGHTLIN		PASS		
TRAILER 1	X41669	AB		2008 GREAT DANE		PASS		
2013-08-01	07:33	3	6885295	0	STATE ROUT	s.22	BC	
POWER UNIT	P93671	BC	04276109	KW		PASS		
SEMI TRAILER	44735D	BC		UTIL		PASS		

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION ITEM	DEFECT(S)
2013-07-31	16:58	3	6885372	0	ROADSIDE	s.22	BC	s.22
POWER UNIT	09174P	BC	09582853	PTRB		PASS		
SEMI TRAILER	98814C	BC		UTIL		PASS		
2013-07-29	17:04	1	8197200	0	KAMLOOPS	s.22	BC	
POWER UNIT	09165P	BC	03526127	2006 FREIGHTLIN		FAIL	41 44	
TRAILER 1	X41669	AB		2008 GREAT DANE		FAIL	44 47	
2013-07-27	18:07	1	8196510	0	GOLDEN	s.22	BC	
POWER UNIT	09175P	BC	04502550	2005 FREIGHTLIN		FAIL	41 51	
TRAILER 1	98788C	BC	01963688	2008 UTILITY		FAIL	44	
2013-07-26	06:47	1	6834030	0	SC33 BOW H	s.22	BC	
POWER UNIT	12998P	BC	00582523	FRHT		PASS		
SEMI TRAILER	29219D	BC		UTIL		PASS		
2013-07-25	08:37	1	8195323	0	HUNTER CRE	s.22	BC	
POWER UNIT	15129P	BC	00131214	2007 KENWORTH		PASS		
TRAILER 1	96216B	BC	02971193	2006 UTILITY		PASS		
2013-07-24	09:05	3	6802730	0	SC33 BOW	s.22	BC	
POWER UNIT	04166P	BC	03622451	PTRB		PASS		
SEMI TRAILER	98787C	BC		UTIL		PASS		
2013-07-20	17:41	3	6802878	0	SC33 BOW	s.22	BC	
POWER UNIT	P93683	BC	10764690	FRHT		PASS		
SEMI TRAILER	84842C	BC		UTIL		PASS		
2013-07-18	10:36	1	6734474	0	SC33 BOW H	s.22	BC	
POWER UNIT	16150P	BC	00413629	FRHT		PASS		
SEMI TRAILER	44729D	BC		UTIL		PASS		
2013-07-16	16:00	3	6802811	3	SC38 STA	s.22	BC	
POWER UNIT	09172P	BC	03589084	FRHT		OOS	40	
SEMI TRAILER	80442C	BC		UTIL		PASS		
2013-07-13	04:52	3	6693707	0	SC33 BOW	s.22	BC	
POWER UNIT	12998P	BC	00582523	FRHT		PASS		
SEMI TRAILER	05245D	BC		UTIL		PASS		
2013-07-11	14:36	1	6677201	0	SC38 STA	s.22	BC	
POWER UNIT	P79528	BC	00025509	FRHT		FAIL	43 44	
SEMI TRAILER	4ER331	AB		VANR		PASS		

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION	ITEM DEFECT(S)
2013-07-10	00:45	3	6898144	0	I5 MP226	s.22	BC	s.22
POWER UNIT	08689P	BC	01632101	KW		PASS		
SEMI TRAILER	W49594	AB		UTIL		PASS		
2013-07-09	14:00	3	6802588	0	SC38 STA	s.22	BC	
POWER UNIT	15700P	BC	00219747	KW		PASS		
SEMI TRAILER	44790D	BC		UTIL		PASS		
2013-07-05	11:11	1	6734583	0	SC33 BOW	s.22	BC	
POWER UNIT	08677P	BC	10070282	FRHT		PASS		
SEMI TRAILER	22943D	BC		UTIL		FAIL	51	
2013-07-04	08:45	1	6610830	0	SC33 BOW	s.22	BC	
POWER UNIT	04166P	BC	03622451	PTRB		PASS		
SEMI TRAILER	12510D	BC		UTIL		FAIL	44	
2013-07-01	10:05	2	6589210	0	SC33 BOW H	s.22	BC	
POWER UNIT	12409P	BC	03565565	FRHT		FAIL	47	
SEMI TRAILER	30445C	BC		UTIL		PASS		
2013-07-01	09:55	3	7051778	0	SB	s.22	BC	
POWER UNIT	03459P	BC	00967378	KW		PASS		
SEMI TRAILER	44805D	BC		UTIL		PASS		
2013-06-25	11:39	1	8185240	0	KAMLOOPS	s.22	BC	
POWER UNIT	14356P	BC	02730189	2007 VOLVO		FAIL	44 4	
TRAILER 1	29287D	BC	01970155	2008 GREAT DANE		PASS		
2013-06-22	16:30	3	6501697	0	SC33 BOW H	s.22	BC	
POWER UNIT	03999P	BC	02211029	FRHT		PASS		
SEMI TRAILER	20056D	BC		WANC		PASS		
2013-06-18	12:46	1	8181811	3	DELTA	s.22	BC	
POWER UNIT	14357P	BC	10795651	2009 FREIGHTLIN		PASS		
TRAILER 1	29209D	BC	01922108	2008 GREAT DANE		OOS	41	
2013-06-18	06:54	3	6447595	0	WOODBURN P	s.22	WA	
POWER UNIT	10929P	BC	10618844	INTL		PASS		
SEMI TRAILER	X41670	AB		GDAN		PASS		
2013-06-15	10:59	1	8180693	3	HUNTER CRE	s.22	BC	
POWER UNIT	08689P	BC	01632101	2003 KENWORTH		OOS	43 4	
TRAILER 1	4ER333	AB		2012 VANGUARD		FAIL	40	
						OOS	44	

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION	ITEM DEFECT(S)
2013-06-14	09:35	1	6434395	0	SC33 BOW	s.22	BC	s.22
TRUCK	08677P	BC	10070282	FRHT		FAIL	41 43	
SEMI TRAILER	22852D	BC		UTIL		PASS		
2013-06-12	04:58	3	6390024	0	SC33 BOW H	s.22	BC	
POWER UNIT	12998P	BC	00582523	FRHT		PASS		
SEMI TRAILER	07012D	BC		UTIL		PASS		
2013-06-11	16:45	3	8179221	0	HUNTER CRE	s.22	BC	
POWER UNIT	14356P	BC	02730189	2007 VOLVO		PASS		
TRAILER 1	X68560	AB		2009 GRT DANE		PASS		
2013-06-11	09:34	2	6374791	0	SC33 BOW H	s.22	BC	
POWER UNIT	08642P	BC	01192322	KW		PASS		
2013-06-10	20:11	3	0726760	0	LEDUC - VI	s.22	AB	
POWER UNIT	12412P	BC		FREIGHTLIN		FAIL	40	
SEMI TRAILER	W67383	AB		UTILITY		PASS		
SEMI TRAILER	22913D	BC		UTILITY		PASS		
2013-06-06	12:01	1	8176451	3	HUNTER CRE	s.22	BC	
POWER UNIT	P93187	BC	09874313	2010 FREIGHTLIN		OOS	44	
TRAILER 1	10470D	BC	10498892	2012 UTILITY		FAIL	40 41	
						PASS		
2013-06-06	02:21	1	8175970	0	HUNTER CRE	s.22	BC	
POWER UNIT	12979P	BC	04937980	1998 PETERBILT		FAIL	46 55	
TRAILER 1	98786C	BC	01963539	2008 UTILITY		FAIL	47	
2013-06-05	15:31	1	8175763	0	LAIDLAW	s.22	BC	
POWER UNIT	12119P	BC	09868148	2004 FREIGHTLIN		FAIL	40 41	
2013-06-05	04:23	1	8174953	0	HUNTER CRE	s.22	BC	
POWER UNIT	01375P	BC	09861668	2007 VOLVO		PASS		
TRAILER 1	73557C	BC	10102067	2011 UTILITY		FAIL	55	
2013-06-04	12:33	1	6304732	0	SC07 FT	s.22	BC	
POWER UNIT	P93675	BC	00263666	KW		PASS		
SEMI TRAILER	18729B	BC		WANC		PASS		
2013-06-04	11:53	1	8173741	3	HOPE	s.22	BC	
POWER UNIT	12976P	BC	03647208	2006 FREIGHTLIN		OOS	43	
						FAIL	41 47	

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION	ITEM DEFECT(S)
2013-06-02	14:10	2	6276313	0	SC33 BOW H	s.22	BC	s.22
POWER UNIT	10468P	BC	03773135	KW		PASS		
SEMI TRAILER	39985D	BC		UTIL		PASS		
2013-06-01	20:10	1	8172390	0	KAMLOOPS	s.22	BC	
POWER UNIT	12999P	BC	10713889	2007 FREIGHTLIN		FAIL	44	
TRAILER 1	29215D	BC	01645562	2008 GREAT DANE		FAIL	44	
2013-06-01	07:50	1	8172110	0	KAMLOOPS	s.22	BC	
POWER UNIT	P93693	BC	02227341	2005 KENWORTH		FAIL	41 41	
TRAILER 1	55520B	BC	01486441	2004 GREAT DANE		FAIL	41	
2013-05-31	15:46	3	6275947	0	SC33 BOW	s.22	BC	
POWER UNIT	01353P	BC	00597447	FRHT		PASS		
SEMI TRAILER	X68560	AB		GDAN		PASS		
2013-05-30	01:10	2	8171300	0	SURREY	s.22	BC	
POWER UNIT	08689P	BC	01632101	2003 KENWORTH		PASS		
TRAILER 1	05248D	BC	10383723	2012 UTILITY		PASS		
2013-05-29	07:26	3	8170750	0	HUNTER CRE	s.22	BC	
POWER UNIT	12401P	BC	02231582	2005 KENWORTH		PASS		
TRAILER 1	98787C	BC	01963601	2008 UTILITY		PASS		
2013-05-28	09:47	3	8170311	0	HUNTER CRE	s.22	BC	
POWER UNIT	08642P	BC	01192322	2003 KENWORTH		PASS		
TRAILER 1	96700C	BC	02921756	2005 UTILITY		PASS		
2013-05-25	12:45	3	6210775	0	SC33 BOW H	s.22	BC	
POWER UNIT	12409P	BC	03565565	FRHT		PASS		
SEMI TRAILER	98780C	BC		UTIL		PASS		
2013-05-25	09:26	1	8169442	0	HUNTER CRE	s.22	BC	
POWER UNIT	12991P	BC	03919308	2007 KENWORTH		PASS		
TRAILER 1	84822C	BC	03289924	2006 UTILITY		PASS		
2013-05-24	19:51	2	8169396	0	RICHMOND	s.22	BC	
POWER UNIT	07228P	BC	07238242	2007 KENWORTH		FAIL	40 51	
2013-05-23	11:00	1	8168223	0	SURREY	s.22	BC	
POWER UNIT	12998P	BC	00582523	2001 FREIGHTLIN		FAIL	44	
TRAILER 1	X41669	AB		2008 GREAT DANE		FAIL	41	
2013-05-22	11:50	3	6211221	0	SC33 BOW	s.22	BC	
TRUCK	12409P	BC	03565565	FRHT		PASS		
SEMI TRAILER	84818C	BC		UTIL		PASS		

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION	ITEM DEFECT(S)
2013-05-19	07:03	2	8166361	0	LAILAW	s.22	BC	s.22
POWER UNIT	P93687	BC	00327083	2007 FREIGHTLIN		FAIL	41	
TRAILER 1	84823C	BC	03050967	2006 UTILITY		FAIL	44	
2013-05-16	13:03	1	8165881	0	KAMLOOPS	s.22	BC	
POWER UNIT	01372P	BC	03733087	2006 FREIGHTLIN		PASS		
TRAILER 1	30445C	BC	03066182	2006 UTILITY		PASS		
2013-05-14	10:33	3	8164330	3	HUNTER CRE	s.22	BC	
POWER UNIT	01353P	BC	00597447	2007 FREIGHTLIN		OOS	40	
TRAILER 1	22942D	BC	10628426	2013 UTILITY		PASS		
2013-05-14	09:36	1	8164296	0	SURREY	s.22	BC	
POWER UNIT	07259P	BC	10208509	2007 FREIGHTLIN		FAIL	40 4	
TRAILER 1	W32434	AB		2008 GREAT DANE		FAIL	41	
2013-05-14	07:54	1	6088267	0	SC33 BOW	s.22	BC	
POWER UNIT	10922P	BC		FRHT		FAIL	51	
SEMI TRAILER	999999	BC		GDAN		FAIL	41	
2013-05-13	11:50	3	6058924	0	S/B	s.22	BC	
TRUCK	P93187	BC	09874313	FRHT		PASS		
SEMI TRAILER	29219D	BC		UTIL		PASS		
2013-05-13	07:01	2	6073276	0	SC33 BOW	s.22	BC	
POWER UNIT	12403P	BC	03845693	FRHT		PASS		
SEMI TRAILER	12457D	BC		UTIL		FAIL	44	
2013-05-09	07:21	3	8162030	0	HUNTER CRE	s.22	BC	
POWER UNIT	07228P	BC	07238242	2007 KENWORTH		FAIL	40	
TRAILER 1	H6303H	ON		2011 WANA		PASS		
2013-05-08	23:50	1	6030095	0	SC33 BOW H	s.22	BC	
POWER UNIT	P97125	BC	02245144	INTL		FAIL	44 5	
SEMI TRAILER	88765C	BC		UTIL		FAIL	44	
2013-05-08	15:07	4	8161790	0	PARKSVILLE	s.22	BC	
POWER UNIT	P90970	BC	02815689	2005 STERLING		FAIL	44	
TRAILER 1	4HM927	AB		2013 VANGUARD		FAIL	44	
2013-05-08	12:41	2	6041978	0	SC38 STA	s.22	BC	
POWER UNIT	08642P	BC	01192322	KW		FAIL	41	
SEMI TRAILER	B45364	ME		HYTR		PASS		

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE VEH TYPE	TIME PLATE#	LEVEL JR	MICRO# VEH REG	NSC PTS VEHICLE DESC	LOCATION	DL# PASS/FAIL	DLJR INSPECTION ITEM	DRIVER NAME DEFECT(S)
2013-05-06 POWER UNIT TRAILER 1	10:50 P93187 84837C	1 BC BC	8160382 09874313 10042150	3 2010 FREIGHTLIN 2010 UTILITY	HUNTER CRE	s.22 PASS OOS	BC 47	s.22
2013-05-05 POWER UNIT SEMI TRAILER	09:58 P87523 34063D	1 BC BC	5989616 00950178	3 KW UTIL	SC33 BOW H	s.22 OOS FAIL FAIL	BC 47 44 4 44 4	
2013-05-04 POWER UNIT TRAILER 1	10:43 03459P 84843C	1 BC BC	8160010 00967378 10175467	0 2008 KENWORTH 2012 UTILITY	HUNTER CRE	s.22 PASS PASS	BC	
2013-05-04 POWER UNIT TRAILER 1	10:40 P93885 D5494J	3 BC ON	8160040 09845578	0 2007 FREIGHTLIN 2007 MANAC	KAMLOOPS	s.22 FAIL PASS	BC 55	
2013-05-03 POWER UNIT SEMI TRAILER	16:06 P93671 X41668	3 BC AB	6030383 04276109	0 KW GDAN	WHATCOM CO	s.22 PASS PASS	BC	
2013-05-02 POWER UNIT SEMI TRAILER	15:05 12991P 86241B	1 BC BC	5972069 03919308	0 KW UTIL	SC33 BOW	s.22 PASS PASS	BC	
2013-05-01 POWER UNIT SEMI TRAILER	20:15 08677P 12510D	3 BC BC	5989672	0 FRHT UTIL	SC38 STA	s.22 PASS PASS	BC	
2013-05-01 POWER UNIT SEMI TRAILER	11:19 P79528 88765C	3 BC BC	5948667 00025509	0 FRHT UTIL	STATE ROUT	s.22 PASS PASS	BC	
2013-05-01 POWER UNIT SEMI TRAILER	08:00 10929P 16179C	3 BC BC	5961670 10618844	0 INTL HYTR	SC72 RID	s.22 PASS PASS	WA	
2013-04-25 POWER UNIT SEMI TRAILER	12:05 09172P 84811C	2 BC BC	5898065 03589084	3 FRHT UTIL	SC33 BOW	s.22 OOS OOS	BC 44 47	
2013-04-24 POWER UNIT SEMI TRAILER	03:18 07233P W49594	3 BC AB	5873776 00327083	0 FRHT UTIL	SC33 BOW	s.22 ----- PASS PASS	BC	

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION ITEM	DEFECT(S)
2013-04-23	10:35	3	6011565	0	I5 MP164	s.22	BC	s.22
POWER UNIT	07259P	BC	10208509	FRHT		PASS		
SEMI TRAILER	4ER339	AB		VANR		PASS		
2013-04-21	11:24	2	5847225	0	SC33 BOW H	s.22	BC	
POWER UNIT	P93679	BC		VOLV		PASS		
SEMI TRAILER	20096D	BC		WANC		PASS		
2013-04-21	07:06	3	8155510	0	DELTA	s.22	BC	
POWER UNIT	01353P	BC	00597447	2007 FREIGHT		FAIL	41 !	
2013-04-19	14:25	2	5832581	0	SC33 BOW	s.22	BC	
POWER UNIT	08689P	BC	01632101	KW		FAIL	41	
SEMI TRAILER	X41671	AB		GDAN		PASS		
2013-04-18	13:54	3	5832480	0	SC33 BOW	s.22	BC	
POWER UNIT	09172P	BC		FRHT		PASS		
SEMI TRAILER	63036C	BC		UTIL		PASS		
2013-04-18	13:46	1	8154832	0	LAIDLAW	s.22	BC	
POWER UNIT	12119P	BC	09868148	2004 FREIGHTLIN		FAIL	44	
TRAILER 1	10417D	BC	10164538	2005 UTILITY		PASS		
2013-04-17	02:11	3	0698965	0	HINTON - V	s.22	BC	
POWER UNIT	01619P	BC	10619217	FREIGHTLIN		PASS		
SEMI TRAILER	29221D	BC		UTILITY		PASS		
2013-04-16	14:20	3	8153861	0	LAIDLAW	s.22	BC	
POWER UNIT	08689P	BC	01632101	2003 KENWORTH		FAIL	40	
2013-04-13	11:53	3	5779539	0	N/B	s.22	BC	
POWER UNIT	12130P	BC	10604227	FRHT		PASS		
SEMI TRAILER	V51498	AB		GDAN		PASS		
2013-04-13	10:33	3	5779536	0	N/B	s.22	BC	
POWER UNIT	P97126	BC	02172581	FRHT		PASS		
SEMI TRAILER	63036C	BC		UTIL		PASS		
2013-04-12	19:46	3	8152141	0	HUNTER CRE	s.22	BC	
POWER UNIT	01372P	BC	03733087	2006 FREIGHTLIN		FAIL	40	
TRAILER 1	10420D	BC	10449708	2012 UTILITY		PASS		
2013-04-12	15:56	1	8152060	0	GOLDEN	s.22	BC	
POWER UNIT	03488P	BC	00547686	2005 PETERBILT		FAIL	41 44 45	
TRAILER 1	84833C	BC	00864260	2008 UTILITY		FAIL	41 44	

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE VEH TYPE	TIME PLATE#	LEVEL JR	MICRO# VEH REG	NSC PTS VEHICLE DESC	LOCATION	DL# PASS/FAIL	DLJR INSPECTION ITEM	DRIVER NAME DEFECT(S)
2013-04-06 POWER UNIT SEMI TRAILER	07:20 10954P 33487D	2 BC BC	0698731 09973332	3 FREIGHTLIN UTILITY	BALZAC - V	s.22 FAIL OOS	AB 40 41 41 46	s.22
2013-04-03 POWER UNIT SEMI TRAILER	02:16 01353P 98788C	3 BC BC	5673849 00597447	0 FRHT UTIL	SC38 STA	s.22 PASS PASS	BC	
2013-04-02 POWER UNIT TRAILER 1	23:06 08689P 20097D	3 BC BC	8147060 01632101 10580990	0 2003 KENWORTH 2013 WABASH	SURREY	s.22 FAIL PASS	BC 40	
2013-04-02 POWER UNIT SEMI TRAILER	07:47 09172P V53561	3 BC BC	5661966 03589084	0 FRHT UNK	SC35 ANA	s.22 PASS PASS	BC	
2013-03-28 POWER UNIT	21:51 12976P	3 BC	8146065 03647208	0 2006 FREIGHTLIN	GOLDEN	s.22 PASS	BC	
2013-03-27 POWER UNIT	22:42 12407P	3 BC	8145323 10695252	0 2013 FREIGHTLIN	GOLDEN	s.22 PASS	BC	
2013-03-26 POWER UNIT SEMI TRAILER	13:26 07259P B44490	1 BC ME	5591107 10208509	3 FRHT HYTR	SC38 STA	s.22 OOS FAIL	BC 44 44	
2013-03-26 POWER UNIT SEMI TRAILER	07:54 11841P 84845C	2 BC BC	5590828	0 KW UTIL	SC33 BOW H	s.22 PASS PASS	BC	
2013-03-25 POWER UNIT TRAILER 1	10:07 P86209 86559C	2 BC BC	8144028 00239977 10234635	0 2000 KENWORTH 2012 UTILITY	ABBOTSFORD	s.22 FAIL PASS	BC 55	
2013-03-24 POWER UNIT TRAILER 1	08:29 01375P 98814C	3 BC BC	8143832 09861668 10338714	0 2007 VOLVO 2012 UTILITY	HUNTER CRE	s.22 FAIL PASS	BC 55	
2013-03-23 POWER UNIT TRAILER 1	08:28 10453P T66076	3 BC AB	8143700 00871139	0 2008 VOLVO 2012 GREAT DANE	HUNTER CRE	s.22 FAIL PASS	BC 55	
2013-03-21 POWER UNIT	18:33 09175P	3 BC	8143131 04502550	0 2005 FREIGHTLIN	LAIDLAW	s.22 PASS	BC	

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE VEH TYPE	TIME PLATE#	LEVEL JR	MICRO# VEH REG	NSC PTS VEHICLE DESC	LOCATION	DL# PASS/FAIL	DLJR INSPECTION ITEM	DRIVER NAME DEFECT(S)
2013-03-21 POWER UNIT	08:46 07233P	3 BC	8142640 00327083	0 2007 FREIGHTLIN	DELTA	s.22 FAIL	BC 40 5	s.22
2013-03-20 POWER UNIT TRAILER 1	20:23 12991P 84832C	3 BC BC	8142560 03919308 09760484	0 2007 KENWORTH 2007 UTILITY	SURREY	s.22 PASS PASS	BC	
2013-03-18 POWER UNIT SEMI TRAILER	23:56 08648P 4HM921	3 BC AB	5519581	0 PTRB UNK	SC38 STA	s.22 FAIL PASS	BC 40	
2013-03-15 POWER UNIT TRAILER 1	12:58 03999P 10416D	1 BC BC	8140753 02211029 01739012	3 2003 FREIGHTLIN 2005 UTILITY	HUNTER CRE	s.22 OOS OOS	BC 44 44	
2013-03-14 POWER UNIT SEMI TRAILER	21:50 10928P 84807C	3 BC BC	5495014 10618690	0 INTL UTIL	SC33 BOW	s.22 PASS PASS	BC	
2013-03-14 POWER UNIT SEMI TRAILER	17:09 08688P 22942D	3 BC BC	5495177 02777288	0 FRHT UTIL	SC38 STA	s.22 PASS PASS	BC	
2013-03-14 POWER UNIT SEMI TRAILER	16:12 10468P 84820C	2 BC BC	5495417 03773135	0 KW UTIL	SC38 STA	s.22 FAIL PASS	BC 41	
2013-03-12 POWER UNIT TRAILER 1	07:21 12998P 84824C	3 BC BC	8138960 00582523 03720173	0 2001 FREIGHTLIN 2007 UTILITY	HUNTER CRE	s.22 PASS PASS	BC	
2013-03-08 POWER UNIT SEMI TRAILER	16:13 00507P 71827C	3 BC BC	5448637 00719501	0 FRHT UTIL	SC38 STA	s.22 PASS PASS	BC	
2013-03-08 POWER UNIT SEMI TRAILER	07:55 04166P 20101D	2 BC BC	5448437 03622451	0 PTRB WANC	SC33 BOW	s.22 PASS PASS	BC	
2013-03-07 POWER UNIT TRAILER 1	20:05 13000P 98781C	2 BC BC	8137690 02439273 01656900	3 2008 FREIGHTLIN 2008 UTILITY	LAIDLAW	s.22 PASS OOS	BC 41	
2013-03-05 POWER UNIT SEMI TRAILER	21:48 03999P 22902D	2 BC BC	5398444 02211029	0 FRHT VANR	SC33 BOW H	s.22 FAIL PASS	BC 44	

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE VEH TYPE	TIME PLATE#	LEVEL JR	MICRO# VEH REG	NSC PTS VEHICLE DESC	LOCATION	DL# PASS/FAIL	DLJR INSPECTION ITEM	DRIVER NAME DEFECT(S)
2013-03-05 POWER UNIT SEMI TRAILER	06:56 12403P 77841C	2 BC BC	5398441 03845693	3 FRHT UTIL	SC33 BOW H	s.22 PASS OOS	BC 47	s.22
2013-03-01 POWER UNIT SEMI TRAILER	11:30 08677P 05262D	2 BC BC	5378471 10070282	0 FRHT UTIL	SC33 BOW	s.22 PASS PASS	BC	
2013-02-28 POWER UNIT TRAILER 1	12:52 10453P 4DY976	3 BC AB	8135092 00871139	0 2008 VOLVO 2012 VANGUARD	DELTA	s.22 FAIL PASS	BC 40 5	
2013-02-27 POWER UNIT TRAILER 1	14:56 04166P 84835C	1 BC BC	8134791 03622451 10149384	0 2007 PETERBILT 2008 UTILITY	SURREY	s.22 FAIL FAIL	BC 44 44 4	
2013-02-27 POWER UNIT SEMI TRAILER SEMI TRAILER ELECTRICITY	14:40 12412P S22473 T66855 99999	1 BC AB AB BC	0696604	0 FRHT UTIL UTIL	BALZAC VIS	s.22 FAIL FAIL PASS PASS	AB 41 44	
2013-02-26 POWER UNIT SEMI TRAILER	11:06 P79528 40627B	3 BC BC	5422766 00025509	0 FRHT GDAN	SC38 STA	s.22 PASS PASS	BC	
2013-02-26 POWER UNIT TRAILER 1	08:21 03459P 4ER328	3 BC AB	8133854 00967378	0 2008 KENWORTH 2012 VANGAURD	HUNTER CRE	s.22 PASS PASS	BC	
2013-02-22 POWER UNIT SEMI TRAILER	05:37 10928P 86657C	3 BC BC	5296454 10618690	0 INTL UTIL	SC33 BOW H	s.22 PASS PASS	BC	
2013-02-14 POWER UNIT SEMI TRAILER	12:59 12403P 16121C	3 BC BC	5351602 03845693	0 FRHT GDAN	SC38 STA	s.22 PASS PASS	BC	
2013-02-13 POWER UNIT TRAILER 1	19:02 05727P 18729B	3 BC BC	8129560 01896963 00327002	0 2004 VOLVO 2000 WABASH	SURREY	s.22 FAIL PASS	BC 55	
2013-02-13 POWER UNIT SEMI TRAILER	16:25 12130P 98779C	3 BC BC	5229266 10604227	0 FRHT UTIL	SC33 BOW	s.22 PASS PASS	BC	

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE VEH TYPE	TIME PLATE#	LEVEL JR	MICRO# VEH REG	NSC PTS VEHICLE DESC	LOCATION	DL# PASS/FAIL	DLJR INSPECTION ITEM	DRIVER NAME DEFECT(S)
2013-02-13 POWER UNIT TRAILER 1	11:25 08689P 29219D	3 BC BC	8129199 01632101 02210468	0 2003 KENWORTH 2008 UTILITY	HUNTER CRE	s.22 FAIL PASS	BC 40	s.22
2013-02-12 POWER UNIT TRAILER 1	12:00 10922P 84835C	3 BC BC	8128998 03707629 10149384	0 2007 FREIGHTLIN 2008 UTILITY	HUNTER CRE	s.22 FAIL PASS	BC 40	
2013-02-12 POWER UNIT TRAILER 1	09:25 09174P 86656C	3 BC BC	8128924 09582853 10195074	0 2010 PETERBILT 2012 UTILITY	ABBOTSFORD	s.22 PASS PASS	BC	
2013-02-11 POWER UNIT SEMI TRAILER	10:30 10468P 84824C	3 BC BC	5204794 03773135	0 KW UTIL	NB	s.22 FAIL PASS	BC 40	
2013-02-11 POWER UNIT SEMI TRAILER	09:15 07250P 08864D	2 BC BC	5192044 02172601	0 FRHT UTIL	SC33 BOW	s.22 PASS FAIL	BC 47	
2013-02-08 POWER UNIT TRAILER 1	16:58 08677P 98782C	2 BC BC	8128361 10070282 01656713	0 2006 FREIGHTLIN 2008 UTILITY	HUNTER CRE	s.22 PASS PASS	BC	
2013-02-07 POWER UNIT TRAILER 1	17:11 03999P 84806C	3 BC BC	8127930 02211029 02503028	0 2003 FREIGHTLIN 2005 UTILITY	HUNTER CRE	s.22 PASS PASS	BC	
2013-02-04 POWER UNIT TRAILER 1	15:02 P93885 84827C	1 BC BC	8126420 09845578 03773812	0 2007 FREIGHTLIN 2007 UTILITY	LAIDLAW	s.22 FAIL FAIL	BC 48 44	
2013-02-01 POWER UNIT	13:36 09161P	2 BC	8125602 03847220	0 2007 KENWORTH	SURREY	s.22 FAIL	BC 41	
2013-01-31 POWER UNIT TRAILER 1	07:59 04166P 84821C	3 BC BC	8124940 03622451 03254103	0 2007 PETERBILT 2006 UTILITY	HUNTER CRE	s.22 PASS PASS	BC	
2013-01-27 POWER UNIT TRAILER 1	13:50 10937P 29213D	1 BC BC	8123933 03458597 01957154	3 2006 FREIGHTLIN 2008 GREAT DANE	LAIDLAW	s.22 FAIL OOS	BC 42 41	
2013-01-26 POWER UNIT SEMI TRAILER	00:20 07259P 23100Y	2 BC BC	5045981 10208509	0 FRHT GDAN	SC33 BOW H	s.22 PASS PASS	BC	

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE VEH TYPE	TIME PLATE#	LEVEL JR	MICRO# VEH REG	NSC PTS VEHICLE DESC	LOCATION	DL# PASS/FAIL	DLJR INSPECTION ITEM	DRIVER NAME DEFECT(S)
2013-01-25 POWER UNIT TRAILER 1	07:43 12386P 05246D	3 BC BC	8123584 10104464 10383711	0 2011 VOLVO 2012 UTILITY	HUNTER CRE	s.22 FAIL PASS	BC 40	s.22
2013-01-25 POWER UNIT TRAILER 1	07:14 P79528 80442C	3 BC BC	8123581 00025509 10186436	0 2000 FREIGHTLIN 2012 UTILITY	HUNTER CRE	s.22 FAIL PASS	BC 40	
2013-01-24 POWER UNIT TRAILER 1	11:23 12117P T89203	2 BC TN	8123490 10350135	3 2012 VOLVO 2003 HYUNDAI	KALEDEN	s.22 PASS OOS	BC 47	
2013-01-24 POWER UNIT	09:28 12123P	3 BC	8123220 04180780	0 2009 FREIGHTLIN	DELTA	s.22 PASS	BC	
2013-01-23 POWER UNIT TRAILER 1	21:04 12116P 86659C	2 BC BC	8123120 10346220 10195118	3 2012 VOLVO 2012 UTILITY	GOLDEN	s.22 FAIL OOS	BC 40 41	
2013-01-23 POWER UNIT TRAILER 1	12:24 08649P 98786C	3 BC BC	8122885 02485930 01963539	0 2005 PETERBILT 2008 UTILITY	LAIDLAW	s.22 FAIL PASS	AB 40	
2013-01-22 POWER UNIT SEMI TRAILER	17:40 12403P 55523B	2 BC BC	5003328 03845693	0 FRHT GDAN	SC07 FT	s.22 PASS PASS	BC	
2013-01-21 POWER UNIT TRAILER 1	14:15 07267P T66076	3 BC AB	8122081 02227341	0 2005 KENWORTH 2012 GREAT D	LAIDLAW	s.22 FAIL PASS	BC 40 !	
2013-01-21 POWER UNIT TRAILER 1	14:06 10937P 86618C	3 BC BC	8122072 03458597 10208038	0 2006 FREIGHTLIN 2012 UTILITY	LAIDLAW	s.22 PASS PASS	BC	
2013-01-21 POWER UNIT TRAILER 1	08:17 09165P 4HM830	3 BC AB	8121902 03526127	0 2006 FREIGHTLIN 2013 VANGUARD	HUNTER CRE	s.22 PASS PASS	BC	
2013-01-18 POWER UNIT SEMI TRAILER	10:00 12118P 10471D	1 BC BC	0691565	0 FRHT UTILITY	JUMPING PO	s.22 FAIL PASS	BC 44	
2013-01-17 POWER UNIT TRAILER 1	08:27 12116P 29212D	3 BC BC	8121050 10346220 01862844	0 2012 VOLVO 2008 GREAT DANE	HUNTER CRE	s.22 PASS PASS	BC	

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION	ITEM DEFECT(S)
2013-01-17	04:24	1	4970576	0	DUNSMUIR G	s.22	BC	s.22
POWER UNIT	12130P	BC	10604227	FRHT		PASS		
SEMI TRAILER	V30472	AB		VANR		PASS		
2013-01-16	07:43	3	8120482	0	HUNTER CRE	s.22	BC	
POWER UNIT	07267P	BC	02227341	2005 KENWORTH		FAIL	40	
TRAILER 1	84824C	BC	03720173	2007 UTILITY		PASS		
2013-01-14	18:55	3	8119941	0	HUNTER CRE	s.22	BC	
POWER UNIT	10948P	BC	09649734	2009 VOLVO		PASS		
TRAILER 1	84817C	BC	03050962	2006 UTILITY		PASS		
2013-01-13	11:17	3	8119645	0	LANGLEY	s.22	BC	
POWER UNIT	09161P	BC	03847220	2007 KENWORTH		PASS		
TRAILER 1	V33356	AB		2012 GREAT DANE		PASS		
2013-01-11	05:11	1	4905219	0	SC33 BOW	s.22	BC	
POWER UNIT	10910P	BC		FRHT		FAIL	40	
SEMI TRAILER	W32405	AB		GDAN		PASS		
2013-01-10	11:08	3	4905779	0	N/B	s.22	BC	
POWER UNIT	11841P	BC	00343911	KW		PASS		
SEMI TRAILER	29216D	BC		UTIL		PASS		
2013-01-09	12:34	2	4905401	0	SC33 BOW H	s.22	BC	
POWER UNIT	10910P	BC	10564421	FRHT		PASS		
SEMI TRAILER	05245D	BC		UTIL		PASS		
2013-01-09	06:00	3	4988434	0	15TH NW &	s.22	BC	
POWER UNIT	08688P	BC	02777288	FRHT		PASS		
SEMI TRAILER	55520B	BC		GDAN		PASS		
2013-01-07	21:04	3	8118330	0	HUNTER CRE	s.22	BC	
POWER UNIT	10477P	BC	02190954	2008 KENWORTH		PASS		
TRAILER 1	84833C	BC	00864260	2008 UTILITY		PASS		
2013-01-07	18:40	2	4937162	0	CLACKAMAS	s.22	BC	
POWER UNIT	04166P	BC	03622451	PTRB		PASS		
SEMI TRAILER	W32487	BC		UTIL		PASS		
2013-01-07	11:50	3	4905837	0	INTERSTATE	s.22	BC	
POWER UNIT	08690P	BC	00356628	KW		FAIL	40	
SEMI TRAILER	05266D	BC		UTIL		PASS		

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION	ITEM DEFECT(S)
2013-01-07	11:10	3	8118141	0	HUNTER CRE	s.22	BC	s.22
POWER UNIT	12388P	BC	10022141	2010 VOLVO		PASS		
TRAILER 1	84854C	BC	02450053	2005 UTILITY		PASS		
2013-01-06	18:49	2	8118064	3	KAMLOOPS	s.22	BC	
POWER UNIT	10453P	BC	00871139	2008 VOLVO		PASS		
TRAILER 1	55521B	BC	01518770	2004 GREAT DANE		OOS	41	
2013-01-06	14:22	3	8118038	0	HUNTER CRE	s.22	BC	
POWER UNIT	01619P	BC	10619217	2013 FREIGHTLIN		PASS		
TRAILER 1	S41852	AB		2012 GDANE		PASS		
2013-01-06	11:19	3	8118010	0	HUNTER CRE	s.22	AB	
POWER UNIT	12389P	BC	10109897	2011 VOLVO		FAIL	40	
TRAILER 1	84824C	BC	03720173	2007 UTILITY		PASS		
2013-01-03	08:47	3	8117450	0	LIDLAW	s.22	AB	
POWER UNIT	07228P	BC	07238242	2007 KENWORTH		FAIL	41	
2012-12-22	08:55	3	4761631	0	SC33 BOW H	s.22	BC	
POWER UNIT	08688P	BC	02777288	FRHT		PASS		
SEMI TRAILER	V05310	TN		TRLR		PASS		
2012-12-21	10:52	3	4855284	0	SR	s.22	BC	
POWER UNIT	01353P	BC	00597447	FRHT		PASS		
SEMI TRAILER	4ER332	AB		VANA		PASS		
2012-12-20	12:46	3	4762049	0	SC38 STA	s.22	BC	
POWER UNIT	05748P	BC		FRHT		PASS		
SEMI TRAILER	84854C	BC		UTIL		PASS		
2012-12-19	10:05	1	4745014	0	SC33 BOW	s.22	BC	
POWER UNIT	08642P	BC	01192322	KENS		PASS		
SEMI TRAILER	05223D	BC		UTIL		PASS		
2012-12-18	08:38	2	4733883	3	SC33 BOW H	s.22	BC	
POWER UNIT	00507P	BC	00719501	FRHT		OOS	47	
SEMI TRAILER	S41852	AB		GDAN		PASS		
2012-12-15	11:59	3	8115547	0	LIDLAW	s.22	BC	
POWER UNIT	07261P	BC	03267342	2006 PETERBILT		PASS		
2012-12-14	12:30	2	4704551	0	SC38 STA	s.22	BC	
POWER UNIT	00507P	BC	00719501	FRHT		PASS		
SEMI TRAILER	63042C	BC		UTIL		PASS		

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE VEH TYPE	TIME PLATE#	LEVEL JR	MICRO# VEH REG	NSC PTS VEHICLE DESC	LOCATION	DL# PASS/FAIL	DLJR INSPECTION ITEM	DRIVER NAME DEFECT(S)
2012-12-14 POWER UNIT TRAILER 1	07:55 09174P 84819C	3 BC BC	8115479 09582853 03251800	0 2010 PETERBILT 2006 UTILITY	HUNTER CRE	s.22 PASS PASS	BC	s.22
2012-12-12 POWER UNIT TRAILER 1	07:39 12125P 12456D	3 BC BC	8115273 10505157 02778723	0 2010 FREIGHTLIN 2005 UTILITY	HUNTER CRE	s.22 PASS PASS	BC	
2012-12-11 POWER UNIT SEMI TRAILER	16:58 09174P 16121C	2 BC BC	4660845 09582853	3 PTRB GDAN	SC38 STA	s.22 PASS OOS	BC	44
2012-12-11 POWER UNIT TRAILER 1	12:12 09180P 27161D	3 BC BC	8115204 10572840 00211494	0 2013 FREIGHTLIN 2007 UTILITY	HUNTER CRE	s.22 PASS PASS	BC	
2012-12-05 POWER UNIT TRAILER 1	12:51 09175P V53561	3 BC AB	8114694 04502550	0 2005 FREIGHTLIN 2012 VANGUARD	HAIG	s.22 PASS PASS	BC	
2012-12-05 POWER UNIT TRAILER 1	09:49 07261P 4ER328	3 BC AB	8114592 03267342	0 2006 PETERBILT 2012 VANGUARD	HAIG	s.22 FAIL PASS	BC	40
2012-12-05 POWER UNIT TRAILER 1	08:55 P97124 84806C	3 BC BC	8114575 02252296 02503028	0 2005 INTERNATNA 2005 UTILITY	SURREY	s.22 PASS PASS	BC	
2012-12-05 POWER UNIT SEMI TRAILER	07:20 10930P 05535D	2 BC BC	0680492 10163691	3 VOLVO UTL	BALZAC - V	s.22 PASS OOS	BC	46
2012-12-04 POWER UNIT TRAILER 1	10:31 P98961 07187C	1 BC BC	8114459 03506574 01660398	0 2006 FREIGHTLIN 2004 UTILITY	KAMLOOPS	s.22 FAIL FAIL	BC	44 44 5
2012-12-04 POWER UNIT TRAILER 1	10:21 12120P 4FE794	3 BC AB	8114449 10287216	0 2007 FREIGHTLIN 2012 VANGUARD	LIDLAW	s.22 FAIL PASS	BC	40
2012-12-02 POWER UNIT SEMI TRAILER	07:56 10946P SZ2258	3 BC MB	4569660 10097522	0 VOLV HYTR	SC33 BOW H	s.22 PASS PASS	BC	

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION	ITEM DEFECT(S)
2012-11-30	14:20	3	4570152	0	SC38 STA	s.22	BC	s.22
TRUCK	09172P	BC	03589084	FRHT		PASS		
SEMI TRAILER	63036C	BC		UTIL		PASS		
2012-11-29	13:30	3	4554864	0	SR	s.22	BC	
POWER UNIT	P86209	BC	00239977	KW		PASS		
SEMI TRAILER	63042C	BC		UTIL		PASS		
2012-11-29	04:27	3	4569897	0	SC33 BOW H	s.22	BC	
POWER UNIT	08688P	BC	02777288	FRHT		PASS		
SEMI TRAILER	55521B	BC		GDAN		PASS		
2012-11-28	17:51	3	4538937	0	SC33 BOW H	s.22	BC	
POWER UNIT	08689P	BC	01632101	KW		PASS		
SEMI TRAILER	88765C	BC		UTIL		PASS		
2012-11-28	12:49	3	4557285	0	COTTONWOOD	s.22	BC	
POWER UNIT	P86209	BC	00239977	KW		PASS		
SEMI TRAILER	63042C	BC		UTIL		PASS		
2012-11-27	15:14	1	8113970	0	LIDLAW	s.22	BC	
POWER UNIT	10907P	BC	03025705	2008 FREIGHTLIN		FAIL	40	!
TRAILER 1	07012D	BC	02503098	2005 UTILITY		PASS		
2012-11-27	08:40	2	4538820	3	SC33 BOW	s.22	BC	
POWER UNIT	09165P	BC	03526127	FRHT		PASS		
SEMI TRAILER	84853C	BC		UTIL		OOS	41	
2012-11-27	08:21	2	4539551	0	LONGVIEW	s.22	WA	
POWER UNIT	10484P	BC	03700736	PTRB		PASS		
SEMI TRAILER	02965D	BC		GDAN		PASS		
2012-11-27	06:25	2	4538766	3	SC33 BOW	s.22	BC	
POWER UNIT	P79528	BC	00025509	FRHT		PASS		
SEMI TRAILER	84813C	BC		UTIL		OOS	47	
2012-11-26	11:46	1	8113869	3	SURREY	s.22	BC	
POWER UNIT	07259P	BC	10208509	2007 FREIGHTLIN		OOS	44	
TRAILER 1	90144B	BC	01862766	2008 GREAT DANE		FAIL	40	4
						PASS		
2012-11-25	12:52	1	8113804	3	LIDLAW	s.22	AB	
POWER UNIT	08649P	BC	02485930	2005 PETERBILT		OOS	45	
TRAILER 1	84812C	BC	02898424	2005 UTILITY		FAIL	40	4
						OOS	45	
						FAIL	44	51

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION ITEM	DEFECT(S)
2012-11-23	14:46	3	4498527	0	SC33 BOW	s.22	BC	s.22
POWER UNIT	10910P	BC	10564421	FRHT		PASS		
SEMI TRAILER	06541B	BC		UTIL		PASS		
2012-11-20	13:16	3	4498885	0	NB	s.22	BC	
POWER UNIT	01353P	BC	00597447	FRHT		PASS		
SEMI TRAILER	22901D	BC		VANA		PASS		
2012-11-20	10:25	3	4498894	0	PRAIRIE RD	s.22	BC	
POWER UNIT	P89317	BC	01846874	PTRB		PASS		
SEMI TRAILER	22942D	BC		UTIL		PASS		
2012-11-20	09:55	3	4498893	0	UPPER SAMI	s.22	BC	
POWER UNIT	P86209	BC	00239977	KW		PASS		
SEMI TRAILER	80443C	BC		UTIL		PASS		
2012-11-20	07:34	1	4467678	3	SC33 BOW	s.22	BC	
POWER UNIT	07228P	BC	07238242	KW		PASS		
SEMI TRAILER	X41671	AB		GDAN		OOS	47	
						FAIL	41	
2012-11-19	09:45	3	4498787	0	SC38 STA	s.22	BC	
POWER UNIT	P87523	BC	00950178	KW		FAIL	40	
SEMI TRAILER	86240B	BC		UTIL		PASS		
2012-11-16	13:16	1	8113115	0	KAMLOOPS	s.22	BC	
POWER UNIT	08638P	BC	08618565	2007 PETERBILT		FAIL	41 44	
TRAILER 1	16178C	BC	03082453	2009 HYUNDAI		FAIL	44	
2012-11-16	05:15	3	4452349	0	SC33 BOW	s.22	BC	
POWER UNIT	P86209	BC	00239977	KW		PASS		
SEMI TRAILER	63038C	BC		UTIL		PASS		
2012-11-15	13:40	2	4438801	3	SC33 BOW H	s.22	BC	
POWER UNIT	01353P	BC	00597447	FRHT		OOS	47	
SEMI TRAILER	4EY678	AB		UNK		PASS		
2012-11-15	08:44	3	8112862	0	HUNTER CRE	s.22	BC	
POWER UNIT	10468P	BC	03773135	2007 KENWORTH		PASS		
TRAILER 1	10416D	BC	01739012	2005 UTILITY		PASS		
2012-11-09	14:14	2	4396808	3	SC33 BOW	s.22	BC	
POWER UNIT	10908P	BC	03566648	FRHT		FAIL	41	
SEMI TRAILER	84819C	BC		UTIL		OOS	41	

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION	ITEM DEFECT(S)
2012-11-07	11:33	3	4349538	0	SB HWY 9	s.22	BC	s.22
POWER UNIT	07263P	BC	03565565	FRHT		PASS		
SEMI TRAILER	03188Y	BC		MILY		PASS		
2012-10-30	10:16	1	8110946	0	SURREY	s.22	BC	
POWER UNIT	03999P	BC	02211029	2003 FREIGHTLIN		FAIL	40	
TRAILER 1	16123C	BC	02531026	2005 GREAT DANE		FAIL	41 4	
2012-10-29	10:27	2	4262447	3	SC33 BOW	s.22	BC	
POWER UNIT	10928P	BC	10618690	INTL		PASS		
SEMI TRAILER	90142B	BC		GDAN		OOS	41	
2012-10-26	14:20	3	4272220	0	SC38 STA	s.22	BC	
POWER UNIT	08642P	BC	01192322	KW		PASS		
SEMI TRAILER	20061D	BC		UTIL		PASS		
2012-10-26	10:39	3	4248145	0	SC53 CLE	s.22	BC	
POWER UNIT	10484P	BC	03700736	PTRB		PASS		
SEMI TRAILER	98780C	BC		UTIL		PASS		
2012-10-25	15:33	3	4234910	0	SC33 BOW	s.22	BC	
POWER UNIT	10910P	BC	10564421	FRHT		PASS		
SEMI TRAILER	4ER333	AB		VANR		PASS		
2012-10-24	13:44	3	4234722	0	DEMING	s.22	BC	
POWER UNIT	03459P	BC	00967378	KW		PASS		
SEMI TRAILER	84838C	BC		UTIL		PASS		
2012-10-24	13:30	2	4263022	0	I	s.22	BC	
POWER UNIT	10910P	BC	10564421	FRHT		FAIL	40 4	
SEMI TRAILER	22900D	BC		VANA		PASS		
2012-10-24	11:34	3	8110352	0	HUNTER CRE	s.22	BC	
POWER UNIT	10910P	BC	10564421	2007 FREIGHTLIN		FAIL	40	
TRAILER 1	22900D	BC	10590974	2013 VANGUARD		PASS		
2012-10-22	18:30	3	4262453	0	SC07 FT	s.22	BC	
POWER UNIT	10468P	BC		KW		PASS		
SEMI TRAILER	4CK965	BC		VANA		PASS		
2012-10-22	12:07	1	4248036	0	SC33 BOW	s.22	BC	
POWER UNIT	03461P	BC	03919308	KW		PASS		
SEMI TRAILER	63033C	BC		UTIL		FAIL	44 45	

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION	ITEM DEFECT(S)
2012-10-21	12:14	1	8110022	0	KAMLOOPS	s.22	BC	s.22
POWER UNIT	10930P	BC	10163691	2011 VOLVO		FAIL	55	
TRAILER 1	80441C	BC	10186432	2012 UTILITY		FAIL	44	
2012-10-18	14:18	3	4172920	0	STANWOOD,	s.22	BC	
POWER UNIT	10908P	BC	03566648	FRHT		PASS		
SEMI TRAILER	80439C	BC		UTIL		PASS		
2012-10-18	13:55	3	8109781	0	ABBOTSFORD	s.22	BC	
POWER UNIT	P89317	BC	01846874	2004 PETERBILT		FAIL	40	
TRAILER 1	86659C	BC	10195118	2012 UTILITY		PASS		
2012-10-18	09:38	3	4218595	0	I	s.22	BC	
POWER UNIT	04756P	BC	03876943	KW		PASS		
SEMI TRAILER	16176C	BC		HYTR		PASS		
2012-10-18	09:18	3	4172927	0	SC33 BOW	s.22	BC	
POWER UNIT	07233P	BC	00327083	FRHT		PASS		
SEMI TRAILER	4GU993	AB		FRUE		PASS		
2012-10-17	14:50	3	8109576	0	GOLDEN	s.22	BC	
POWER UNIT	08648P	BC	10013446	2007 PETERBILT		PASS		
2012-10-17	13:50	3	4152780	0	N/B	s.22	BC	
POWER UNIT	P86209	BC	00239977	KW		PASS		
SEMI TRAILER	X41668	AB		GDAN		PASS		
2012-10-17	12:24	3	8109544	0	HUNTER CRE	s.22	BC	
POWER UNIT	04810P	BC	04937980	1998 PETERBILT		FAIL	40	
TRAILER 1	X41669	AB		2008 G DANE		PASS		
2012-10-17	09:47	3	4164178	0	SC33 BOW H	s.22	BC	
POWER UNIT	00507P	BC	00719501	FRHT		PASS		
SEMI TRAILER	86241B	BC		UTIL		PASS		
2012-10-16	17:53	2	4152824	0	SC38 STA	s.22	BC	
POWER UNIT	00507P	BC	00719501	FRHT		PASS		
SEMI TRAILER	86241B	BC		UTIL		PASS		
2012-10-16	15:33	3	4164600	0	I	s.22	BC	
POWER UNIT	09172P	BC	03589084	FRHT		PASS		
SEMI TRAILER	07005D	BC		UTIL		PASS		
2012-10-16	11:50	3	4164606	0	SC33 BOW H	s.22	BC	
POWER UNIT	10910P	BC	10564421	FRHT		PASS		
SEMI TRAILER	4CK965	BC		VANR		PASS		

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE VEH TYPE	TIME PLATE#	LEVEL JR	MICRO# VEH REG	NSC PTS VEHICLE DESC	LOCATION	DL# PASS/FAIL	DLJR INSPECTION ITEM	DRIVER NAME DEFECT(S)
2012-10-16 POWER UNIT TRAILER 1	10:04 03459P 12460D	3 BC BC	8109593 00967378 02734856	3 2008 KENWORTH 2005 UTILITY	ABBOTSFORD	s.22 PASS OOS	BC 52	s.22
2012-10-11 POWER UNIT TRAILER 1	13:47 10484P 10417D	3 BC BC	8109008 03700736 10164538	0 2009 PETERBILT 2005 UTILITY	HUNTER CRE	s.22 PASS PASS	BC	
2012-10-10 POWER UNIT TRAILER 1	10:39 01375P 23100Y	3 BC BC	8108811 09861668 01421888	0 2007 VOLVO 2004 GREAT DANE	LAIDLAW	s.22 PASS PASS	BC	
2012-10-09 POWER UNIT TRAILER 1	22:07 P97124 S41918	2 BC AB	8108774 02252296	0 2005 INTERNATNA 2011 GREAT DANE	SURREY	s.22 FAIL FAIL	BC 40 55	
2012-10-09 POWER UNIT SEMI TRAILER	12:51 00507P 86590C	3 BC BC	4060659 00719501	0 FRHT UTIL	SC38 STA	s.22 PASS PASS	BC	
2012-10-09 POWER UNIT SEMI TRAILER	09:10 P89317 10425D	3 BC BC	4218583 01846874	0 PTRB UTIL	SC38 STA	s.22 PASS PASS	BC	
2012-10-08 POWER UNIT SEMI TRAILER	06:20 10484P 63035C	1 BC BC	4046435 03700736	3 PETR UTIL	SC33 BOW H	s.22 OOS PASS	BC 47	
2012-10-04 POWER UNIT SEMI TRAILER	08:07 P87523 S41918	1 BC AB	4026190 00950178	0 KW GDAN	EB SR 101	s.22 FAIL PASS	BC 51	
2012-10-03 POWER UNIT TRAILER 1	12:17 08642P 84821C	1 BC BC	8108321 01192322 03254103	3 2003 KENWORTH 2006 UTILITY	HUNTER CRE	s.22 FAIL OOS FAIL	BC 40 4 47 44	
2012-10-03 POWER UNIT SEMI TRAILER	05:15 07259P 84836C	3 BC BC	4189824 10208509	0 FRHT UTIL	SR9 MP95	s.22 PASS PASS	BC	
2012-09-27 POWER UNIT TRAILER 1	09:18 09172P 12456D	3 BC BC	8107626 03589084 02778723	0 2006 FREIGHTLIN 2005 UTILITY	LAIDLAW	s.22 PASS PASS	BC	

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE VEH TYPE	TIME PLATE#	LEVEL JR	MICRO# VEH REG	NSC PTS VEHICLE DESC	LOCATION	DL# PASS/FAIL	DLJR INSPECTION ITEM	DRIVER NAME DEFECT(S)
2012-09-25 POWER UNIT	18:26 P93885	1 BC	8107453 09845578	3 2007 FREIGHTLIN	KAMLOOPS	s.22 OOS	BC 44	s.22
TRAILER 1	98786C	BC	01963539	2008 UTILITY		FAIL FAIL	41 5 44 5	
2012-09-25 POWER UNIT	13:27 10950P	1 BC	8107429 10603519	3 2013 FREIGHTLIN	LAIDLAW	s.22 FAIL	BC 40	
TRAILER 1	86613C	BC	10208028	2012 UTILITY		OOS	46	
2012-09-24 POWER UNIT	14:07 05727P	1 BC	8107254 01896963	0 2004 VOLVO	SURREY	s.22 PASS	BC	
TRAILER 1	55523B	BC	02596157	2005 GREAT DANE		FAIL	55	
2012-09-23 POWER UNIT	15:12 P30970	1 BC	8107159 02134044	3 2004 FREIGHTLIN	LAIDLAW	s.22 FAIL	BC 44	
TRAILER 1	16123C	BC	02531026	2005 GREAT DANE		OOS FAIL	46 51	
2012-09-21 POWER UNIT	15:27 08690P	3 BC	3911127 00356628	0 KW	SC38 STA	s.22 PASS	BC	
SEMI TRAILER	B41418	ME		HYTR		PASS		
2012-09-21 POWER UNIT	05:15 09181P	2 BC	3896052	0 VOLV	SC33 BOW	s.22 FAIL	BC 41	
SEMI TRAILER	80443C	BC		UTIL		PASS		
2012-09-19 POWER UNIT	15:15 10908P	3 BC	3896048 03566648	0 FRHT	SC33 BOW	s.22 PASS	BC	
SEMI TRAILER	55524B	BC		GDAN		PASS		
2012-09-18 POWER UNIT	13:07 08695P	1 BC	8106633 00042508	0 2007 FREIGHTLIN	GOLDEN	s.22 FAIL	BC 44	
TRAILER 1	86614C	BC	10208076	2012 UTILITY		FAIL	47	
2012-09-17 POWER UNIT	20:20 03999P	2 BC	3851797 02211029	3 FRHT	SC33 BOW	s.22 OOS	BC 47	
SEMI TRAILER	98814C	BC		UTIL		PASS		
2012-09-17 POWER UNIT	12:15 05748P	3 BC	3933567 00582523	0 FRHT	SC38 STA	s.22 PASS	BC	
SEMI TRAILER	98778C	BC		UTIL		PASS		
2012-09-14 POWER UNIT	06:47 01353P	1 BC	3839271 00597447	0 FRHT	SC33 BOW	s.22 PASS	BC	
SEMI TRAILER	90145B	BC		GDAN		PASS		

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION	ITEM DEFECT(S)
2012-09-11	20:39	1	3793834	0	SC33 BOW	s.22	BC	s.22
POWER UNIT	P97125	BC	02245144	INTL		PASS		
SEMI TRAILER	55522B	BC		GDAN		PASS		
2012-09-11	08:00	1	3777694	0	SC39 EVE	s.22	BC	
POWER UNIT	09165P	BC	03526127	FRHT		PASS		
SEMI TRAILER	84845C	BC		UTIL		PASS		
2012-09-06	21:07	3	8105270	0	HUNTER CRE	s.22	BC	
POWER UNIT	10453P	BC	00871139	2008 VOLVO		PASS		
TRAILER 1	4DY975	AB		2012 VANGUARD		FAIL	55	
2012-09-05	07:36	3	3715355	0	S/B	s.22	BC	
POWER UNIT	08642P	BC		KW		PASS		
SEMI TRAILER	999999	BC		UTIL		PASS		
2012-08-31	12:26	1	8104829	0	NORTH DELT	s.22	BC	
POWER UNIT	P84508	BC	00190625	2002 VOLVO		FAIL	50 55	
TRAILER 1	1329JP	OK		2008 STOU		FAIL	50	
2012-08-31	10:19	3	8104790	0	ABBOTSFORD	s.22	BC	
POWER UNIT	08690P	BC	00356628	2003 KENWORTH		PASS		
TRAILER 1	84807C	BC	02449936	2005 UTILITY		PASS		
2012-08-31	06:20	3	8104765	0	HUNTER CRE	s.22	BC	
POWER UNIT	09165P	BC	03526127	2006 FREIGHTLIN		PASS		
TRAILER 1	93514B	BC	02210544	2008 UTILITY		FAIL	55	
2012-08-23	07:06	3	3618167	0	SC33 BOW	s.22	BC	
POWER UNIT	00507P	BC	00719501	FRHT		PASS		
2012-08-15	18:36	2	3530857	3	SC33 BOW	s.22	BC	
POWER UNIT	01353P	BC	00597447	FRHT		PASS		
SEMI TRAILER	83086C	BC		UTIL		OOS	41	
2012-08-15	09:52	1	8103336	0	GOLDEN	s.22	BC	
POWER UNIT	10453P	BC	00871139	2008 VOLVO		FAIL	40 41	
TRAILER 1	X68559	AB		2009 GREAT DANE		PASS		
2012-08-13	19:07	3	8103159	0	LAIDLAW	s.22	BC	
POWER UNIT	03488P	BC	00547686	2005 PETERBILT		PASS		
TRAILER 1	16123C	BC	02531026	2005 GREAT DANE		PASS		
2012-08-13	12:19	1	8103134	0	KNUTSFORD	s.22	BC	
POWER UNIT	09175P	BC	04502550	2005 FREIGHTLIN		FAIL	41 46	
TRAILER 1	4FX431	AB		2013 UTILITY		PASS		

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE VEH TYPE	TIME PLATE#	LEVEL JR	MICRO# VEH REG	NSC PTS VEHICLE DESC	LOCATION	DL# PASS/FAIL	DLJR INSPECTION ITEM	DRIVER NAME DEFECT(S)
2012-08-01 POWER UNIT	13:34 01353P	3 BC	8102216 00597447	0 2007 FREIGHTLIN	DELTA	s.22 PASS	BC	s.22
2012-08-01 POWER UNIT TRAILER 1	13:34 P79528 48966C	1 BC BC	8102221 00025509 03050980	0 2000 FREIGHTLIN 2006 UTILITY	DELTA	s.22 FAIL FAIL	BC 40 55 41	
2012-08-01 POWER UNIT TRAILER 1	12:02 P98961 80442C	1 BC BC	8102212 03506574 10186436	3 2006 FREIGHTLIN 2012 UTILITY	DELTA	s.22 PASS FAIL FAIL	BC 44 45 40 46 47 55	
2012-07-30 POWER UNIT SEMI TRAILER	04:40 P86209 84749C	3 BC BC	3348130 00239977	0 KW UTIL	SC33 BOW	s.22 PASS PASS	BC	
2012-07-27 POWER UNIT SEMI TRAILER	08:58 07263P 86656C	3 BC BC	3347726 03565565	0 FRHT UTIL	ROADSIDE	s.22 PASS PASS	BC	
2012-07-26 POWER UNIT SEMI TRAILER	04:55 P86209 03188Y	3 BC BC	3317023 00239977	0 KW UTIL	SC33 BOW H	s.22 PASS PASS	BC	
2012-07-24 POWER UNIT SEMI TRAILER	13:15 P89317 55522B	2 BC BC	3305579 01846874	0 PTRB GDAN	SC33 BOW	s.22 PASS PASS	BC	
2012-07-24 POWER UNIT SEMI TRAILER	10:09 07263P 96375B	3 BC BC	3305154 03565565	0 FRHT GDAN	PORTLAND A	s.22 PASS PASS	BC	
2012-07-21 POWER UNIT TRAILER 1	16:24 08689P 02950D	1 BC BC	8101263 01632101 02210558	0 2003 KENWORTH 2008 UTILITY	SURREY	s.22 PASS FAIL	BC 51	
2012-07-20 POWER UNIT	18:13 09174P	3 BC	8101227 09582853	0 2010 PETERBILT	HUNTER CRE	s.22 PASS	BC	
2012-07-19 POWER UNIT SEMI TRAILER	03:32 P86209 05260D	3 BC BC	3265438 00239977	0 KW UTIL	SC33 BOW H	s.22 PASS PASS	BC	
2012-07-18 POWER UNIT SEMI TRAILER	06:50 P97126 20039D	1 BC BC	3240454 02172581	0 FRHT UTIL	SC33 BOW	s.22 PASS PASS	BC	

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION	ITEM DEFECT(S)
2012-07-13	08:22	1	8100560	0	HUNTER CRE	s.22	BC	s.22
POWER UNIT	04756P	BC	03876943	2007 KENWORTH		PASS		
TRAILER 1	98779C	BC	01657426	2008 UTILITY		FAIL	47 5	
2012-07-12	17:45	3	3198247	0	SC38 STA	s.22	BC	
POWER UNIT	08677P	BC	10070282	FRHT		PASS		
SEMI TRAILER	84817C	BC		UTIL		PASS		
2012-07-11	03:40	2	3170042	0	SC07 FT	s.22	BC	
POWER UNIT	P87523	BC		KW		PASS		
SEMI TRAILER	02950D	BC		UTIL		PASS		
2012-07-10	19:45	3	3170208	0	SC38 STA	s.22	BC	
POWER UNIT	09172P	BC	03589084	FRHT		PASS		
SEMI TRAILER	86656C	BC		UTIL		PASS		
2012-07-09	19:48	3	3484393	0	SC33 BOW H	s.22	BC	
POWER UNIT	P87523	BC	00950178	KW		PASS		
SEMI TRAILER	05266D	BC		UTIL		PASS		
2012-07-05	09:31	3	8099727	0	HUNTER CRE	s.22	BC	
POWER UNIT	00507P	BC	00719501	2007 FREIGHTLIN		FAIL	40	
TRAILER 1	84824C	BC	03720173	2007 UTILITY		PASS		
2012-07-04	23:42	2	8099697	3	SURREY	s.22	BC	
POWER UNIT	P97124	BC	02252296	2005 INTERNATNA		FAIL	40 4	
TRAILER 1	88765C	BC	10212350	2007 UTILITY		OOS	41	
2012-07-04	15:06	2	8099672	0	SURREY	s.22	BC	
POWER UNIT	07259P	BC	10208509	2007 FREIGHTLIN		FAIL	41 5	
2012-07-04	06:17	2	3113588	0	SC33 BOW H	s.22	BC	
POWER UNIT	P97126	BC	02172581	FRHT		PASS		
SEMI TRAILER	90144B	BC		GDAN		PASS		
2012-06-29	08:00	2	3155429	0	I5 MP208	s.22	BC	
POWER UNIT	07228P	BC	07238242	KW		FAIL	44	
2012-06-28	10:30	1	3052853	0	SC15 POR	s.22	BC	
POWER UNIT	04756P	BC	03876943	KW		FAIL	49	
SEMI TRAILER	63042C	BC		UTIL		PASS		
2012-06-27	15:57	1	3086654	0	COTTONWOOD	s.22	BC	
POWER UNIT	P86209	BC	00239977	KW		PASS		
SEMI TRAILER	90148B	BC		GDAN		PASS		

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION	ITEM DEFECT(S)
2012-06-22	13:03	3	3010098	0	SC38 STA	s.22	BC	s.22
POWER UNIT	07259P	BC	10208509	FRHT		FAIL	40	
SEMI TRAILER	4ER333	AB		VANR		PASS		
2012-06-21	11:46	1	8098465	0	HUNTER CRE	s.22	BC	
POWER UNIT	09161P	BC	03847220	2007 KENWORTH		FAIL	40	
TRAILER 1	V88891	AB		2007 G DANE		PASS		
2012-06-17	08:32	1	8097835	0	HAIG	s.22	BC	
POWER UNIT	01372P	BC	03733087	2006 FREIGHTLIN		FAIL	46	
TRAILER 1	55518B	BC	02517167	2005 GREAT DANE		FAIL	45 4	
2012-06-13	09:51	3	8097527	0	HUNTER CRE	s.22	BC	
POWER UNIT	P87530	BC	01358658	2003 KENWORTH		PASS		
TRAILER 1	71827C	BC	10005562	2011 UTILITY		FAIL	55	
2012-06-12	14:03	2	2895187	0	SC33 BOW	s.22	BC	
POWER UNIT	04756P	BC	03876943	KW		PASS		
SEMI TRAILER	05201D	BC		GDAN		PASS		
2012-06-10	08:50	2	2856830	3	SC33 BOW	s.22	BC	
POWER UNIT	01353P	BC	00597447	FRHT		PASS		
SEMI TRAILER	86657C	BC		UTIL		OOS	46	
2012-06-09	07:05	3	2856826	0	SC33 BOW	s.22	BC	
POWER UNIT	05729P	BC	02989579	VOLV		PASS		
SEMI TRAILER	84842C	BC		UTIL		PASS		
2012-06-07	05:06	2	0664932	0	HINTON VIS	s.22	BC	
POWER UNIT	07269P	BC		KEN		FAIL		
SEMI TRAILER	84831C	BC		UTILITY		PASS	47	
2012-06-06	21:20	2	3143758	0	SC38 STA	s.22	BC	
POWER UNIT	01353P	BC	00597447	FRHT		FAIL	41	
SEMI TRAILER	05224D	BC		UTIL		PASS		
2012-06-06	15:00	1	2823702	3	SC33 BOW	s.22	BC	
POWER UNIT	P97126	BC	02172581	FRHT		FAIL	43 4	
SEMI TRAILER	05266D	BC		UTIL		OOS	41	
2012-06-06	08:11	2	2806449	3	SC33 BOW	s.22	BC	
POWER UNIT	07259P	BC	10208509	FRHT		FAIL	40	
SEMI TRAILER	88765C	BC		UTIL		OOS	47	

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION	ITEM DEFECT(S)
2012-06-06	05:56	1	8096583	0	HUNTER CRE	s.22	BC	s.22
POWER UNIT	04776P	BC	02602609	2005 PETERBILT		PASS		
TRAILER 1	40627B	BC	03060614	2006 GREAT DANE		FAIL	41	
2012-06-05	17:59	1	8096503	3	LAILDLAW	s.22	BC	
POWER UNIT	01353P	BC	00597447	2007 FREIGHTLIN		OOS	44	
TRAILER 1	05248D	BC	10383723	2012 UTILITY		PASS		
2012-06-05	16:43	1	8098616	0	LAILDLAW	s.22	BC	
POWER UNIT	07261P	BC	03267342	2006 PETERBILT		PASS		
TRAILER 1	40625B	BC	03046632	2006 GREAT DANE		PASS		
2012-06-05	16:23	1	2806824	0	SC38 STA	s.22	BC	
POWER UNIT	P86209	BC	00239977	KW		FAIL	49	
SEMI TRAILER	V51475	AB		GDAN		FAIL	44	
2012-06-05	14:50	3	2925345	0	I5 MP222	s.22	WA	
POWER UNIT	P97126	BC	02172581	FRHT		PASS		
SEMI TRAILER	10462D	BC		UTIL		PASS		
2012-06-05	11:20	1	8098674	3	LAILDLAW	s.22	BC	
POWER UNIT	P87523	BC	00950178	2002 KENWORTH		OOS	45	
TRAILER 1	86656C	BC	10195074	2012 UTILITY		FAIL	44	
2012-06-05	08:11	1	8096263	0	LAILDLAW	s.22	BC	
POWER UNIT	08688P	BC	02777288	2005 FREIGHTLIN		PASS		
TRAILER 1	10420D	BC	10449708	2012 UTILITY		PASS		
2012-06-05	02:17	1	8098586	0	HUNTER CRE	s.22	BC	
POWER UNIT	04810P	BC	04937980	1998 PETERBILT		FAIL	49	
TRAILER 1	16179C	BC	03082366	2009 HYUNDAI		PASS		
2012-06-04	00:38	3	2806695	0	SR-9 MP 62	s.22	BC	
POWER UNIT	07259P	BC	10208509	FRHT		PASS		
SEMI TRAILER	96700C	BC		UTIL		PASS		
2012-05-30	06:04	3	2806740	0	I	s.22	BC	
POWER UNIT	P86209	BC	00239977	KW		PASS		
SEMI TRAILER	84833C	BC		UTIL		PASS		
2012-05-26	18:51	2	2716706	0	SC33 BOW	s.22	BC	
POWER UNIT	P79528	BC	00025509	FRHT		PASS		
SEMI TRAILER	61164B	BC		UTIL		PASS		

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
CVSA INSPECTION RESULTS
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

INSP DATE	TIME	LEVEL	MICRO#	NSC PTS	LOCATION	DL#	DLJR	DRIVER NAME
VEH TYPE	PLATE#	JR	VEH REG	VEHICLE DESC		PASS/FAIL	INSPECTION	ITEM DEFECT(S)
2012-05-26	11:42	1	8095429	0	SURREY	s.22	BC	s.22
POWER UNIT	05748P	BC	00582523	2001 FRTLINER		FAIL	42	
TRAILER 1	63030C	BC	02288472	2008 UTILITY		PASS		
2012-05-26	08:55	2	2716717	0	SC33 BOW	s.22	BC	
POWER UNIT	07263P	BC	03565565	FRHT		PASS		
SEMI TRAILER	05245D	BC		UTIL		PASS		
2012-05-24	06:57	3	2717415	0	STATE ROUT	s.22	BC	
POWER UNIT	01353P	BC	00597447	FRHT		PASS		
SEMI TRAILER	98777C	BC		UTIL		PASS		
2012-05-23	09:45	2	8099252	0	LANGLEY	s.22	BC	
POWER UNIT	08753P	BC	00263666	2000 KENWORTH		PASS		
TRAILER 1	24887C	BC	03011599	2006 DOEPKER		PASS		
2012-05-22	20:45	2	2716672	0	SC33 BOW	s.22	BC	
POWER UNIT	P97125	BC	02245144	INTL		PASS		
SEMI TRAILER	55518B	BC		GDAN		PASS		
2012-05-19	12:52	1	8094831	0	SURREY	s.22	BC	
POWER UNIT	P90970	BC	02815689	2005 STERLING		FAIL	41 43	
TRAILER 1	05265D	BC	10390315	2012 UTILITY		PASS		
2012-05-18	15:46	1	8094795	0	LAIDLAW	s.22	BC	
POWER UNIT	08647P	BC	00193960	2007 FREIGHTLIN		PASS		
TRAILER 1	86558C	BC	10234609	2012 UTILITY		PASS		
2012-05-17	11:27	1	2608289	0	SC15 POR	s.22	BC	
POWER UNIT	P91787	BC	06461671	FRHT		FAIL	41 44	
SEMI TRAILER	90146B	BC		GDAN		PASS		
2012-05-15	15:42	3	2582832	0	LACEY	s.22	BC	
POWER UNIT	07266P	BC	02196631	FRHT		PASS		
SEMI TRAILER	93510B	BC		UTIL		PASS		
2012-05-14	09:46	1	8094003	0	HUNTER CRE	s.22	BC	
POWER UNIT	03459P	BC	00967378	2008 KENWORTH		PASS		
TRAILER 1	S41852	AB		2012 GRT DANE		FAIL	44	
2012-05-11	16:52	3	2567781	0	N/B	s.22	BC	
POWER UNIT	05748P	BC	00582523	FRHT		PASS		
SEMI TRAILER	05268D	BC		UTIL		PASS		

TOTALS	NUMBER OF INSPECTION REPORTS	NUMBER OF UNITS INSPECTED	NUMBER OF NSC POINTS
	639	262	246

CVSE-NSCSP351 (P)
2015-05-11

MINISTRY OF TRANSPORTATION
NATIONAL SAFETY CODE SYSTEM
NSC CARRIER PROFILE
ACCIDENT INFORMATION
FROM: 2012-MAY-11 TO: 2015-MAY-11

NSC CARRIER: BC 00000200300205

VEHICLE REPORT#	VEHICLE D/L PLATE	JR DRIVER NAME	DATE	TIME	TYP	LOCATION	JR	FAULT RESP	NSC PTS	CHR LAID
2983757	s.22	s.22	2015-01-21	19:10	PD	LYNNWOOD	WA	UNK	2	N
R4455675			2014-10-15	04:23	PD	CHILLIWAC	BC	UNK	2	
2846622			2014-04-08	19:16	PD	RENTON	WA	NF	0	N
2854226			2014-03-17	12:27	PD	MOUNT VER	WA	NF	0	N
R4449412			2014-01-09	18:10	PD	FIELD	BC	F	2	Y
0743323			2013-12-18	17:00	F	CALGARY	AB	NF	0	
0748422			2013-12-16	08:00	PD	CALGARY	AB	NF	0	
0744272			2013-12-02	12:50	PD	CALGARY	AB	UNK	2	
R4455977			2013-11-12	04:55	I	HOPE	BC	F	4	
R4357383			2013-08-15	15:53	PD	SURREY	BC	NF	0	
R4400449			2013-03-21	00:34	I	GOLDEN	BC	F	4	
0687936			2013-01-29	14:30	PD	CALGARY	AB	NF	0	
R4174539			2013-01-24	18:30	PD	GOLDEN	BC	F	2	
R4392272			2013-01-23	00:00	PD	CHILLIWAC	BC	NF	0	
0708541			2013-01-05	18:00	PD	CALGARY	AB	NF	0	
R4326433			2012-12-05	00:00	PD	RICHMOND	BC	NF	0	
R4423631			2012-11-27	21:36	PD	REVELSTOK	BC	NF	0	
2609626			2012-10-04	07:40	PD	PORT ANGE	WA	UNK	2	Y
R4167321			2012-09-10	02:11	I	CHILLIWAC	BC	NF	0	
R4021695			2012-06-07	23:12	PD	RICHMOND	BC	NF	0	
D4333238			2012-06-05	04:00	PD	DELTA	BC	F	2	
2561367			2012-05-15	15:29	PD	OLYMPIA	WA	NF	0	N

TOTALS	NUMBER OF ACCIDENT REPORTS	NUMBER OF NSC POINTS
	22	22

SECTION 11

PAGE: 120

***** END OF PROFILE *****