

PUBLIC PCR REPORT

Report Detail

Date: 2019-07-03 13:23:34

Community name: Hagensborg

Service area: CENTRAL CARIBOO

Road Name: Rte 20 EB

Report type: Request

Submitted By

Name: RCMP

Email:

Phone: 1-250-561-3191

Follow up request: No

Additional Information: 60 km east of Hagensborg on Hwy 20 large boulder in east bound lane, too large for woman to move, reported to RCMP by s.22 June 28 2019

Info

Road Name: Rte 20 EB

Road Number: 20

Action Code: STC

Activity Code:

Description:

Type: r

Season: s

Notes

2019-07-05 10:53:19

ID# 105945 Crew responded to clear up rock.

Information:

Caller Contacted By: Road Foreman

Contacted Date and Time: June 28, 2019 23:56

Contractor's Representative: Robin Foster

Sun 30-Jun-19 06:40a

=====

AREA 17 ~ CENTRAL CARIBOO

DATE/TIME: 06/28/2019 11:26P KAE

NAME: rcmp/mo

PHONE: s.22

LOCATION: bella coola/60 km east of
hagenborg on hwy 20 /3.5 km east of
big rock

ISSUE: large boulder eb lane/too big
for woman to move/was able to move
smalle rocks callers name s 22

delay s.22

06/28/2019 11:38P KAE SHANE NA LM 2CI

06/28/2019 11:51P KAE dean na lm 2ci

06/28/2019 11:55P JAR PASSED TO DEAN -

HE WILL GO OUT AND TAKE A LOOK, ETA

1.5 HOURS

Message History Account: 567102

Taken: Fri 28-Jun-2019 11:26p KAE

Given: Sat 29-Jun-2019 9:23p JES

Serial#: 1

Delivered To: file

=====0000567102=====



BRITISH COLUMBIA

Ministry of Transportation
and InfrastructureMAINTENANCE
CONTRACTOR'S
ROCKFALL REPORT

This rockfall report is only required for rockfall events greater than "fist" size reaching the travelled lanes.
This rockfall report does not need to be completed for rockfall events confined to the ditch or shoulder area.

ISA AMA:	Report for month of: (yy/mm)	Hwy / Road#:	Landmark No:	Travelled Dist: (km)				
117 D/B	119 016	2101	514131410	15.01				
Location: (describe)			Direction from landmark: (check one)					
Hedman Pass			☐ N ☐ S ☒ E ☐ W					
Estimated rockfall date: (yy/mm/dd)		Estimated Rockfall Volume (see estimating guide below):						
119 01/28		<table border="1"> <tr> <th>Ditch</th> <th>Travelled Lanes</th> </tr> <tr> <td> ☐ None ☐ < 0.03 m³ ☐ 0.03 - 0.1 m³ ☐ 0.1 - 0.3 m³ ☐ 0.3 - 0.5 m³ ☐ 0.5 - 1 m³ ☐ 1 - 5 m³ ☐ Other </td> <td> ☐ None ☐ < 0.03 m³ ☐ 0.03 - 0.1 m³ ☒ 0.1 - 0.3 m³ ☐ 0.3 - 0.5 m³ ☐ 0.5 - 1 m³ ☐ 1 - 5 m³ ☐ Other </td> </tr> </table>			Ditch	Travelled Lanes	☐ None ☐ < 0.03 m ³ ☐ 0.03 - 0.1 m ³ ☐ 0.1 - 0.3 m ³ ☐ 0.3 - 0.5 m ³ ☐ 0.5 - 1 m ³ ☐ 1 - 5 m ³ ☐ Other	☐ None ☐ < 0.03 m ³ ☐ 0.03 - 0.1 m ³ ☒ 0.1 - 0.3 m ³ ☐ 0.3 - 0.5 m ³ ☐ 0.5 - 1 m ³ ☐ 1 - 5 m ³ ☐ Other
Ditch	Travelled Lanes							
☐ None ☐ < 0.03 m ³ ☐ 0.03 - 0.1 m ³ ☐ 0.1 - 0.3 m ³ ☐ 0.3 - 0.5 m ³ ☐ 0.5 - 1 m ³ ☐ 1 - 5 m ³ ☐ Other	☐ None ☐ < 0.03 m ³ ☐ 0.03 - 0.1 m ³ ☒ 0.1 - 0.3 m ³ ☐ 0.3 - 0.5 m ³ ☐ 0.5 - 1 m ³ ☐ 1 - 5 m ³ ☐ Other							
Estimated rockfall time: (hh/mm)		Site Conditions (check if any apply) ☐ Heavy Precipitation in last 48 hrs ☐ Freeze/Thaw conditions in last 48 hrs ☐ Ditch filled with compact snow or ice ☐ Vehicle Damage *(see note below) Comments:						
12 00 AM								
* If greater than 1m ³ on travelled lanes or vehicle damage Road Foreman verification of rockfall location and volume is required Verified by (Foreman Name) _____ Date (yy/mm/dd): _____								
Print Name:		Signature:						
Tyler Pootlass		Tyler Pootlass						
Phone No.:		Name of Maintenance Contractor:		Date: (yy/mm/dd)				
250 982 2409		PRL		19/06/28				

Submit to District Manager, Transportation within 7 days following the end of each month (except for below):
 For rockfall event greater than 1 m³ on travelled lanes or vehicle damage:
 Fax copy of the completed report to the Ministry Geotechnical Office for your area within 48 hrs following rockfall event (see fax list).
 Reports completed electronically can be sent via e-mail button below.

Ministry Geotechnical Fax No.'s

Coquillam	604-527-3116
Nanaimo	250-751-3290
Victoria	250-387-7735
Kamloops	250-828-4083
Nelson	250-354-6698
Prince George	250-565-6065
Pouce Coupe	250-786-6835

If fax no. not correct check for latest version
of form on Ministry Internet Site

E-mail Option for Digital Forms

E-Mail Completed

If e-mail button does not work email to:
TRAH_ROCKFALL@gov.bc.ca

17 2013/10

ESTIMATING ROCKFALL VOLUMES	
< 0.03 m ³	5 Gallon Bucket (~ 0.02 m ³).....
0.03 to 0.1 m ³	Mid-size Microwave Oven (~ 0.07 m ³).....
0.1 to 0.3 m ³	45 Gallon Drum (~ 0.2 m ³).....
0.3 to 0.5 m ³	Kitchen Stove (~ 0.4 m ³).....
0.5 to 1.0 m ³	Mid-size Refrigerator (~ 0.75 m ³).....
1.0 to 5.0 m ³	More Easily Estimated
> 5.0 m ³	More Easily Estimated

Received Time Oct. 9, 2019 6:43AM No. 1963

June

28

179-186

Friday

May 2019

S M T W T F S
1 2 3 4
5 6 7 8 9 10 11
12 13 14 15 16 17 18
19 20 21 22 23 24 25
26 27 28 29 30 31



°F
°C

Dean found nest from
Tyler ditching at fuel
Place of first Saw Hal
to (1941)
Sut L1403 So En on

7:00

7:30

8:00

8:30

9:00

9:30

10:00

10:30

1:00

1:30

2:00

2:30

:00

:30

:00

:30

:00

:30

:00

:30

:00

:30

:00

:30

:00

:30

Braille

July 2019

S M T W T F S
1 2 3 4 5 6
7 8 9 10 11 12 13
14 15 16 17 18 19 20
21 22 23 24 25 26 27
28 29 30 31



°F
°C

June

29

180-185

Saturday

8:00 12:00 AM Dean Report
8:30 to Rock on Rd, Minivan
9:00 Ward Stud. RZ, People
9:30 02 Police pushed van off
10:00 Road into ditch Dean found
10:30 off Rd.
11:00
11:30
12:00
12:30

Important

June

30

181-184



°F
°C

Sunday

8:00 Bear Cubs Killed on
8:30 Thurston Rd POSSIBLE
9:00 No trace as well, ended
9:30 She was strayed but stay
10:00 on company did not find her.
10:30
11:00
11:30
12:00
12:30

17

SERVICE AREA:

End KM: 316054

Start KM: 315-918

Total KM: 1410

Foreman Area: Belle Creek

Observer's Name: Tyler

Unit No. P5043

Date: 2019/06/29

YEAR / MONTH / DAY

[illegible]

Road Foreman's Signature:

INTERIOR ROADS

Received

EMPLOYEE TIME CARD

Employee Name: Don Cms/12

Employee Code: 01505

Work Date: 19 06 29 Year Month Day

Service Area: 16 (17)

CMC Number

Job Number

Work Order #

Over Time

CTO ☒

Pay

HOURS

Scheduled 12:00

Actual 04:00

OT 4

Task ID, Number

Comp. Y/N

M.O.T. Mgr Area

Activity Number

Accomp-ishment

Unit of Measure

Highway Number

Bridge Number

Site Number

Landmark

Start km

End km

Class-ification

Pay Code

ST

T- 1/2

DT

Number

Hrs.

Meter Reading

Owned by Interior

Govt

Location Pit/Yard #

Material Code

Quantity Used

Interior Roads B Coola

COMMENTS:

CALL OUT from Dispatch - RCMT

Rock Removal - Vehicle Accident

SANDHILL 12:00 AM - 4:00 AM

SIGNATURE

320-4 4382

Employee: [Signature]

Supervisor: [Signature]

INTERIOR ROADS

Employee Name: Percy Portness

Employee Code: PER 100

Work Date: 19 06 29

Service Area: 16

Time Card

Time Started: 08:20

Time Finished: 12:00

Scheduled: 08:20

Actual: 08:20

Overtime: 0

CMC Number:

Job Number:

Work Order #: 1

Task ID: DBR 840A

Activity Number: 840A

Unit of Measure:

Highway Number:

Bridge Number:

Site Number:

Landmark:

Start km:

End km:

Task: DBR 840A

Class: 4

ST: 4

T + 1/2:

DJ:

Number:

Hrs:

Meter Reading:

Owned by Interior Govt:

Location:

Material Code:

Quantity Used:

Interior Roads B Coala

Comments: Tcp Rock Patrol

Signature: Percy Portness

Supervisor:

Employee: Percy Portness

No. 4974

P. 2/7

