

**From:** s.22  
**To:** [Mustaq, Andaleeb TRAN:EX](#); [Templeton, Dan J TRAN:EX](#); [Miket, Cheralee TRAN:EX](#); [Dinney, Michael TRAN:EX](#); [Gohir, Mohsin TRAN:EX](#); [Stevenson, Christie TRAN:EX](#)  
**Cc:** [Brandon Masschelein](#); [Polydore, Brian TRAN:EX](#)  
**Subject:** RE: PRJ 12523-0002: Hwy 1 - 216 to 264 Widening Advance Work: 232nd Bridge Strike Update  
**Date:** April 26, 2022 7:40:19 PM  
**Attachments:** [image001.png](#)

---

**[EXTERNAL] This email came from an external source. Only open attachments or links that you are expecting from a known sender.**

Hi team,

A few additional notes here

- I arrived on location at 4:02 AM and noticed that the truck had struck the underside of the overpass
- Went and spoke with the driver who seemed injured from his forehead and was in shock
- I guided the driver to safety and made him sit in my truck
- I phoned Vijay (Key west CSO at 4:08 AM)
- I phoned police/ambulance at 4:09 AM
- Vijay arrived on site at 4:20 AM
- RCMP arrived on site at 4:22 AM
- I requested Key west to setup exit closures
- Main road arrived on site and helped out with the flagging
- I visually inspected the bridge for damages; didn't note any obvious damage
- I discussed with the RCMP officer to call out the tow truck and planned to reopen the exits
- CVSE arrived on site – Rick Wiltshire approximately 6:46 AM
- Kent (MOTI) on site to inspect the bridge structure

---

**From:** Mustaq, Andaleeb TRAN:EX <Andaleeb.Mustaq@gov.bc.ca>  
**Sent:** Tuesday, April 26, 2022 10:31 AM  
**To:** Templeton, Dan J TRAN:EX <Dan.Templeton@gov.bc.ca>; s.22  
s.22 ; Miket, Cheralee TRAN:EX <Cheralee.Miket@gov.bc.ca>; Dinney, Michael TRAN:EX <Michael.Dinney@gov.bc.ca>; Gohir, Mohsin TRAN:EX <Mohsin.Gohir@gov.bc.ca>; Stevenson, Christie TRAN:EX <Christie.Stevenson@gov.bc.ca>  
**Cc:** s.22 ; Polydore, Brian TRAN:EX <Brian.Polydore@gov.bc.ca>  
**Subject:** PRJ 12523-0002: Hwy 1 - 216 to 264 Widening Advance Work: 232nd Bridge Strike Update

Hello All,

An update from this morning's incident where the contractor's dump truck with open box traveling along Hwy 1 westbound on ramp hit the 232<sup>nd</sup> St overpass.

Truck driver was injured and transported to hospital; status update is pending on the extent of the injuries.

Ministry Bridge Engineer inspected the 232<sup>nd</sup> bridge and both the overpass and Hwy 1 onramp/offramp opened to traffic at approximately 9:05am. Details of incident outlined below.

**1. Location:**

- Westbound Highway 1 onramp at 232<sup>nd</sup>

**2. Impact to Traffic**

- WB Hwy 1 onramp and offramp closed from 4:10am to 9:05am (traffic detoured to secondary onramp)
- WB Hwy 1 onramp/offramp OPENED 9:05am

**3. Incident Description**

- dump truck with open box hit the 232<sup>nd</sup> St overpass

**4. Public Comments**

- TMCBC informed at 4:18am, DriveBC updates posted online, News media reported from scene

**5. ETO: Estimated time of opening:**

- WB Hwy 1 onramp/offramp OPENED at 9:05am

**6. Detailed Event Description**

- Contractor's dump truck for Hwy 1-216 to 264 Preload project was traveling on Hwy 1 WB onramp with box in upright position and struck the 232<sup>nd</sup> overpass

**7. Injuries\Fatalities**

- Injuries: People Involved: 1 (confirmed, transported to hospital, non life threatening, pending update)

**8. MoTI Staff on Site/on Call**

- Area Manager/Bridge Area Manager: Updated
- Bridge/Structural Engineer: Inspected on Site
- Field Services Supervisor: Oversaw Site

**9. Incident Responders reported to scene**

- Maintenance Contractor: Mainroad
- RCMP, Fire, Ambulance
- Tow Trucks: 3 Clover Towing Trucks
- Sand truck: Mainroad

**10. Site History**

- Prime Contactor: Key West

**11. Weather/Road Conditions**

- Weather: Clear, +4C
- Road Conditions, dry road

**12. Maintenance Contractor**

- MC on scene at 4:40am

**13. Traffic Management**

- Mainroad and Key West provided traffic management for detour

Photos of the incident attached.

Thank you,

Andaleeb Mustaq  
Assistant Ministry Representative  
Provincial Field Services

**Ministry of Transportation & Infrastructure**

Address: 8298 216<sup>th</sup> St. Langley, BC V1M 2X8

Email: [andaleeb.mustaq@gov.bc.ca](mailto:andaleeb.mustaq@gov.bc.ca)

Phone: 604.612.7170





2022-04-26 7:38 AM  
49° 8' 12.4" N, 122° 34' 53.1" W

s.22



2022-04-26 8:37 AM  
49° 8' 12.1" N, 122° 34' 52.5" W

s.22



2022-04-26 8:23 AM

49° 8' 12.0" N, 122° 34' 52.6" W

s.22

Page 6 of 17 TRA-2022-21896



2022-04-26 6:51 AM  
49° 8' 12.5" N, 122° 34' 52.5" W

s.22



2022-04-26 4:07 AM  
49° 8' 11.6" N, 122° 34' 51.3" W

S. 22  
F17 TRA-2022-2189





2022-04-26 5:32 AM  
49° 8' 12.6" N, 122° 34' 52.5" W

\$ 22  
17 TRA-2022-2189



## VEHICLE INSPECTION REPORT / NOTICE and ORDER

Vehicle(s) inspected this **26** of **APR** YR **2022** at **06:36** (24hr Clock) on **ON RAMP HWY 1 AT 232ND WB** at or near **Langley**  
 INSPECTION LEVEL: **2 - Walk-Around Driver and** CAMPAIGN: **CVSA** Violation Ticket #: **s.22**

**INSPECTION RESULT: Out of Service****OUT OF SERVICE BY: MOTOR VEHICLE ACT / REGS UNTIL HIGHLIGHTED ITEMS BELOW ARE REPAIRED.****INSPECTION ITEMS NOTED BELOW TO BE REPAIRED: SEE NOTICE AND ORDER 1****SEND PROOF OF REPAIRS TO: 8150 Nordel Way Delta V4G8A9 /FAX:604-581-4371**

The undersigned Peace Officer has reasonable and probable grounds to believe that the vehicle(s) inspected and described below does not comply with the Motor Vehicle, Commercial Transport or Passenger Transportation Act and Regulations. The owner/operator is hereby given notice to:

PU: ☒ 1. Immediately remove the vehicle from the highway until such time as it complies with the Motor Vehicle Act and Regulations (Division 25)

This Notice and Order does not authorize operation of the vehicle(s) with identified defects. Non-compliance with this Notice and Order is an offence. Police: ☐ Peace Officer: ☒

**Power Unit: Out of Service**

CVSA decal:

Owner: **KEY-WEST ASPHALT (333) LTD.**  
 Address: **31244 SOUTH FRASER WAY**  
 City: **ABBOTSFORD** Prov: **BC** Postal Code: **V2T6L5**  
 Registration: **S.15** NSC #: **202726490** Jur: **BC**  
 Plate #: **RL6172** Year: **2008** Make: **PETERBILT**  
 Body Style: **DUMP TRUCK** VIN: **s.15**  
 GVW: **0044000** Odometer: **662415** **KM**  
 CVIP decal: **FQ47510** CVIP Jur: **BC**  
 Cargo Seal #: **UN:** **DG Type:**

**Driver:** **s.22****D.L.#** **s.22****D.O.B.:** **s.22****Jur:** **BC****INSPECTION RESULTS**

"X" - Violation Present "O" - Out of Service "C" - Pass with Caution "N" - Inspection Note

INSPECTION ITEMS	#	PU	COMMENTS
Driver	40	X	Fail to wear seatbelt as required
Steering	43	O	Steering column broken due to driver injury
Suspension	46	O	Axle shift on Axle 3 due to collision with overpass
Body & Frame	51	X	Rear frame rails broken due to collision with overpass.
	51	X	hydraulic ram to lift box had to be removed due to collision
Miscellaneous	55	X	Box from vehicle wedged under the over pass due to collision

**BRAKE INFORMATION****\*\*\* BRAKE DETAILS NOT APPLICABLE FOR THIS INSPECTION \*\*\*****ADDITIONAL COMMENTS:**

Langley RCMP File s.15  
 Plates seized roadside CVI Decal Removed  
 Pre trip dated 26 April 22 and 25 April 22 seized by Officer MV048  
 Owner served with Notice and Order

Peace Officer (Inspector): **R.WILTSHIRE**Number: **MV048**

Signature: \_\_\_\_\_

8150 Nordel Way Delta V4G8A9

Assist:

I HEREBY ACKNOWLEDGE RECEIPT OF A COPY OF THIS INSPECTION REPORT.

DRIVER SIGNATURE: \_\_\_\_\_

**SEE REVERSE FOR DETAILS REGARDING COMPLIANCE.**

The information on this form is collected under the authority of the Motor Vehicle Act, Section 217. The information will be used to process your vehicle inspection and/or Notice and Order. If you have any questions please contact the issuing Officer or call CVSE at (250) 952-0577. Visit [www.cvse.ca](http://www.cvse.ca)

## VEHICLE INSPECTION COMPLIANCE INFORMATION

ON THE DATE AND PLACE NOTED A VEHICLE(S) REGISTERED IN YOUR NAME WAS INSPECTED IN ORDER TO ENSURE THE SAFE PERFORMANCE OF THE VEHICLE(S). THE COMPONENTS MARKED WITH AN "O" MUST BE CORRECTED IMMEDIATELY. THE COMPONENTS MARKED WITH AN "X" MUST BE REPAIRED BEFORE THE TIMEFRAME INDICATED. THE COMPONENTS MARKED WITH A "C" ARE NOTED TO MAKE YOU AWARE OF POSSIBLE VIOLATIONS. "PU" INDICATES POWER UNIT, "T1" TRAILER #1, "T2" TRAILER #2 AND "T3" TRAILER #3.

ANY QUERIES REGARDING THIS REPORT SHOULD BE DIRECTED TO THE COMMERCIAL VEHICLE SAFETY AND ENFORCEMENT BRANCH, MINISTRY OF TRANSPORTATION AND INFRASTRUCTURE, PO BOX 9250 STN PROV GOVT, VICTORIA, BC V8W 9J2. VISIT [WWW.CVSE.CA](http://WWW.CVSE.CA)

## NOTICE AND ORDER COMPLIANCE INFORMATION

You **MUST** do the following (as indicated on Page 1):

A Notice and Order 1 has been issued to s.22

The vehicle is to be immediately removed from the highway and towed to a location of the operator's choice or place designated by the peace officer, at the owner's expense. It is to be kept from the highway until such time as it is repaired and passes an inspection performed by an Authorized Inspector at a Designated Inspection Facility.

This Notice and Order does not authorize operation of the vehicle(s) with identified defects. Non-compliance with this Notice and Order is an offence.

## NOTICE

The owner may choose not to have the vehicle inspected or repaired, but rather to surrender the vehicle license and number plates to the Vice President Operations – ICBC or his/her designate. Should the vehicle license and number plates be surrendered or seized by a Peace Officer, the vehicle owner must make a separate application to ICBC or its agents for a refund.

It is the obligation of the registered owner to advise a subsequent registered owner of any outstanding vehicle inspection requirements.

## DISPOSITION

Violation(s) corrected: Yes ☐ No ☐ Date: \_\_\_\_\_ Agency: \_\_\_\_\_

Peace Officer (Print): \_\_\_\_\_ Number: \_\_\_\_\_

## WARNING

IT IS AN OFFENCE TO OPERATE A VEHICLE WHICH DOES NOT COMPLY WITH THE MOTOR VEHICLE ACT AND REGULATIONS OR THIS NOTICE AND ORDER. FAILURE TO COMPLY WITH A NOTICE AND ORDER MAY RESULT IN THE REFUSAL OF FURTHER VEHICLE LICENSE TRANSACTIONS. PENALTIES FOR OPERATING A VEHICLE IN CONTRAVENTION OF A NOTICE AND ORDER INCLUDE A FINE AND SEIZURE OF THE VEHICLE LICENSE AND NUMBER PLATES.

The information on this form is collected under the authority of the Motor Vehicle Act, Section 217. The information will be used to process your vehicle inspection and/or Notice and Order. If you have any questions please contact the issuing Officer or call CVSE at (250) 952-0577. Visit [www.cvse.ca](http://www.cvse.ca)

















